

**ZIEGLER** CAT901 West 94th Street  
Minneapolis MN 55420-4236MINNESOTA  
IOWA  
MISSOURI  
WISCONSIN952-888-4121 800-352-2812  
515-957-3800 800-342-7002  
515-957-3800 800-342-7002  
515-957-3800 800-342-7002Sold To: M B E INCORPORATED  
530 RIVER ST S  
DELANO MN 55328

Invoice Number: SW000175662

Date: 11/08/13  
Account No.: 5320900

Ship To:

Page: 1

W7448

**Invoice Information**WO Number: FM32968  
WO Date: 9/17/13  
  
Store: MINNEAPOLIS  
Payment Terms: CHARGE  
P/O Number: D6R  
Ship Via:  
Invoice Type: 1H1H1HMake: CATERPILLAR  
Model: D6RDSLGP  
Serial: 09PN01039  
PIN:  
Id No:  
Cust Unit: L120  
  
Meter: 4188.0**Invoice Summary**Parts: 7,116.99  
Labor: 11,916.00  
Misc: 1,017.85  
Taxes: 1,428.63

Amount Due: \$21,479.47

Invoice Total: 21,479.47

ENTERED  
11/19DUE BY 10TH OF THE NEXT MONTH  
A service charge of 1 1/2 % per month will be assessed on all past due accounts.

To ensure proper credit, please detach this portion, at the perforation, and return with remittance.

M B E INCORPORATED  
530 RIVER ST S  
DELANO MN 55328Account Number: 5320900  
Invoice Number: SW000175662  
Invoice Date: 11/08/13

Please remit to:

ZIEGLER INC.  
SDS 12-0436  
PO BOX 86  
MINNEAPOLIS, MN 55486-0436

Amount Due: \$21,479.47

Amount Enclosed: \_\_\_\_\_



901 West 94th Street  
Minneapolis MN 55420-4236



MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Invoice Number: SW000175662 Date: 11/08/13 Account No.: 5320900 Page: 2

Quantity	Item	N/R	Description	Unit Price	Extended
----------	------	-----	-------------	------------	----------

**CLEAN MACHINE**

CLEAN AREA TO BE REPAIRED

REPAIR PROCESS COMMENTS:

REMOVED BELLYPANS AND PANELS. CLEANED MACHINE FOR  
ENGINE REPAIR.

F/R LBR

500.00 \*

SEGMENT 01 TOTAL

500.00 T

**REPAIR RADIATOR TANK**

REPAIR RADIATOR NECK -- CRACKED

REPAIR PROCESS COMMENTS:

REMOVED THE OLD RADIATOR NECK. CLEANED THE AREA  
WHERE THE NEW ONE WILL BE INSTALLED. INSTALLED  
THE NEW RADIATOR NECK. SWAPPED THE STEP TUBE FROM  
THE OLD NECK. CHECKED FOR LEAKS. DID NOT FIND ANY  
LEAKS.

1 8N-8846	NECK FILLER	S5	11.30	11.30
	TOTAL PARTS	SEG. 10		11.30 *
	TOTAL LABOR	SEG. 10		58.00 *
	SEGMENT 10 TOTAL			69.30 T

**REPAIR RADIATOR**

CUSTOMER COMPLAINT:

RADIATOR WAS LEAKING BADLY.

PUNCTURE IN ONE OF THE RADIATOR CORES.

REPAIR PROCESS COMMENTS:

RAN MACHINE INTO THE SHOP AND REMOVED THE GRILL  
AND RIGHT SIDE ENGINE PANELS. STARTED MACHINE TO  
PINPOINT WHERE THE LEAK WAS COMING FROM. FOUND  
ONE CORE LEAKING BADLY. DRAINED COOLANT DOWN &  
REMOVED THE ONE LEAKING CORE. REPLACED IT ALONG  
WITH THE BOTTOM TANK SEAL AND TOP CONNECTING  
HOSES. PUMPED COOLANT BACK INTO THE SYSTEM AND  
TOPPED OFF WITH AN ADDITIONAL 4 GALLONS OF ELC.  
STEAMED OFF RADIATOR AREA AND RAN MACHINE TO  
CHECK FOR ANY ADDITIONAL LEAKS. NONE WERE FOUND.  
INSTALLED GRILL AND PANELS.

\*\*THE RADIATOR CORE THAT WAS REPLACED WAS THE  
THIRD ONE FROM THE RIGHT SIDE OF THE MACHINE AS  
VIEWED FROM SEATED IN THE CAB.

4 1P-4278	CLAMP	S5	1.30	5.20
1 6I-2431	SEAL	S5	41.78	41.78
2 106-4572	HOSE	S5	4.69	9.38
1 175-0505	CORE AS-RADI	S5	489.14	489.14
9 238-8648	COOLANT-ELC	S5	12.75	114.75
	TOTAL PARTS	SEG. 11		660.25 *
	TOTAL LABOR	SEG. 11		696.00 *
	SEGMENT 11 TOTAL			1356.25 T

**FLUSH RADIATOR**

FLUSH RADIATOR GROUP -- HAS OIL IN COOLANT SYSTEM

REPAIR PROCESS COMMENTS:

RAN WATER AND STEAM CLEANER SOAP IN THE COOLING



901 West 94th Street  
Minneapolis MN 55420-4236



MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Invoice Number: SW000175662 Date: 11/08/13

Account No.: 5320900 Page: 3

Quantity	Item	N/R	Description	Unit Price	Extended
----------	------	-----	-------------	------------	----------

SYSTEM. STALLED MACHINE OUT AND RAN FOR AN ADEQUATE TIME IN ORDER TO THE HAVE THE THERMOSTAT OPEN AND FOR THE SOAP TO GET EVERYWHERE. DRAINED. RAN STRAIGHT WATER IN SYSTEM. RAN MACHINE AGAIN. DRAINED. FOUND THE WATER TO STILL BE TOO FULL OF OIL. FILLED WITH CAT BRAND FLUSH AND WATER. RAN MACHINE UNTIL HOT AGAIN. DRAINED. FLUSHED THE COOLING SYSTEM WITH CLEAN HOT WATER UNTIL NO SOAP WAS COMING OUT OF THE DRAIN ON THE RADIATOR AND THE DRAIN ON THE TRANSMISSION OIL COOLER. FINISHED DRAINING, CLOSED DRAINS, FILLED MACHINE WITH COOLANT. RAN MACHINE TO MIX COOLANT. CHECKED THE FREEZING TEMPERATURE AT -32 DEGREE FAHRENHEIT.

4 4C-4610	CLEANER	S5	13.57	54.28
	TOTAL PARTS	SEG. 12		54.28 *
	TOTAL LABOR	SEG. 12		464.00 *
	SEGMENT 12 TOTAL			518.28 T

**TROUBLESHOOT ENGINE**

**CUSTOMER COMPLAINT:**

CHASKA, IN CITY LIMITS, MN

TROUBLESHOOT ENGINE LOTS OF OIL IN COOLING SYSTEM

**CAUSE OF FAILURE:**

HEAD GASKET

**RESULTANT DAMAGE:**

PRESSURE RADIATOR

**REPAIR PROCESS COMMENTS:**

ARRIVED AT MACHINE I TOOK RADIATOR CAP OFF AND FOUND OIL RESIDUE IN COOLING SYSTEM. ST CLOUD PUT A OIL COOLER ON THE MACHINE A FEW MONTHS AGO SO I FIGURED THAT IT WAS RESIDUAL OIL SO I SUCKED THE TOP OF THE TANK. I THEN RAN THE MACHINE TO LOOSEN UP MORE OIL IN THE COOLING SYSTEM. WHEN I WAS DOING THAT I NOTICED THAT THERE WAS COOLANT COMING OUT OF THE OVER FLOW HOSE. I THEN RAN MACHINE UP TO OPERATING TEMP. I THEN RELEASED THE PRESSURE FROM THE COOLING SYSTEM AND PUT MY COOLANT PRESSURE TESTER ON IT. WITH THE ENG AT IDLE I COULD WATCH THE PRESSURE GAUGE BUILD TO 15 PSI IN UNDER A MIN. I THE BLED THE SYSTEM AGAIN AND TRIED IT AGAIN. IT DID THE SAME THING. THE TEST WAS INDICATING THAT THERE WAS A BAD HEAD GASKET AND BUILDING COMPRESSION INTO THE RADIATOR. I THEN SENT THE MACHINE TO THE SHOP TO FLUSH THE RADIATOR AND REPLACE THE HEAD GASKET.

**CUSTOMER COMPLAINT:**

WATERTOWN.MN

**REPAIR PROCESS COMMENTS:**

CHECKED COOLANT LEVEL. FOUND COOLANT IS LOW. ADDED 5 GAL OF COOLANT. CHECKED ENGINE COMPARTMENT FOR COOLANT LEAKS. REMOVED RIGHT SIDE PANEL. PRESSURE TESTED COOLANT SYSTEM. FOUND RADIATOR HAS A BROKEN CORE ON THE LOWER RIGHT HAND SIDE AT THE BOTTOM OF THE CORE. REINSTALLED SIDE PANEL. TAGGED MACHINE, ONLY RUN TO LOAD ON A TRAILER FOR TRANSPORT AND CHECK COOLANT.

TOTAL LABOR	SEG. 20	480.00 *
SEGMENT 20 TOTAL		480.00 T

MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Invoice Number: SW000175662

Date: 11/08/13

Account No.:

5320900

Page: 4

Quantity	Item	N/R	Description	Unit Price	Extended
----------	------	-----	-------------	------------	----------

REMOVE & INSTALL CYLINDER HEAD ASSEMBLY  
 REMOVE AND INSTALL CYLINDER HEAD  
 REPAIR PROCESS COMMENTS:

REMOVED BELLY PANS. REMOVED THE HOOD. REMOVED ALL THE ENGINE SIDE PANELS AND ACCESS DOORS FROM THE MACHINE. REMOVED THE PRE CLEANER. REMOVED THE AIR CLEANER. DRAINED COOLANT. REMOVED THE COOLANT ELBOW AND THERMOSTAT HOUSING FROM THE ENGINE. REMOVED THE FLOOR MAT AND THE FLOOR PLATES FROM THE CAB. REMOVED THE MUFFLER SUPPORT AND FAN. REMOVED THE TRANSMISSION FILL TUBE AND DIPSTICK. REMOVED THE EXHAUST MANIFOLD, TURBO, INTAKE HOSES, AND EXHAUST STACK. REMOVED THE VALVE COVER. REMOVED THE FUEL INJECTION LINES AND FUEL NOZZLES. REMOVED THE ROCKERS. REMOVED THE PUSH TUBES. REMOVED THE LIFTERS. REMOVED THE HEAD BOLTS. REMOVED THE CYLINDER HEAD FROM THE MACHINE. SENT THE CYLINDER HEAD TO SPEC SHOP FOR CLEANING AND INSPECTING. SPEC SHOP FOUND THE HEAD TO BE CRACKED. A REMAN HEAD WAS ORDERED. FOUND COUNTER BORES NEEDED TO BE CUT AFTER CHECKING LINER PROTRUSION. AFTER LINER PACKS AND BEARINGS WERE ROLLED IN. INSTALLED HEAD SPACER PLATE. INSTALLED HEAD GASKET. INSTALLED LIFTERS. INSTALLED CYLINDER HEAD. TORQUED HEAD BOLTS TO 115 FT LBS THEN TO 185 FT LBS IN SEQUENCE. INSTALLED PUSH TUBES. INSTALLED ROCKER ARMS. SET VALVE LASH TO .015 IN ON INTAKE AND .025 IN ON EXHAUST. TORQUED JAM NUTS. INSTALLED VALVE COVER. CHECKED ALL 6 FUEL NOZZLES. FOUND THAT 2 OF THEM WERE STILL FUNCTIONAL. FOUND ONE WITH A DROPPED TIP. ALSO FOUND THE REMAINING 3 WERE NOT IN GOOD CONDITION. INSTALLED 4 RE MAN NOZZLES. INSTALLED FUEL INJECTION LINES. FOUND THE OLD EXHAUST MANIFOLD TO BE CRACKED. INSTALLED A CAT CLASSIC MANIFOLD. INSTALLED THE TURBO AND ALL THE AIR INTAKE LINES. INSTALLED THE TRANSMISSION DIPSTICK TUBE AND FILL TUBE. INSTALLED THE MUFFLER SUPPORT AND FAN. INSTALLED A NEW THERMOSTAT. INSTALLED THE THERMOSTAT HOUSING AND COOLANT LINES. INSTALLED THE AIR CLEANER. FILLED MACHINE WITH WATER AND A NEW OIL FILTER. PRELUBED THE ENGINE WITH OIL THROUGH THE OIL SAMPLE PORT. AFTER RUNNING MACHINE, REMOVED THE OIL FILTER AND CUT OPEN. FOUND SOME DEBRIS IN THE OIL FILTER. INSTALLED A NEW OIL FILTER, AND TOPPED OFF THE ENGINE OIL. AFTER RUNNING THE ENGINE AGAIN, REMOVED THE ENGINE OIL FILTER AND CUT OPEN. FOUND THE FILTER TO BE CLEAN. INSTALLED A NEW OIL FILTER, AND TOPPED OFF THE ENGINE OIL. INSTALLED ALL THE ENGINE SIDE PANELS, BELLY PANS, AND THE HOOD BACK ONTO THE MACHINE. SWAPPED OUT THE BATTERIES FOR BETTER USED BATTERIES. CLEANED MACHINE WHERE REPAIRS WERE MADE.

1 392-3548

KIT GASKET

S5

355.90

355.90

TOTAL PARTS SEG. 22

355.90 \*

TOTAL LABOR SEG. 22

1392.00 \*

SEGMENT 22 TOTAL

1747.90 T

REPLACE WITH CAT REMAN CYLINDER HEAD ASSEMBLY

MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Invoice Number: SW000175662 Date: 11/08/13 Account No.: 5320900 Page: 5

Quantity	Item	N/R	Description	Unit Price	Extended
----------	------	-----	-------------	------------	----------

**REPAIR PROCESS COMMENTS:**

WASHED HEAD, MAGNAFLUXED HEAD AND FOUND IT TO BE CRACKED FROM INTAKE SEAT GOING TO AND DOWN INJECTOR HOLES ON CYLINDERS NO#1, 2 & 5. REPLACED HEAD WITH ONE REMAN PN#OR-2549. RETURNED CORE, WASHED HEAD AND SWITCHED OVER FITTINGS. TAPE OFF PORTS AND BROUGHT OUT TO MAIN SHOP. TAK.

1 OR-2549	HEAD CYL REM	S5	1437.06	1437.06
1	CORE CHARGE	S5	1285.78	1285.78
1-	CORE CREDIT	S5	1285.78	1285.78-

TOTAL PARTS	SEG. 24	1437.06 *
-------------	---------	-----------

TOTAL LABOR	SEG. 24	115.00 *
-------------	---------	----------

SEGMENT 24 TOTAL		1552.06 T
------------------	--	-----------

**MACHINE/GRIND/MILL LINER SEAT/INSERT**
**REPAIR PROCESS COMMENTS:**

CLEANED AND INSPECTED CYLINDER BLOCK. MACHINED ALL SIX COUNTER BORES FOR 0.030" INSERTS, PN# 9L-5855. DE-BURRED CYLINDER BLOCK AND TAGGED ENGINE, STATING THE ENGINE MUST BE FINAL CLEANED BEFORE ASSEMBLY. JDN.

6 9L-5855	SHIM	S5	7.59	45.54
TOTAL PARTS	SEG. 25		45.54 *	
TOTAL LABOR	SEG. 25		819.00 *	
SEGMENT 25 TOTAL			864.54 T	

**REPAIR ENGINE**

REPAIR ENGINE ---INSTALL LINER PACKS --ROLL IN BEARINGS --INSPECT OIL PUMP--TEST NOZZLES

**REPAIR PROCESS COMMENTS:**

AFTER THE CYLINDER HEAD WAS REMOVED. CHECKED THE LINER PROJECTION OF THE ENGINE. FOUND THAT NUMBER 5 LINER WAS LOW, AND THE ENGINE REQUIRED COUNTER BORES TO BE CUT. REMOVED ALL 6 LINER PACKS.

CLEANED ALL SOOT, OIL, AND COOLANT FROM THE CRANKCASE. CLEANED THE BLOCK DECK. HAD SPEC SHOP CUT THE COUNTER BORES INTO THE BLOCK. RE-CLEANED THE DECK AND THE CRANKCASE. MEASURED NEW CLASSIC MAIN BEARINGS FOR CONSISTENCY. ALL WERE WITHIN .0005 INCH OF EACH OTHER AND WITHIN .001 INCH OF THE MAIN BEARINGS REMOVED. ROLLED IN NEW MAIN BEARINGS. TORQUED THE BOLTS TO 30 FT LBS PLUS 90 DEGREES TURN. MEASURED THE NEW CAT ROD BEARINGS FOR CONSISTENCY. FOUND THAT ALL ROD BEARINGS WERE WITHIN .0005 INCH OF EACH OTHER AND .001 OF THE OLD BEARINGS. MEASURED ALL THE LINER FLANGES.

FOUND THEM TO BE WITHIN SPEC. INSTALLED RE MAN LINER PACKS ALONG WITH NEW CAT ROD BEARINGS.

TORQUED THE NUTS TO 30 FT LBS PLUS 90 DEGREES TURN. CLEANED ANY OIL AND DEBRIS OFF THE DECK.

INSPECTED OIL PUMP IT WAS OK TO BE REUSED.

INSTALLED OIL PUMP AND INSTALLED OIL PAN.

2 OL-0364	LOCK	S5	.24	.48
1 OR-4124	NOZZLE AS	S5	80.79	80.79
1	CORE CHARGE	S5	79.22	79.22
1-	CORE CREDIT	S5	79.22	79.22-
2 OR-4124	NOZZLE AS	S5	80.79	161.58

MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Invoice Number: SW000175662 Date: 11/08/13

Account No.: 5320900

Page: 6

Quantity	Item	N/R	Description	Unit Price	Extended
2			CORE CHARGE	79.22	158.44
2-			CORE CREDIT	79.22	158.44-
1	0R-4124		NOZZLE AS	80.79	80.79
1			CORE CHARGE	79.22	79.22
1-			CORE CREDIT	79.22	79.22-
6	0R-4488		CYL KIT	477.88	2867.28
6-			CORE CHARGE	231.29	1387.74
2	OS-1571		CORE CREDIT	231.29	1387.74-
1	OS-1590		CAP SCREW	.55	1.10
2	1P-4278		CAP SCREW	.61	.61
3	1R-1807		CLAMP	1.30	2.60
6	1T-0416		LUBE FILTER	15.41	46.23
1	2M-5407		BOLT	2.27	13.62
12	2N-2766		GASKET	.90	.90
1	2P-8746		LOCK NUT	4.94	59.28
11	2S-6160		GASKET	1.03	1.03
1	3J-7354		WASHER	1.49	16.39
2	3K-0360		SEAL O RING	.72	.72
1	3R-1317		SEAL	.96	1.92
1	4M-6480		HOSE	10.35	10.35
67	5P-1465		GASKET	.84	.84
1	6B-7469		CM-HOSE STK	.12	8.04
1	6N-0009		SPACER	6.59	6.59
1	6N-1558		RING	6.05	6.05
9	6V-1426		RING-SEAL	5.03	5.03
2	6V-1427		STUD	9.62	86.58
1	7F-7590		STUD	10.27	20.54
6	7W-4486		GASKET	1.24	1.24
1	8H-9788		WASHER	1.03	6.18
1	8M-0904		GASKET	.78	.78
2	8M-5248		SEAL O RIN	.80	.80
1	8M-5253		SEAL O RIN	3.56	7.12
1	8N-6854		GASKET	2.28	2.28
1	8S-8874		LOCK-NUT	2.58	2.58
1	9L-1658		STUD	3.11	3.11
6	9L-9098		SEAL	9.51	9.51
1	9M-4849		SEAL O RING	4.12	24.72
3	9S-8752		NUT	4.14	4.14
6	9X-2836		SCREW	.20	.60
1	9X-6458		WASHER HARD	1.10	6.60
2	100-3652		THRUST-PLATE	.50	.50
1	111-8010		REGULATOR	33.45	66.90
3	114-2687		SEAL-O-RING	52.41	52.41
1	127-1966		HOSE	3.88	11.64
1	131-6645		HOSE	55.70	55.70
1	134-0641		WASHER	9.52	9.52
1	169-4199		GASKET-OIL	1.21	1.21
1	169-4200		GASKET	31.71	31.71
1	188-6126		GASKET	28.68	28.68
1	210-9479		HOSE	1.06	1.06
7	238-8647		CAT ELC	22.16	22.16
1	238-8649		COOLANT-ELC	25.87	181.09
1	261-0899		MANIFOLD-CLA	61.10	61.10
6	271-2489		SEAL-WASHER	231.80	231.80
6	328-5572		BEARING-ROD	1.33	7.98
12	371-8946		CM HOSE BULK	24.37	146.22
7	376-9085		BRG-MAIN-CLA	1.16	13.92
				10.81	75.67
			TOTAL PARTS	SEG. 26	4548.27 *
15.00			TOTAL LABOR	SEG. 26	6902.00 *
2.00			CAT DE OIL ULS		203.25
			CAT HYD OIL 10W		37.10
			TOTAL MISC CHGS	SEG. 26	240.35 *



901 West 94th Street  
Minneapolis MN 55420-4236



MINNESOTA 952-888-4121 800-352-2812  
IOWA 515-957-3800 800-342-7002  
MISSOURI 515-957-3800 800-342-7002  
WISCONSIN 515-957-3800 800-342-7002

Invoice Number: SW000175662 Date: 11/08/13

Account No.: 5320900

Page: 7

Quantity	Item	N/R	Description	Unit Price	Extended
----------	------	-----	-------------	------------	----------

SEGMENT 26 TOTAL

11690.62 T

RESEAL TRANS LINES/HOSES  
REPAIR PROCESS COMMENTS:

FOUND A HOSE THAT WAS LEAKING FROM THE PRIORITY VALVE. REMOVED ONE END OF THE HOSE AND FOUND THE O-RING MISSING. INSTALLED THE O-RING AND INSTALLED THE LINE. NO MORE LEAKS.

1 8M-4986 SEAL O RING S5 4.39 4.39

TOTAL PARTS SEG. 30 4.39 \*

SEGMENT 30 TOTAL 4.39 T

PERFORM TECHNICAL ANALYSIS 1  
PERFORM TA INSPECTIO

F/R L/M 349.00 \*

SEGMENT 98 TOTAL 349.00 T

TRAVEL TO/FROM MACHINE

105.00	TOTAL LABOR TRAVEL MILEAGE	SEG. 99	240.00 *
			178.50
	TOTAL MISC CHGS	SEG. 99	178.50 *
	SEGMENT 99 TOTAL		418.50 T

SERVICE SUPPLIES AND ENVIRONMENTAL CHARGES

500.00 T

TAX EXEMPTION LICENSE 9732569

MN SALES TAX-6.875%

1378.50 T

TRANSIT TAX 0.25%

50.13 T

DUE BY 10TH OF THE NEXT MONTH

INVOICE TOTAL

21,479.47



901 West 94th Street  
Minneapolis MN 55420-4236



Sold To: M B E INCORPORATED  
530 RIVER ST S  
DELANO MN 55328

MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Page: 1

Invoice Number: SW140133903

Date: 8/28/13

Account No.: 5320900

Ship To:

007411

**Invoice Information**

WO Number:	FM31751	Make:	CATERPILLAR
WO Date:	7/16/13	Model:	D6RDSLGP
Store:	MPLS FIELD SERVICE	Serial:	09PN01039
Payment Terms:	CHARGE	PIN:	
P/O Number:	D6R 9PN01039	Id No:	
Ship Via:		Cust Unit:	L120
Invoice Type:	1H1H1H	Meter:	4125.0

**Invoice Summary**

Parts:	201.48	Amount Due:	\$1,618.54
Labor:	1,020.00		
Misc:	287.30		
Taxes:	109.76		
Invoice Total:	1,618.54		

ENTERED

DUE BY 10TH OF THE NEXT MONTH  
A service charge of 1 1/2 % per month will be assessed on all past due accounts.

To ensure proper credit, please detach this portion, at the perforation, and return with remittance.

*ml*

M B E INCORPORATED  
530 RIVER ST S  
DELANO MN 55328

Account Number: 5320900  
Invoice Number: SW140133903  
Invoice Date: 8/28/13

Please remit to:

ZIEGLER INC.  
SDS 12-0436  
PO BOX 86  
MINNEAPOLIS, MN 55486-0436

Amount Due: \$1,618.54

Amount Enclosed:

MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Invoice Number: SW140133903 Date: 8/28/13 Account No.: 5320900 Page: 2

Quantity	Item	N/R	Description	Unit Price	Extended
----------	------	-----	-------------	------------	----------

**TROUBLESHOOT TURBOCHARGER**
**CUSTOMER COMPLAINT:**

CHASKA, IN CITY LIMITS, MN

**REPAIR PROCESS COMMENTS:**

ARRIVED AT MACHINE REMOVED THE TURBO INLET TUBE AND FOUND THAT THE IMPELLER WAS RUBBING THE HOUSING. I THEN REMOVED THE OIL LINES FOR THE TURBO I THEN REMOVED THE EXHAUST. I THEN UNBOLTED THE TURBO AND REMOVED IT. I THEN INSTALLED THE NEW TURBO WITH NEW GASKETS. I THEN INSTALLED THE EXHAUST AND THE INLET TUBE. I THEN INSTALLED THE OIL LINES WITH NEW GASKETS. RAN MACHINE. CHECKED TURBO PRESSURE AND IT WAS GOOD

1	1T-0416	BOLT	S	2.27	2.27
2	3B-4628	COTTER	S	.14	.28
1	4N-9216	HOSE	S	11.45	11.45
2	5P-0597	CLAMP	S	4.49	8.98
1	7W-4486	WASHER	S	1.03	1.03
1	8N-5132	CLAMP	S	13.86	13.86
TOTAL PARTS				SEG. 01	37.87 *
TOTAL LABOR				SEG. 01	240.00 *
SEGMENT 01 TOTAL					277.87 T

**TROUBLESHOOT FUEL SYSTEM**
**REPAIR PROCESS COMMENTS:**

ARRIVED AT MACHINE FOUND MACHINE TO BE RUNNING RUFF AND SPITTING FUEL OUT OF THE EXHAUST. I THEN DID A CYL CUT OUT TEST AND FOUND THE #4 INJECTOR BAD. I THEN REMOVED THE INJECTOR AND FOUND THE NOZZLE MISSING OUT OF THE INJECTOR. I THEN RAN BACK TO THE SHOP FOR PARTS. WHEN I RETURNED TO THE MACHINE. I INSTALLED THE INJECTOR AND THE MACHINE RAN GOOD. CUSTOMER DID NOT WANT TO REMOVE CYL HEAD TO RETRIEVE THE NOZZLE. ALSO THE INJECTOR CORE WAS BAD.

1	0R-4124	NOZZLE AS	S	80.79	80.79
1		CORE CHARGE	S	79.22	79.22
1-		NO CREDIT	S	.00	.00
2	1L-3047	WASHER	S	1.80	3.60
TOTAL PARTS				SEG. 02	163.61 *
TOTAL LABOR				SEG. 02	540.00 *
SEGMENT 02 TOTAL					703.61 T

**TRAVEL TO/FROM MACHINE**

130.00	TOTAL LABOR	SEG. 99	240.00 *
	TRAVEL MILEAGE		221.00
	TOTAL MISC CHGS	SEG. 99	221.00 *
	SEGMENT 99 TOTAL		461.00 T

 SERVICE SUPPLIES AND  
 ENVIRONMENTAL CHARGES

66.30 T



901 West 94th Street  
Minneapolis MN 55420-4236



MINNESOTA 952-888-4121 800-352-2812  
IOWA 515-957-3800 800-342-7002  
MISSOURI 515-957-3800 800-342-7002  
WISCONSIN 515-957-3800 800-342-7002

Invoice Number: SW140133903 Date: 8/28/13 Account No.: 5320900 Page: 3

Quantity	Item	N/R	Description	Unit Price	Extended
TAX EXEMPTION LICENSE 9732569					
			MN SALES TAX-6.875%		103.73 T
			HENNEPIN TAX 0.15%		2.26 T
			TRANSIT TAX 0.25%		3.77 T
			DUE BY 10TH OF THE NEXT MONTH		
				INVOICE TOTAL	1,618.54



901 West 94th Street  
Minneapolis MN 55420-4236



MINNESOTA	952-888-4121	800-352-2812
IOWA	515-957-3800	800-342-7002
MISSOURI	515-957-3800	800-342-7002
WISCONSIN	515-957-3800	800-342-7002

Sold To: M B E INCORPORATED  
530 RIVER ST S  
DELANO MN 55328

Page: 1

Invoice Number: SW080113797

Date: 7/18/13

Account No.: 5320900

Ship To:

W7136

**Invoice Information**

WO Number:	WJ98374	Make:	CATERPILLAR
WO Date:	7/09/13	Model:	D6RDSLGP
Store:	ST. CLOUD	Serial:	09PN01039
Payment Terms:	CHARGE	PIN:	
P/O Number:	D6RDSLGP	Id No:	
Ship Via:		Cust Unit:	L120
Invoice Type:	1H1H1H	Meter:	4114.0

*DeR 1039*

**Invoice Summary**

Parts:	869.64	Amount Due:	\$2,944.69
Labor:	1,631.01		
Misc:	254.62		
Taxes:	189.42		
Invoice Total:	2,944.69		

**DUE BY 10TH OF THE NEXT MONTH**  
A service charge of 1 1/2 % per month will be assessed on all past due accounts.

To ensure proper credit, please detach this portion, at the perforation, and return with remittance.

M B E INCORPORATED  
530 RIVER ST S  
DELANO MN 55328

Account Number: 5320900  
Invoice Number: SW080113797  
Invoice Date: 7/18/13

Please remit to:

ZIEGLER INC.  
SDS 12-0436  
PO BOX 86  
MINNEAPOLIS, MN 55486-0436

Amount Due: \$2,944.69

Amount Enclosed:

Invoice Number: SW080113797 Date: 7/18/13 Account No.: 5320900 Page: 2

Quantity	Item	N/R	Description	Unit Price	Extended
----------	------	-----	-------------	------------	----------

REPLACE WITH EXCHANGE ENGINE OIL COOLER

CUSTOMER COMPLAINT:

THERE IS ENGINE OIL IN THE RADIATOR.

CAUSE OF FAILURE:

THE OIL COOLER WAS LEAKING OIL INTO THE COOLING SYSTEM.

REPAIR PROCESS COMMENTS:

CAME OUT TO THE MACHINE AND IT HAD BLOWN A COOLANT HOSE AND THEIR MECHANIC WAS FIXING IT. THE MACHINE WAS HOT AND THE OIL SAMPLE CAME BACK POSITIVE WITH COOLANT IN THE OIL ALSO. DRAINED THE REST OF THE COOLANT THAT DIDN'T SPILL. THEN REMOVED THE OIL FILTER, BASE AND TUBES. THEN REMOVED THE ELBOW IN FRONT OF THE COOLER. REMOVED THE COOLER AND FOUND THAT THERE WAS LOTS OF OIL IN THE COOLING SYSTEM. PRESSURE CHECKED THE OIL COOLER AND FOUND THAT IT LEAKED DOWN .2 PSI IN THREE MINUTES ACCORDING SPEC IT WOULD HAVE TO LEAK DOWN .3 PSI. PUT THE OIL COOLER IN A PAIL OF WATER AND HAD SOME AIR LEAK OUT THEN IT STOPPED DUE TO THE COOL WATER. DECIDED TO REPLACE THE OIL COOLER. CLEANED ALL THE MATING SURFACES.

INSTALLED REMAN OIL COOLER AND TORQUED IT TO 35 FT LBS. THEN INSTALLED THE OIL FILTER BASE AND TORQUED IT TO 18 FT LBS. THEN INSTALLED THE OIL SUPPLY AND PRESSURE TUBE TO FILTER BASE.

EVERYTHING WAS RESEALED. DISASSEMBLED THE FILTER BASE AND RESEALED IT WHILE IT WAS OFF. FILLED THE SYSTEM WITH COOLING SYSTEM CLEANER AND RAN THE MACHINE FOR A HALF AN HOUR AND THEN DRAINED THE COOLING SYSTEM. FILLED THE SYSTEM WITH SOAP AND WATER TWICE MORE AND RAN IT FOR A HALF AN HOUR STALLING THE MACHINE OUT GETTING IT HOT. COOLING SYSTEM WILL BE FILLED ON ANOTHER SEGMENT.

1	OR-3499	CORE A OIL	S5	523.42	523.42
1		CORE CHARGE	S5	203.46	203.46
1-		CORE CREDIT	S5	203.46	203.46-
1	148-0293	GASKET KIT	N5	36.70	36.70
TOTAL PARTS			SEG. 01	560.12	*
TOTAL LABOR			SEG. 01	1105.50	*
SEGMENT 01 TOTAL				1665.62	T

 DRAIN & REFILL ENGINE COOLANT  
 WITH LONGLIFE

CUSTOMER COMPLAINT:

FLUSH AND FILL COOLANT.

CAUSE OF FAILURE:

OIL IN COOLING SYSTEM.

REPAIR PROCESS COMMENTS:

AFTER CLEANING ON THE OTHER SEGMENT. FILLED SYSTEM WITH WATER AND RAN IT FOR A SHORT TIME. DRAINED THE SYSTEM AND THEN FILLED THE SYSTEM WITH 4 GALS OF CONCENTRATE AND ANOTHER 15 GALLONS OF ELC. RAN THE MACHINE FOR AWHILE AND CHECKED THE COOLANT PROTECTION AND HAD -35 DEGREE F. FOUND NO LEAKS IN THE SYSTEM.

2	4C-4610	CLEANER	S5
4	238-8647	CAT ELC	S5
1	238-8648	COOLANT-ELC	S5
3	238-8649	COOLANT-ELC	S5



901 West 94th Street  
Minneapolis MN 55420-4236



MINNESOTA 952-888-4121 800-352-2812  
IOWA 515-957-3800 800-342-7002  
MISSOURI 515-957-3800 800-342-7002  
WISCONSIN 515-957-3800 800-342-7002

Invoice Number: SW080113797 Date: 7/18/13 Account No.: 5320900 Page: 3

Quantity	Item	N/R	Description	Unit Price	Extended
			F/R ALL	731.03	*
			SEGMENT 02 TOTAL	731.03	T
<hr/> <p>TRAVEL TO/FROM MACHINE JOBSITE AT HWY 25 AND 40TH ST NEAR BUFFALO, MN.</p>					
78.00			TOTAL LABOR SEG. 99	120.00	*
			TRAVEL MILEAGE	132.60	
			TOTAL MISC CHGS ** SEG. 99	132.60	*
			SEGMENT 99 TOTAL	252.60	T
<hr/> <p>SERVICE SUPPLIES AND ENVIRONMENTAL CHARGES</p>					
				106.02	T
<p>TAX EXEMPTION LICENSE 9732569</p>					
			MN SALES TAX-6.875%	189.42	T
<p>DUE BY 10TH OF THE NEXT MONTH</p>					
			INVOICE TOTAL	2,944.69	



901 West 94th Street  
Minneapolis MN 55420-4236

~~COPY~~



MINNESOTA 952-888-4121 800-352-2812  
IOWA 515-957-3800 800-342-7002  
MISSOURI 515-957-3800 800-342-7002  
WISCONSIN 515-957-3800 800-342-7002

Sold To: M B E INCORPORATED  
530 RIVER ST S  
DELANO MN

55328

Invoice Number: WJ98315

Page: 1

Date: 7/11/13

Account No.: 5320900

Ship To:

W 7138

**Invoice Information**

WO Number: WJ98315  
WO Date: 7/03/13  
Store: ST. CLOUD  
Payment Terms: CHARGE  
P/O Number: D6R  
Ship Via:  
Invoice Type: 1H1H1H

Make: CATERPILLAR  
Model: D6RDSLGP  
Serial: 09PN01039  
PIN:  
Id No:  
Cust Unit: L120 DCR  
Meter: 4110.0 1039

**Invoice Summary**

Parts:	242.72	Amount Due:	\$2,121.63
Labor:	636.93		
Misc:	1,105.50		
Taxes:	136.48		
Invoice Total:	2,121.63		

A service charge of 1 1/2 % per month will be assessed on all past due accounts.

To ensure proper credit, please detach this portion, at the perforation, and return with remittance.

M B E INCORPORATED  
530 RIVER ST S  
DELANO MN

55328

Account Number: 5320900  
Invoice Number: WJ98315  
Invoice Date: 7/11/13

**PROFORMA INVOICE**

Please remit to:

ZIEGLER INC.  
SDS 12-0436  
PO BOX 86  
MINNEAPOLIS, MN 55486-0436

Amount Due: \$2,121.63

Amount Enclosed:



901 West 94th Street  
Minneapolis MN 55420-4236



MINNESOTA 952-888-4121 800-352-2812  
IOWA 515-957-3800 800-342-7002  
MISSOURI 515-957-3800 800-342-7002  
WISCONSIN 515-957-3800 800-342-7002

Invoice Number: WJ98315

Date: 7/11/13

Account No.: 5320900

Page: 2

Quantity	Item	NR	Description	Unit Price	Extended
----------	------	----	-------------	------------	----------

\* \* \* PROFORMA INVOICE \* \* \*

PERFORM MAINTENANCE ON LEVEL-1, 2&3 PM (1000 HR)

CUSTOMER SITE

MONROSE MN

\*\*\*\*\* PREVENTIVE MAINTENANCE SERVICE \*\*\*\*\* \*

\* YOUR MACHINE MAINTENANCE WAS COMPLETED USING OUR  
CUSTOMIZED INSPECTION CHECK LIST. THIS SERVICE  
INCLUDES THE LABOR, PARTS, FLUIDS, OIL SAMPLES AND  
TRAVEL COST WITHIN A 50 MILE RADIUS.

1	1R-0735	ELEMENT AS	S
1	1R-0739	FILTER AS	S
1	1R-0750	FILTER AS	S
1	1R-1712	FILTER A	SS
1	2K-4472	O RING	SS
1	3S-7781	GASKET	SS
1	4T-6788	OIL FILTER	S
1	6D-9157	SEAL	S
1	6I-2501	ELEMENT AS	S
1	6V-5188	SEAL	S
1	6V-9633	GASKET	S
1	8H-2778	GASKET	SS
1	9G-9981	BREATHER	S
1	132-8876	TRANS FILTR	S

F/R ALL 1943.75 \*

SEGMENT 01 TOTAL 1943.75 T

-----  
SERVICE SUPPLIES AND  
ENVIRONMENTAL CHARGES 41.40 T

TAX EXEMPTION LICENSE 9732569

MN SALES TAX-6.875% 136.48 T

INVOICE TOTAL 2,121.63



CUSTOMER : 5320900 M B E INCORPORATED  
EQUIP NUMBER : L120  
MAKE : AA CATERPILLAR  
MODEL : D6RDSLGP  
SERIAL NUMBER : 09PN01039  
PLAN : D6R 55 D6R 9PN1-UP LCPCM \*  
JOB/COMPONENT : 742 7503 PERFORM MAINTENANCE ON LEVEL-1,2&3 PM (1000 H  
AGREEMENT : 0300G00883 MBE INC. D6R 9PN01039  
TECHNICIAN : 0055 ABBOTT - 0055  
CALL NUMBER : 10  
SCHEDULE DATE : 10/31/12  
EQUIP LOCATION : MONTROSE MN

**CHECKLIST INFORMATION**

-----  
OK STEP ----- DESCRIPTION -----

PA 10 DATE PERFORMED: 7-8-13

DATE PERFORMED: 7-8-13

SMU: 4110

EMPLOYEE NAME: Diane Abbott

5-0.1 SOS  
1-EECC SOS

**REPAIRS NEEDED:**

## \*\*\*\*\* **PRE-START**

30 If hydraulic oil needs to be changed, add a separate segment and use job code 744 and component code 5095. Change hydraulic oil.  
Hydraulic refill (12.5 GALS HYD)

**COMMENTS:** \_\_\_\_\_

CUSTOMER : 5320900 M B E INCORPORATED  
EQUIP NUMBER : L120  
MAKE : AA  
MODEL : D6RDSLGP  
SERIAL NUMBER : 09PN01039 CATERPILLAR

CHECKLIST INFORMATION

OK STEP ----- DESCRIPTION -----

DSA 40 **NOTE!**  
All refill capacities are approximate  
amounts!

COMMENTS: \_\_\_\_\_

DSA 50 Check engine oil and coolant levels.  
(Note fluids added)  
If coolant is low, find problem!  
No maintenance with ELC coolant!  
Radiator capacity is 18.5 GALS.

COMMENTS: \_\_\_\_\_

\*\*\*\*\*  
WARM-UP  
\*\*\*\*\*

DSA 70 Start engine and check for unusual  
noises or smoke.  
Let engine warm up before taking oil  
sample and draining oil.  
Check gauges, controls and operation of  
machine.

COMMENTS: \_\_\_\_\_

DSA 80 CHECK FLUID LEVELS (Note fluids added)  
- Transmission  
- Hydraulic  
- Brake fluid  
- Final drives  
- Pivot shaft  
- Recoil spring  
- Winch (If equipped)

COMMENTS: \_\_\_\_\_

\*\*\*\*\*  
LC-1  
\*\*\*\*\*

DSA 100 Take SOS sample from engine oil.  
Fill out label (1 SOS SAMPLE)

COMMENTS: \_\_\_\_\_

DSA 110 Change engine oil and filters.  
Cut filter open and inspect for foreign  
material.  
Oil filter number (1-1R0739)  
Engine oil refill (7.4 GALS DEO)

COMMENTS: Changed eng oil & filter, cut filter open, no debris  
refilled 6.95 gallons of 10w 30

DSA 120 Dispose of drain oil and complete  
service reports.

COMMENTS: \_\_\_\_\_


\*\*\*\*\*  
LC-2  
\*\*\*\*\*

PREVENTIVE MAINTENANCE SYSTEM  
CALL CHECKLIST  
WORK ORDER/SEG: WJ98315 01GLER INC.  
OLIS. MN.NUMBER : 5320900 M B E INCORPORATED  
L NUMBER : L120 CATERPILLAR  
AL NUMBER : AA D6RDSLGP  
09PN01039

## CHECKLIST INFORMATION

- | STEP | DESCRIPTION  |
|------|--|
| 140  | Take SOS sample and fill out labels for:<br>- Transmission<br>- Hydraulic<br>- Final drives (4-SOS SAMPLE)   |
| 150  | Check condition of fan pulleys, belts and fan drive bearings. Check for excessive radial and axial movement by prying on hub.  |
| 160  | Install a new secondary fuel filter (1-1R0750)<br>Fuel filter number<br>Install a new fuel water separator (1-1R1712)<br>Water separator number  |
| 170  | Change transmission oil filter element.<br>Cut filter open and inspect for foreign material.<br>Transmission filter number (1-3434465)<br>Filter seal numbers (1-2K4472 1-6D9157)                        |
| 180  | Change Hydraulic system filter element.<br>Cut filter open and inspect for foreign material.<br>Hydraulic filter number (1-1R0735)<br>Filter gasket number (1-6V9633)                                    |
| 190  | Change hydraulic Case Drain filter.<br>Cut filter open and inspect for foreign material.<br>Case drain filter number (1-4T6788)  |
| 200  | Replace primary air filter element.<br>Primary filter number (1-6I2501)  |
| 220  | Take SOS coolant sample from radiator<br>Fill out label (1 SOS SAMPLE)   |
| 230  | SAFETY ITEMS<br>Check machine for:<br>- Safety lock link<br>- Back up alarm<br>- Seat belts<br>- Brake condition and operation<br>- Parking brake condition and operation<br>(Note repairs)<br>Comments: |

PM-3



CUSTOMER : 5320900 M B E INCORPORATED  
EQUIP NUMBER : L120  
MAKE : AA  
MODEL : D6RDSLGP  
SERIAL NUMBER : 09PN01039

CHECKLIST INFORMATION

OK STEP ----- DESCRIPTION -----

OKA 240 Check air filter indicator and check  
pre-cleaner.  
Blow out cab filters.

COMMENTS: \_\_\_\_\_

OKA 250 Drain water and sediment from fuel tank.  
Note, if water is found, then service  
primary filter and replace fuel filter.

COMMENTS: \_\_\_\_\_

OKA 260 Drain brake air tank. (Note condition)

COMMENTS: \_\_\_\_\_

OKA 270 WALK AROUND INSPECTION (Note repairs)  
Check machine for:  
Oil leaks, damage and etc.  
Check condition of:  
GET, Tires, Loader linkage, Electrical,  
system and batteries.

COMMENTS: \_\_\_\_\_

OKA 280 CHECK:  
- Fan/alternator belts  
- Water pump weep hole  
- Coolant hoses  
- Radiator

COMMENTS: \_\_\_\_\_

OKA 290 Lubricate with MPG.M.  
Note if operator is greasing machine.  
Grease number (1-1833424)

COMMENTS: \_\_\_\_\_

OKA 300 Clean engine crankcase breather element  
and check breather tube.

COMMENTS: \_\_\_\_\_

OKA 310 Replace transmission breathers.  
Breather number (1-1856684)

COMMENTS: \_\_\_\_\_

OKA 320 Clean transmission and torque converter  
screen.  
Transmission screen seal {1-6V5188}  
Torque converter screen gskt (1-3S7781)

COMMENTS: \_\_\_\_\_

OKA 330 Change transmission oil  
Transmission refill (38.5 GALS TDTO)

COMMENTS: Changed trans oil, refilled at gallons of 30w

OKA 340 Change oil in both final drives  
Final drive refill (7.2 GALS TDTO)

COMMENTS: Changed oil in finals, 6.75 gallons of 30w all together

CUSTOMER : 5320900 M B E INCORPORATED  
EQUIP NUMBER : L120  
MAKE : AA  
MODEL : D6RDSLGP  
SERIAL NUMBER : 09PN01039

CHECKLIST INFORMATION

OK STEP ----- DESCRIPTION -----

~~OK~~ 350 Disassemble and clean fuel tank cap and  
filler neck screen.

COMMENTS: \_\_\_\_\_

~~OK~~ 360 Visually inspect rollover protective  
structure (ROPS) for damage and/or  
loose or missing hardware.

COMMENTS: \_\_\_\_\_

~~OK~~ 370 ~~354~~

COMMENTS: \_\_\_\_\_

~~OK~~ 380 Inspect all cooling system hoses.  
Report all hard, cracked or damaged  
hoses.

COMMENTS: \_\_\_\_\_

~~OK~~ 390 Replace secondary air filter element.  
Secondary filter number (1-6I2502)

COMMENTS: \_\_\_\_\_

~~OK~~ 400 Replace cab air filters.  
Cab filter numbers (1-6I0988 1-6T5068)

COMMENTS: \_\_\_\_\_

410 At an additional cost!  
Engine tune-up?  
Cooling system service?  
2000 hours is when we should recommend  
these items, but at an additional cost!

COMMENTS: \_\_\_\_\_

\*\* END OF REPORT \*\*

Sample For:

 SHOP SAMPLE  
 KEN COWLES  
 2225 255TH ST  
 SAINT CLOUD MN 56301-8742

 Serial #: 09PN01039  
 Compartment: Diesel Engine  
 Unit #: L120  
 Model #: D6RDSLGP  
 WO #: WJ98315

 ACTION  
 Sample #: 130702728  
 Date Received: 7/10/13  
 Oil Brand: Caterpillar  
 Oil Blend: Diesel Engine 0  
 Oil Weight: 10W30

**CURRENT SAMPLE INFORMATION**

Date Taken	Changed		Quarts Oil Added	Meter	Meter on Oil	WEAR METALS ANALYSIS						INFRARED ANALYSIS			PHYSICAL TESTS							
	Oil	Filter				K Potassium PPM	CU Copper PPM	NA Sodium PPM	FE Iron PPM	CR Chromium PPM	AL Aluminum PPM	SI Silicon PPM	PB Lead PPM	SN Tin PPM	SOot	Sulfation	Oxidation	PO-Ferrous Debris	Viscosity	Anti-Freeze	Fuel Dilution	Water
7/08/13	Y	Y		4110	252	5	4	104	53	1	2	5	5	0	71	13	8	22	14.5	P	N	N

**Interpretation**
**The analysis**

of the oil sample taken

from your Diesel Engine

indicates that Iron and Soot are

slightly high. This oil sample tests

positive for antifreeze contamination.

**Recommendation**

Check for coolant getting into the oil.

Possible failure. Also suggest cutting oil filter open, pulling out pleats and checking for metal

pieces.

The analysis of the oil sample taken

from your Diesel Engine

indicates that Iron and Soot are

slightly high. This oil sample tests

positive for antifreeze contamination.

**TRENDING SAMPLE INFORMATION**

Date Taken	Changed		Quarts Oil Added	Meter	Meter on Oil	WEAR METALS ANALYSIS						INFRARED ANALYSIS			PHYSICAL TESTS											
	Oil	Filter				K Potassium PPM	CU Copper PPM	NA Sodium PPM	FE Iron PPM	CR Chromium PPM	AL Aluminum PPM	SI Silicon PPM	PB Lead PPM	SN Tin PPM	SOot	Sulfation	Oxidation	PO-Ferrous Debris	Viscosity	Anti-Freeze	Fuel Dilution	Water				
7/08/13	Y	Y		4110	252	5	4	104	53	1	2	5	5	0	71	13	8	22	14.5	P	N	N				
8/27/12	Y	Y		4110	252	5	4	104	53	1	2	5	5	0	71	13	8	22	14.5	P	N	N				
6/13/12	Y	Y		3858	281	0	3	12	54	1	1	4	5	0	140	21	10	11	14.6	N	N	N				
3/21/12	Y	Y		3577	242	0	3	14	41	1	2	4	2	1	78	15	9	9	14.3	N	N	N				
10/19/11	Y	Y		3335	304	1	9	19	40	1	3	5	3	1	130	28	23	13	14.7	N	N	N				
6/20/11	Y	Y		3031	280	1	9	19	40	1	3	5	3	1	139	27	23	9	15.1	N	N	N				
4/21/10	Y	Y		2751	2508	1	23	35	39	1	2	6	2	0	139	27	20	6	11.0	N	P	N				
						0	1	12	11	1	1	7	1	0	13	17	14	28	11.1	P	N	N				
<b>CURRENT SAMPLE</b>		<b>IS INCLUDED</b>		<b>IN TRENDING</b>		246	4	1	12	11	1	1	7	1	0	135	9	17	20	16						
<b>THIS ANALYSIS IS INTENDED AS AN AID IN PROBLEMS</b>																										
<b>SFF REVERSE SIDE FOR TEST EXPLANATIONS</b>																										



- To realize the full benefits of the diagnostic capabilities of the oil analysis program, the user should do the following:
1. Provide complete and accurate information on the sample label.
  2. Adhere to proper sampling procedures.
  3. Be on a regular and continuous sampling program.
  4. Cut oil filters open and inspect (particles in the oil large enough to be seen by the naked eye are too large for analysis and may indicate imminent failure).

Metals are shown in parts per million (PPM) and are evaluated according to hours or miles the oil has been in use, amount of oil added, recent component repairs, type of operation and other conditions that might affect the concentration.

Caterpillar Inc. has established "normal" wear rates for their products. Interpretation of oil samples from other brands of machines is based on other manufacturer recommendations or general guidelines established for similar components. Elevated readings indicate excessive wear and shortened component life, but may not indicate an imminent failure.

#### TEST EXPLANATION

##### WEAR METALS

Possible sources of high readings in Caterpillar product.

- COPPER:** Air compressor bushings; oil cooler tubes; thrust washers; wrist pin bushings; oil pump bushings; anti-seize compounds after a repair; additives in the new oil; condensation (water). In transmissions, discs and thrust plates.
- IRON:** Cylinder walls; oil pump; crankshafts, gear teeth.
- CHROMIUM:** Piston rings, valve stems, new engine break-in, ball and roller bearings.
- ALUMINUM:** Main and rod bearings; pistons; rocker shaft in some engines. Transmission pump bushings, torque converter impeller or turbine.
- SILICON:** Dirt; anti-foam additives in new oil. (Dirt is an abrasive and normally elevates all readings to indicate excessive wear and shortened component life).
- LEAD:** Overlay on main and rod bearings; fuel contaminated with gasoline (tetraethyl lead).
- SODIUM:** Produced when engine coolant contacts a hot surface and the water evaporates leaving a residue; oil additive.
- POTASSIUM:** Element used to detect coolant.
- TIN:** Piston plate coating; overlay on main and rod bearings.

##### PHYSICAL TEST

- PQ** Measurement of ferrous debris.
- VISCOSITY:** A bath viscometer is used to measure viscosity at 100 C., and readings are reported in centistokes. Viscosity results are used to detect possible fuel dilution; oil thickening from high soot and/or oxidation or use of the wrong oil, and in some cases, oil transfer. Viscosity should trend within 2 centistokes.
- ANTIFREEZE:** Water pump seal; oil coolers; liner seals; head gaskets. Test for more than .1% by volume ethylene glycol antifreeze in engine oil. Ethylene glycol causes serious sludge and varnish formation.
- FUEL DILUTION:** Failed nozzles; fuel transfer pump seals; under valve cover fuel lines. Test for more than .4% diesel fuel in engine oil. (Invalid test results can be produced by volatile liquids if used to clean sample gun or container).
- WATER:** Coolant leaks; condensation (due to low operation temp.); contaminated new oil. Test for more than .1% by volume. Can rust components, promote oil oxidation and forms acid with combustion products.

- PARTICLE COUNT** A method of reporting the number and size (in microns) of particles in a volume of fluid. Cannot be performed if water is present or if oil is too dark in color.

- INFRARED ANALYSIS** Will be run on oil samples when additional information is necessary for interpretation.

- SOOT:** Indication of lugging; over fueling; air inlet restriction; filter plugging. Reported in terms of absorbance X 100 (The maximum normally allowed is 60).

- OXIDATION:** Oxidation occurs in all compartments. It is accelerated by heat and contaminants such as water. Oxidized oil allows a buildup of sludge and varnish. Reported in terms of absorbance X 100 (The maximum normally allowed is 34 for engine and 17 for non-engine).

- SULFATION:** Sulfur products caused by combustion of diesel fuel which contains sulphur. Sulphur products cause corrosion and may lead to piston ring sticking. Reported in terms of absorbance X 100 (The maximum normally allowed is 34).

- NITRATION:** Nitrogen products resulting from the combustion process occur in all engines but only reach problem levels in natural gas engines. Nitrogen compounds cause the oil to thicken, lose its lubricating capabilities, and leads to filter plugging, heavy deposits and lacquering. Reported in terms of absorbance X 100 (The maximum normally allowed is 16).

NOTE: Prior to performing any major repairs based solely on SOS test results, consult your Caterpillar SOS Supervisor.



Sample For: **SHOP SAMPLE**  
**KEN COWLES**  
**2225 255TH ST**  
**SAINT CLOUD MN 56301-8742**

Serial #: **09PN01039**  
 Compartment: **Powershift Transmission**  
 Unit #: **L120**  
 Model #: **D6RDSLGP**  
 WO #: **WJ98315**

Sample #: **130702731**  
 Date Received: **7/10/13**  
 Oil Brand: **Caterpillar**  
 Oil Blend: **Trans/Drive Tra**  
 Oil Weight: **30**

**M B E INCORPORATED**

CURRENT SAMPLE INFORMATION					WEAR METALS ANALYSIS							INFRARED ANALYSIS		PARTICLE COUNT				PHYSICAL TESTS				
Date Taken	Changed		Quarts Oil Added	Meter	Meter on Oil	CU Copper PPM	FE Iron PPM	CR Chromium PPM	AL Aluminum PPM	SI Silicon PPM	PB Lead PPM	NA Sodium PPM	Soot	Oxidation	ISO Code	µm 5	µm 10	µm 15	PQ-Ferrous Debris	Viscosity	Anti-Freeze	Water
	Oil	Fltr																				
7/08/13	Y	Y		4110	1079	1	13	0	2	9	0	3	0	9	18/13	1963	123	45	6	13.5	N	N

**Interpretation**

Results of latest sample indicate elements tested didn't exceed normal specifications for this compartment. No excessive wear is indicated at this time.

**Recommendation**

Continue to monitor compartment by sampling at recommended intervals.

TRENDING SAMPLE INFORMATION					WEAR METALS ANALYSIS							INFRARED ANALYSIS		PARTICLE COUNT				PHYSICAL TESTS				
Date Taken	Changed		Quarts Oil Added	Meter	Meter on Oil	CU Copper PPM	FE Iron PPM	CR Chromium PPM	AL Aluminum PPM	SI Silicon PPM	PB Lead PPM	NA Sodium PPM	Soot	Oxidation	ISO Code	µm 5	µm 10	µm 15	PQ-Ferrous Debris	Viscosity	Anti-Freeze	Water
	Oil	Fltr																				
7/08/13	Y	Y		4110	1079	1	13	0	2	9	0	3	0	9	18/13	1963	123	45	6	13.5	N	N
6/13/12	N	Y		3577	546	1	12	0	2	8	0	2	0	9	18/13	1963	123	45	6	13.5	N	N
10/19/11	Y	Y		3031	992	3	17	1	3	17	0	3	0	9	19/14	3161	261	107	9	13.0	N	N
4/21/10	N	Y		2508	469	2	14	0	2	12	0	3	0	11	17/14	847	234	106	8	12.1	N	N
9/16/08	Y	Y		2039	1044	5	12	0	2	12	0	3	0	11	17/14	1027	321	144	12	12.2	N	N
3/19/08	N	Y		1576	581	4	11	0	3	14	0	3	0	11	18/14	1361	367	141	7	13.1	N	N
8/08/07	Y	Y		995	11	18	1	3	18	0	3	0	11	21/19	19674	6748	2798	3	13.3	N	N	

**CURRENT SAMPLE IS INCLUDED IN TRENDING**
**SEE REVERSE SIDE FOR TEST EXPLANATIONS**

THIS ANALYSIS IS INTENDED AS AN AID IN PREDICTING MECHANICAL WEAR, NO GUARANTEE, EXPRESSED OR IMPLIED, IS MADE AGAINST FAILURE OF THIS COMPONENT



Sample For: **SHOP SAMPLE**  
**KEN COWLES**  
**2225 255TH ST**  
**SAINT CLOUD MN 56301-8742**

Sample #: **09PN01039**  
 Compartment: **Radiator**  
 Unit #: **L120**  
 Model #: **D6RDSLGP**  
 WO #: **WJ98315**  
 MBE INCORPORATED

Serial #: **130790210**  
 Date Received: **7/10/13**  
 Date Taken **7/08/13**  
 Service Meter: **4110**  
 Hours on Sample: **4110**

**ACTION**

SHOP SAMPLE		COOLANT PROPERTIES		COOLANT ANALYSIS	
Sample For:	Sample #: 09PN01039	Conductivity (µmhos/cm)	(<7500)	Supplemental Coolant Additive (ppm)	545
Glycol Concentration (%) <small>Estimate Glycol Assumed Unless Specified Otherwise</small>	55%	(30 - 65%)	2804	Color	See Back Charts
Freeze Point (°F)	-47		(<7500)	RED	ELC
Boil Point (°F) 0.0 psi	230	pH	8.3	Visual Contamination	EXT CLOUDY / CONTA

**Interpretation**  
 Sample has some oil contamination.

**Recommendation**

The presence of oil in the sample is an indication of a leak between the coolant system and one of the oil systems (engine, hydraulic, etc) or could be from combustion in cooling system. Is there a possibility that the presence of oil in this sample may have come from the way the sample was taken (oil in the sample gun, reusing sample tubing, or an oily sample bottle)?

RENDING SAMPLE INFORMATION				COOLANT ANALYSIS							
Date Taken	Changed Cool	Meter Reading Filter	Hours On Cool	GLYC	FP	BP	CONDUCT	pH	SCA	Color	Visual Contamination
7/08/13	Y	4110	55	-47	230	2804	8.3	545	RED	ELC	EXT CLOUDY / CONTA
8/08/07	U	995	0	48	30	3220	7.4	815	RED		CLEAR
1/09/06	N	699	0	44	20	223	7.5	1085	ORANGE		CLEAR
1/11/06	N	9175	0	50	34	227	3110	9.7	1355	RED	CLEAR

**CURRENT SAMPLE IS INCLUDED IN TRENDING**

**THIS ANALYSIS IS INTENDED AS AN AID IN PREDICTING MECHANICAL WEAR. NO GUARANTEE, EXPRESSED OR IMPLIED, IS MADE AGAINST FAILURE OF THE POWER UNIT.**

**SEE REVERSE SIDE FOR TEST EXPLANATIONS**