Page 1

# National Fleet Testing Services, Inc.

utestwithme@gmail.com

912 Coyote Drive Junction City, Kansas 66441 (913) 634-7329

## Report of Inspection

ANNUAL SAFETY INSPECTION FOR

### AERIAL DEVICES AND DIGGER DERRICKS

In accordance with OSHA 1910.67, ANSI A92.2, ANSI A10.31

Customer	<u> </u>	SU/ SALIN	A	Inspection Date	March 4, 2016
Location	SALINA, K	3.		Unit Number	_05894
Manufactur	er <u>HIRANGER</u>			Project Number	KSUSALINA05894-030416
Model Num	ber 5FI-48PBI			Serial Number	088634299003
			Type of Ed	quipment	
Single Bucket		Х		Single Bucket Mat	terial Handler
	Double Bucket			Double Bucket Ma	aterial Handler

Boom Truck/Crane

Inspected By

Michael Clark

Digger Derrick

#### Confidential

National Fleet Testing Services, Inc.

Customer	KSU/ SALINA
Date	March 4, 2016
Unit No	_05894

#### Defect Classification

Category I Those defects that are designated most serious. Defects in this category cause free-fall or free-rotation type incident and are related

directly to the operational safety of the device. We have recommended that these be repaired as soon as possible.

Category II Those defects that could lead to a downtime or a more costly repair.

Category III Those defects that can be scheduled into a maintenance program

and repaired at a later date; not an operational or safety related

item

Category IV There were no defects found at the time of the inspection.

#### DISCLAIMER

The information provided in this report is the result of the specific testing and inspection procedures conducted by an authorized vational Fleet Testing Services, Inc. contractor on the equipment and identified herein, as limited by the scope of work authorized by the customer (the "Test Results"). The Test Results reflect on the econdition of the components tested or inspected within the scope of work authorized. We have reviewed neither the maintenance records or the actual use of the equipment before or after the date of the testing or inspection. NO ATTEMPT HAS BEEN MADE AND NO INFORMATION IS RENDE RED WITH RESPECT TO ANY CONDITIONS OF THE EQUIPMENT OR ANY COMPONENT OTHER THAN AS EXPRESSLY STATED IN THE WRITTEN TEST RESULTS. SPECIFICALLY, BUT WITHOUT LIMITATIONS, NO INFROMATION, TESTING OR INSPECTION SERVICES ARE RENDERED CONCERNING EQUIPMENT D 3SIGN, SUITABILITY OF THE EQUIPMENT FOR ANY PARTICULAR PURPOSE OR THE FUTURE SERVICABIL ITY OF THE EQUIPMENT. THE TEST RESULTS SHOULD NOT BE CONTRUED AS STATEMENT 'THAT THE EQUIPMENT IS SAFE OR SERVICEABLE.

The information provided in this report is not a substitute for proper use, maintenance, modificat on, inspections and repair of the equipment which remains the sole responsibility of the owner/operator of the equipment, who shall assure safe operation of the equipment within its intended limitation. Furthermore, nothing in the Test Results should be construed as a recommendation for corrective action and National Fleet Testing Services, Inc. or any of its authorized contractors has not and will not supervise corrective action of any condition found to exist, as such is the sole responsibility of the owner/operator and is hereby expressly excluded from the scope of work performed by an authorized National Fleet Testing Services, Inc. contractor. The Test Results are intended solely for informational purposes of the customer and should not be utilized or relied upon by any other person.



#### Confidential

National Fleet Testing Services, Inc.

Customer	KSU/ SALINA		
Date	March 4, 2016		
Unit No.	05894		

#### INSPECTION SUMMARY

UNIT DISPOSITION:	
Pre-Service	
In-Service	X
Collision	
Before Repair	
After Repair	
During Repair	
Overhaul	
Other	

INSPECTION METHODS:		Passed:	
A.E./ Load Test	Х	Х	
Dielectric Test	Х	X	
Magnetic Particle	Х	X	
Ultrasonics Inspection	Х	X	
Visual Inspection	Х	X	
Liner(s)	Х	X	
Hot Sticks			
Other			

**Deficiency Summary** 

			Deficioney Cummary
ITEM	CATEGORY		Description
1	III	Indic	ations of a hydraulic oil leak inside the turntable.
2	III		ations of a hydraulic oil leak at the upper control valve at the
			controls (ball valve needs to be replaced).
3	III	Reco	mmend removal of debris inside the lower boom underneath
		the c	ompensating chain and cylinder.
4	111	Reco	mmend clean and lubricate the roller links on the compensating
		chair	1.

Michael Clark		
Inspector(s):	Customer Representative	

16811/

#### Confidential

March 4, 2016 Date National Fleet Testing Services, Inc. Unit No: 05894 912 Coyote Drive Junction City, KS 66441 DIELECTRIC TEST REPORT FORM Insulating section extended Boom to minimum extension Height 25' required by the manufacturer. Boom over side of Truck Boom over V rear of Truck Boom H ight recorded for consistency or duplication of test results. Company KSU/ SALINA Location SALINA, KS. Type of Equipment SB Manufacturer HIRANGER Weather Condition CLEAR Model 5FI-48PBI 5% Humidity Serial No. 088634299003 AC Test Voltage: DC ☑ Time 9:00 pm ☐ Date of Mfr. Raise voltage 0 to KV in 30 s sconds, Record Reading A; Hold Vollage at KV for 3 minutes, Record B. CHASSIS INSULATING SYSTEM UPPER BOOM/THIRD STAGE MINIMUM EXTENSION Test Voltage 100 Test Voltage Test Voltage Reading A Reading A 2uA Reading B 2uA Reading A 20uA Reading B Pass J Fail Reading B 20uA Pass Fail Pass V Fail JIB TEST (SPLD Only) BASKET LINER(S) TEST Liner #1 HYDRAULIC OIL BREAKDOWN Jib #1 Pass Pail Id No.: Liner 1 Average Hydraulic Breakdown Reading A Pass 🗸 Voltage N/A Reading B Fail L Jib #2 Pass Fail Liner #2 Any Readings under 18 KV are Id No.: N/A unacceptable. Reading A Fail [ Pass Fail \_ Reading B Pass 🔲 Boom Condition Dielectric Test Results V Fail \_ Pass V 6. Liner/Tools removed and replaced 1. Area Roped /Coned 2. Tire / Outrigger pads in place 7. Sticker/Stamp applied to unit, liner, jib V 3. Visual inside boom complete 8. All personnel jibs removed and tested П 4. Upper Controls extended 9. Transferable tip in place on 3rd stage П П 5. DT unit ground within barrice de 10. Number 2 jumper wire from first stage to turret V 11. Fire extinguisher in place by equipment 1 Comments:

This is to certify that the above test procedures, where applicable, comply with the requirements of the American National Standard for vehicle-mounted elevating and rotating work platforms, ANSI A92.2-1969, 1979, 1990.

Inspector: MC

NOTICE: The above tests do no guarantee the continuing insulation of the tested areas. It shall be the user's responsibility to maintain the insulating qualities of the aerial device through periodic testing.

INVDICE

MARCH 09,2016

INVOICE #: 8115391

BILL TO: 100491 KANSAS STATE UNIV.-SALINA 2409 SCANLAN SALINA, KS 67401 SHIP TO:

PHONE: 785/826-2600

CUST PO#: 1610560

UNIT TYPE MAKE/MODEL SERIAL# UNIT# CPL INJ
BUCKET TRUCK

FITTING LEAKS, CENTER SPOOL VALVE LEAKS

SHOP LABOR

270.00

REPLACED BOTH FITTINGS IN LIVE SWIVEL FOR THE BOOM ROTATION. HAD TROUBLE GETTING THE OLD DNES OUT BECAUSE THEY WERE GLUED IN. ONE FITTING BROKE OFF AND HAD TO EASY OUT IT. TOOK BOOTS LOOSE ON THE CONTROL VALVE AND FOUND ALL THREE HANDLES LEAKING. REMOVED THE HANDLES, RESEALED AND PUT BACK TOOETHER.

PART NUMBER PARTS

DESCRIPTION

AMOUNT

TOTAL PARTS .....

72.90

PART SALES ..... 72.90

NET 10TH

INVOICE TOTAL ... \$342.90

DDWGDGGGGGG

INVOICE

MARCH 03,2016

INVOICE #: 8115134

BILL TO: 100451 KANSAS STATE UNIV.-SALINA 2409 SCANLAN SALINA, KS 67401 SHIP TO:

\* SAME \*

PHONE: 785/826-2600

CUST PO#: 1610560

UNIT TYPE | AKE/MODEL | SERIAL# UNIT# CPL INJ BUCKET TRUCK | IRANGRSF148PB1

REPLACE UPPER AND LOWER HOSES IN BOOM, REPLACE OIL AND FILTER. SHOP LABOR 1,350.00 PART PARTS UNIT TOTAL QUANTITY NUMBER DESCRIPTION **AMOUNT** PRICE UPPER BUNDLE HOSES H61135 1 822.83 822.83 LOWER BUNDLE HOSES H64184 922,50 922.50 1 COUPLING 1114544 13 8.91 71.28 NUT & SLEEVE ASSY 20.16 H10896 16 1.26 431256 CONNECTOR 2 6.43 12.86 SHIP TRUCK FREIGHT 1. 100.59 108,59 OIL FILTER OFI 85551 MISC 1 23.00 23.00 . 25 0250-01 1/4" HEAT SHRINK TUBING- 108 27.40 . 25 M93367-4-0 NYLON CABLE TIE, 4 INCH 30 7.50 NYLON CABLE TIE 14 INCH MS3367-2-0 10 3. 50 . 35 OIL FILTER CFI 85551 1 23.00 23.00 AIRCRAFT OIL (BUCKET) 15 AIRCRAFT DIL 4 252.50 1,010.00

NET 10TH

INVOICE TOTAL ... \$4,402.22

K811/

INVOICE

AUGUST 06, 2015

INVOICE #: B111657

BILL TO: 100491

SHIP TO:

KANSAS STATE UNIV. -SALINA

2409 SCANLAN SALINA, KS 67401 \* SAME #

PHONE: 785/826-2600

CUST PO#: 1610084

UNIT TYPE MEKE/MODEL SERIAL# UNIT# CPL INJ

BOOM TRUCK REP

REPAIR BOOM TRUCK

SHOP LABOR

1,020.00

REMOVED LIVE SWIVEL. TORE DOWN SWIVE AND INSPECTED PARTS. HONED OUT TUBE DUE TO MINOR DAMAGE. CLEANED, RESEALED AND REASSEMBLED INSTALLED SWIVEL BACK INTO UNIT. REPLACED ALL HOSES ON LOWER SIDE REMOVED MOTOR FROM SWING. TORE DOWN MOTOR AND INSPECTED PARTS. FOUND THAT THE SHAFT AND BEARING WERE BAD IN THE MOTOR. CLEANED MOTOR AND REPLACED SHAFT AND BEARING. RESEALED AND REASSEMBLED MOTOR. INSTALLED MOTOR BACK ONTO UNIT. GREASED GEAR BOX. FILLED WITH OIL (ND RAN UNIT. NO LEAKS FOUND.

PART NUMBER FARTS

DESCRIPTION

TANDOMA

TOTAL PARTS .....

856.25

NET 10TH

INVOICE TOTAL ... \$1,876.25

\*\*\*\*\*\*\*\*\*\*\*\*