

ANNUAL INSPECTION REPORT

Prepared By	Kerry Lewis	Serial Number	10026	Model	UB50	Customer unit	# G8538
Customer	MISSOURI DOT			-	Date	January 3, 20	17
City	Jefferson City		State/Province	ce Mis	souri	Zip Code	65102
Inservice Date	December 15, 1997		Firs	st Rebuil	d Completed	Date	December 15, 2007
			Second Rebuild Completed		Date		
				R	ebuild is due on:	Date	December 15, 2017
PTO HOURS	3,155		CHASSIS H	OURS	15,963		
AUX ENG. HOU	RS 111.9		CHASSIS N	IILES	180,842		

TEST AND REPORT LIMITATIONS

This report is provided to you with the understanding that ASPEN AERIALS, INC.'s responsibility is solely to conduct the inspection and assist you with the interpretation of the results. The decisions you make thereafter, concerning the equipment, are your responsibility. Aspen Aerials is not responsible for decisions you make or their consequences.

WARNING

This inspection determines the state of the equipment only at the time the inspection was performed! Any overloads, accidents or abuse of this equipment, after the test, could result in the inspection performed, no longer being valid. Structural damage may have occurred even though the equipment visually may appear intact and usable after said overloads accidents or abuse. Furthermore, materials experience a normal aging process whether abuse occurs or not. Therefore, the unit must be inspected before each use, to insure its structural integrity.

Description of codes used in this report	Defect Code	
Immediate action is required - Take unit out of service	1 <u>CRITICAL</u>	
Repair as soon as possible, it may become critical	2	
Repair soon, next time the unit is in for maintenance	3	
No repair needed. Area should be watched for further degradation	4	
Review Notes prior to using unit	5	
Item Inspected and no work is required	OK	
Not Applicable	NA	

WELDING NOTE

Aspen Aerials requires that all structural welding on this unit, be performed to AWS D1.1 steel and D1.2 aluminum standards.

Contact the Service Department at Aspen Aerials for welding instructions, prior to any welding being performed.

MANUALS AND DECALS	Defect Code #5
$\overline{ extsf{X}}$ ANSI/SIA Manual of Responsibilities in the manual sto	
$\overline{\times}$ Operators & Service manual with truck	049077 Decal on front bumper needs to be replaced.
$\overline{\times}$ Capacity decals in place, secure & legible, at all control	stations
$\overline{\times}$ All safety & instructional decals installed, secure and le	gible.
TRUCK CAB AND UNIT POWER PANEL	2.66
□ Chassis instrument panel checked	Defect Code #3 Notes:
✓ Unit power, switch panel checked and operational	Axle lock engage lamp is out.
	PTO lamp on wired rite is out.
☐ Tag/Pusher Axle function ☐	Windshield
	Lights
7/2 Tag/Tustiel Axie pressure	
ELECTRICAL WIRES AND HYDRAULIC HOSES	Defect Code #3
Wires Hoses	Notes:
	Front axle locks have minor leaks on both sides.
	A1 hose off HPI vale has a crimp leak
⊠ 12Volt	
⊠ 120Volt	
LIMIT SYSTEM	Defect Code #3
$\overline{ extsf{X}}$ Test all switches for proper functioning	Notes:
⊠ Mounting	70 degree Mercury switch leaking. Bulb tip is cracked. Sending replacement.
X T-2 plate, switch contact	
X Axle Lock Interlock	
$\overline{ imes}$ Limit switch function panel checked	
	ts
,	
WORNING CHINDERS	
HYDRAULIC CYLINDERS	Defect Code OK
○ Check for leaks or damage ○ Visually leanest Wolds	Notes:
✓ Visually Inspect Welds ✓ Firstings	
▼ Fittings ✓ Halding Values	
✓ Pins	
Check for Rust/Corrosion	
Serial Number 10026	Page 2 c

Serial Number

INTERCOM SYSTEM		Defect Code OK		
Test		Notes:		
▼ T1 station	$\overline{ extsf{X}}$ Check headset at each station			
Number of heads	set stations three			
CONTROL SYSTEM		Defect Code #3		
⊠ All joysticks/push button	controls return to neutral when released	Notes:		
Check condition of conti	rol enclosures and protective boots	Fast slow selector not working on the walk around box.		
Check control enable sy	Fast Slow function			
Foot Switch, if equipped	I ☐ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○			
Cable Connections				
∇ontrol Set Installation	□ Ground Controller			
Is unit equipped with a Plus	-One system? No			
Was a program revision inst	alled during this inspection? No	Type of Controls MRC-10X		
Program Rev.	Ground Cont	Platform Control #		
CHASSIS, SUBFRAME, PEDES	STAL, DECK, BODY	Defect Code #3		
∀ Visually Inspect Welds	🗵 Engine Area	Notes:		
∇ Suspension	🔀 Mud Flaps	Compressor has a minor gasket leak Oil pan sensor connector needs to be repaired		
Frame Clips		Pack rust developing on sub frame and tag axle area.		
▼ Mounting Bolts	Tag/Pusher Axle Components	Multiple minor leaks on engine and tranny. Tire pressure low. Passenger side tag axle shock is broken.		
$\overline{ imes}$ Body boxes	Check subframe condition			
		Front springs are flat. Odometer and tach are not working properly		
		out the contract of the contra		
AUXILIARY ENGINE, COMPR	ESSOR, GENERATOR	Defect Code OK		
⋈ Battery connections che	ecked	Notes:		
⊠ Hoses/Wires	🔀 Engine Oil	Commence making air but both regulators are leaking. The		
		Compressor making air but both regulators are leaking. The blow off on the bottom of the tank is leaking by.		
	⊠ Belts			
	🗵 Exhaust			
□ AC Electrical System		Air Filter Part # Non Stock		
Generator output	5 vac at 60 Hz	Oil Filter Part # Non Stock		
Air compressor loads 90	psi	Fuel Filter Part # Non Stock		

10026

Serial Number

HYDRAI	ULIC S'	YSTEM				Defect Code #3	
				Notes:			
▼ Tank condition, gauges, filters, cap				Main line off pump and leveling section have cr	imp leaks.		
 Check hydraulic pressures and ensure proper adjustment 							
∇ PTO and Pump operation							
	t relief						
⊠ Per	form h	olding valve test					
		y Override System					
	_	/ Unit Selector					
⊠ Mo	unting	of Components					
		lve Blocks					
	•					Return Filter Part # 064079	
						Pressure Filter Part # 063339	_
					Leveling Filter Part # N/A		
AXIFIC	OCK A	ND COUNTERWEIG	HT SYSTEMS			2 (, (,) #3	
Front	Rear					Defect Code #3	i.
Locks	Lock					Drivers side front axle, the C22 hose has a crimp le	eak and line
X	▼ Visually Inspect Welds				should be replaced.		
$\overline{\times}$				Adjusted both sides and tightened Both rear cylinders have seal leaks.			
$\overline{\times}$				•			
$\overline{\times}$							
$\overline{\times}$							
$\overline{\times}$	$\overline{\times}$	Cylinders					
$\overline{\times}$	$\overline{\times}$	Fasteners				_	
				Operation, in/out, contact with switches			
Rear Sliding counterweight installed? Yes				∑ Diverter valve and springs checked			
						□ Drive System □ Dr	
TURNT	ABLES	#1 AND #2				_	
▼ Tui	rntable	bolts inspected ar	nd torque tested	⋉ τ1 ⋉	Γ2	Defect Code O	K
⊠ Ch	eck op	eration		⊠ T1 ⊠	Τ2	Notes:	
			⊠ Visua	ally inspect b	earings		
☐ Gear Box Mounting ☐ Gear Box Operation				on			
Brake torque value T-1 ft/l				T-1	ft/lbs		
Are brakes insta		talled? No					
Brake torque val				1-2	ft/lbs		
Serial	Numb	er 10026					Page 4 of 6

BOOMS			Defect Code OK		
$\overline{ imes}$ Visually inspect welds			Notes:		
$\overline{ imes}$ Visually inspect all cylind	der connections				
		⊠ Rollers			
■ Bushings		▼ Wearpads			
		▼ Tie Down Strap			
		⊠ Boom Rest			
□ LInkarms/Pivots	Boom Wear Pad I	Measurements (A-52)			
PLATFORM or WALKWAY					
	tion	▼ Platform Rests	Defect Code #5 Notes:		
∇ Visually inspect welds ar		Slide Condition	Shined the platform leveling relief valve to achieve proper		
			pressure. Relief is 3300 PSI		
	ons	Ladder (if installed)			
	⊠ 12V lig	ght receptacles	☐ 120v/220v Electrical Outlets		
TILT ALARM / ENGINE KILL S	YSTEMS				
Test engine kill system	▼ T1 ▼ Platfo	orm 🗵 Cab	Defect Code OK		
Other Locations N/A			Notes:		
▼ Test stepping relays					
processepping relays					
▼ Test tilt alarm horn operation					
□ Check mounting installat					
OTHER			Defect Code OK		
Unauthorized Modifications	or Additions	No	Notes:		
∇ Paint and overall appear	rance	,			
X Applicable safety bulleti					
☐ Greasing and lubricating					
区 Decals □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □					
Is hy-rail gear installed on this unit? No Hy-rail visual inspection					
Any changes in personnel or ownership? Customer Comments? Other notes.					

Page 5 of 6

10026

Serial Number

MAINTENANCE RECOMMENDATIONS

- 1. Protect the exposed cylinder rods by applying a light coating of oil at least once a week.
- 2. When necessary, adjust all hydraulic hoses and electrical wires through the booms and pivot points.
- 3. Maintain the proper tire pressure, as recommended by the tire manufacturer.
- 4. Lubricate the unit as recommended in the service manual. Remove excessive grease.
- 5. Lubricate the T-1 and T-2 rotation gear teeth with open gear compound when gear teeth become dry.
- 6. Replace all hydraulic filters annually.
- 7. Test oil yearly. Change at least every 5 years
- 8. Remove rust that develops on components and repaint, as necessary.
- The pin connections and boom pivot points must be kept clean and free of excessive grease and debris to allow for proper pre-operation and frequent inspections.
- 10. Clean and lubricate the axle lock assembles, as required.
- 11. Clean and lubricate the sliding counterweight components at regular intervals (if installed).
- 12. The ball screw device on the sliding counterweight must be lubricated every 80 hours of operation. Use white lithium grease.
- 13. Lubricate the hydraulic diverter valves, at the rear sliding counterweight, weekly. Use silicone.
- 14. Clean the switches and buttons with electrical contact cleaner, monthly.
- 15. Clean dump valve cartridges, as necessary, to prevent corrosion. Apply dielectric grease for protection.
- 16. Each day, before the unit is operated, perform a pre-operation inspection.
- 17. Perform frequent inspections every 3 months or 200 hours, whichever occurs first.
- 18. Perform all service procedures, as outlined in the manufacturers parts and service manual.