

Service Invoice

Benco Machinery, LLC 7600 N Bryant Ave. Oklahoma City, OK 73121 P.405.486.7789

Customer Number:	
10019	

Work Order #:	18000384
Date Opened:	5/24/2018
Date Closed:	7/1/2018
Tech:	МН

Customer PO #:

Cu	stomer Info:
Ε	Benco Machinery, LLC
7	7600 N. Bryant Ave
(Oklahoma City, OK 73121
-	

Location of Repair:	
Watonga	

Make	Model	Serial Number	Hours In	Hours Out
J Deere	872G	PEF658277	5772	5776

Service requested:

Unit has multiple code. Drive to job site, and diagnose codes.

Work Order Summary per segment:	Travel Labor	Parts	Repair Labor	Mileage	Segment Total
01] Travel and diagnose codes. Replace turbo.	\$969.80	\$3,459.70	\$1,104.15	\$872.60	\$6,406.25
02] Further issues found bad DEF pump.	\$0.00	\$1,386.20	\$1,535.66	\$0.00	\$2,921.86
				Total	\$9,328.11

Work Performed 1]			rformed 1] Part # Description			Quantity	Price				
Travel to job site to diagn			el to job site to diagnose trouble codes. Order parts,		to job site to diagnose trouble codes. Order parts.		RE550231	Turbocharge	r	1	\$3,145.19
and return to replace turk		,	R56466	R56466 O-ring		3	\$5.40				
			R529141	Gasket		1	\$3.00				
			R534121	Cap screw		4	\$14.60				
				Gasket	Gasket		\$7.88				
				Element		1	\$155.22				
				Element		1	\$96.97				
				Filter kit		1	\$31.44				
	Hours/Mileage		Rate	Total	I	Parts Total	\$3,459.70				
Travel Labor	14.92	\$65.00		\$969.80	1	Travel Labor	\$969.80				
Mileage	436.3	\$2.00		\$872.60	1	Mileage	\$872.60				
Repair Labor	12.99		\$85.00	\$1,104.15	1	Repair Labor	\$1,104.15				

Work Performed 2]			Part #	Description		Quantity	Price	
Travel to job site to diagn	Travel to job site to diagnose more trouble codes. order			RE553796 DEF injection pump		1	\$1	,373.30
	parts, then return to job site to replace DEF pump. Clear			DEF injection	pump	2.5		\$12.90
codes, and test machine.								
	Hours/Mileage		Rate	Total		Parts Total	\$1	,386.20
Travel Labor				\$0.00		Travel Labor		\$0.00
Mileage				\$0.00		Mileage		\$0.00
Outside Labor	1	\$1	,535.66	\$1,535.66		Repair Labor	\$1	,535.66

Explanation of work performed:

Traveled to Watonga, OK job site. Machine has multiple codes stored. I found twenty-nine in memory. Five codes are related for turbo actuator issue. Code 641'5 has occured fifty-eight times starting at 5,757 hours. Code became inactive after opening, and inspecting turbo. Only remaining code is engine derate code 1569.31 occured seventy-two times. Rustin informed me that the fuel filter, water/fuel seperator are the only components that he has worked on. I will order turbo, and parts to replace turbocharger'. I returned to the job site to remove the turbo, and replace it with new parts, o-rings, gaskets, hardware, elements, and filter kit. I cleaned all parts that would be reused. Made all connections with sensors, and wiring harness. Checked to make sure all bolts were tight. Double checked fluids, and allowed system to recalibrate, and learn new turbo with sensors. The system did NOT acknowledge sensors, and three of the stored codes returned. I attempted to clear codes, then restart. A new code for DEF fluid pump failure is now showing. I consulted the management team for next process. Contacted C.L. Boyd to travel to job site and perform diagnostic testing with John Deere program.

Work performed #2- From C.L. Boyd. Arrived at machine due to customer's concern of turbo codes coming active with machine running. Customer has previously consulted with Richie B. and he informed them that replacing the turbo would likely resolve the issue. Confirmed that new turbo had been installed. Started unit and drove around the yard. No codes are showing at this time. Customer returned unit to work, and codes appeared . Codes- 641.5, 641.06, 641.07, 1569.31, and 5435.11 are now active. Removed engine compartment doors, and cover. Inspected harness from ECU to VGT turbo area. Found a spot where the harness goes over the top of the valve cover that has been rubbing, and rubbed two wires. One was for turbo actuator. I repaired wiring, and tested. Reinstalled harness, and performed a VGT valve learn. Started unit and ran for about ten minutes with no issues. Code 5435.11 was active the entire time. Performed a DEF pump diagnostic test, and the pressure would never build above 0.3 psi. Visually inspected pump connections, and DEF tank header connections and all looked good. Informed customer that machine would need a new DEF pump. Will return to install new pump. Arrived with new pump, and fluid. Opened compartment door and removed bad DEF pump. Removed filter from pump, and checked for debris/dirt. Filter was clean, and will be reused. Installed new pump and reconnected hoses, and wiring harness. Filled tank with 2.5 gallons of DEF fluid which brought tank to 89.4% full. Performed DEF pump diagnostic test with Service Advisor. After 15 seconds of priming, the pressure went from 2.0 psi to 150 then leveled off and held at 130 psi. Shut off unit and check for leaks. No issues found. Restarted machine and let it run for 10 minutes at varying RPM's while monitoring VGT van position actual and desired as well as DEF pump outlet pressure. Repaired drivewire 5007PUR, and new DEF pump resolved issues of VGT codes, and DEF pump pressure low codes on machine. Replaced all engine

Due Date	NA
Please Pay This Amount	\$9,328.11

SERVICE INVOICE

Invoice Number: Invoice Date

485451 11/22/2019

Location: Work Order Number:

03 84139

Payment Type:

Account

Meter 1 of 3 JOHN DEERE 872GP Serial Number: EQ Id: Fleet No: 6593 1DW872GXPEF658277 Service Reminders: EF658277 TRAVEL -F-0000011 Retail

COMPLAINT:



CORRECTION:

Traveled 38 miles Traveled 38 miles

Miscellaneous

Description

MIL SVC 4

MILEAGE #4 GM488208 NF

Quantity 76.00

Misc:

Net Price Extended Price Taxed Ind

Labor:

Gen1- Retail COMPLAINT:

Check the machine emission system The DPF/DOC is stopped up

CORRECTION:

Check the machine emission system Hooked up the machine to Service Advisor Checked for any codes on the machine There was 27 different codes on the machine All of the codes were stored though The unit was low on coolant The operator said they had to add coolant weekly Disconnected the batteries Removed all four panels on both sides Removed the hood Removed the after treatment structure Removed the DPF/DOC assembly Disassembled the DPF/DOC Removed one brace and drained the coolant Removed the EGR cooler Sent the cooler and DPF/DOC to be cleaned and tested Removed and replaced the fuel dosing pressure regulator Removed and replaced the fuel dosing valve

SERVICE INVOICE

Invoice Number: 485451 Invoice Date 11/22/2019 Location: 03 Work Order Number: 84139 Payment Type: Account

Prv Phone	9:				
Make/Model:	Meter	Serial Number:	Page:		2 of 3
JOHN DEERE 872GP	1000	The second secon	EQ ld:	Fleet No:	-
Service Reminders:	0093	1DW872GXPEF658277	EF658277		

The DPF/DOC was good, just needed to be cleaned Reinstalled the DPF/DOC with new gaskets

Reinstalled the after treatment structure

The EGR test came back and it failed the test

Ordered a new EGR cooler

installed the new EGR cooler with new gaskets

Filled the unit with new coolant

Calibrated the DPF/DOC

Bled air from the fuel dosing system

Checked the dosing pressure and it was good

Reinstalled all of the panels

Operation check the machine, it was good for DPF/DOC

But during the checks, the machine threw a code of 523680.05

Looked up the code on Service Advisor

Removed the cover for 6WD controller

Removed cover for X41 plug between the cab and rear Found an open wire W041 to the solenoid (blue wire)

Ran a 9' length of new wire from solenold connector to X41 connector behind cab

Ran the machine for one hour to check the operation of the machine, no issues were noted

Taped off the wire and zip tled along large harness as needed. Installed a small side shield

Ran the machine for 1 hour to make sure there were no problems

The machine ran great

PartNumber	Description			
14M7718	LOCK NUT	Quantity	Net Price	Extended Price Taxed Ind
24M7544	WASHER	2.00		Taxed Ind
51M7041	O-RING	2.00		
51M7045	O-RING	1.00		
57M7542	ELEC. CONNEC	3.00		
AT366435	Strap	1.00		
DZ102534	HEAT EXCHA	1.00		
H77698	TIE BAND	1.00	1	
PM38657	SEALANT	12.00		
R104846	ELEC, CONN	1.00		
R44302	TIE BAND	2.00		
R528237	SEALING RI	20.00		
R529640	GASKET	1.00		
R537859	GASKET	2.00		
R566072	O-Ring	2.00		
R56905	O-RING	8.00		
		3.00		

SERVICE INVOICE

	THE HAVOICE
Invoice Number: Invoice Date Location: Work Order Number: Payment Type:	485451 11/22/2019 03 84139 Account

JOHN DEERE 872GP		Meter Serial Number:		Page:		3 of 3
Service Reminders:	or .	6593	1DW872GXPEF658277	EQ Id:	Fleet No:	
R78059 RE526831 RE533910 RE539465 RE542996 RE550177 RE554363 RE568261 177932 175020 175020 1744 Iscallaneous REIGHT L&M Charges:	ELECTRICAL LINE FUEL FILTER FILTER ELE Flow Control Hyd. Valve VALVE CLAMP CLAMP CLAMP O-RING TAPE TAPE wire Description FREIGHT		1 2 1. 1.	00 00 00 00 00		

Miscellaneous Charges:

Environmental Fees

Labor: Parts: OL&M: Misc:

Sales Tax:

Total: \$12,649.46

PARTS INVOICE

Invoice No: 489651

Date: 12/11/2019

Page: 1 of 2

Payment Type:

Account

Supplied Quantity	Back Order Quantity	Part Number			4	Net	Extended	
			Part Description	Bin	List			Tax
1.00	0.00	T77613	O-RING	Loc	Price	Price	Price	Ind
4.00	0.00	14M7665	Nut	3401C				
12.00	0.00	19M7572	CAP SCREW					
12.00	0.00	19M7572	CAP SCREW	2305C				
12.00	0.00	19M7662		2305C				
6.00	0.00	19M9145	CAP SCREW	2309C				
12.00	0.00	24M7239	Cap Screw WASHER					
6.00	0.00	24M7559	WASHER	2001E				
12.00	0.00	24M7618	WASHER					
1.00	0.00	38H5012	ADAPTER FI	2001C				
1.00	0.00	38H5026	Elbow Fitting					
1.00	0.00	51M7043	O-RING					
24.00	0.00	T129981	SHIM 3403B					
12.00		T129982	SHIM					
4.00	0.00	T221053	Plate					
4.00		T239757	INSERT					
13.00	0.00	T240964	SHIM	7307B				
12.00	0.00	T240965	SHIM	5201C				
2.00	0.00	T299148	Retainer	7908				
2.00	0.00	T299164	INSERT					
15.00	0.00	T418899	INSERT	7208A				
6.00	0.00	T418904	INSERT	7306C				
4.00	0.00	9M10207	Cap Screw	7307A				
1.00	0.00	HC16797	Hydraulic Cylinder					
1.00	0.00 A	T219733	TEMPERATUR					
1.00	-	T398271	COMPRESSOR	4205A				

PARTS INVOICE

Invoice No:

489651

Date:

12/11/2019

Page:

2 of 2

Payment Type:

Account

Supplied	Back Order Quantity	Part Number	Part	en:		
duantity			Description	Bin	List	
1.00	0.00	AT471493	Cultab	Loc	Price	

Switch

4204C

Net Price

Extended Tax Price Ind

Invoice Notes:

AT471493

405-492-2619,

Parts:

Misc:

Sales Tax.

Deposit:

Total:

\$9,100.44