CUSTOM	1041	MAKE	MODEL	VIN	Engine SN	ODOMETER	HOURS
11	12 2005	PETERBILT	CONVENTIONAL	1XP5DU9X15N842727	KCB09412/ KCB14	949 170,918	0
			Sold O	perations			
JOB#1 0							
CAUSE	INT REPLACE ENG	INE WITH CUSTOMER S	UPPLIED ENGINE				
CORRECT	TION						
	COOLANT, REI ROCKERS, CON BOLTS, TORCH TRANS COOLE	MOVED HOOD, RADIAT NNECTED CHAIN TO HE IED SEIZED REAR ENGIN R, TRANS SUPPORT BR	OR, P/S PUMP, STARTER, AD BOLT BECAUSE ENGII NE MOUNT BOLTS, REMO ACKET, FRAME CROSSOV	INES. REMOVED RADIATOR, 'S HEATER CORE LINES, ECM, C NE HAD NO REAR LIFTING BR JVED TURBO DOWN PIPE, EX ER SUPPORT AND LIFTED EN	CAC PIPES, VALVE COV LACKET, REMOVED FRO CHAUST Y-PIPE, DRIVEL IGINE OUT. MOVE OLD	ER, REAR JAKE, REAR ONT ENGINE MOUNT JINE, SHIFT TOWER, O MOTOR MOUNTS	
	AND OIL SUM! MAIN BEARING	P DUE TO USED ENGINE GS AND FOUND WEAR.	ADVISED CUSTOMER A	OLD ENGINE TO BE PLACED (MP VS REAR. WHILE OIL PAN ND INSTALLED NEW ROD AN	N WAS REMOVED. REN D MAIN BEARINGS. PU	MOVED ROD AND JT ON PLACTIC PEICE	
				ED ENGINE INTO CHASSIS. ST			
				VALVE ON COMPRESSOR FR			R.
			AND RECHECKED FOR LE	IGINE. RAN UNIT AND CHECK	KED FOR LEAKS, TOPP	ED OFF ALL FLUID	
QTY	ITEM		RIPTION	ADD.		UNIT PRICE	EXTD PRIC
	LABOR 01	ENG	INE				
1	104F/02-12176-000	BEA	RING-PILOT,72 X 30	X 19MM			
1	104F/05-17223-004	CAP	-PRESSURE, 13/14 P	SI			
1	104F/ABP N25 208925 25	CLU	TCH,15-1/2" X 2" EE	, 400 *D			
1	104F/ABP N35 50EST	CLA	MP-BAND,FLAT,EA	SYSEAL, 5IN			
3	104F/ABP N35 50PLS	CLA	MP-5IN, STAINLESS	STEEL,PRE-			
3	104F/BEN 476445028	TUE	E-RELCTR SLEEVE	1.5"-SPOOL			
2	104F/BRZ 9216H	CLA	MP-HOSE,13/16-1 1/	2IN,1/*D			
1	104F/DN P206411	GUI	LLOTIN				
1 1	104F/DR 10461053	42M	T - 12V REMAN STA	ARTER *D			
-1 1	104F/DR 10461053-CORI	E 42M	T - 12V REMAN STA	ARTER *D			
1 1	104F/DR 10461053-CORI	E 42M	T - 12V REMAN STA	ARTER *D			
1 1	104F/FUL 4305294	GAS	SKET *D				
1 1	04F/PSM 3500075	HEA	TER *D				
1 1	04F/SP 127760	BRA	KE-CLUTCH BRAN	CE DISC ASS *D			
12 1	04K/1163715	STU	D				
1 1	04K/1316645	HOS	SE				
2 1	04K/1978418	GAS	SKET				
2 1	04K/1978419	-	SKET				
1 1	04K/2097309	PLU					
-	04K/2101746		L AS-SUCT				
-	04K/2173673	-	L-ISOLATI				
-	04K/2173674	1000	TENER AS				
	04K/2233505						
-			L-PRESS I				
-	04K/2242675	Name and Address of the Owner, where the Person of the Owner, where the Person of the Owner, where the Owner, which is the Owner, wh	L-PRESS I				
_	04K/2256948	THE RESERVE TO THE PERSON NAMED IN COLUMN	L-O-RING				
_	04K/2398140	-	SE-WTR INL				
	04K/2436717	BEA	ARING-KIT				
1 10	4K/2822403	TUI	BE ASSY				
6 10	4K/2832238	GA	SKET				
		The second second second			The second second second		

Sold Operations (Cont.)							
QTY	ITEM	DESCRIPTION	UNIT PROCE				
1	104K/2894135	GASKET-TURBO					
6	104K/2920484	BEARING-ROD					
12	104K/3E8017	LOCKNUT					
1	104K/5332152	SEAL GP-CSHA					
1	104K/5P8211	SEAL					
40	104O/15W40	OIL					
1	104S/F4HZ 3K506 C	MOUNTING GASKET-POWER STEERING					
4	104X/05-08968	MOUNT-ENG					
2	104X/05-09057SPL	WASHER, SNUBBING					
2	104X/05-09121SPL	WASHER, SNUBBING					
1	104X/06-01105	NUT-JAM					
4	104X/07-03286P0LY	BSHG-POLY					
1	104X/12575	MAY-32					
6	104X/16704	GREEN-BULK					
1	104X/23401-7	2/O 3/8 STUD					
1	104X/23634	HEAT SHRINK					
2	104X/23847	TERM					
4	104X/44039	3/8X3/4 BOLT					
1	104X/44084	I/2X3 BOLT					
2	104X/44092	BOLT					
4	104X/44122	5/8X4 BOLT					
2	104X/44140	3/4X4-1-2					
1	104X/592502	DISC					
2	104X/66129	3/8 LOCK NUT					
2	104X/66131	1/2 LOCKNUT					
4	104X/66133	5/8-11 LOCK NUT					
2	104X/66134	3/4 NUT					
2	104X/7486	DISC					
1	104X/80414	3-8 WSHR					
_	104X/80416	1/2 WSHR					
_	104X/80418	5/8 WSH					
_	104X/FF5319	FILTER					
_	104X/HWC02552						
_		JAM NUT					
_	104X/JX0516401	FRONT ENGINE MOUNT					
_	104X/JX22338	ROD END					
_	104X/JX25795	ROD END					
1	04X/LF691A	FILTER					
1	04X/M705	BK-CLEAN					
1	04X/PBB16-PB-DS	11OZ PENTRATE					
F	RT	FREIGHT	NAME OF THE PARTY				

Invoice Number: Sold Operations (Cont.) JOB#2 28 REPAIR FOR ABS LIGHT ON AND WHEEL SPIN LIGHT ON COMPLAINT CAUSE HOOKED UP THE LAPTOP TO THE TRUCK AND CHECKED ABS FAULT CODES. HAVE ONE CODE FOR J1922-J1939 COMMUNICATION TIMEOUT OR NO ENGINE COMMUNICATION. FOUND RIGHT AWAY THE ABS MODULE NEEDED TO BE CORRECTION SELF CONFIGURED. AFTER DOING THE SELF CONFIGURE THE ABS LIGHT WENT OUT BUT THE WHEEL SPIN CONTROL LIGHT STAYED ON, CHECKED THE CONFIGURATION AGAIN, VERFIED THE SYSTEM DID HAVE A TRACTION CONTROL VALVE WHICH IT DOES. RAN THE ATC VALVE TEST AND IT PERFORMED THE TEST PROPERLY AND THE LIGHT WENT OUT AND THEN CAME BACK ON, CHECKED CODES AGAIN, STILL JUST THE COMMUNICATION CODE, CHECKED THE TROUBLESHOOTING FOR THE CODE AND IT WAS JUST CHECKING THE J-1939 -/+ LINES FOR VOLTAGE. TESTED THE DIAG PLUG AND BOTH LINES WE ROUGHLY 2.5V WITHIN SPEC, REMOVED THE DASH PANELS AND DISCONNECTED CONNECTOR A AND TESTED PINS 1 AND 3 WITH THE SAME RESULTS. LOOKED UP THE OHM SPEC FOR THE ATC VALVE AND IT WAS 9-15. TESTED OUT AT 16.6 OHMS. LOCATED THE VALVE AND DISCONNECTED IT, JUMPED THE TWO PINS AND RE MEASURED AT THE ECU. ENTIRE WIRING CIRCUIT TESTED AT .7 OHMS. THE EXTRA RESISTANCE IS FROM THE VALVE BUT IT IS NOT CODING SO I DONT BELEIVE ITS AN ISSUE. HOOKED CAT ET TO THE TRUCK AND REVIEWED THE PARAMETERS. CHANGED THE ENGINE BRAKE PARAMETER SO THE JAKES COME ON DURING COASTING INSTEAD OF JUST DURING BRAKING. TRIED LOOKING FOR PARAMETERS THAT MAY NEED TO BE CHANGED FOR THE CAT SIDE FOR THE ABS ECU BUT DID NOT FIND ANYTHING. REINSTALLED DASH PANELS. THERE SEEMS TO BE A CONFIGURATION ISSUE WITH THE ENGINE AND BRAKE ECU. CONNECTED TO UNIT ABS BUT CANNOT COMMUNICATE WITH BENDIX MODUAL. REMOVED MIDDLE DASH PANEL AND 18 PIN PLUG FROM ABS MODUAL. FOLLOWED WIRING SCHEMATIC TO PINS 8,9,10 AND FOUND BATTEY VOLTAGE ONLY. VERIFIED ALL FUSES ARE GOOD, TRIED TO TRACE KEY POWER WIRE THROUGH DASH BUT WOULD NEED TO DISMANTLE DASH, RAN KEYED VOLTAGE TO 18 PIN CONNECTOR AND NOW CAN CONNECT TO ABS MODUAL. RAN COMPONENT TEST AND FOUND ALL MODULATING VALVES WORKING. VERIFIED NO CODES. VERIFIED ABS LIGHT IS OUT WITH ROAD TEST. REASSEMBLED DASH. QTY ITEM ABS SYSTEM REPAIR LABOR 28 COMPUTER DIAGNOSTIC COMP ı JOB#3 11 DOT INSPECTION COMPLAINT CAUSE COMPLETED D.O.T INSPECTION. CORRECTION UNIT PRIC DESCRIPTION ITEM STICKER 104X/FED DOT INSPECTION LABOR 11 Job #3 Subtotals JOB #4 43 REPAIR FOR MARKER LIGHTS INOP

COMPLAINT

CAUSE

CORRECTION

IN-OP LIGHTS WERE ON LEFT SIDE OF BUMPER. TRACED WIRING AND FOUND TWO BROKEN WIRES. REPAIRED WITH HEAT

SHRINK BUTT CONNECTOR AND VERIFIED LIGHTS WORKED.

UNIT PRIC DESCRIPTION LIGHTS LABOR 43 Job #4 Subtotals

JOB#5 QC

COMPLAINT

QTCC QUALITY CONTROL CHECK WAS PERFORMED ON THIS VEHICLE

CAUSE

CORRECTION

UNIT PRIC EXTD PRICE DESCRIPTION OTCC QUALITY CONTROL CHECK WAS PERFORMED O Job #5 Subtotals

DISCLAIMER OF WARRANTIES:

ANY WARRANTIES ON THE PRODUCT SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND QUALITY TRUCK CARE CENTER INC. NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION14 THEREOF, A FINANCE CHARGE OF ONE AND ONE-HALF PERCENT(1 1/2%) PER MONTH IS APPLIED TO ALL ACCOUNTS 30 DAYS PAST DUE. THIS EQUALS AN ANNUAL PERCENTAGE RATE OF EIGHTEEN PERCENT (18%).

	ESTIMATED	BILLED
LABOR		
PARTS		
MISC		-
SUBLET		-
PREPAY		1
SUBTOTAL		1
SHOP SUPPLIES		1
TAX		
TOTAL		\$17,889.18

Please Remit Payment to: Quality Truck Care Center, Inc. 5725 Green Valley Rd Oshkosh, WI 54904

CONSTURE OF PERSON RESPONSIBLE OR AGENT FOR PERSON RESPONSIBLE FOR PAYMENT

IMPORTANT: If service has been performed on wheel nuts or axle u-bolts, customer is responsible for retorquing to specs 25 to 100 miles after the service work

Page 4 of 4

Auto E-Mail: N