

315/886-3213

Br	Trk	Make	Model	Serial	Equipment	Meter	Sls	Customer	P.O.
06		ET	CHJP	K5687	16726	10	\$99		

Order	Ship	R/O	Description	Each	Amount
-------	------	-----	-------------	------	--------

316/886-3213

Dr	Trk	Make	Model	Serial	Equipment	Meter	Sl's	Customer	P.O.
06		ET	CHJP	K5687	18726	10	599		

Order	Ship	B/O	Description	Each	Amount
			Closed	9/18/00	

SERVICE TRIP TO REPAIR UPPER AGITATOR IN SPREAD HOPPER
 =====
 DROVE TO CUSTOMERS LOCATION. TALKED WITH FOREMAN. INFORMED
 US THAT THE UPPER AGITATOR WOULD NOT TURN WHEN HOPPER WAS
 FULL OF MATERIAL. INSPECTED THE HOPPER AND FOUND THE
 MATERIAL BEING USED WAS WET BLOW SAND. CUSTOMER INFORMED
 US THAT THIS WOULD BE THE MATERIAL MOST OFTEN USED WITH THE
 UNIT. CALLED ETNYRE AND WAS INSTRUCTED TO MODIFY THE UPPER
 AGITATOR BAR. REMOVED THE GRATE ASSEMBLIES TO GAIN ACCESS
 TO THE UPPER AGITATOR. TOOK THE TORCH AND REMOVED
 APPROXIMATELY EIGHT INCHES OF BAR BETWEEN THE SUPPORT RODS.
 INSTALLED THE GRATE ASSEMBLIES. LOADED THE HOPPER WITH SAND
 AND MADE A TEST RUN IN THE YARD. AGITATOR SEEMED TO WORK
 FINE AT THIS TIME. WHEN WE WERE FINISHED WE PICKED UP AND
 RETURNED TO THE YARD.
 CLAIM DENIED-OPERATOR ERROR

170

Total 534.13

CAUSE:

COMPUTER ISSUE

CORRECTION:

DROVE TO THE MACHINE, INSPECTION FOUND THE DISPLAY SCREEN BLANK. REMOVED SCREWS FROM COVER AND TESTED WIRING. TESTED ALL WIRING FROM COMPUTER TO DISPLAY, ALL WITHIN SPEC. PER SERVICE MANUAL TRIED TO CALIBRATE WITH NO POSITIVE RESULT. REMOVED COMPUTER AND REPLACED WITH A NEW COMPUTER UNIT. AFTER REPLACEMENT WAS INSTALLED ONLY HALF OF THE DISPLAY WORKED. REMOVED SCREEN AND RECALIBRATED THE WHOLE SYSTEM. TOOK FOR A 30 MINUTE TEST RUN WORKING PROPERLY.

COVERAGE :

MILES ROUND TRIP 190 MILES

TOTAL

WORK DESCRIPTION :
DISPLAY SCREEN INOP.

CAUSE:
COMPUTER ISSUE

CORRECTION:
DROVE TO THE MACHINE, INSPECTION FOUND THE DISPLAY SCREEN BLANK. REMOVED SCREWS FROM COVER AND TESTED WIRING. TESTED ALL WIRING FROM COMPUTER TO DISPLAY, ALL WITHIN SPEC. PER SERVICE MANUAL TRIED TO CALIBRATE WITH NO POSITIVE RESULT. REMOVED COMPUTER AND REPLACED WITH A NEW COMPUTER UNIT. AFTER REPLACEMENT WAS INSTALLED ONLY HALF OF THE DISPLAY WORKED. REMOVED SCREEN AND RECALIBRATED THE WHOLE SYSTEM. TOOK FOR A 30 MINUTE TEST RUN WORKING PROPERLY.

COVERAGE :
MILES ROUND TRIP 190 MILES

ITEM /	DESCRIPTION	QTY	PRICE	CORE	TOTAL
tdslss0					
6702194	CIRCUIT BOARD				
6702526	COMPUTER				
6701467	SWITCH				
6701468	SEAL-PUSHBUTTON,GRAY				
6702648	INVERTER				
6703494	DISPLAY-				
6702028	SWITCH-I				
	MILEAGE				
	SHIPPING HANDLING				
	SHOP SUPPLIES				
LABOR	DISPLAY SCREEN NOT WORKING				

8,453.53 TOTAL

QTY

PRICE

CORE

TOTAL

8,453.53 TOTAL

1

1

ET CHIP K5687
NEW ETNYRE HYDROSTATIC CHIP
SPREADER SERIAL NO. K5687
WITH JUMMINS 6BT5.9 145 HP DIESEL ENGINE
SERIAL NO.
FRONT WHEEL DRIVE, LIMITED SLIP DIFFERENTIAL
4-WHEEL BRAKES
MANUAL SLIDING CONSOLE, LEFT TO RIGHT
POWER STEERING
13' WIDE HOPPER WITH AGITATOR
24" WIDE CONVEYOR BELTS, HYDROSTATIC DRIVE,
AUTOMATIC CONTROLS

1 1 ET CHIP K5687
NEW ETNYRE HYDROSTATIC CHIP
SPREADER SERIAL NO. K5687
WITH DUMMINS 6BTS.9 145 HP DIESEL ENGINE
SERIAL NO.
FRONT WHEEL DRIVE, LIMITED SLIP DIFFERENTIAL
4-WHEEL BRAKES
MANUAL SLIDING CONSOLE, LEFT TO RIGHT
POWER STEERING
13' WIDE HOPPER WITH AGITATOR
24" WIDE CONVEYOR BELTS, HYDROSTATIC DRIVE,
AUTOMATIC CONTROLS
MOUNTED ON 385 65R 22.5 TIRES
LIGHTS, HORN, WARNING PACKAGE, BACK-UP ALARM,
COMPUTER CONTROL APPLICATION RATE, AND
SPEED CONTROL
DISCOUNT
1 1 ET CHIP K3516
TRADE IN ALLOWANCE
FOR 1970 ETNYRE CHIP SPREADER
1 1 26 GALION 4952
TRADE IN ALLOWANCE FOR 1969
GALION 9-WHEEL ROLLER S/N 4952
THIS BECOMES A TITLE PASSING INVOICE UPON

CONTINUED

91,400.00