ORDER:

1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	CAS CAS CAS MIS CAS CAS NAP CAS CAS	87574330 87441006 87436120 590-3080 87563692 86625515 209491 392269A2 87436117 FREIGHT FREIGHT 87026034C B134A12	AC ASS'Y HOSE TUBE HOSE,ASSY EVAPORATOR CONDENSER SWITCH A/C TAPE SWITCH, SEAT BAR HOSE,ASSY FREIGHT FREIGHT CORE AIR COND. COMPRESSOR PKG-FLUID	V5J2 V5I4 CORE SHOP	
					Total P

Total Parts

Tax Total WO

\$7,385.35

WO#: 2583456 SV RIGHT REAR TRACK ROLLER REPLAC

Comments:

Complaint: Right rear track roller failed

Cause: Failed roller

Correction: Removed the damaged roller and installed a new one. I adjusted the right track.

Labor:

Description Labor

Shop Supplies

Amount

Total Labor

Parts:

Qty Vendor Part Number 1.00 CAS 47378992 Description TRACK ROLLER Bin U4

Price Ext. Price

Total Parts

Tax

Total WO

\$829.96

WO#: 2583459 SV WILL NOT MOVE

Comments:

Complaint: Machine won't move


Cause: Electrical short


Correction: I found that the both wires going to the enable valve have a short to ground. Neither wiring schematics match this machine. I tested all the relays and the fuses, they tested good. What I believe is the interlock relay 3 of the terminals have continuity with both wires on the enable wire connector wires. Both should only have 1 wire that has continuity with ground. I found that the left hand joystick float switch had a short in it which caused the 2 wires going to the enable solenoid to have continuity together. I fixed that and the machine still wouldn't move. I then found that the cab switch wasn't being activated all the way. I adjusted it and now the machine moves.

Labor:

Description

Amount





CE ORDER:

1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	CAS CAS MIS CAS CAS NAP CAS CAS CAS CAS	87574330 87441006 87436120 590-3080 87563692 86625515 209491 392269A2 87436117 FREIGHT FREIGHT 87026034C B134A12	AC ASS'Y HOSE TUBE HOSE,ASSY EVAPORATOR CONDENSER SWITCH A/C TAPE SWITCH, SEAT BAR HOSE,ASSY FREIGHT FREIGHT CORE AIR COND. COMPRESSOR PKG-FLUID	V5J2 V5I4 CORE SHOP	
					Total D.

Total Parts

Tax Total WO

\$7,385.35

WO#: 2583456 SV RIGHT REAR TRACK ROLLER REPLAC

Comments:

Complaint: Right rear track roller failed

Cause: Failed roller

Correction: Removed the damaged roller and installed a new one. I adjusted the right track.

Labor:

Description Labor Shop Supplies Amount

Total Labor

Parts:

Qty Vendor Part Number 1.00 CAS 47378992 Description TRACK ROLLER Bin U4

Total Parts

itai Faits

Tax Total WO Ext. Price

Price

\$829.96

WO#: 2583459 SV WILL NOT MOVE

Comments:

Complaint: Machine won't move

Cause: Electrical short

Correction: I found that the both wires going to the enable valve have a short to ground. Neither wiring schematics match this machine. I tested all the relays and the fuses, they tested good. What I believe is the interlock relay 3 of the terminals have continuity with both wires on the enable wire connector wires. Both should only have 1 wire that the terminals have continuity with ground. I found that the left hand joystick float switch had a short in it which caused the 2 wires has continuity with ground. I found that the left hand joystick float switch had a short in it which caused the 2 wires going to the enable solenoid to have continuity together. I fixed that and the machine still wouldn't move. I then found that the cab switch wasn't being activated all the way. I adjusted it and now the machine moves.

Labor:

Amount

Description

-- CUSTOMER COPY --

3 of 4