2012 Challenger MT675D NR9350

Engine & Transmission Replacement

Total Parts/Labor
\$74,248.57

W0230007367 04-01-22 685107

23 F UNA

DX03290 12-27-21 10 10 10

9078348

AF MT675D B313075

CLEAN MACHINE

CLEAN MACHINE FOR REPAIRS

CUSTOMER COMPLAINT: CLEAN FOR REPAIRS REPAIR PROCESS COMMENTS: WASHED THE MUD AND GREASE OFF THE MACHINE BEFORE GOING TO THE SHOP TO BE FIXED. 2.35 RT HOURS 46010 AG CLEANING

TOTAL LABOR SEG. 01

SEGMENT 01 TOTAL

INSPECT MACHINE

PERFORM PMI INSPECTION WITH ESITMATE

CUSTOMER COMPLAINT:

PMI

REPAIR PROCESS COMMENTS:

INSPECTED MACHINE AND LOGGED WHAT WAS FOUND.

F/R LBR

SEGMENT 02 TOTAL

23 F UNA 2

DX03290 12-27-21 10 10 10

9078348

AF MT675D B313075

REPAIR TRANSMISSION

REPAIR TRANS FOR NOT PULLING.

CUSTOMER COMPLAINT: TRACTOR STOPS MOVING CAUSE OF FAILURE: CVT REPAIR PROCESS COMMENTS: CUSTOMER SAID IT WOULD STOP MOVING WHEN IT WAS HEATED UP AND CLUTCH WAS PUSHED. READ BACK STORIES, IN 2020 A FIELD TECH WENT OUT FOR THIS SAME PROBLEM AND CVT HAD METAL IN IT AND THEY KEPT RUNNING IT. THE ENGINE WAS BAD, HAD MAIN BEARINGS OUT OF IT, SO I WAS NOT ABLE TO TEST TRANSMISSION. CUSTOMER SAID HE WANTED IT REPLACED, ORDERED NEW CVT. REMOVED CAB. HAD TO REMOVE ALL WIRING HARNESSES AND EVERY HYDRAULIC LINE. THERE WAS ALOT OF THEM GOT DOWN TO THE TOP OF THE CVT. REMOVED TOP AND REMOVED CONTROL VALVES. REMOVED CVT AND REMOVED HYD PUMP TO THE CVT. CHECKED FOR BAD GEARS, THEY LOOKED GOOD. ALAN WANTED ME TO REMOVE THE PTO HOUSING AND CHECK REAR AXLE BEARINGS TO MAKE SURE THEY WERE NOT BAD. REMOVED HOUSING, CHECKED THE BEARNGS. THEY LOOKED

GOOD. CLEANED ALL OF THE GEARS AND CVT HOUSING

23 F UNA 2

3

DX03290

12-27-21 10 10 10

9078348

AF MT675D B313075

WITH BRAKE CLEAN. GOT ALL OF THE METAL OUT. REINSTALLED THE CVT INSERT. ADJUSTED SIDE TO SIDE PER SERVICE MANUAL. HOOKED UP A HYDRUULIC FILL AND PRIMED THE CVT. MADE SURE THE PUMPS WOULD SWING. HOOKED UP LINES IN THE CVT AND REINSTALLED THE CONTROL VALVES. STARTED TO REINSTALL THE HYDRAULIC STACK AND ALL OF THE HYDRAULIC LINES. REINSTALLED THE WIRING HARNESSES AND REINSTALLED THE CAB. FILLED THE CVT WITH 821 XL PLUS OIL. WILL RUN AND TEST WHEN THE ENGINE IS REPLACED. TESTED TRANSMISSION AND COULD NOT GET IT TO CALIBRATE. KEPT SAYING THE CLUTCH WAS NOT PUSHED DOWN WHEN IT WAS. HOOKED UP EDT AND CHECKED THE CLUTCH. EVERYTIME I PUSHED IT TO THE FLOOR IT WOULD STOP READING 100% VALUE AND DROP BACK DOWN TO 0%. UPDATED SOFTWARE TO SEE IF IT WOULD FIX IT. ADJUSTED THE CLUTCH TO READ 100% WHEN PUSHED TO THE FLOOR. WAS THEN ABLE TO GET THE TRANSMISSION TO CALIBRATE. RAN AND CHECKED FOR LEAKS. FOUND A FEW LEAKS AND FIXED THEM. EVERYTHING WORKED AS I'T SHOULD

A THE Y	THING WORKE	IN WO II	SHOULD.	
4	BULK821		LUBRICANT-BULK	PERS
		45100		
1	3008359X1		O-RING/METRIC	N
		45100		
2	3014123X1		O-RING	M
		45100		
1	3014124X1		O-RING	N
		45100		

W023	30007367 04	01-22 6	85107		23	F UNA	2	4
DX0	3290 12-	27-21 1	0 10 10				90783	48
AF	MT675D	B3130	75					
2	3014125X1		O-RING	N				
1	4285539M3	45100 45100	OIL COOLER	S				
1	4289086M2	45100	HYDR, HOSE	N				
2.	4289997M1	45100	TRANSDUCER	N				
4	72310677	45100	BUSHING	N				
3	72313421	45100	O-RING/11X3-F					
4	72313426	45100	O-RING/12.3X2					
2	72313450	45100	O-RING/24X2,5	-FPM S				
2	72313458	45100 45100	O-RING/27X3-F	PM 805				
1	72313469	45100	O-RING/36.2X3	-PPM N				
1	72426251	45100	KIT, SEAL	N				
1	72608824 72655135	45100	GASKET-0,3	N				
1	72655135	45100	VARIO-TRANS	ML26N N				
		45100	CORD DEPOSIT	24				

23 F UNA

DX03290

12-27-21 10 10 10

9078348

AF MT675D

B313075

24 79035450G

821XL+/GALLON DISPS

45405

TOTAL PARTS SEG. 03

AG LABOR AG LABOR 98.42 RT HOURS 46010 12.00 RT HOURS 46010

TOTAL LABOR

SEG. 03

4.00

INBOUND FREIGHT 15555

TOTAL MISC CHGS SEG. 03

SEGMENT 03 TOTAL

REPAIR ENGINE

REPAIR ENGINE FOR NOISE AND LOW OIL PRESSURE,

CUSTOMER COMPLAINT: BAD KNOCK IN ENGINE, CUSTOMER REQUESTED ENGINE OVERHAUL OR REPLACEMENT REPAIR PROCESS COMMENTS:

23 F UNA 2

DX03290

12-27-21 10 10 10

9078348

AF MT675D B313075

REMOVED HOOD, DRAINED WATER OUT, DRAINED ENGINE OIL. IT HAD A LOT OF METAL IN THE OIL. UNHOOKED HYDRAULIC LINES TO THE FRONT AXLE. DRAINED A/C. REMOVED ALL PARTS TO PULL FRONT AXLE OUT. BLOCKED UP THE ENGINE. UNBOLTED THE FRONT AXLE FRAME. PULLED THE FRONT AXLE FRAME AWAY FROM THE REST OF THE TRACTOR AND BLOCKED UP. REMOVED OIL PAN. CHECKED MAIN BEARINGS, THEY WERE GONE. THERE WERE BEARING PARTS IN THE BOTTOM OF THE OIL PAN. ALAN TOLD CUSTOMER, IT WOULD NEED A LONG BLOCK. STARTED REMOVING PARTS OFF THE ENGINE AND HOOKED HOIST UP. REMOVED THE ENGINE AND SET ON BLOCKS. TRANSFERRED BELL HOUSING AND FLYWHEEL TO NEW ENGINE. INSTALLED THE NEW ENGINE INTO MACHINE. STARTED PUTTING PARTS BACK ON. ORDERED A NEW CCV AND REPLACED. THE OLD TURBO WAS SHOT. ORDERED A NEW TURBO AND REPLACED. CRANK SENSOR WAS WORN. ORDERED NEW AND REPLACED. INSTALLED REMAN INJECTORS, AS THAT WAS ALL THAT WAS AVAILABLE. WASHED THE AXLE AND FRAME OFF. PUT BACK INTO PLACE. TORQUED FRAME BOLTS. REINSTALLED ALL PARTS. TOPPED OFF WITH OIL AND ANTIFREEZE. STARTED ENGINE TO CHECK FOR ANY LEAKS. RECHARGED A/C. REINSTALLED HOOD.

٠,		THE STATE STATES	******			
	9	ACP0320100		COOLANT-50/50	SI-OS	
			45100			
	1	ACW0830170		SENSOR	S	
			45100			
	6	BULK10W30		LUBRICANT-BULK	10WS	
			45100			

WO23	30007367	04-01-22	685107		23	F	UNA	2	7
DX03	3290	12-27-21	10 10 10					907	8348
AF	MT6751	В31	3075						
4	V614600	724 45100	O-RING	N					
1	V6146029	930	O-RING	S					
1	V6146032	45100 45100	O-RING	N					
7	V615881	120	GASKET	S					
1	V640016	45100 45100	PLUG	N					
1	V640016		PLUG	N					
2	V640016		PLUG	N					
1	V836015		THERMOSTAT	S					
1	V836329		GASKET	N		-			
1	V8368625		FILTER, OIL	S					
1	V836867		GASKET	s					
1	V836867		DIPSTICK	c					
1	V837073		BREATHER VALVE	S					
1	V837074		PULLEY, IDLER-PK1	2 S					
1	V837084		THERMOSTAT	S					
		45100							

CONT D

WO23	0007367 04	-01-22	685107		23	F UNA	2 8
DX03	290 12	-27-21	10 10 10				9078348
AF	MT675D	B313	3075				
2	V837091436	45100	FUEL FILTER KIT	s			
1	V866873827	45100	TURBO, REMAN	N			
1		45100	CORE DEPOSIT	N			
1-		45100	FULL CREDIT	S			
6	V867079432	45100	REMAN INJECTOR	N			
6		45100	CORE DEPOSIT	N			
6-		45100	FULL CREDIT	N			
1	4279550M1	45100	HOSE	N			
1	4282175M2	45100	TENSIONER PULLEY	S			
1	4282379M2	45100	HOSE	N			
1	4285534M1	45100	COOLER	S			
1	4286479M2	45100	ELEMENT, A/F 600C	S			
1	4287376M2	45100	BELT	И			
1	4299993M1	45100	O-RING	м			
1	4348738M1	45100	BELT/600C	s			

WO23	0007367 04-	01-22	685107			23	F	UNA	2	9
DX03	290 12-2	27-21	10 10 10						9078	8348
AF	MT675D	B31	3075							
2	4348897M2	45100	STUD BOLT-M8/M3	LO N						
1	4350486M4	45100	TUBE	N						
2	658081M2	45100	DAMPER	S						
1	72437627	45100	ELEMENT	S						
2		45100	CORE DEPOSIT	N						
1-		45100	FULL CREDIT	N						
1	865279486T	45100	EXCH. LONG ENG.	s		1				
1-		45100	FULL CREDIT	N						
			TOTAL PARTS		SEG.	04				
	AG LABOR AG LABOR AG LABOR		84.16 RT HOUR 10.75 RT HOUR 5.00 OT HOUR	RS 4	6010 6010					
			TOTAL LABOR		SEG.	04				
8.	00		INBOUND FREI	GHT 1	5555					
			TOTAL MISC C	HGS	SEG.	04				

23 F UNA 2 10

DX03290 12-27-21 10 10

9078348

AF MT675D B313075

SEGMENT 04 TOTAL

REPAIR SUSPENSION CYLINDER

CUSTOMER COMPLAINT: LEFT FRONT CAB CYLINDER LEAKING REPAIR PROCESS COMMENTS: ORDERED AND REPLACED CYLINDER BEFORE CAB WAS WAS INSTALLED. SHOWED ALAN THE BUSHINGS THAT HELD THE CAB CN. THEY WERE GONE AND RUBBING ON METAL. ORDERED AND REPLACED THE BUSHINGS. PUT BACK TOGETHER AND TRIED TO DO A CAB CALIBRATION. IT CAME UP THE RIGHT FRONT CYLINDER OUT OF RANGE. IT WAS UNHOOKED WHEN IT CAME IN, SO IT WILL PROBABLY NEED REPLACED TO GET CAB TO WORK PROPERLY. WILL ASK CUSTOMER WHAT HE WANTS TO DO. ALAN TALKED TO CUSTOMER AND HE WANTED IT FIXED. HOOKED UP EDT AND THE RIGHT FRONT WAS NOT READING ANY HEIGHT. RAISED CAB AND REMOVED CAB CYLINDER. HOOKED IT UP ON THE LEFT SIDE AND IT STILL WOULD NOT READ. THE CYLINDER SENSOR WAS BAD. ORDERED A NEW CAB CYLINDER, HOOKED IT UP TO THE RIGHT SIDE HARNESS. IT WOULD READ HEIGHT. TRANSFERRED HOSES OVER TO NEW CYLINDER AND INSTALLED. WAS ABLE TO GET CAB TO CALIBRATE. RAN AND CHECKED FOR LEAKS. 2 3014717X1 SCREW-12P M12X55 1N

45100

WO23	0007367 04-	01-22	685107			23	F	UNA	2	11
DX03	290 12-	27-21	10 10 10					01111		8348
AF	MT675D	B31	3075							
2	4295028M2	45100	BUSH	N						
2	4295703M1	45100	SPACER	N						
4	4297162M1	45100	BUSH	N						
1	4352383M93	45100	AIR SUSPENSI	ON N						
1	4352383M93	45100	AIR SUSPENSI	ON N		-				
			TOTAL PAR	TS	SEG.	05				
	AG LABOR		12.00 RT H	OURS	46010					
			TOTAL LAB	OR	SEG.	05				
4.	.00		INBOUND F	REIGHT	15555					
			TOTAL MIS	C CHGS	SEG.	05				
			SEGMENT	05 TOTAL						

TEST DYNO

RUN TRACTOR ON DYNO.

23 F UNA 2 12

DX03290 12-27-21 10 10 10

9078348

AF MT675D B313075

CUSTOMER COMPLAINT: RUN ON DYNO FOR CUSTOMER REPAIR PROCESS COMMENTS: CUSTOMER WANTED TO SEE TRACTOR RAN ON THE DYNO. HOOKED UP DYNO AND RAN MACHINE. IT MADE RATED POWER.

F/R LBR

SEGMENT 06 TOTAL

REPAIR THROTTLE

REPAIR THROTTLE FOR NOT REVING ENGINE UP.

ENGINE WOULD NOT REV PAST 1500 RPM AFTER REBUILD, HOOKED UP EDT AND CHECKED FOR CODES. NO CODES PRESENT. UPDATED SOFTWARE, MACHINE STILL WOULD NOT REV UP. GOT AHOLD OF BRENT B. HE WANTED TO JUMP IN ON MY COMPUTER. HE TOOK OVER COMPUTER AND CHECKED A FEW THINGS. IT WAS SHOWING DERATE, BUT NO ACTIVE CODES. HE DIDN'T REALLY KNOW WHAT TO DO. HE WENT AHEAD AND ERASED THE STORED CODES. IT WENT OUT OF DERATE AND WOULD REV FULL THROTTLE. AG LABOR 7.08 RT HOURS 46010

TOTAL LABOR

SEG. 07

23 F UNA 2 13

DX03290 12-27-21 10 10 10

9078348

AF MT675D B313075

SEGMENT 07 TOTAL

REPAIR FOWER TAKEOFF DRIVE

REPAIR PTO LIGHT.

PTO LIGHT KEPT FLASHING NO MATTER WHAT BUTTON WAS PUSHED. WENT THROUGH AUTO 5 CALIBRATION AND CALIBRATED PTO. LIGHT WOULD GO OUT WHEN IT WAS SUPPOSED TO.

AG LABOR

2.42 RT HOURS 46010

TOTAL LABOR

SEG. 08

SEGMENT 08 TOTAL

REPAIR BRAKE ACTUATOR

REPAIR FOR BRAKE PRESSURE DROP.

PARKING BRAKE WOULD COME ON WHEN BOTH OF THE FOOT PEDALS WAS PUSHED. HOOKED UP EDT AND WATCHED THE PRESSURES. WHEN BOTH PEDALS WERE PUSHED, THE BRAKE PRESSURE WOULD GO TO LOW BAR CAUSING PARKING

CONT D

23 F UNA 2 14

DX03290 12-27-21 10 10 10

9078348

AF MT675D B313075

BRAKES TO COME ON. CHECKED EACH BRAKE. WHEN PUSHED THEY WERE GOOD AROUND 60 BAR. THE NEXT STEP WAS TO CHECK THE ACCUMULATOR. IT SHOULD HAVE 44 BAR. PULLED OFF AND CHECKED. IT ONLY HAD AROUND 12 BAR. THIS WAS LETTING THE PRESSURE DROP AND SET THE PARKING BRAKE, ORDERED AND REPLACED ACCUMULATOR. REBLED THE BRAKES AND MADE SURE THEY WORKED PROPERLY. OPERATED MACHINE AND WHEN THE BRAKES WERE PUT ON, IT WOULD NOT GO INTO PARK. TOLD CUSTOMER WHAT I HAD DONE AND HE SAID IT WENT INTO PARK WHEN HE BOUGHT IT SO IT WAS WRONG FOR SEVERAL YEARS.

1 4276645M1

ACCUMULATOR N

45100

TOTAL PARTS SEG. 09

AG LABOR

6.00 RT HOURS 46010

TOTAL LABOR SEG. 09

SEGMENT 09 TOTAL

ADD MACHINE

TIME NOT CHARGED TO THE JOB PER AMS

CONT D

23 F UNA 2 15

DX03290 12-27-21 10 10 10

9078348

AF MT675D B313075

TIME NOT CHARGED TO JOB.

SEGMENT 11 TOTAL

PERFORM MAINTENANCE ON HYDRAULIC SYSTEM

SERVICE HYD SYSTEM AND REPAIR LEAK ON FILTER BASE.

DRAINED HYD OIL, ORDERED NEW FITERS AND O-RINGS. DRAINED OIL, REMOVED FILTER AND REPLACED, REMOVED FRONT CANISTER WHERE THERE WAS AN OIL LEAK. REPLACED O-RINGS AND REPLACD CANISTER. WILL CHECK FOR LEAKS WHEN IT IS REFILLED. ADDED 26 GALLONS OF BULK 821, RAN AND DID NOT SEE ANY LEAKS.

Owners school total	TA TATE TATE	OBD MAI DENNS	
BULK821		LUBRICANT-BUL	K PERS
	45100		
1444800X1		ORING-151.77X	5.33 8
	45100		
4285174M1		ELEMENT/FILTE	R/6008
	45100		
4289985Ml		O-RING	R
	45100		
4289986M1		O-RING	S
	45100		
4289991Ml		O-RING	24
	45100		
4289992M1		BUSHING	N
	45100		
	1444800X1 4285174M1 4289985M1	45100 4285174M1 4285174M1 4289985M1 4289986M1 4289991M1 45100 4289992M1	BULK821 LUBRICANT-BUL 45100 CRING-151.77X 45100 ELEMENT/FILTE 45100 O-RING 4289985M1 O-RING 4289986M1 O-RING 4289991M1 O-RING 4289992M1 BUSHING

WO230007367 04-01-22 685107 23 F UNA 2 16 DX03290 12-27-21 10 10 10 9078348 AF MT675D B313075 1 72453362 BEND 45100 TOTAL PARTS SEG. 12 AG LABOR 5.50 RT HOURS 46010 TOTAL LABOR SEG. 12 2.00 INBOUND FREIGHT 15555 TOTAL MISC CHGS SEG. 12 SEGMENT 12 TOTAL

REPAIR HOSES & LINES

REPAIR LEAK ON HYD HOSE UNDER ENGINE.

HYDRAULIC HOSE FOR THE FRONT END SUSPENSION WAS LEAKING, ORDERED NEW, REMOVED THE OLD HOSE AND INSTALLED THE NEW ONE, RAN AND CHECKED FOR LEAKS.

AG LABOR 1.00 RT HOURS 46010 AG LABOR 1.00 RT HOURS 46010

23 F UNA

DX03290

12-27-21 10 10 10

9078348

AF MT675D

B313075

TOTAL LABOR SEG. 13

SEGMENT 13 TOTAL

REPAIR FOR WARRANTY FUEL INJ VALVE/NOZZLE

REPAIR FOR MULTIPLE FAILED REMAN INJECTORS.

CUSTOMER COMPLAINT: REMAN INJECTORS FAILED REPAIR PROCESS COMMENTS: AFTER I GOT ENGINE RUNNING, IT RAN FOR ABOUT 5 MINUTES THEN STARTED SMOKING AND MISSING, HOOKED UP EDT AND CUT OUT EACH CYLINDER. WHEN CUT OUT, #3 WOULD STOP SMOKING AND ENGINE MISS DID NOT CHANGE, ORDERED A NEW INJECTOR, REMOVED HOSES, INTAKE HOSES, A/C, BRACKETS, AND FRONT VALVE COVER, INSTALLED NEW INJECTOR. REINSTALLED EVERYTHING AND STARTED UP MACHINE. RAN GOOD FOR ABOUT 2 MINUTES, THEN IT STARTED KNOCKING AND SMOKING WORSE THAN BEFORE, SOUNDED LIKE 2 INJECTORS FELL OUT OR ONE WAS NOT SHUTTING OFF AND SPRAYING ALL THE TIME. TALKED TO ALAN HE WANTED 5 NEW ONES INSTALLED WHERE THE REMANS WERE INSTALLED. WE HAVE BEEN GETTING BAD REMANFACTURED INJECTORS. ORDERED 5 NEW ONES.

23 F UNA 2 18

DX03290 12-27-21 10 10 10

9078348

AF MT675D B313075

REMOVED HOSES. INTAKE HOSES, A/C, BRACKETS, AND ALTERNATORS. REMOVE EXHAUST DOC TO GET BACK VALVE COVER OFF. REPLACED THE REMAINING 5 INJETORS WITH NEW ONES, PUT EVERYTHING BACK ON AGAIN. STARTED MACHINE AND IT RAN LIKE IT WAS SUPPOSED TO.

6 V837079432

INJECTOR COMPL.

6

CORE DEPOSIT

6-

FULL CREDIT N

45100

45300

45100

TOTAL PARTS

SEG. 98

LESS 100%-PARTS

AG LABOR

24.00 RT HOURS

46010

TOTAL LABOR

SEG. 98

LESS 100%-LABOR

SEGMENT 98 TOTAL