SAME AS BELOW Ship To: Invoice To:

SERVICE INVOICE

STK#/FLEET#

F005489 EXCAVATOR 350D

HRS PIN/EIN WARRANTY DATE HRS X FF350DX805444

PARTS LABOR ENVIROMENTALFEE MILEAGE CHARGE SHOP SUPPLIES SUB TOTAL ==> IOWA STATE 6% WRIGHT CO 1% CHARGE SALE

3626.65

Ship To:	

SERVICE INVOICE

STK#/FLEET#

F005489 EXC

EXCAVATOR 350D HRS PIN/EIN X FF350DX805444

WARRANTY DATE

HRS

SEGMENT# 1 C 199 N/A

02/28/24 02/28/24

HYDRAULIC LEAK

Drove to customers shop in Eagle Grove. Checked into gear box being overfull. Pulled pilot pump to check main seal. That all looked good on pilot pump. Pulled both main pumps and loaded all three into truck. Drove back to shop and ordered parts.

Unloaded all three pumps and resealed input shafts on all three pumps.

Washed and cleaned pumps and loaded back into truck and drove back to customers shop. Installed main pumps and pilot pump. Filled oil in gearbox and topped off hydraulic oil. Ran and tested for leaks.

IFRT	INBND FREIGHT	1
M800650	Packing	4
PEN0734	BRAKE CLEAN	2
0981201	O-RING	6
3097272	SEAL;OIL	1
40M1855	SNAP RING	1
4191664	O RING	2
4506418	O RING	1
4639126	SEAL	2
70013269	15W40 OIL	1

12011000

SEGMENT TOTAL ==>

2917.56

***** WORK ORDER TOTALS ******
CONTINUED ON PAGE 02

Please pay from this invoice. Invoices over 30 days old will incur a finance charge of 1.5% per month.

Customer Signature

SAME AS BELOW Ship To: Invoice To: SERVICE INVOICE HRS WARRANTY DATE HRS PIN/EIN STK#/FLEET# 12154 FF350DX805444 F005489 EXCAVATOR 350D 1946.01 SPINDLE; ASS'Y 9145787 PARTS LABOR SEGMENT TOTAL ==> 12011000 ***** WORK ORDER TOTALS ***** PARTS LABOR ENVIROMENTALFEE SHOP SUPPLIES SUB TOTAL ==> IOWA STATE 6% WEBSTER CO 1% CHARGE SALE 24617.29 JS

Please pay from this invoice.
Invoices over 30 days old will incur a finance charge of 1.5% per month.

Customer Signature

X.

Ship To:	SAME AS	BELOW	
Invoice To:			

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS
F005489	EXCAVATOR		FF350DX805444			
	350D					
HT696		CARRIER	ROLLER	3		= 04 08
IFRT		INBND F	REIGHT	6		
NAP303		24V BUL	В	2		
NAP91314		BRAKLEE	IN	3		
RE525523		FUEL FI	LTER KIT	1		
TH109453		SEAL		1		
T77858		O-RING		8		
0373413		RING		4		
0373414		SHIM		2		
0492208		RING; BA	CK-UP	4		
0836104		BUSHING	;	2		
0867308		NUT		2		
0962008		O-RING		4		
0975006		PISTON		1		
0981201		O-RING		8		
3033593		COVER; T	TRANSMISS	1		
3040904		CATCH		2		
40M7178		Snap Ri	ing	1		
4241780		BUSHING	3	1		
4297381		O-RING		8		
4390776		SEAL		1		
4630525		PILOT F	FILTER	1		
4630841		A/C HOS	3E	1		
4648103		BOLT		4		
70013269		15W40 C	OIL	8		
70013307		SPIRAX	HYDRA	3		
70013317		TELLUS	S4 46	58		
70013348		SPIRAX	80W90	80		
70013368		PRE-MIX	K	2		
80802		CLEAR F	RTV	1		
00002				CONTINUE	ED ON PAGE	E 04

SAME AS BELOW		
Invoice To:	Ship Via	Purchase Order
0		

SERVICE INVOICE

STK#/FLEET#

F005489

EXCAVATOR 350D HRS PIN/EIN 12154 FF350DX805444

WARRANTY DATE

HRS

SEGMENT# 1 C 132 N/A

03/09/23 03/10/23

INSPECT FOR REPAIRS

Sadler construction 350dlc check over for repairs. Removed hydraulic pump to diagnose leak in bell housing and found input shaft, seal to main hydraulic pump leaking. Found all bolts but two were still holding on pump. Removed broken bolts from bell housing. Installed new seals on pump and put on new drive coupler. Old coupler bolts were not tight and that caused coupler to slide of shaft which then took out the main pump seal. Set drive coupler and reinstalled pump and mounted with new bolts. Replaced two hydraulic hoses in pump compartment that went to main control valve.

Removed rotary manifold to diagnose leak and found seals were shot and stem is grooved bad. Ordered new stem and seal kit.

Resealed rotary manifold and installed back into machine and hooked up lines.

Pulled left hand boom cylinder to reseal. Removed rod from cylinder and put into cylinder bench. Our bench would not remove nut. Took cylinder out to Murphys and their bench would not touch it either. Took back to shop and cut off old nut with torch and cleaned up threads on rod. Resealed cylinder and put back together and onto machine. Pulled right hand cylinder down and pulled apart. Put into bench and had same issue with not being able to get nut off. Cut old nut off with torch and cleaned up treads. Ordered new nut and gland. Installed new seal kit and put cylinder back together and back on machine.

CONTINUED ON PAGE 02

SAME AS BELOW Ship Salesperson 080

SERVICE INVOICE

STK#/FLEET#

F005489

EXCAVATOR

HRS PIN/EIN 12154 FF350DX805444 WARRANTY DATE

HRS

350D Drained hydraulic tank and replaced oil and filter. Oil was black and needed to be changed. Changed engine oil and filter. Changed fuel filters, air filters and cab filters. Took two bad top rollers of right side track and replaced with new. Lifted machine off ground and replaced 2 rollers on undercarriage. Tightened track.

Took left track lose and put two new rollers on undercarriage and one top roller. Tighten tracks and greased whole machine.

Drained and changed oil in final drives and swing motor oil. Replaced bad a/c line to compressor and hooked up a/c machine and charged system.

Replaced broken grease zirk on h-link.

Topped off oil level in final drives and hydraulic tank. Found left final drive is now leaking after moving machine.

Will need new seal. Customer will wait for this repair.	
AT154162	
AT264339 O RING	
O PING	
AT264418 AIR FILTER 2	
AT330978	
AT330980 FILTER	
C/F POLLER	
AT349831 PACKING 1	
CH16109	
DH400836 HYDRAULIC 1	
DZ118283 FILTER KIT 1	
n-+1 Vit	
FYAUUUU0000	
FYA00033065 FILTER	
FYB00000680 Breather	
FYB00003277 Coupling 8	
F3171R CONTINUED ON PAGE U3	100000000

X.

Please pay from this invoice. Invoices over 30 days old will incur a finance charge of 1.5% per month. Customer Signature

Invoice

Date	Invoice #
3/1/2024	3693

Bill To	

Ship To	

O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
350D JD	CHECK		3/1/2024	pickup		
Quantity	Item Code		Descript	ion	Price Each	Amount
384 384	KM5149A/48 HT529 CR5923 HT804	TRACK CHAIL BOLT NUT SPROCKET 35 Sales Tax				

6978.11



						-	OHN DE	
			*** PF	ROFORMA INVOICE **	2			
voice To Account No:	15002708	Deliver To:				SER	VICE IN	OICE
					Invoice Nu Invoice Loc Work Order Nu Payment	Date cation:		/16/2024 15 507025 Account
Make/Model:						Page:		4 of 4
JOHN DEERE 350D			Meter	Serial Number:	EQ ld:		Fleet No:	
JOHN DEEKE 300D			12911	FF350DX805444	DX805444			
Y27845 Ilscellaneous REIGHT	5G 46 ZINC FREE Description FREIGHT & SHIPPIN	NG					\$301.88 Extended Price \$153.14	Taxed In
Miscellaneous Cha								\$250.0
Service Accessories	S							\$250.0
abor:						Sub-Total:		
ease remit payments t	to Murphy Tractor at	the address sl	hown on yo	our monthly statement.				
Customer PO No; Tax Exempt No; Advisor:						Labo Part OL&M Mis Sales Ta	s: /1: c:	
						Tota	ıl: \$17,	625.87
					Date:			



*** PROFORMA INVOICE ***

Invoice To Account No: 15002708 Deliver To: SERVICE INVOICE Invoice Number: Invoice Date 08/16/2024 Location: 15 Work Order Number: 507025 Payment Type: Account Page: 3 of 4 Make/Model: Meter Serial Number: EQ Id: Fleet No: JOHN DEERE 350D 12911 FF350DX805444 DX805444

RUN MACHINE WITH SAME ISSUE.

CAP OFF TORQUE CONTROL SOLENOID AND RUN MACHINE --PUMP 02 OPERATING BETTER BUT STILL NOT TO SPEC.

REINSTALL HOSE TO CONTROL SOLENOID.

REMOVE BOTH HOSES FROM PILOT HYDRAULIC MANIFOLD AND BYPASS MANIFOLD HOOK DIRECTLY TOGETHER.

RUN MACHINE AND FOUND PUMP 02 OPERATES BETTER THAN LAST TEST BUT STILL NOT TO SPEC.

REROUTE HOSES BACK TO NORMAL THROUGH PILOT MANIFOLD.

FOUND PUMP 02 FLOW SOLENOID ADJUSTMENT SCREW LOOSE AND BACKED OUT -- TURNED BACK IN TO SPEC AND TIGHTEN JAM NUT.

OPERATE MACHINE AND RECHECK -SAME ISSUE.

REMOVE TORQUE CONTROL SOLENOID AND PUMP 02 FLOW SOLENOID ASSEMBLIES FROM PILOT MANIFOLD AND CHECK -- NO ISSUES.

REINSTALL SOLENOIDS.

CHECKED SERVICE ADVISOR AND FOUND WIRING FOR PUMP 02 FLOW SOLENOID AND TORQUE CONTROL SOLENOID SWAPPED AROUND.

LOCATE WIRING CONNECTORS TO APPROPRIATE SOLENOIDS.

RUN MACHINE AND CHECK PUMP 01 AND PUMP 02 CONTROL PRESSURES AND OUTPUT PRESSURES -BOTH IN SPEC. DO CYCLE TIMES TEST -- MACHINE IN SPEC.

MACHINE OPERATES NORMALLY AT THIS TIME.

TECH WILL DELIVER FILTER

PartNumber	Description	Quantity	Net Price Extended Price	Taxed Ind
3033593	COVER	1,00		Y
3081085	Pinion Shaft	1.00		Y
40M7120	SNAP RING	1.00		Y
40M7178	Snap Ring	1.00		Y
4630525	FILTER ELE	1.00		Y
4718274	VALVE	1.00		Y
9213855	Pressure Relief Valve	2.00		Y
9742779	GASKET	1.00		Y
A852122	ADAPTER FI	1.00		Y
AT264339	O-RING	2.00		Y
FYB00001128	BEARING	1.00		Y
FYB00001129	BEARING	1.00		Y
FYB00003277	COUPLING	1.00		Y
PM38657	SEALANT	1.00		Y
PM492140	SEALANT	1.00		Y
TH109453	SEAL	2.00		Y
TY26101	BRAKE CLEAN	3.00		Y
TY26674	PLUS-50II 15W40 CK4/SN 32OZ	2,00		

CONTINUED ON NEXT PAGE->



*** PROFORMA INVOICE ***

SERVICE INVOICE Deliver To: Invoice To Account No: 15002708 Invoice Number: 08/16/2024 Invoice Date Location: 507025 Work Order Number: Account Payment Type: 2 of 4 Page Fleet No EQ ld: Serial Number: Meter Make/Model: DX805444 FF350DX805444 12911 JOHN DEERE 350D

CORRECTION:

DRAIN HYDRAULIC TANK.

DISCONNECT AND CAP HYDRAULIC HOSES.

REMOVE EXHAUST SYSTEM.

REMOVE BOTH HYDRAULIC PUMPS AND GEARBOX ASSEMBLY.

NOTE: FOUND PUMP DRIVE SHAFT BROKEN OFF IN DRIVE COUPLER.

CUSTOMER STATED THAT WHEN THEY BOUGHT MACHINE TOP PUMP GEAR-CASE BOLTS WERE GONE AND PUMP HANGING

SUSPECT SHAFT COMPROMISED FROM PUMP ANGLE AND WEIGHT HANGING ON MAIN PUMP GEAR-SHAFT.

TAKE PUMPS BACK TO SHOP FOR INSPECTION.

DISASSEMBLE PUMPS FROM DRIVE SECTION.

CLEAN UP PARTS AND INSPECT.

INSTALL NEW MAIN DRIVE SHAFT, BEARINGS, SEALS AND REAR QUILL PLATE REASSEMBLE PUMPS TO PUMP DRIVE ASSEMBLY AND RESEAL/TORQUE TO SPEC.

INSTALL NEW DRIVE COUPLER TO PUMP ASSEMBLY AND TORQUE TO SPEC.

FILL PUMP GEAR-CASE OIL TO FULL MARK.

INSTALL NEW PUMP DRIVE COUPLER ASSEMBLY ON REAR OF ENGINE AND TORQUE TO SPEC.

INSTALL NEW CROSSOVER RELIEF VALVES IN PROPEL MOTORS WHILE OPERATOR INSTALLING REMAINING SHIELDING.

REFILL HYDRAULIC TANK AND PERFORM PUMP START UP PROCEDURE -- PRIME PUMPS.

RAN MACHINE AND FOUND NUMBER 02 PUMP NOT RESPONDING CORRECTLY.

OPERATOR DID STATE THAT THEY HAD ISSUES WITH LEFT HAND TRACK NOT RESPONDING PROPERLY -LAGGING BEHIND.

CHECK PUMP CONTROL PRESSURES AND PUMP OUTPUT PRESSURES FOR PUMPS 01 AND 02.

FOUND PUMP 01 OPERATING NORMALLY BOTH OUTPUT (5200 PSI) AND CONTROL PRESSURES (580). FOUND PUMP 02 CONTROL PRESSURE LAGGING BEHIND AT WOT (60 PSI), AT IDLE PUMP 02 WILL RESPOND NORMALLY.

CHECK PILOT CONTROL PRESSURE AT WOT WITH PILOT CONTROLLERS IN NEUTRAL -- 149 PSI -- IN SPEC GOOD.

CHECK DTAC FOR ANY KNOWN RELATED ISSUES -COULD NOT ACCESS DTAC, HAD NO CELL SERVICE. REMOVE PILOT CONTROL PRESSURE SENSORS AND SWAP FROM TOP TO BOTTOM TO CHECK SENSORS -NO CHANGE -

REMOVE HOSE FROM PUMP 01 TORQUE CONTROL AND CAP OFF --RUN MACHINE AND CHECK OPERATION --NO CHANGE.

SWITCH HOSE SA AND SB FOR PUMP 01 AND PUMP 02 -MACHINE WILL COME ON-LINE AND OPERATE PUMP 02 NORMALLY -PUMP 02 IS IN GOOD WORKING CONDITION.

REMOVE PILOT VALVES FROM SA (01 PUMP) AND SB (02 PUMP) -FOUND VALVES DAMAGED/GALLED.

RUN MACHINE AND CHECK OPERATION -SAME ISSUE LOW POWER AND PUMP 02 NOT RESPONDING. CLEAN UP VALVES AND REINSTALL.

ORDER NEW PILOT SIGNAL MANIFOLD.

WENT BACK AND INSTALLED NEW PILOT SIGNAL MANIFOLD.

CONTINUED ON NEXT PAGE->

*** PROFORMA INVOICE ***

Invoice To Account No: 15002708

Deliver To:

SERVICE INVOICE

Invoice Number: Invoice Date Location: Work Order Number:

08/16/2024 15 507025

Payment Type:

Page:

Account 1 of 4

Make/Model: JOHN DEERE 350D

Meter Serial Number: 12911 FF350DX805444 EQ ld:

Fleet No:

DX805444

/Travel - 1 Retail

COMPLAINT:

01 Travel, to and from field service jobsite

CORRECTION:

Miscellaneous SURCHARGE

Labor:

Description FUEL SURCHARGE Quantity 608.00 Net Price Extended Price Taxed Ind

\$91.20

0.15 Sub-Total:

\$2,972.40

/GOLD PNT INSPECTION Retail

COMPLAINT:

02 Gold Point Inspection

Full multi-point machine inspection performed by qualified technician.

For Inspection details see attached inspection report.

CORRECTION:

GOLD POINT MACHINE

Labor: \$0.00

Parts: \$0.00

OL&M: \$0.00

Misc:

\$0.00

Sub-Total:

\$0.00

350DLCG1289259 Retail

COMPLAINT:

03 HYDRAULIC PUMPS, PUMP DRIVE COUPLER, R&R

CAUSE:

PILOT MANIFOLD INTERNAL PARTS GALLED PUMP 2 FLOW CONTROL VALVE OUT OF ADJUSTMENT SB AND ST (PUMP 2 & TORQUE CONTROL) SOLENOID WIRING REVERSED

CONTINUED ON NEXT PAGE->