

An error has occurred while processing PictureBox 'pbLogo':

Invalid image data.

----- InnerException -----

Object is currently in use elsewhere.

REPAIR
IDFRC
Dealer C

Terms: Net

Date: 04/13/2022

Open Date:

W. O. #:

P.O. #:

Acct #: IDF2008

Page #: 1 of 8

Written By:

Released By:

Department:

Account:

Ordered By:

Phone:

Year: 2020
Mileage: 345987

Make: Kenworth
Model: W990


Serial #:
Eng Serial #:

1XK1DP9X9LJ389256
Y200471

Operation: 1 Complaint: ***UNIT TOWED IN***POSSIBLE WARRANTY*** CHECK AND ADVISE
UNIT LOST WATER PUMP AND MAY BE WORSE THEN JUST THE
PUMP PROBABLY EGR COOLER

Note:

| <u>Correction:</u> | <u>Labor Amount</u> |
|---|---------------------|
| PERFORM COMBUSTION LEAK CHECK, CHECKED OVER ENGINE, FOUND THERE IS NO COOLANT IN THE EXPANSION TANK, DO NOT SEE ANY COOLANT ON THE GROUND, INSPECTED THE WATER PUMP, FOUND THE WATER PUMP DAMAGED, PULLED TRUCK INTO SHOP, HOOKED UP DAVIE AND GOT SESSION REPORT, DRAIN WHAT WAS LEFT OF THE COOLANT, REMOVED THE R/S CAC PIPE, COOLANT FILTER AND BELT, PINNED THE TENSIONER, UNPLUGGED WATER PUMP ELECTRICAL CONNECTORS, REMOVED WATER PUMP, INSPECTED THE COOLING MODULE FOR DAMAGE DUE TO WATER PUMP, LOOKS OK, STARTED TO SORT THROUGH 4 PAGES OF FAULT CODES, CLEANED OUT THE REST OF THE COOLING MODULE, INSTALLED NEW O-RING ON NEW WATER PUMP, INSTALLED THE WATER PUMP, TORQUED BOLTS RE-INSTALLED THE BELT, RE-INSTALLED THE COOLANT FILTER FOR NOW, REPLACED THE AIR TRANSFER CONNECTION GASKET AND RE-INSTALLED THE R/S CAC PIPE. RE -INSTALLED COOLANT DRAIN PLUG AND FILLED COOLING SYSTEM, LOOKED UP T/S STEPS FOR COMBUSTION GASES IN THE COOLING SYSTEM. REMOVED COOLANT LINES FROM THE AIR COMPRESSOR, FOUND BOTH LINES BROKE IN THE FITTINGS, ORDERED NEW, REMOVED THE FITTINGS FROM THE AIR COMPRESSOR, REMOVED INTAKE AND DISCHARGE HOSES FROM COMPRESSOR, INSTALLED PLASTIC PLUGS IN THE INTAKE AND DISCHARGE PORTS, INSTALLED TEST FITTINGS, PRESSURED UP THE COOLANT SIDE OF THE COMPRESSOR HEAD TO SPECIFIED 140 PSI, CHECKED FOR BUBBLES, FOUND NO BUBBLES, REMOVED TEST PLUGS AND FITTINGS, RE -INSTALLED INTAKE AND DISCHARGE PIPES, REMOVED THE AIR FILTER HOUSING, R/S CAC PIPE, INTAKE HORN, STARTED TO UNPLUG AND LAY THE ELECTRICAL ASIDE. TO TEST EGR COOLER. FINISHED REMOVING THE EGR COOLER, INSTALLED TEST FITTINGS AND VALVE, PRESSURE TEST THE COOLER. FOUND HELD PRESSURE FOR 20 MIN WITH 0 PSI DECAY. REMOVED BROKEN PIECES OF LINES FROM FITTINGS, INSTALLED NEW SEALING WASHERS ON AIR COMPRESSOR COOLANT LINE FITTINGS IN THE AIR COMPRESSOR, INSTALLED THE NEW LINES. HOOKED UP AIR COMPRESSOR SIGNAL LINE. REMOVED THE TEST EQUIPMENT FROM THE EGR COOLER, REMOVED THE VALVE COVER, UNPLUGGED INJECTOR HARNESS, INJECTORS AND ENGINE BRAKE SOLENOIDS, REMOVED THE ROCKER FENCE, REMOVED FUEL LINES FROM THE RAIL AND THE HEAD, REMOVED INJECTORS, PLUGGED OFF OPEN COOLANT PORTS, RE-INSTALLED THE WATER/COOLANT, | 7,068.00 |



IDFRC048762

An error has occurred while processing PictureBox 'pbLogo':
Invalid Image data.
----- InnerException -----
Object is currently in use elsewhere.

REPAIR
IDFRC
Dealer C

Terms: Net

BILL To:

Date: 04/13/2022

Open Date:

W. O. #:

P.O. #:

Acct #: IDF2008

Page #: 2 of 8

Ordered By:

Written By:

Released By:

Department:

Account:

Phone:

Year: 2020
Mileage: 345987

Make: Kenworth
Model: W990

Serial #:
Eng Serial #:

1XK1DP9X9LJ389256
Y200471

PRESSURED UP THE COOLING SYSTEM. CHECKED THE INJECTOR CUPS FOR LEAKING, USED BORESCOPE TO LOOK AT THE TOPS OF PISTONS, REMOVED FLUID FROM TOPS OF PISTONS, LETTING SIT WITH PRESSURE ON THE COOLING SYSTEM. CHECKED TOPS OF PISTONS AGAIN. CANNOT SEE ANY WATER ON TOP OF THE PISTONS, DECIDED TO PULL CYLINDER HEAD, REMOVED FUEL LINES AND BRACKETRY FROM THE CYLINDER HEAD, REMOVED THE ROCKER ASSEMBLIES, PUSH TUBES, HEAD BOLTS IN SEQUENCE, REMOVED THE CYLINDER HEAD, CHECKED THE GASKET-OK, CHECKED THE LINERS-OK, LOOKED OVER THE CYLINDER HEAD AND FOUND A CRACK IN BETWEEN VALVE ON #3. TOOK PICTURES OF CYLINDER HEAD, HEAD GASKET AND LINERS. OPENED UP TCS CASE, HAD TO ATTACH MULTIPLE PICTURES, ATTACHED A WORD DOCUMENT OF ALL THE PICTURES. VERIFIED THAT THE TCS WAS FILLED OUT CORRECTLY, TCS CASE # 220315-04951099, DRAINED ENGINE OIL, REMOVED OIL PAN, PICKUP PIPE, STIFFENER PLATE AND TUBE, OIL PUMP, ANTI-POLISH RINGS FROM LINERS, REMOVED THE PISTONS, REMOVED THE LINERS, INSPECTED THE LINERS AND PISTONS FOR OBVIOUS DAMAGE, DO NOT SEE ANY AT THIS TIME, WIPE DOWN THE BLOCK AND CHECKED THE LINER SEATS, SEE THAT ALL SEAT THAT THE MACHINING MARKS ARE STILL THERE BUT FAINT IN SPOTS. TOOK PICTURES AND PUT INTO A WORD DOCUMENT. USED WHITE BRISTLE WHEEL AND THE INDIA STONE TO CLEAN THE BLOCK DECK. SENT PICTURES TAKEN TO TCS. TCS REPLIED BACK ON THE CASE, ASKED FOR MORE PICTURES, TOOK PICTURES OF THE RUST IN THE BLOCK, ON THE LINERS AND THE COOLANT SAMPLE, ATTACHED PICTURES TO WORD DOCUMENT AND ATTACHED TO TCS. SET UP THE CUTTING TOOL. CUT THE FIRST LANDING. CLEANED UP THE BLOCK AND INSTALLED LINER WITHOUT O-RINGS AND CHECKED LINER PROTRUSION, RE INSTALLED THE LINER AGAIN, FOUND THE LINER FLATTER AND PROTRUSION WITHIN SPEC. SET TOOL UP TO CUT #2. CUT #2 AND CHECKED PROTRUSION-OK, CUT 3 AND CHECKED PROTRUSION-OK, CUT #4 AND WENT TO CHECK PROTRUSION AND FOUND THE LINER AND THE APR DAMAGED. ORDERED NEW LINER, MEASURED PROTRUSION ON #4 AND HAD TO CUT MORE, MEASURED PROTRUSION AGAIN-OK. CUT #5 AND 6. MEASURED PROTRUSION-OK, CLEANED UP THE LINER O-RING GROOVES IN THE BLOCK, GATHERED O-RINGS AND FOUND HAD 12 OF THE VIOLET O-RINGS AND 6 OF THE BLACK O-RINGS, NEEDED 12 OF THE BLACK AND 6 OF THE VIOLET O-RINGS, INSTALLED 1-3 O-RINGS AND LINERS. REMOVED FUEL LINES, BRACKETS, PLUGS AND SENSOR FROM HEAD, REMOVED EXHAUST MANIFOLD, CLEANED AND INSPECTED MANIFOLD, INSTALLED MANIFOLD WITH NEW GASKETS ON NEW HEAD, TORQUED MANIFOLD BOLTS, CLEANED OUT THE INJECTOR BORES, CLEANED UP INJECTORS AND REPLACED THE SEAL RING AND BOTH O-RINGS, INSTALLED INJECTORS WITH NEW HOLD DOWN BOLTS, TORQUED BOLTS, INSTALLED FUEL RAIL, INSTALLED NEW 1-6 FUEL LINES, TORQUED

An error has occurred while processing PictureBox 'pbLogo':
Invalid Image data.
----- InnerException -----
Object is currently in use elsewhere.

REPAIR
IDFRO
Dealer C

Terms: Net

Bill To:

Ordered By:

Phone:

Year: 2020
Mileage: 345987

Make: Kenworth
Model: W990

Serial #:
Eng Serial #:

1XK1DP9X9LJ389256
Y200471

Date: 04/13/2022
Open Date:
W. O. #:
P.O. #:
Acct #: IDF2008
Page #: 3 of 8

Written By:
Released By:
Department:
Account:

THE RAIL MOUNTING BOLTS, TORQUED ALL FUEL LINE NUTS, CLEANED AND INSTALLED INTAKE/MIXER WITH NEW GASKET, TORQUED BOLTS, INSTALLED FRONT LIFTING BRACKET. TRANSFERRED THE PUSH TUBE GUIDES, CLEANED/INSPECTED/INSTALLED ALL VALVE BRIDGES, GOT LAST LINER AND O-RINGS, LUBED THE O-RINGS, INSTALLED LINERS 4,5,6, PREPPED THE #1 PISTON TO BE INSTALLED. CLEANED UP 2 THROUGH 6 PISTONS AND RODS, CLEANED CARBON OUT OF THE RING LANDS, CLEANED UP ROD CAPS, INSTALLED NEW RINGS, BEARINGS IN RODS AND CAPS, WIPED DOWN THE LINERS AND OILED, ORIENTATED THE RING GAPS, INSTALLED #1, #6 AND #2 PISTONS. APPLIED OIL TO ROD CAP BOLT THREADS AND UNDER THE HEADS, TORQUED THE CAP BOLTS, ORIENTATED THE PISTON RINGS, INSTALLED #3, 4, 5 PISTONS AND TORQUED THE ROD CAPS, INSTALLED THE ANTI POLISH RINGS, RAN TAP IN ALL HEAD BOLT HOLES, CLEANED OUT ALL BOLT HOLES, ENSURED THAT ALL OIL PORTS IN BLOCK ARE CLEAR- OK. WIPED DOWN THE TOP OF THE BLOCK AND THE BOTTOM OF THE HEAD, LAYED HEAD GASKET IN POSITION, SET HEAD IN PLACE. INSTALLED ALL HEAD BOLTS, TORQUED ALL BOLTS TO SPEC ACCORDING TO RMI, CLEANED PUSH TUBES, ROCKER ASSEMBLY BOLTS, ROCKER ASSEMBLIES, INSTALLED PUSH TUBES AND ROCKER ASSEMBLIES AND TORQUED BOLTS, PERFORMED OVERHEAD ADJUSTMENT, HOOKED UP THE AFTERTREATMENT FUEL INJECTOR LINE AT THE FUEL MODULE AND HC DOSER, INSTALLED BRACKETS, REPLACED THE VALVE TRAIN CASING GASKET AND INSTALLED THE CASING, TORQUED BOLTS AND HOOKED UP INJECTORS AND ENGINE BRAKE SOLENOIDS, HOOKED UP FUEL HEAD RETURN LINE WITH NEW SEALING WASHERS. INSTALLED TURBO MOUNT GASKET AND NEW TURBO MOUNTING BOLTS AND TORQUED. NOTICED THAT THE VALVE TRAIN CASING AND THE #1 EXHAUST ROCKER TOUCHING, ADJUSTED THE CASING SO WOULD NOT BE TOUCHING, INSTALLED HEAT SHIELD, INSTALLED EGR VENTURI, EGR COOLER WITH NEW SEALS, TORQUED THE HOLD DOWN STRAPS, INSTALLED BRACKET OVER THE COOLER, INSTALLED EGR VALVE WITH NEW GASKETS AND CLAMPS, REPLACED O-RINGS ON COOLANT LINES AND HOOKED UP, BOLTED HARNESS DOWN, INSTALLED COOLANT PIPE ON HEAD AND HOOKED UP EGR COOLER BLEED LINE WITH NEW SEALING WASHERS, CONNECTED ALL ELECTRICAL. INSTALLED EXHAUST GAS PRESSURE LINES, FAN SHROUD UPPER BRACKET, INTAKE HORN. ZIP TIED UP WIRING ON HOT SIDE AND FRONT STARTED TO PUT THE L/S TOGETHER. CLEANED UP BLOCK, CLEANED UP OIL PICKUP PIPE, TUBES, FIXING PLATE, OIL PAN, OIL PUMP, REPLACED OIL TUBE O-RINGS, INSTALLED OIL PUMP, TORQUED BOLTS, INSTALLED FIXING PLATE AND TORQUED BOLTS AS PER SPEC, INSTALLED THE PICKUP PIPE AND TORQUED BOLTS, REPLACED OIL PAN GASKET, SILICONED THE BLOCK JOINTS, INSTALLED OIL PAN AND TORQUED ALL BOLTS, INSTALLED WIRING BRACKETS, REPLACED BOTH FUEL FILTERS, PRIMED FUEL SYSTEM, FILLED COOLING SYSTEM WITH WATER. CLEANED OUT AND

An error has occurred while processing PictureBox 'pbLogo':

Invalid image data.

----- InnerException -----

Object is currently in use elsewhere.

REPAIR
IDFRC
Dealer C

Terms: Net

Date: 04/13/2022

Open Date:

W. O. #:

P.O. #:

Acct #: IDF2008

Page #: 4 of 8

Written By:

Released By:

Department:

Account:

BILL To:

Ordered By:

Phone:

Year: 2020

Mileage: 345987

Make: Kenworth

Model: W990

Serial #:

Eng Serial #:

1XK1DP9X9LJ389256

Y200471

INSTALLED THE CAC PIPES WITH NEW GASKETS, INSTALLED AIR FILTER HOUSING,
FILLED OIL PAN WITH 48 QTS 10-W30 DELVAC OIL. STARTED AND LET RUN AND BUILD
AIR, CHECKED OIL PRESSURE- OK.

| Item | Description | Quantity | Price | Credit | Amount |
|-----------|---|----------|--------|----------|--------|
| 2267065PE | COOLANT PUMP CARTRIDGE, VARIABLE SPEED | 1 | \$0.00 | \$990.22 | |
| 2130588PE | O-RING, 130X4 | 1 | \$0.00 | \$6.13 | |
| 1923003PE | GASKET | 1 | \$0.00 | \$11.62 | |
| 1858039PE | SEAL-13.4X24.0X1.5MM | 2 | \$0.00 | \$2.70 | |
| 2134899PE | PIPE-COOLANT, COMPRESSOR | 1 | \$0.00 | \$27.15 | |
| 2102335PE | COOLANT PIPE | 1 | \$0.00 | \$14.60 | |
| 1822941PE | BOLT-FLANGE M1 | 7 | \$0.00 | \$32.48 | |
| 2161004PE | Bolt, Cylinder Head, M18x200 | 26 | \$0.00 | \$104.78 | |
| 1313120PE | BOLT-FLANGE M8 | 6 | \$0.00 | \$8.88 | |
| 1865847PE | O-RING INJECTOR | 6 | \$0.00 | \$39.48 | |
| 1638270PE | O-RING INJECTO | 6 | \$0.00 | \$37.56 | |
| 2138143PE | GASKET-EXHAUST MANIFOLD | 6 | \$0.00 | \$115.20 | |
| 2106210PE | GASKET- TURBOCHARGER EXHAUST | 1 | \$0.00 | \$20.25 | |
| 1895972PE | BOLT-FLANGE TURBOCHARGER | 4 | \$0.00 | \$71.00 | |
| 2047593PE | PIPE-FUEL INJECTION, 1-4 | 4 | \$0.00 | \$791.40 | |
| 2047594PE | PIPE-FUEL INJECTION, 5-6 | 2 | \$0.00 | \$395.70 | |
| 1930520PE | PIPE-INJECTION FUEL | 2 | \$0.00 | \$379.88 | |
| 1907399PE | GASKET-AIR INTAKE | 1 | \$0.00 | \$21.67 | |
| 2035973PE | GASKET-EXHAUST, EGR | 1 | \$0.00 | \$26.82 | |
| 1979191PE | V-CLAMP, D=75.2MM | 1 | \$0.00 | \$46.04 | |
| 1917870PE | GASKET,EXHAUST | 1 | \$0.00 | \$10.30 | |
| 1979190PE | V-CLAMP, 82MM | 1 | \$0.00 | \$46.07 | |
| 2116602PE | O-RING, 7.4X2 | 2 | \$0.00 | \$8.98 | |
| 2116602PE | O-RING, 7.4X2 | 1 | \$0.00 | \$4.49 | |
| 1898204PE | RING SEAL | 2 | \$0.00 | \$2.94 | |
| 1858037PE | RING-USIT 11.4X22X1.5 | 1 | \$0.00 | \$3.33 | |

An error has occurred while processing PictureBox 'pbLogo':
Invalid Image data.
----- InnerException -----
Object is currently in use elsewhere.

2585 North Boulevard
Idaho Falls, ID 83401
(208) 526-8334
(800) 893-8334
Fax (208) 528-6832

Remit To:
Kenworth Sales Company
Dept.# 001
PO Box 27088
Salt Lake City, UT 84127-0088

REPAIR
IDFRO
Dealer C

Terms: Net:

Bill To: Paccar Warranty
2585 N BLVD
IDAHO FALLS, ID 83401

Date: 04/13/2022
Open Date:
W. O. #:
P.O. #:
Acct #: IDF2008
Page #: 3 of 8

Ordered By:

Written By:
Released By:
Department:
Account:

Phone:

Year: 2020 Make: Kenworth Serial #: 1XK1DP9X9LJ389256
Mileage: 345987 Model: W990 Eng Serial #: Y200471

THE RAIL MOUNTING BOLTS, TORQUED ALL FUEL LINE NUTS, CLEANED AND INSTALLED INTAKE/MIXER WITH NEW GASKET, TORQUED BOLTS, INSTALLED FRONT LIFTING BRACKET. TRANSFERRED THE PUSH TUBE GUIDES, CLEANED/INSPECTED/INSTALLED ALL VALVE BRIDGES, GOT LAST LINER AND O-RINGS, LUBED THE O-RINGS, INSTALLED LINERS 4,5,6, PREPPED THE #1 PISTON TO BE INSTALLED. CLEANED UP 2 THROUGH 6 PISTONS AND RODS, CLEANED CARBON OUT OF THE RING LANDS, CLEANED UP ROD CAPS, INSTALLED NEW RINGS, BEARINGS IN RODS AND CAPS, WIPE DOWN THE LINERS AND OILED, ORIENTATED THE RING GAPS, INSTALLED #1, #6 AND #2 PISTONS. APPLIED OIL TO ROD CAP BOLT THREADS AND UNDER THE HEADS, TORQUED THE CAP BOLTS, ORIENTATED THE PISTON RINGS, INSTALLED #3, 4, 5 PISTONS AND TORQUED THE ROD CAPS, INSTALLED THE ANTI POLISH RINGS, RAN TAP IN ALL HEAD BOLT HOLES, CLEANED OUT ALL BOLT HOLES, SURED THAT ALL OIL PORTS IN BLOCK ARE CLEAR-OK. WIPE DOWN THE TOP OF THE BLOCK AND THE BOTTOM OF THE HEAD, LAYED HEAD GASKET IN POSITION, SET HEAD IN PLACE, INSTALLED ALL HEAD BOLTS, TORQUED ALL BOLTS TO SPEC ACCORDING TO RMI, CLEANED PUSH TUBES, ROCKER ASSEMBLY BOLTS, ROCKER ASSEMBLIES, INSTALLED PUSH TUBES AND ROCKER ASSEMBLIES AND TORQUED BOLTS, PERFORMED OVERHEAD ADJUSTMENT, HOOKED UP THE AFTERTREATMENT FUEL INJECTOR LINE AT THE FUEL MODULE AND HC DOSER, INSTALLED BRACKETS, REPLACED THE VALVE TRAIN CASING GASKET AND INSTALLED THE CASING, TORQUED BOLTS AND HOOKED UP INJECTORS AND ENGINE BRAKE SOLENOIDS, HOOKED UP FUEL HEAD RETURN LINE WITH NEW SEALING WASHERS. INSTALLED TURBO MOUNT GASKET AND NEW TURBO MOUNTING BOLTS AND TORQUED. NOTICED THAT THE VALVE TRAIN CASING AND THE #1 EXHAUST ROCKER TOUCHING, ADJUSTED THE CASING SO WOULD NOT BE TOUCHING, INSTALLED HEAT SHIELD, INSTALLED EGR VENTURI, EGR COOLER WITH NEW SEALS, TORQUED THE HOLD DOWN STRAPS, INSTALLED BRACKET OVER THE COOLER, INSTALLED EGR VALVE WITH NEW GASKETS AND CLAMPS, REPLACED O-RINGS ON COOLANT LINES AND HOOKED UP, BOLTED HARNESS DOWN, INSTALLED COOLANT PIPE ON HEAD AND HOOKED UP EGR COOLER BLEED LINE WITH NEW SEALING WASHERS, CONNECTED ALL ELECTRICAL. INSTALLED EXHAUST GAS PRESSURE LINES, FAN SHROUD UPPER BRACKET, INTAKE HORN. ZIP TIED UP WIRING ON HOT SIDE AND FRONT STARTED TO PUT THE LS TOGETHER. CLEANED UP BLOCK, CLEANED UP OIL PICKUP PIPE, TUBES, FIXING PLATE, OIL PAN, OIL PUMP, REPLACED OIL TUBE O-RINGS, INSTALLED OIL PUMP, TORQUED BOLTS, INSTALLED FIXING PLATE AND TORQUED BOLTS AS PER SPEC, INSTALLED THE PICKUP PIPE AND TORQUED BOLTS, REPLACED OIL PAN GASKET, SILICONED THE BLOCK JOINTS, INSTALLED OIL PAN AND TORQUED ALL BOLTS, INSTALLED WIRING BRACKETS, REPLACED BOTH FUEL FILTERS, PRIMED FUEL SYSTEM, FILLED COOLING SYSTEM WITH WATER. CLEANED OUT AND

An error has occurred while processing PictureBox 'pbLogo':
 Invalid image data.

 Object is currently in use elsewhere.

REPAIR
IDFRO
Dealer C

Terms: Net

Bill To:

Date: 04/13/2022

Open Date:

W. O. #:

P.O. #:

Acct #: IDF2008

Page #: 5 of 8

Written By:

Released By:

Department:

Account:

Ordered By:

Phone:

| | | | | |
|-----------------|--------------------------------|---------------|-------------------|------------|
| Year: 2020 | Make: Kenworth | Serial #: | 1XK1DP9X9LJ389256 | |
| Mileage: 345987 | Model: W990 | Eng Serial #: | Y200471 | |
| 1935753PE | O-RING | 2 | \$0.00 | \$6.36 |
| 1858035PE | RING-SEAL 15X24X1.5 | 2 | \$0.00 | \$2.94 |
| 2234788PE | OIL FILTER ELEMENT | 1 | \$0.00 | \$35.34 |
| K37-1022 | FILTER-FUEL | 1 | \$0.00 | \$45.62 |
| 2277129PE | FUEL FILTER | 1 | \$0.00 | \$55.58 |
| 1863266PE | RING-SEALING | 2 | \$0.00 | \$67.12 |
| 2302341PE | KIT - VALVE COVER/CASING | 1 | \$0.00 | \$41.09 |
| | GASKET | | | |
| 1603977PE | O-RING | 5 | \$0.00 | \$93.25 |
| 1982746PE | CYLINDER LINER SET, H=+0.25MM | 6 | \$0.00 | \$1,794.90 |
| 2146311PE | PISTON RING SET | 6 | \$0.00 | \$960.18 |
| 2111441PE | GASKET-PAN | 1 | \$0.00 | \$172.11 |
| 1608394PE | RING-SEALING | 2 | \$0.00 | \$20.06 |
| 1608393PE | RING-SEALING | 2 | \$0.00 | \$18.00 |
| 1858819PE | BEARING SHELL CON-ROD | 6 | \$0.00 | \$220.32 |
| | STANDARD UPPER | | | |
| 1655712PE | BEARING SHELL | 6 | \$0.00 | \$220.32 |
| 1843659PE | FILTER-COOLANT | 1 | \$0.00 | \$49.93 |
| CC2610FLG | FLUSH-COOLANT | 1 | \$0.00 | \$22.53 |
| 2188417PEX | CYLINDER HEAD, MX13 EPA17, HHP | 1 | \$0.00 | \$6,331.09 |
| 2188417PEXC | CORE CYL HEAD | 1 | (\$1,802.50) | \$1,802.50 |
| 2312234PE | GASKET-CYLINDER HEAD, | 1 | \$0.00 | \$905.86 |
| | SERVICE | | | |
| 2127551PE | RING SEAL, INJECTOR | 6 | \$0.00 | \$52.92 |
| 1922496PE | ELEMENT-OIL, CENTRIFUGAL | 1 | \$0.00 | \$44.11 |
| 1982821PE | PLUG | 1 | \$0.00 | \$10.38 |
| EC3501 | COOLANT-TRP EL RED | 12 | \$0.00 | \$124.08 |
| 1982746PE | CYLINDER LINER SET, H=+0.25MM | 1 | \$0.00 | \$299.15 |
| 1603978PE | O-RING | 12 | \$0.00 | \$223.80 |
| D42-1003 | GASKET-CHARGE AIR PIPING | 1 | \$0.00 | \$4.79 |
| OIL | 10W/30 | 48 | \$0.00 | \$205.44 |

Operation 1 Total 22,314.94

An error has occurred while processing PictureBox 'pbLogo':
Invalid image data.
----- InnerException -----
Object is currently in use elsewhere.

REPAIR
IDFRO
Dealer C

Terms: Net

BILL To:

Date: 04/13/2022

Open Date:

W. O. #:

P.O. #:

Acct #: IDF2008

Page #: 6 of 8

Ordered By:

Written By:

Released By:

Department:

Account:

Phone:

| | | | |
|------------------------|-----------------------|----------------------|-------------------|
| Year: 2020 | Make: Kenworth | Serial #: | 1XK1DP9X9LJ389256 |
| Mileage: 345987 | Model: W990 | Eng Serial #: | Y200471 |

| | |
|---------------------|--|
| Operation: 2 | Complaint: ***POSSIBLE WARRANTY*** CHECK AND ADVISE PM SENSOR CODES |
| Note: | |

Correction:

SORT THROUGH FAULT CODES, CHECKED SOFTWARE LEVEL, FOUND IT IS BEHIND, TRYING TO ACCESS SOFTWARE CHANGES TO SEE WHAT SOFTWARE ADDRESSES. FIGURED OUT THE SOFTWARE, FOUND PCI IS 3 SOFTWARE NUMBERS BEHIND, FOUND NO FAULT CODES RELATED TO SOFTWARE, TEST DRIVE, NOTICED WHEN PULLING OUT THERE WAS BLACK SMOKE FROM THE STACK, SENT FOR P/A ON DPF AND HC DOSER MOUNTING PARTS. DUMPED THE FLUSH OUT OF THE COOLING SYSTEM AND RAN WATER THROUGH TILL WATER CAME OUT CLEAN, REPLACED THE COOLANT FILTER, FILLED COOLING SYSTEM WITH NEW ELC. PRESSURE WASHED OFF BOTH SIDES OF ENGINE. REMOVED PASSENGER STEP, STEP MOUNTING BRACKET, REMOVED DOC INLET CLAMP, REMOVED TEMP SENSORS, DPF DIFFERENTIAL PRESSURE TUBE, REMOVED DOC AND DPF, VERIFIED THAT DPF IS BREACHED. CLEANED UP GASKET SURFACES, INSTALLED NEW DPF WITH NEW GASKET AND CLAMP, CLEANED THE DOC, INSTALLED WITH NEW GASKET AND CLAMP, HOOKED UP DOC INLET WITH GASKET AND CLAMP, REPLACED THE PM SENSOR, ZIP TIED UP WIRING, RE-INSTALLED STEP BRACKET, REMOVED THE HC DOSER COOLANT LINES AND BLOCKED, CLEANED THE HC DOSER, WENT TO FLOW TEST THE HC DOSER, DAVIE KEPT COMING UP WITH COMMUNICATION ISSUE, T/S U1073 FOR HUMIDITY SENSOR COMMUNICATION, CHECKED THE BATTERY CABLES FOR CORRECT ROUTING AND TERMINAL CONNECTIONS- OK, CHECKED VOLTAGE TO THE HUMIDITY SENSOR, FOUND ONLY GETTING 2.13 VOLTS TO SENSOR, FOUND FUSE LOCATION G9 FOR ENGINE POWER 2 15 A FUSE, FOUND BLOWN, REPLACED FUSE AND CHECKED HUMIDITY SENSOR VOLTAGE, FOUND NOW GETTING BATTERY VOLTAGE, TRIED TO FLOW TEST AGAIN AND FOUND WOULD PERFORM TEST NOW, FLOW TESTED THE HC DOSER, FOUND FLOWS 8 FL OZ EACH TIME- OK, CLEANED UP THE PIPE AND INSTALLED NEW ISOLATER, GASKET AND BOTH BOLTS AND MOUNTED THE HC DOSER, TORQUED BOLTS, HOOKED UP COOLANT LINES TO DOSER, PULLED OUTSIDE AND LETTING WARM UP FOR REGEN. TOOK WARRANTY PARTS. STARTED UNIT IN REGEN.

Labor Amount

1,790.25

An error has occurred while processing PictureBox 'pbLogo':
Invalid Image data.
----- InnerException -----
Object is currently in use elsewhere.

REPAIR
IDFRO
Dealer C

Terms: Net

Date: 04/13/2022

Open Date:

W. O. #:

P.O. #:

Acct #: IDF2008

Page #: 7 of 8

Written By:

Released By: Brandi Zahn

Department:

Account:

Ordered By:

Phone:

Year: 2020
Mileage: 345987

Make: Kenworth
Model: W990

Serial #:
Eng Serial #:

1XK1DP9X9LJ389256
Y200471

| <u>Item</u> | <u>Description</u> | <u>Quantity</u> | <u>Price</u> | <u>Credit</u> | <u>Amount</u> |
|-------------------|------------------------------------|-----------------|--------------|---------------|---------------|
| 2274612PEX | DPF KIT, W/ CLAMPS, GASKETS, EPA17 | 1 | | | \$2,611.83 |
| 2131533PEXC | CORE DPF | 1 | | | \$772.50 |
| 1827320PE | GASKET | 1 | | | \$15.55 |
| LP34216 | CLAMP-V, 5 INCH SPHERICAL, | 1 | | | \$36.32 |
| 1816833PE | GASKET-INJECTO | 1 | | | \$14.44 |
| 1899870PE | ISOLATOR-THERMAL | 1 | | | \$3.74 |
| 2158132PE | FLANGE BOLT, M6 X 60 | 2 | | | \$27.16 |
| 2160125PRX | SENSOR, PARTICULATE | 1 | | | \$396.21 |
| 546155000 D | PARTICULATE SENSOR CORE | 1 | | | \$128.75 |
| 1976039PE | WASHER | 4 | | | \$18.36 |
| PARTS REVIEW | COMPLETE | 1 | | | \$0.00 |
| Operation 2 Total | | | | | 4,913.86 |

An error has occurred while processing PictureBox 'pbLogo':
Invalid Image data.

InnerException
Object is currently in use elsewhere.

REPAIR
IDFRC
Dealer C

Terms: Net:

Date: 04/13/2022

Open Date:

W. O. #:

P.O. #:

Acct #: IDF2008

Page #: 8 of 8

Written By:

Released By:

Department:

Account:

1XK1DP9X9LJ389256

Y200471

Parts:

Core Credit:

Freight:

Labor:

Sublet:

Towing:

Mileage:

Shop

Supplies:

Tax:

Environment

al Fee:

Coupon

Credit:

Return

Credit:

Total: \$29,932.55

WTNY

Repair Invoice

Terms and Conditions

The customer identified herein ("Customer") acknowledges that (s)he has inspected the repairs performed by Kenworth Sales Company ("Seller") on Customer's Equipment ("the Equipment") as detailed herein, accepts the same, and agrees to pay the total amount due. Customer agrees to pay a service charge of 1-3/4% per month (21% per annum) on all amounts remaining unpaid after the 10th of the month following receipt, with a minimum charge of \$15.00, together with a daily storage fee of \$30.00 for each piece of Equipment remaining with the Seller 30 days after 1) completion of authorized repairs or 2) cessation of repairs/service for any reason. Customer agrees to pay all collection costs including a reasonable attorney's fee, and hereby waives all claims or rights to claim exemptions under applicable state laws. Customer grants Seller an express Repairman's Lien on the Equipment for the value of the parts and any services provided, and warrants that no third party holds a superior lien on the Equipment except as disclosed by Customer. Any warranties on the product(s) sold hereby are those of the manufacturer. Any claim for warranty coverage resulting from the use of aftermarket, non-OEM parts will not be honored by the OEM. Warranty claims must be submitted within 30 days of discovery of defect. Seller disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of the merchandise or services hereunder. Claims for adjustments or credits must be made within ten (10) days of the date of this document and must be accompanied by a complete copy of this document. Claims concerning Seller's workmanship must be submitted within 90 days of the date of this document. Customer acknowledges that in the course of performing diagnostic and repair services detailed herein, Seller may have connected Customer's Equipment to Original Equipment Manufacturer ("OEM") approved electronic equipment, and that such tool may reset the operating parameters of the Equipment to OEM required settings. Customer accepts any and all risks that may occur in the event of a conflict between such original OEM settings and any post-production modifications made by Customer to the Equipment. Customer releases Seller from liability for any damages to the Equipment or its contents due to loss, theft, destruction, or causes other than gross negligence, and further releases Seller from liability for down time, damage to cargo, or other damage related to delays in completing the requested repairs and/or delay in obtaining parts. Interpretation and enforcement of this document shall be governed by the laws of the State in which it is issued. The purchase and use of non-OEM (original equipment manufacturer) aftermarket parts may void OEM warranty coverage on your equipment, including warranties of fitness for particular purpose and use.

**CUSTOMER
SIGNATURE** ➤