[redacted]

Invoice No.
000016035

Order Date 10/20/22 11:45 am
Closed/OnAcct

[redacted]

00 Freightliner FL70 White
ODO in:52149 out:52149
Lic: YBD7767/MN Cyl 3126 Eng
Vin: 1FV6HJBA1YHF06696 06/99
Eq:
Last in 5/7/2026

Job01 Engine

Labor: 0.00 hrs@$95.00/hr=$0.00

Engine dropped a valve on #3 cylinder.
Pull engine and strip to bare block.
Sent block to Arnolds, Installed sleeve in #3 and bored back to standard.
Surfaced deck, cleaned.
Overhaul with all new pistons, rings and bearings.
Installed new cam bearings.
Install reman connecting rod in #3.
Installed new injector in 3 and new o rings on all others.
Install reman cylinder head.
Install new engine oil pump.
Wash out radiator and charge air cooler, install new rad hoses.
Fill with new oil and coolant
Run engine and test drive.

HBRHCT133-3724VS	Reman Head-S	1.0 @	[redacted]	1704.15	
2184109	New Injector-S	1.0 @		450.00	
321336	Inj O Ring Kit-S	5.0 @		72.45	
312601-017	OH Kit-S	1.0 @		1833.78	
341305	Oil Pump-S	1.0 @		290.00	
361605	Repair Sleeve-S	1.0 @		19.69	
351501	Wrist Pin Brg-S	2.0 @		12.44	
OR2741	Connecting Rod-S	1.0 @		167.80	
2W7213	Cam Bearing-S	6.0 @		124.56	
2165586	Cam Bearing-S	1.0 @		24.77	
1791MP	Oil Filter-N	1.0 @		9.72	
15300027	2 Pin Female Conn 280S-N	2.0 @		6.66	
X007784	4" Exhaust Clamp-N	2.0 @		21.02	
05-16569-02	Radiator Hose-S	1.0 @		24.92	
05-16570-002	Radiator Hose-S	1.0 @		36.49	
RAY 010028-006	Exhaust V Clamp-S	1.0 @		11.85	
3626	Fuel Filter-N	1.0 @		9.83	
15/40	15/40 Motor Oil Gal.-N	8.0 @		107.52	
ELC EC-1-50/50	Red Ext life coolant-N	7.0 @		61.11	4988.76

Job02 Resurface Flywheel

Sublet: $82.97

Resurface flywheel

-------->---->---->---Continued on the next page--->---->----->------>

[redacted]

Invoice No.
000016035

Order Date 10/20/22 11:45 am
Closed/OnAcct

Job02 Resurface Flywheel

Job03 Machine Block

Sublet: $788.61

Surface deck	273.82
Install sleeve	142.42
Hone	180.00
Clean	139.98
Misc	52.39

Job04 Clutch

Labor: 0.00 hrs@$95.00/hr=$0.00

Had flywheel surfaced.
Installed new clutch, pilot bearing, clutch brake, and shift tower gasket.

MU-129055-DSCB	Clutch-S	1.0 @	[redacted]	398.55	
DDE A0099817225	Pilot Bearing-S	1.0 @		33.03	
HB200	Clutch Brake-S	1.0 @		22.77	
4305294	Shift Tower Gsk-N	1.0 @		7.12	461.47

Job05 Block Heater

Labor: 0.00 hrs@$95.00/hr=$0.00

Install new block heater.

3500015	Block Heater-S	1.0 @	84.95 =$	84.95	84.95

Recommendations: *30K Service*

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

------->---->---->---Continued on the next page--->---->----->------>

[redacted]

Invoice No.
000016220

Page 1
Order Date 03/10/23 08:04 am
Closed/OnAcct

[redacted]

00 Freightliner FL70 White
ODO in:56248 out:56248
Lic: YBD7767/MN Cyl 3126 Eng
Vin: 1FV6HJBA1YHF06696 06/99
Eq:
Last in 5/7/2026

Job01 Huei HPOP

Labor: 0.00 hrs@$95.00/hr=$0.00

Engine will not maintain rpm, stalls out, starts after it cools down.
Found the high pressure oil pump is bad.
Install new pump.

10R7053	HPOP Pump-S	1.0 @	1424.26 =$	1424.26	1424.26

Job02 Timing Sensor

Labor: 0.00 hrs@$95.00/hr=$0.00

Engine has extended crank time.
Replace timing sensor assembly.

245-4630	Sensor Grp-S	1.0 @	[redacted]		336.07

Recommendations: *30K Service*

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

[redacted]

1 03/20/23 1881.35 On Acct

Cost Summary

Labor	
Parts	[redacted]
Tax	
Total	$1881.35

Thank you for choosing Mike's Diesel Repair

[redacted]

Invoice No.
000015130

Order Date 11/04/20 10:32 am
Closed/OnAcct

Mike`s Diesel Repair
1932 330th St
Ghent MN 56239

Home Phone: 507-428-3486
Cell Phone: 507-530-4285

00 Freightliner FL70 White
ODO in:46827 out:50247
Lic: YBD7767/MN Cyl 3126 Eng
Vin: 1FV6HJBA1YHF06696 06/99
Eq:
Last in 5/7/2026

Quotes
1 11/17/20 08:27am 736.00
Mike`s Diesel Re in person.

Job01 ECM

Labor: 0.00 hrs@$80.00/hr=$0.00

Engine misses and dies, check eng light comes on.
Has codes 1-11 2-11 3-11 4-11 5-11 6-11.
These are open codes to injectors.
The ecm is bad
Install used ecm and reset configuration.

509-14756	Used ECM-S	1.0 @	[redacted]	736.00

Recommendations: *30K Service*

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

[redacted]

1 11/17/20 786.60 On Acct

Cost Summary

Labor	[redacted]
Parts	
Tax	
Total	$786.60

Thank you for choosing Mike's Diesel Repair

[redacted]

Invoice No.
000014932

Page 1
Order Date 05/04/20 01:35 pm
Closed/OnAcct

[redacted]

00 Freightliner FL70 White
ODO In:46827 out:46827
Lic: YBD7767/MN Cyl 3126 Eng
Vin: 1FV6HJBA1YHF06696 06/99
Eq:
Last in 5/7/2026

Job01 Water Pump — Labor: 0.00 hrs@$80.00/hr=$0.00

Water pump is leaking.
Install reman water pump.

20R0586	Water Pump-S	1.0 @	[redacted]		
3AH00015SP	Radiator Drain Plug-S	1.0 @			255.72

Job02 Dot Inspection — Labor: 0.00 hrs@$80.00/hr=$0.00

Dot inspection

DOT DECAL	Dot Decal-N	1.0 @	2.50 =$	2.50	2.50

Recommendations: *30K Service*

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

[redacted]

1 06/12/20 277.26 On Acct

Cost Summary

Labor	[redacted]
Parts	
Tax	
Total	$277.26

Thank you for choosing Mike's Diesel Repair