[redacted]

Service Writer : KH

Vehicle : **2016 Kenworth T680 12.9 L 787 CID L6 Paccar MX Diesel**
Tag/State : P981714/IL
VIN : 1XKYDP9X7GJ472477
Color : White
Fleet #/Driver : 88 /
Created : 10/30/2023 9:14:16 AM CDT
Invoiced : 11/15/2023 11:15:36 AM CST

Labor/Notes

Qty	Technician	Description
2.5	MO	LABOR
	REPLACED RELAY FOR ECM POWER. UPDATED HVAC CONTROLLER.	
1	MO	DIAGNOSTIC LABOR
6	MO	LABOR
	CHECKED COMMUNICATION WIRING FOR INSTRUMENT CLUSTER. FOUND BAD INSTRUMENT CLUSTER. REPLACED AND REPROGRAMMED INSTRUMENT CLUSTER.	

Parts

Qty	Code	Description	Conditio
1		RELAY-SPST	
1		GAUGE-CLUSTER ENG	

Labor .....
Parts .....
Shop Supplies .....
Sales Tax Tax Exe

Total $4,037.12

Check #4233: $4,03

[redacted]

[redacted]

Vehicle	**: 2016 Kenworth T680 12.9 L 787 CID L6 Paccar MX Diesel**	Tag/State	: P981714/IL
VIN	: 1XKYDP9X7GJ472477	Color	: White
Fleet #/Driver	: 88 /	Odometer In	: 532672
Created	: 6/12/2024 4:08:54 PM CDT	Odometer Out	: 532672
Invoiced	: 7/3/2024 3:54:51 PM CDT		

Labor/Notes

Qty	Technician	Description
60	BU	LABOR

CHECK ENGINE NOISE. FOUND DROPPED INTAKE VALVE ON #5. REMOVE ALL LINES AND BRACKETS. PULLED HEAD. DAMAGED CYLINDERS. INSTALL OVERHAUL KIT. NEW CYLINDER HEAD. REPLACE #5 INJECTOR AND INTAKE BRACKET ARM. FILL WITH OIL AND COOLANT. ROAD TEST. REPLACE #2 FUEL LINE WAS LEAKING.

Parts

Qty	Code	Description	Condition
1		OVERHAUL KIT	
6		CYLINDER LINER	
1		CYLINDER HEAD MX	
1		INJECTOR MX-13	
1		BOLT FLANGE M8X55	
1		ROCKER ARM-INTAKE	
1		GASKET-EXHAUST	
1		GASKET	
1		FUEL INJECTION PIPE	
12		CHEVRON DELO ELC RED 50/50	
12		MOBIL DELVAC HDEO SAE 15W-40	
1		L0034-094 NO. 105 (MTR/ASM) TUBE GREASE	

Labor	.....	
Parts	.....	
Shop Supplies	.....	
Sales Tax	Tax Exem	
Total		**$27,243.42**

[redacted]

Vehicle : **2016 Kenworth T680 12.9 L 787 CID L6 Paccar MX Diesel**
VIN : 1XKYDP9X7GJ472477
Fleet #/Driver : 88 /
Created : 8/13/2026 10:05:25 AM CDT
Invoiced : 8/31/2026 10:13:27 AM CDT

Service Writer : LH
Tag/State : P981714/IL
Color : White
Odometer In : 89344
Odometer Out : 89344

Labor/Notes

Technician	Description
MO	SERVICE CALL
MO	LABOR

CUSTOMER SAID TRUCK WOULDN'T START. WENT TO CUSTOMER'S FARM AND TRIED TO GET STARTED AND WAS UNABLE TO GET STARTED. HAD TRUCK TOWED TO SHOP. TRUCK HAD NO COMMUNICATION TO SCANNER. TOOK DASH APART AND STARTED TO TEST COMMUNICATION WIRES TO ABS AND CECU MODULES. CHECKED COMMUNICATION WIRES TO INSTRUMENT CLUSTER AND VGT ACTUATOR ON ENGINE. SOMETIMES TRUCK WOULD START AND RUN AND THEN IT WOULD DIE. INSTALLED A TEST ECM ON TRUCK AND IT RAN AS IT SHOULD. REPLACED ECM AND TRUCK RAN AS IT SHOULD.

[redacted]

Parts

Qty	Code	Description	Condition
1		ENGINE CONTROL MODULE, MX-13 EPA 10/13	

Sublet/Misc.

Qty	Code/Tech*	Description	Condition
1		TOWING SERVICE	

[redacted]

Labor .....
Parts .....
Sublet/Misc. .....
Shop Supplies .....
Sales Tax Tax Exempt #

Total **$6,151.08**

Check #5748: $6,151.08 **PAYMENT** **$6,151.08**

[redacted]

Vehicle : **2016 Kenworth T680 12.9 L 787 CID L6 Paccar MX Diesel**
VIN : 1XKYDP9X7GJ472477
Fleet #/Driver : 88 /
Created : 8/20/2024 8:19:01 AM CDT
Invoiced : 8/23/2024 3:26:05 PM CDT

Service Writer : KH
Tag/State : P981714/IL
Color : White

Labor/Notes

Qty	Technician	Description
1	BU	TURN FLYWHEEL
16	BU	LABOR

REMOVED TRANSMISSION, INSTALLED NEW CLUTCH ,PILOT BEARING AND CLUTCH BRAKE.
REMOVED FLYWHEEL AND HAD RESURFACED.
FOUND BAD CARRIER BEARING AND YOKE OUT OF TIME
REMOVED YOKE, INSTALLED NEW CARRIER BEARING AND RETIMED YOKE.
ALSO REPAIRED MULTIPLE AIR LEAKS.

Parts

Qty	Code	Description	Condition
1		CLUT SELFADJ 15.5,1700 TRQ,DAMP 7-S	
2		BLOT-FLANGE M8X30	
1		18" WHIP HOSE	
6		HOSE	
2		FITTING	
2		1/4 M SAE X 1/8 MALE PIPE STR	
2		1/8 INCH BRASS COUPLING	
1		FITTING BRANCH	
1		HT PILOT BEARING + SR 2.833 X	
1		2 TORQUE LIMITING BRAKE	
1		CARRIER BRG 2106611X 5003323	

Labor .....
Parts .....
Shop Supplies .....
Sales Tax Tax Exempt # O

Total **$3,647.25**