

roger.kisner
rkisner@purplewave.com

21952 2 G 1 W S 5 5 R 9 7 9 3 1 8 3 0 0 CITY OF HOISINGTON 01/09/12
2007 CHEVROLET IMPALA POL WHITE P O BOX 60 11:45
HOISINGTON KS 67544 09:58
90265 90265 02/27/07 67718 01/10/12
9949
H: (620) 653-4995 W: (620) 653-4995 DARYL

(1) NO HEAT FROM HEATER AT ENGINE IDLE
PURGE AIR FROM COOLING SYSTEM Labor T07 6 39.00
12377963B (DEXCOOL) 2 9.76
(Tech:07) A Total Repair (Customer) 48.76

(2) HEADLIGHTS GO BRIGHT WHEN TURNING
DIAGNOSE PROBLEM Labor T07 14 91.00
REPLACE MULTI-FUNCTION SWITCH 15289426 (SWITCH) 1 80.28
(Tech:07) A Total Repair (Customer) 171.28

Cash: 225.04

.00	.00 Labor	130.00
.00	.00 Parts	90.04
.00	.00 Sublet	.00
.00	.00 Environmenta	5.00
.00	.00 Oil/Grease	.00
.00	.00 Sub Total	225.04
.00	.00 Tax	.00
.00	.00 Total (Cash)	225.04

22019	2 G 1 W S 5 5 R 9 7 9 3 1 8 3 0 0	CITY OF HOISINGTON	01/17/12
2007	CHEVROLET IMPALA POL WHITE	P O BOX 60	09:06
		HOISINGTON KS 67544	10:02
90549	90549 02/27/07 67718		01/25/12
			9949
	H: (620) 653-4995 W: (620) 653-4995		DARYL

(1) SES LIGHT IS ON--REDUCED ENGINE POWER			
DIAGNOSE PROBLEM	Labor	T07 42	273.00
REPLACE GAS PEDAL ASSEMBLY	12621649 (SENSOR)	1	23.44
REPLACE THROTTLE BODY	19287400 (CLEANER)	1	5.98
REPLACE OIL PRESSURE SENSOR	25830023 (PEDAL)	1	110.24
REPAIR ENGINE WIRING NEAR STARTER	STP130HC (TERMINAL)	1	1.42
TEST & RECHARGE BATTERY	12609500 (BD, THRO)	1	245.14
(Tech:07) A	Total Repair (Customer)		659.22

Cash:	664.22
-------	--------

.00	.00 Labor	273.00
.00	.00 Parts	386.22
.00	.00 Sublet	.00
.00	.00 Environmenta	5.00
.00	.00 Oil/Grease	.00
.00	.00 Sub Total	664.22
.00	.00 Tax	.00
.00	.00 Total (Cash)	664.22

22168	2 G 1 W S 5 5 R 9 7 9 3 1 8 3 0 0	CITY OF HOISINGTON	02/02/12
2007	CHEVROLET IMPALA POL WHITE	P O BOX 60	09:46
		HOISINGTON KS 67544	13:29
91052	91052 02/27/07 67718		02/07/12
			9949
	H: (620) 653-4995 W: (620) 653-4995		DARYL

(1) ENGINE IDLES TOO FAST IN PARK			
DIAGNOSE PROBLEM	Labor	T07 23	149.50
REPLACE & PROGRAM PCM	19210738 (PCM)	1	241.77
(Tech:07) A	Total Repair (Customer)		391.27

Cash:	396.27
-------	--------

.00	.00 Labor	149.50
.00	.00 Parts	241.77
.00	.00 Sublet	.00
.00	.00 Environmenta	5.00
.00	.00 Oil/Grease	.00
.00	.00 Sub Total	396.27
.00	.00 Tax	.00
.00	.00 Total (Cash)	396.27

23073 2 G 1 W S 5 5 R 9 7 9 3 1 8 3 0 0 CITY OF HOISINGTON 05/16/12

2007 CHEVROLET IMPALA POL WHITE P O BOX 60 07:46
HOISINGTON KS 67544 15:43
97138 97138 02/27/07 67718 05/31/12

H: (620) 653-4995 W: (620) 653-4995 9949
DARYL

(1) NO REVERSE--FLUID IS BURNT
REPLACE TRANSMISSION WITH S.R.T.A. Labor T03 100 650.00
3YR./100,000 MILE WARRANTY 17803894 (REMAN TRANSAXL) 1 1937.50
REPLACE RH INNER AXLE BOOT 19259374 (BOOT KIT) 1 37.64
91-2502 (CLAMP) 1 4.49
(Tech:03) A Total Repair (Customer)..... 2629.63

Cash: 2634.63

Scan & Email to Roger

.00	.00 Labor	650.00
.00	.00 Parts	1979.63
.00	.00 Sublet	.00
.00	.00 Environmenta	5.00
.00	.00 Oil/Grease	.00
.00	.00 Sub Total	2634.63
.00	.00 Tax	.00
.00	.00 Total (Cash)	2634.63

23478 2 G 1 W S 5 5 R 9 7 9 3 1 8 3 0 0 CITY OF HOISINGTON 07/06/12

2007 CHEVROLET IMPALA POL WHITE P O BOX 60 15:32
HOISINGTON KS 67544 11:31
99468 99468 02/27/07 67718 07/10/12

H: (620) 653-4995 W: (620) 653-4995 9949
DARYL

(1) ENGINE OVERHEATS			
DIAGNOSE PROBLEM	Labor	T02 29	188.50
PRESSURE TEST COOLING SYSTEM	15140592 (RADIATOR)	1	520.51
REPLACE RADIATOR	12377963B (DEXCOOL)	8	39.04
(Tech:02) A	Total Repair (Customer)		748.05

Cash: 753.05

.00	.00 Labor	188.50
.00	.00 Parts	559.55
.00	.00 Sublet	.00
.00	.00 Environmenta	5.00
.00	.00 Oil/Grease	.00
.00	.00 Sub Total	753.05
.00	.00 Tax	.00
.00	.00 Total (Cash)	753.05

24183	2 G 1 W S 5 5 R 9 7 9 3 1 8 3 0 0	CITY OF HOISINGTON	09/26/12
2007	CHEVROLET IMPALA POL WHITE	P O BOX 60	11:10
		HOISINGTON KS 67544	11:11
103587	103587 02/27/07 67718		10/01/12
			9949
	H: (620) 653-4995 W: (620) 653-4995		DARYL

(1) SES LIGHT IS ON				
ABS LIGHT	Labor	SES	T02 55	357.50
TIRE PRESSURE LIGHT	88964168	(*HUB)	2	552.04
DIAGNOSE PROBLEM	88910539	(END KIT)	2	145.96
REPLACED BOTH WHEEL HUBS	13586335	(SENSOR)	1	72.44
REPLACED BOTH OUTER TIE ROD ENDS	88988755	(CONNECTOR)	1	28.02
REPLACED TIRE PRESSURE SENSOR	PW20R	(PRIMARY WIRE)	1	.50
REPLACED EBCM CONNECTOR	638551-1	(TERMINAL)	6	15.48
	19206781	(TERMINAL)	2	5.26
(Tech:02) A	Total Repair	(Customer)		1177.20

Cash:	1182.20
-------	---------

.00	.00 Labor	357.50
.00	.00 Parts	819.70
.00	.00 Sublet	.00
.00	.00 Environmenta	5.00
.00	.00 Oil/Grease	.00
.00	.00 Sub Total	1182.20
.00	.00 Tax	.00
.00	.00 Total (Cash)	1182.20