

SOR SEE OTHER REPAIR

625 I 0.00

193547 SEE NEXT LINE

(N/C)

G** REPACK FRT BEARINGS

50 PACKED BEARINGS

62522 CTB 2.60

2 15651660 (S) SEAL

4.00

280.28 280.28

4.00 8.00

193547 PACKED BEARINGS DUE TO LOOSNESS 2.6 HRS. TECH625-22

H** REPLACE IDLER ARMS, CENTERLINK AND GEARBOX

50 REPLACED IDLER ARMS, CENTERLINK, FRONT/REAR

SHOCKS & SWAY BAR LINKS

62522 CTB 4.00

1 88-278123 S GEAR

2 190154 IDLER ARM

1 DS-1427 CENTER LINK

1 265-1318 LINK KIT

2 94072 SHOCK

2 94129 SHOCK

431.20 431.20

360.08 360.08 360.08

41.89 41.89 83.78

71.04 71.04 71.04

30.54 30.54 30.54

36.04 36.04 72.08

36.04 36.04 72.08

193547 REPLACED IDLER ARMS AND CENTERLINK (LOOSE). REPLACED FRONT
AND REAR SHOCKS DUE TO ROTTED BUSHINGS AND WEAFNESS. REPLACED SWAYBAR
LINKS DUE TO ROTTED BUSHINGS. 4.0 HRS. TECH625-22

I** GM FRONT END ALIGNMENT \$65.09

FEA GM FRONT END ALIGNMENT \$65.09

62533 CTC 0.90

193547 GM FRONT END ALIGNMENT 0.9 HRS TECH625-33

65.09 65.09

CUSTOMER PAY SHOP MATERIAL CHARGES FOR REPAIR ORDER

30.00

*** VISIT OUR WEBSITE - WWW.EDBOZARTH.COM ***

Add