

Invoice Date

04/27/2015

1XP5D49XX6D633252 V.I.N

79116352 Engine Serial 140695

Vehicle ID # 2006 PETERBILT Cust Unit # 103 379

				2000 1 2 12110		0.0	
Date In	Date In Service	Mileage	Date Out	Bill Type	Terms	Writer	Reviewer
04/22/2015	10/19/2005	1,019,559	04/22/2015	SR	N10TH		23000

Job#2 018001004235

RH SIDE STEER AXLE WHEEL SEAL LEAKING.

SR

Condition Cause

Correction

RH SIDE STEER AXLE WHEEL SEAL LEAKING. OK TO REPLACE IF NEEDED. OK TO DO BRAKES IF NEEDED.

BOTH STEER AXLE WHEEL SEALS ARE LEAKING. DISASSEMBLED BOTH HUBS AND CLEANED ALL. CHECKED AND ALL BEARINGS AND RACES ARE GOOD. INSTALLED NEW SEAL IN RIGHT HUB AND REASSEMBLED RIGHT SIDE HUB. TORQUED HUB NUTS TO SPEC. INSTALLED HUB CAB WITH NEW GASKET AND FILLED HUB.

Qty	Item	Description		Price Each	Extended			
Q.I.J		LABOR TO PERFORM REPAI	RS		253.97			
2	112P/FE75W90D	LUBRICANT-SPICER FE 75W		7.23	14.46			
2	112P/35058		SEAL-OIL SCOTSEAL PLUS XL FRON					
2	112P/453869-8CHR	GASKET-HUB						
4	112P/07480MMM	DISC-CONDITIONING SURFA	CE ROLO	1.10	1.10			
2	112P/82606PTX	CLEANER-BRK PTS 12/CS	.0211020	4.89	9.78			
2		EMERY CLO		1.10	2.20			
2	112I/EMERY		Total Other 0.0	0 Job#2 Total	351.31			
	Total Labor 253.97	Total Parts 97.34	Total Other 0.0	o Joban Total				

Job#3 CKSTRBR

CHECK STEERING AXLE BRAKES

SR

Condition


CHECK STEERING AXLE BRAKES REPLACE IF NEEDED.

Cause

Correction

REPLOACED WHILE DOING THE WHEEL SEALS ON OPERATION 2 NO LABOR ON THIS OPERATION AS WE HAD THE SHOES OFF WHEN DOING THE SEAL

Qty	Item	Description	Price Each	Extended
Qty		KIT-REMAN BRAKE 15X4 STD20K	36.95	73.90
2	112P/RK1443ESTD20		120.43	240.86
2	112P/CM107507	DRUM-BRAKE 15X4 FRONT PACCAR S	51.00	-102.00
-2	112P/RK1443ESTD20-CORE	KIT-REMAN BRAKE 15X4 STD20K		
2	112P/RK1443ESTD20-CORE	KIT-REMAN BRAKE 15X4 STD20K	51.00	102.00
2	COUP	COUPON 0423-7A483	6.00	-12.00
-2		COUPC:N 0423-7A483	5.00	-10.00
-2	COUP	00.0	1-1-#2 T-1-1	292.76
	Total Labor 0.00	Total Paris 314.76 Total Other -22.0	O Job#3 Total	292.70



Invoice Date

04/27/2015

K2151

1XP5D49XX6D633252 V.I.N

79116352 Engine Serial Vehicle ID # 140695 2006 PETERBILT

103 Cust Unit# 379

	2000 1 1110	·-·		
Date Out	Bill Type	Terms	Writer	Reviewer
04/22/2015	SR	N10TH		23000

04/22/2015 Job#1 SERVICE

Date In

SERVICE SPECIAL MOBIL

Mileage

1,019,559

SR

Condition

SERVICE SPECIAL MOBIL

Cause Correction

PERFORM SERVICE SPECIAL

CHANGED OIL AND FILTERS. LUBED CHASSIS

CHECK ALL FLUID LEVELS. OK ANTIFREEZE PROTECTED TO -40


Date In Service

10/19/2005

DCA OK

PERFORMED FULL SERVICE SPECIAL. ALL FLUIDS FULL AND EVERYTHING ELSE LOOKS GOOD. COOLANT AT -60 FREEZE POINT AND 1600PPM.

Qty	Item	Description	Price Each	Extended
		LABOR TO PERFORM REPAIRS		87.20
11	112P/105816EXX	OIL-DELVAC 1300 SUP 15W-40 [BU	10.65	117.15
4	112P/FF2200FLG	FILTER-FUEL	15.57	15.57
1	112P/LF9080FLG	FILTER-OIL	31.75	31.75
1	112P/FF2203FLG	FILTER-FUEL	15.59	15.59
1	112P/550027637	GADUS S3 V220C 2-DRUM (180 KG)	3.17	9.51
3	later and the second	2.00	Job#1 Total	276.77
	Total Labor 87.20	Total Parts 189.57 Total Other 0.00	J00#1 10tal	2,0



Invoice Date

04/27/2015

X2151

1XP5D49XX6D633252 V.I.N

79116352 Engine Serial

140695 Vehicle ID #

Cust Unit # 379

103

2006 PETERBILT

2000 LILIND		0.0		_
Bill Type	Terms	Writer	Reviewer	
SR	N10TH		23000	Ī

04/22/2015 Job#4 AIR LEAK

Date In

AIR LEAK

Date In Service

10/19/2005

SR

Condition

AIR LEAK WILL LEAK DOWN TO ZERO OVER NIGHT, ONLY SPEND ONE HOUR ON IT,

Mileage

1,019,559

Cause

Correction

FOUND PURGE VALVE LEAKING ON AIR DRIER. REMOVED AND REPLACED PURGE VALVE.

Qty	Item		Descrip n				Price Each	Extended
Qty	Helli		LABOR TO P	ERFORM REP	PAIRS			117.72
1	112P/K022105BXW			KIT-PURGE VALVE AD-IS/AD-IP			98.65	98.65
'			Total Parts	98.65	Total Other	0.00	Job#4 Total	216.37
	Total Labor	117.72	Total Parts	50.03	Total Other			

Date Out

04/22/2015

DISCLAIMER OF WARRANTIES

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OR MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND PETERBILT OF DES MOINES NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.

Please remit to: Sioux City Truck Sales, Inc. PO Box 386 Sioux City, IA 51102-0386


Parts:	700.32
Labor:	458.89
Sublet :	0.00
Other Charges :	-22.00
Misc Supplies :	29.83
EPA Charge :	5.74
Sales Tax :	71.69

1,244.47 Total:

Customer Signature

X

700 22



Invoice Date

03/23/2015

V.I.N

1XP5D49XX6D633252

Engine Serial 79116352 140695 Vehicle ID #

Cust Unit# 103

2006 PETERBILT

379

Date In	Date In Service	Mileage	Date Out	Bill Type	Terms	Writer	Reviewer
03/19/2015	10/19/2005	1,010,181	03/19/2015	SR	N10TH	_	23000

Job#1 CKENGMISS

CHECK FOR ENGINE MISS

SR

Condition

CHECK FOR ENGINE MISS WHEN LUGGING AROUND 1200RPM AND ON TOP END OF RPM. UNIT WILL SHAKE, OVERHEAD, AIR TO AIR, CAMS HAVE BEEN CHECKED ALREADY.

Cause

Correction

TOLD TO REPLACE FUEL SHUTOFF VALVE. GOT NEW SHUT OFF VALVE AND REPLACED IT. CHECKED FOR AIR IN THE SUPPLY NONE. WENT INTO QSOL FOUND FUEL SPECS. DID CHECK FOR AIR IN FUEL FILTER MODULE NONE FOUND. RAN ENGINE CHECKED FUEL PREDSURE IN SPECIATIDLE AND HIGH IDLE OUT OF SPEC 260 PSI SHOULD BE 275-325 PSI. CHECKED 250 AND 320 FUEL PRESSURE REGULATORS LOOKED OK BUT REPLACED THEM STILL OUT OF SPEC ON HIGH IDLE REPLACED GEAR PUMP. TOOK FUEL LINE OFF AND GEAR PUMP PUT NEW PUMP ON. RAN ENGINE HIGH IDLE FUEL PRESSUE E IN SPECIGOT 290 PSI. TURNED CORE IN CLEANED OFF ENGINE WITH BRAKE CLEAN. RAN ENGINE AGAIN NO LEAKS

Qty	Item	Description			Price Each	Extended
		LABO TO PERFORM REPAIRS	3			583.05
1	112P/4024808CUM	KIT, FL _ SOLENOID			58.33	58.33
1	112P/129839CUM	COVE HUTOFF VALVE		2.75	2.75	
1	112P/AT010	FUSE-: LUG IN (5EA=1BOX)			0.92	0.92
1	112P/4954474CUM	GASK: T-SUPPORT			13.22	13.22
1	112P/4935092CUM	PUMF UELTRANSFER			322.36	322.36
1	112P/3348322CUM	VALVE-PRESSURE REGULATOR	R		96.51	96.51
1	112P/4009956CUM	REGUINTOR-VALVE PRESSUR	E		98.09	98.09
1	112P/4089163RXCUM	PUM AR FUEL KIT			472.84	472.84
1	112P/82606PTX	CLEABRK PTS 12/CS			4.89	4.89
-1	112P/4089163RXCUM-CORE	PUM: \R FUEL IT			262.50	-262.50
1	112P/4089163RXCUM-CORE	PUM: HAR FUEL KIT			262.50	262.50
	Total Labor 583.05	Total 1 1,009.91	Total Other	0.00	Job#1 Total	1,652.96

Job#3 MISCREP

MISC. REP.

SR

Condition

Cause

REPLACE BROKEN TURN BUCKLE ON THE GRILL.

Correction


REPLACED TWO BROKEN TURN

LES VALLE NEW, GOT THE TURN BUCKLES. FROM A TECH IN THE SHOP

Qty	Item		Desci					Price Each	Extended
			LAP -) PERF	1 REPAIRS				54.50
2	112P/HWC02	2116	COLL	HUCK 3/16	6X0.270"-0.280"			0.18	0.36
2	112P/HWC01	842	PIN-H	KBOLT C9	BLT TRUSS 3/16X			1.19	2.38
	Total Labor	54.50	Total	2.7	Total (Other	0.00	Job#3 Total	57.24

Page 1 of 2

3767509



S. VICE INVOICE

Invoice Date

03/23/2015

K2151

1XP5D49XX6D633252

Engine Serial 79116352

140695 Vehicle ID #

Cust Unit # 103 379

2006 PETERBILT

Date In	Date In Service	.:ileage	Date Out	Bill Type	Terms	Writer	Reviewer
3/19/2015	10/19/2005	010,181	03/19/2015	SR	N10TH		23000
4 ADJ CLUTCH	ADJUST C.	HAND J.	TEM INSPECTION.				SR

Condition Cause

03 Job#4

ADJUST CLUTCH AND SYSTEM IN

CTION.

Correction

ADJUSTED, THE CROSS SHAFT THE CLUTCH IS REPLACED.

DIBUSEUR IS ARE WORN, WILL NEED NEW CROSS SHAFT AND BUSHING WHEN

	1112 02							2: 5 !	C. deaded
Qt	y Item		Desc					Price Each	Extended
	y non		LAE	PERI	.1 RE	PAIRS			109.00
	Total Labor	109.00	Total		CO	Total Other	0.00	Job#4 Total	109.00
	Total Labor				-				

Job#5 SCOOLANT LEAK

COOLANT.

SR

Condition

COOLANT LEAK ON RIGHT SIDE P

WE.

Cause Correction

DRAINED COOLANT, REMOVED NEW FITTING IN PUT HOSE BAC

IN VALVE BACK SIDE OF COOLANT INLET. RERMOVED FITTING PUT 3 Mer 25 ANT BACK IN RAN ENGINE COOLANT STILL FULL. CLEANED FLOOR . U. -

_	Ohi	Item		Desc					Price Each	Extended
Ш	Qty	nem				A REPAIRS				218.00
				LAB	PEra LL 90#	:PT TO#8F			24.41	24.41
	1	112P/VL2443		VALV	LL 90"	.1110401		0.00	Job#5 Total	242.41
		Total Labor	218.00	Tota!		1	Total Other	0.00	JOD#3 Total	

DISCLAIME:

ANY WARRANTIES ON THE PRODUCTS SOLD HERE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WA IMPLIED WARRANTY OR MERCHANTABILITY OR FI DES MOINES NEITHER ASSUMES NOR AUTHORIZE IN CONNECTION WITH THE SALE OF SAID PRODUCT WE HEREBY CERTIFY THAT THESE GOODS WA REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF 7 AND OF REGULATIONS AND ORDERS OF THE UNDER SECTION 14 THEREOF.

Please remit to: Sioux City Truck Sales, Inc.

..ARK -S ...E Th

100

)T1::

1. 120

47 LA

: 0

MADE BY MANUFACTURER, IF ANY. THE EXPRESS OR IMPLIED, INCLUDING ANY RTICULAR PURPOSE, AND PETERBILT OF RSON TO ASSUME FOR IT ANY LIABILITY

N COMPLIANCE WITH ALL APPLICABLE STANDARDS ACT OF 1938, AS AMENDED TR WAGE AND HOUR DIVISION ISSUED

oux City, IA 51102-0386

1,097.06 Parts: 964.55 Labor: 0.00 Sublet: 0.00 Other Charges: 62.70 Misc Supplies: 10.00 EPA Charge : 128.06 Sales Tax:


2,262.37 Total:

Customer Signature

Х

Page 2 of 2

3767509



Invoice Date

07/06/2011

K2151

V.I.N

1XP5D49XX6D633252

Engine Serial 79116352 Vehicle ID # 140695 Vehicle ID # 2006 PETERBILT

Cust Unit #

103 379

Out	Bill Type	Terms	Writer	Reviewer
			A STATE OF THE PARTY OF THE PAR	
2011	SR	N10TH		2339
	2011	2011 SR	2011 SR N10TH	2011 SR N10TH

Job#1 SWAP

SWAP REAR ENDS GEAR RATIO

SR


Condition

SWAP REAR ENDS

Cause Correction

TOOK OUT DRIVE SHAFTS, AND REAR IN'S, CLEANED BOTH AXLE HOUSINGS WITH BRAKE CLEAN SWAPPED OUT BOTH REAR ENDS WITH NEW YOKES, FRONT REAR SERIAL # HNO3672666 AND REAR HN03555676. FILLED WITH NEW OIL AND STRAP KITS, GREASED DRIVE SHAFT, UPDATED GEAR RATIOS IN ECM TEST DROVE

Qty	Item	Description	Price Each	Extended
		LABOR TO PERFORM REPAIRS		807.50
1	112P/682969ETN	CARRIER-SERVICE DSP40, 3	2,592.97	2,592.97
1	112P/676033ETN	CARRIER-411 RSP40 336	1,704.49	1,704.49
4	112P/03-01568	GASKET-AXLE SHAFT	4.42	17.68
2	112P/82194PTX	GASKET MAKER-ULTRA GRY 3.	5.55	11.10
4	1121/13118	CUT-OFF WHEEL	1.46	5.84
1	1121/92408	5/8-11 X 2 GADE 8 C/S	0.83	0.83
2	1121/95121	WASHER, 5/8	0.46	0.92
1	1121/94584	5/8-11 GRD 8 NYL LOCK NUT	0.72	0.72
10	112P/07480MMM	DISC-CONDITIONING SURFACE	1.08	10.80
4	112P/82606PTX	CLEANER-BRK PTS 12/CS (CA	4.22	16.88
1	112P/250-4-81-1X	YOKE ASSY, SPICERLIFE SER	169.14	169.14
1	112P/170-4-281-1X	YOKE ASSY-END SPL170 2.02	154.56	154.56
1	112P/DS1707018X	KIT-170 BEARING STRAP ASS	10.38	10.38
2	112P/250-70-18X25	KIT-BEARING RETAINER (1EA	16.25	32.50
62	112P/550022418	OIL-SPIRAX EW 75W90 400 L	3.41	211.42
1	112P/DS1707018X	KIT-170 BEARING STRAP ASS	10.38	10.38
,	Total Labor 807.50	Total Parts 4,950.61 Total Other	0.00 Job#1 Total	5,758.11



Invoice Date

07/27/2015

K2151

V.I.N

1XP5D49XX6D633252

79116352 Engine Serial Vehicle ID # 140695 2006 PETERBILT

Cust Unit #

103 379

				2000 1 11110	L1	0.0	
Date In	Date In Service	Mileage	Date Out	Bill Type	Terms	Writer	Reviewer
07/24/2015	10/19/2005	1,041,956	07/24/2015	SR	N10TH		23052

Job#1 S OIL LEAK

OIL LEAK

SR

Condition

OIL LEAK AT PAN GASKET, NEW GASKET THIS WEEK CLEAN OFF AND MAKE SURE WHERE LEAKS IS FROM

Cause Correction

REMOVED THE PAN AND FOUND THE EDGE ROLLED WHERE THE GASKET SITS. REPLACED THE PAN AND CHECKED

FOR LEAKS, OK.

Qty	Item	Description			Price Each	Extended
		LABOR TO PERFORM REPA	IRS			0.00
1	112C/3163075	PAINT			11.72	11.72
1	112P/4026684CUM	GASKET-OIL PAN			152.81	152.81
1	112P/3687414CUM	PAN-OIL			1,167.59	1,167.59
1	1121/44212	7/8 X 1 1/8 O RING			0.85	0.85
	Total Labor 0.00	Total Parts 1,332.97	Total Other	0.00	Job#1 Total	1,332.97

DISCLAIMER	OF	WARRANTIES
------------	----	------------

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OR MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND PETERBILT OF DES MOINES NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.


Please remit to: Sioux City Truck Sales, Inc. PO Box 386 Sioux City, IA 51102-0386

Parts :	1,332.97
Labor :	0.00
Sublet :	0.00
Other Charges :	0.00
Misc Supplies :	0.00
EPA Charge :	0.00
Sales Tax :	79.98

1,412.95 Total:

Customer Signature

X



Invoice Date 08/19/2015

1XP5D49XX6D633252 V.I.N

Engine Serial 79116352 Vehicle ID # 140695

103 Cust Unit # 379

2006 PETERBILT

				2000 1 2 12 12			
Date In	Date In Service	Mileage	Date Out	Bill Type	Terms	Writer	Reviewer
07/29/2015	10/19/2005	1,046,080	07/29/2015	SR	N10TH		23052
b#3 CARRY OUT		ICKED UP BY CUSTO	OMER AT FRONT CO	UNTER CARRY	OUT		SR

Condition

PARTS PICKED UP BY CUSTOMER AT FRONT COUNTER CARRY OUT

SR

Cause Correction

			Price Each	Extended
Qty	Item	Description	1.41	2.82
2	112P/HWC07146	PLATE-TRIM FASTENER M-R		
2		LOGO-UNIBILT CAB SLEEPER	148.50	148.50
1	112P/29-02763		n Job#3 Total	151.32
	Total Labor 0.00	Total Parts 151.32 Total Other 0.0	0 30D#3 13ta	

DISCLAIMER OF WARRANTIES

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OR MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND PETERBILT OF DES MOINES NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.


Please remit to: Sioux City Truck Sales, Inc. PO Box 386 Sioux City, IA 51102-0386

Total:	3,995.94
Sales Tax :	226.19
EPA Charge :	10.00
Misc Supplies :	75.00
Other Charges :	0.00
Sublet :	0.00
Labor :	2,595.60
Parts :	1,089.15

Customer Signature

X

1,089.15



Invoice Date

08/19/2015

K2151

1XP5D49XX6D633252 V.I.N

79116352 Engine Serial

140695 Vehicle ID #

103 Cust Unit # 379

2006 PETERBILT

Date In	Date In Service	Mileage	Date Out	Bill Type	Terms	Writer	Reviewer
07/00/2015	10/19/2005	1,046,080	07/29/2015	SR	N10TH		23052
07/29/2015	10/19/2005	1,040,000	0112312010	0.1			

Job#1 ENGINE OIL LEAK

CHECK AND ADVISE ON ENGINE OIL LEAK

SR

Condition

CHECK AND ADVISE ON ENGINE OIL LEAK REPAIR PER ESTIMATE.


Cause

Correction

REMOVED BATTERY CABLES, INTAKE TUBING, AIR TO AIR, UPPER RAD HOSE, UPPER SUPPORT RODS, FAN AND ALT BELTS, CABLES FROM ALT AND ALT, UNBOLT A/C COMPRESSOR PUT IT OFF TO THE SIDE, FAN, FAN CLUTCH, VALVE COVER, UNBOLT ROCKERS, PINNED ENGINE REMOVED PULLEY AND DAMPER, PULLED FRONT CRANK SEAL OFF PULLED OUT ONE OF BOLTS FOR PULLING SEAL OUT HAD TO WORK IT OUT WITH PRY BAR AND CUT THE SEAL, GEAR HOUSING COVERS, GEAR TRAIN, BELLY CROSS MEMBER, OIL PAN, BOLTS TO AIR COMPRESSOR, WIRING BRACKETS TO FRONT GEAR HOUSING, UPPER SUPPORT BRACKETS FROM CYL HEAD TO FRONT GEAR HOUSING. JACKED ENGINE UP REMOVED FRONT MEMBER AND GEAR HOUSING. PUT PLUG IN OIL GALLERY, PLUGGED OFF AIR TO AIR AND INLETS ON ENGINE AND TURBO. CHECKED GEAR HOUSING OK NOT WARPPED OR CRACKED. PUT GASKET IN AND HOUSING WITH NEW BOLTS THAT HAVE SEALING WASHERS ON THEM AND TORQ TO SPEC. PUT ALL GEAR TRAIN ON SET AND TORQ TO SPEC. PUT UPPER AND LOWER GEAR COVERS ON WITH NEW GASKETS.PUT DAMPER AND PULLEY BACK ON PUT VALVE TRAIN BACK ON TORQ AND SET TO SPEC. PUT VALVE COVER ON WITH NEW GASKET. PUT FAN CLUTCH, BELTS, MAGA BRACKET, ALT AND A/C COMPRESSOR BACK ON. PUT GASKET IN AIR COMPRESSOR AND PUT IT ON. PUT ALL BACKETS AND WIRING BACK IN PLACE, UPPER RAD SUPPORTS, UPPER RAD HOSE, AIR TO AIR TUBES, INTAKE TUBING, OLD OIL PAN AND OIL BACK IN. VAC COOLING SYSTEM PUT COOLANT BACK IN. RAN ENGINE OK. CHECKED OIL AND COOLANT LEVEL FULL. PUT BELLY CROSSMEMEBER BACK ON AND WASHED ENGINE OFF.

Qty	Item	Description	Price Each	Extended
۷.,		LABOR TO PERFORM REPAIRS		2,595.60
1	112C/3163075	PAINT	11.72	11.72
1	112P/4962721CUM	SEAL-RECTANGULAR STRIP	16.06	16.06
1	112P/4962722CUM	SEAL-RECTANGULAR STRIP	15.93	15.93
1		GASKET-COVER FRONT ISX	66.24	66.24
7	112P/4985562CUM	WASHER-SNUBBING RND 3/4X2-3/4X	6.46	12.92
2	112P/05-09057SPL	WASHER-SNUBBING RND 3/4X3-3/4X	7.51	15.02
2	112P/05-09121SPL	BOLT-HEX 3/4-16NFX4-1/2 GR8 ZN	4.65	9.30
2	112P/D8500-4573	WASHER	1.10	4.40
4	1121/95123	3/4-16 GD 8 NYLON LOCK NUT	1.44	2.88
2	1121/94587	DISC-CONDITIONING SURFACE ROLO	1.10	2.20
2	112P/07480MMM		152.81	152.81
1	112P/4026684CUM	GASKET-OIL PAN	0.85	0.85
1	1121/44212	7/8 X 1 1/8 O RING	9.28	46.40
5	112K/1U5572	ADDITIVE	4.89	14.67
3	112P/82606PTX	CLEANER-BRK PTS 12/CS	18.38	18.38
1	112P/550019913	OIL-ROTELLA T TRI P 15W40 CJ4,	68.94	68.94
1	112P/4955383CUM	SEAL-OIL	9.75	9.75
1	112P/4985661CUM	SEAL-RING RECTANGULAR		F

3937215 Jeld:



Invoice Date

08/19/2015

1XP5D49XX6D633252 V.I.N

Engine Serial 79116352 Vehicle ID # 140695 2006 PETERBILT

Cust Unit # 103 379

					2006 PETERB	IL1	3/9	
Date	e In	Date In Service	Mileage	Date Out	Bill Type	Terms	Writer	Reviewe
07/29/2015		10/19/2005	1,046,080	07/29/2015	SR	N10TH	!	23052
1	112P/3679931		SEAL-O RING				08.0	10.98
1	112P/4985660	CUM	SEAL-RECTANGULAR	RING			6.11	6.11
1	112P/4299124		SEAL-O RING				9.74	9.74
1	112P/3679932		SEAL,O RING				7.76	7.76
1	112P/4965690		GASKET-SUPPORT A	CCESSORY DRIVE			9.07	29.07
1	112P/429912		SEAL-REAR ORING				2.40	12.40
1	112P/3678724		SEAL-O RING				3.67	3.67
1	112P/405917	2CUM	SEAL-O RING				7.19	7.19
1	112P/212161	CUM	SEAL,O RING				2.78	2.78
1	112P/304922		SEAL-O RING				2.60	2.60
2	112P/05-1691	19-2	MOUNT-ENGINE RUB	BER FRONT			8.72	157.44
3	112P/82606P		CLEANER-BRK PTS 1	2/CS			4.89	14.67
15	112P/368088		SCREW, CAPTIVE WA				5.52	82.80
1	1121/63261		10-1.50 X 45 MM HEX				1.10	1.10
1	1121/67010		10MM FLAT W				0.85	0.85
1	112P/498828	0CUM	GASKET-PUMP HYDE	RAULIC			3.11	3.11
1	112P/310439	2CUM	GASKET-VALVE COVI	ER ISX 2007			1.95	41.95
1	112P/306797	9CUM	CLAMP, V BAND				37.99	37.99
6	112P/CT0551	12	TIE-CABLE 120LB, 15	.25" BLK			0.45	2.70
6	112P/CT0531	17	TIE-CABLE 50LB 15.5	" BLK			0.24	1.44
3	112P/CTD65	11	TIE-CABLE DUAL CLA	AMP BLK 19.2"			3.71	11.13
2	112P/82606P		CLEANER-BRK PTS 1	2/CS			4.89	9.78
-			August 2015 \$10 off th	e purchase of \$100 or	more of			
			TRP Electrical Compo					
			August 2015 \$10 off th	e purchase of \$100 or	more of			
			TRP Electrical Components.					
			August 2015 \$10 off the purchase of \$100 or more of					
			TRP Electrical Compo	nents.				
	Total Labor	2,595.60	Total Parts 925.7	3 Total Other	er 0.00	Job#1	Total	3,521.33

Job#2 LTHDCABLE

REMOVE AND REPLACE LEFT SIDE HOOD CABLE

SR

Condition

REMOVE AND REPLACE BAD HOOD CABLE

Cause

Correction

INSTALL HOOD CABLE ON LEFT SIDE.

Qty	Item		Description	Description				Extended
1	112P/L92-6000-0718		CABLE-HOO	CABLE-HOOD			12.10	12.10
	Total Labor	0.00	Total Parts	12.10	Total Other	0.00	Job#2 Total	12.10