

Invoice

Date	Invoice #
11/1/2016	32039

Bill To
Wilkinson Sandblasting LLC

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
			11/1/2016			

Quantity	Item Code	Description	Price Each	Amount
1	Parts	Replace Hood Latch		
0.25	Labor	Hood Latch	126.05	126.05T
		Labor: Replaced Driver Side Hood Latch	75.00	18.75
6	Parts	Replace Trailer Connector		
1	73098	6 Way Trailer Cord	1.81	10.86T
4	71155	7 Way Connector 15-720	9.32	9.32T
4	71356	14-16 gauge 8-10 ring connector	0.90	3.60T
1.5	Labor	11-1/2"	0.20	0.80T
		Labor	75.00	112.50
1	Parts	Replace Transmission Synchronizer		
1	Parts	Gasket Kit	40.60	40.60T
1	Parts	O-Ring Kit	14.55	14.55T
1	Parts	Tail Shaft Seal Kit	39.06	39.06T
1	Parts	Yoke Nut	28.21	28.21T
1	Parts	Synchronizer	283.22	283.22T
1	Parts	Aux Drive Gear	175.74	175.74T
1	Parts	Snap Ring	0.95	0.95T
1	Parts	Washer	35.27	35.27T
3.5	50W SYN	50W SYN	36.00	126.00T
1	90684	3/8 Pipe to 3/8 Nylon	3.94	3.94T
1	Parts	Shift Knob	59.57	59.57T
12	Labor	Labor: Replaced transmission synchronizer and back box drive gear. Assembled with new seals, gaskets and filled with new oil. Replaced shift knob as it would allow low low range to shift to high range.	75.00	900.00
1	Parts	Repair Exhaust Leak		
1	Freight	Chrome Stack	76.25	76.25T
2	Parts	Shipping on stack	22.80	22.80T
1	09-0801501	Band Clamp	9.25	18.50T
1.5	5" Flex	5" ID X 5" OD 90 Degree	48.75	48.75T
		5" Flex	16.78	25.17T
			Total	

Invoice

Date	Invoice #
11/1/2016	32039

Bill To
Wilkinson Sandblasting LLC

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
			11/1/2016			
Quantity	Item Code	Description			Price Each	Amount
4	EC50PLA	5" Alum Clamp			11.92	47.68
1.5	Labor	...	Labor		75.00	112.50
1	Labor	...	DOT Inspection			
			Labor		60.00	60.00
			Sales Tax		5.50%	65.83