## L5573

	Se	ervice Advisor Qu	oting	Date		4/	7/2017	
_	Custo	mer	Aeviana					
<b>Customer</b> information	Guoto	Contact						
ati		Email	200110				.40	
Ĕ		Phone	1	Mobile				
or		Fax						
υĘ								
<del>.</del> =		Customer Vehicle #	AEV <mark>1180</mark>	Year				
ē			International	Model	4300			
ΙĔΙ	9	Chassis VIN #						
벑		Mileage		Engine Hours		Equi	pment Model	
n	1	Unit Serial #	1HTMMAAN95H162145					
S		Assy Serial #(FA)						
		General Foreman		Job#	operator re	lated damages		
	Item	L	abor Operations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
	1	Complaint-Verify	Drivers side step is bend bad, key is broken off in the ignition, drivers side door needs adjusted or fixed to shut and seal properly, rear tail shelf needs plates welded between tail shelf and frame back together,					
	2	Cause- Diagnostics	Performed DOT Inspection					\$0.00
Job 1	3	Correction-Repair	straighten brackets on drivers step(1), extract broken key from ignition(.5), adjust drivers door latch and hinges(1), weld rear tail plate and frame(1.5)	-	£2.	4	\$90.00	\$360.00
	4	Labor Total						\$360.00
	Item		Part Description	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
		ignition key		2506694c1	jim	1	\$20.00	\$20.00
	(3-2)							\$0.00
	(3-3)							\$0.00
	(3-4)							\$0.00
	(3-5)							\$0.00
l .	(3-6)							\$0.00
		Part Total				1-		\$0.00 \$20.00
l		Job 1 Total			-			
$\vdash$			abor Operations	Work Order	Took ID	Labor Time	Labor Data	\$380.00
	Item 1	Complaint-Verify	abor Operations found 1 outrigger valve and boot needs repalced(looks like it broke and they welded a piece of iron to it for a temp fix), there are no wheel chocks or outrigger pads, there are 2 auger teeth missing, rear bumber is bent	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
	2	Cause- Diagnostics	Performed Aerial Inspection					\$0.00
	3	Correction-Repair	replace outrigger valve and boot(4), install new wheel chocks and outrigger pads, replace auger teeth(.5), straighten rear bumper on both sides(1.5)			6	\$90.00	\$540.00

101	6	Labor Total				<u> </u>	\$540.00
	Item	Part Description	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
Job		outrigger valve section	454151	jim	1	\$301.64	\$301.64
'		outrigger valve section	448864	jim	1	\$19.51	\$19.51
		outrigger valve section seal kit	446948	jim	1	\$2.59	\$2.59
	(3-4)	wheel chocks	88747	jim	4	\$26.21	\$104.84
		outrigger pads 21/2"x24"x24"	88363	jim	4	\$43.17	\$172.68
l		auger teeth inside dirt tooth	129171	jim	1	\$2.49	\$2.49
1 1		auger teeth outside dirt tooth	129429	iim	1	\$3.02	\$3.02
1	(3-8)						\$0.00
	(3-9)				·		\$0.00
	(3-10)				-		\$0.00
	(3-11)						\$0.00
	(3-12)						\$0.00
	(3-13)						\$0.00
	(3-14)						\$0.00
1	5	Part Total					\$606.77
1	6	Job 2 Total					\$1,146.77
	Item	Labor Operations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
	1	Complaint-Verify				1	\$0.00
		Cause- Diagnostics		<del>  </del>		<del> </del>	\$0.00
	2			<del> </del>			\$0.00
	3	Correction-Repair					\$0.00
က	6	Labor Total					\$0.00
Job	Item	Part Description	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
13	(3-1)						\$0.00
	(3-2)						\$0.00
	(3-3)						\$0.00
l '	(3-4)						\$0.00
	5	Part Total					\$0.00
	6	Job 3 Total		<del> </del>			\$0.00
	Item	Labor Operations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
	1	Complaint-Verify		1.00	24201 111110		\$0.00
	2	Cause- Diagnostics					\$0.00
	3	Correction-Repair	•	<del>                                     </del>		<del></del>	\$0.00
1	6	Labor Total		<del>                                     </del>	<del> </del>	<del></del> -	\$0.00
4	Item	Part Description	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
go	(3-1)	t dit besetiption	T dictioning of	1 41 60 10	Quantity	1 4101 1100	\$0.00
ラ	(3-2)			+			\$0.00
	(3-3)			<del>  </del>		<del> </del>	\$0.00
	(3-4)			<del>  </del>			\$0.00
1		Part Total		<del>                                     </del>			\$0.00
1	6	Job 4 Total		<del>  </del>			\$0.00
	Item	Labor Operations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
:	1	Complaint-Verify	7.7.17 91401	, , , , , , , , , , , ,			\$0.00
	2	Cause- Diagnostics		<del>  </del>			\$0.00
1	3	Correction-Repair					\$0.00
۱	6	Labor Total					\$0.00
5	Item	Part Description	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
Job	(3-1)	, a.e poonipuon		1. 4. 40 10	Manual		\$0.00
٦	(3-2)			<del>                                     </del>			\$0.00
1	(3-3)		<del> </del>	<del>                                     </del>			\$0.00
1	(3-4)						\$0.00
1		Part Total					\$0.00
		Job 5 Total		†			\$0.00
		· · · · · · · · · · · · · · · · · · ·					· *

 Parts:
 \$626.77

 Labor:
 \$900.00

 Shop Supplies
 \$25.00

**Total:** \$1,551.77

Page 3 of 3

		_						
	Se	ervice Advisor Qu	oting Amy Holt	Date		4/	5/2017	
드	Custo	mer	Aeviana					
		Contact						
Ja		Email						
E		Phone		Mobile				
Customer information		Fax						
Ë		Customer Vehicle #	AEV1180	Year	2005			
er		Make	International	Model	4300			
Ĕ		Chassis VIN #						
stc		Mileage		<b>Engine Hours</b>		Equ	ipment Model	
ns		Unit Serial #	1HTMMAAN95H162145		263			
O		Assy Serial #(FA)						
		General Foreman		Job#	regular ma	intenance		
	Item		abor Operations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
	,		Found turn pipe is missing on exhaust, needs new exhaust clamp					
	2		Performed DOT Inspection					\$0.00
	3		replace turn pipe on the exhaust,			1	\$90.00	\$90.00
		Labor Total	replace tall pipe on the exhaust,			•	\$50.00	\$90.00
_	Item	F	Part Description	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
	(3-1)	tailpipe	•	p206311	jim	1	\$39.63	\$39.63
Job		exhaust clamp 4"		x007784	jim	1	\$11.46	\$11.46
,	(3-3)							\$0.00
	(3-4)							\$0.00
٠.	(3-5)							\$0.00
	(3-6)		**					\$0.00 \$0.00
		Part Total						\$51.09
		Job 1 Total						\$141.09
	Item	L	abor Operations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
	1		found there are 6 lower control boots torn, found there are 3 warning placards that need replaced, 1 auger hose needs replaced, auger windup cable shackle is missing, 1 outrigger hose needs replaced, lower control throttle is in-op, 1 hydraulic hose #6 needs replaced, auger stow strap needs replaced,					\$0.00
	2	Cause- Diagnostics	Performed Aerial Inspection					\$0.00
Job 2	3	Correction-Repair	replace 6 lower control boots(1), replace placards(.5), replace 3 auger hoses(1), replace auger shackle and stow strap(.5), replace 1 outrigger hose(1), replace both hoses on tool reel(1), further diagnose lower control throttle(1)			6	\$00.00	\$540.00
1,050		Labor Total				0	\$90.00	\$540.00
	Item		Part Description	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
		lower control boots		448864	jim	6	\$19.51	\$117.06

				200.40	" T	240	\$0.41	\$98.40
l		auger hose		302-12	jim	240	\$0.41	\$20.40
		auger hose		302-4	jim	120		
		auger shackle		67495	jim	1	\$42.98	\$42.98
		outrigger hoses		451tc-6	jim	1,560	\$0.19	\$296.40
		fittings		10643x4x4	jim	2	\$3.07	\$6.14
	(3-7)	fittings		10643x10x10	jim	4	\$7.78	\$31.12
	(3-8)	fittings		10643x6x6	jim	16	\$3.45	\$55.20
	(3-9)	auger stow strap		65305437	jim	1	<u>\$5</u> 4.48	\$54.48
1		hose tool reel		451tc-8	jim	300	\$0.36	\$108.00
	(3-11)							\$0.00
	(3-12)							\$0.00
	(3-13)							\$0.00
	(3-14)							\$0.00
	5	Part Total						\$830.18
	6	Job 2 Total			Ì			\$1,370.18
	Item	Labor Ope	erations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
		Complaint-Verify						\$0.00
	2	Cause- Diagnostics		<del>                                     </del>	<del>  </del>			\$0.00
				<del></del>				
	3	Correction-Repair						\$0.00
(L)	6	Labor Total						\$0.00
Job	Item	Part Desc	ription	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
ヿゔヿ	(3-1)							\$0.00
	(3-2)							\$0.00
	(3-3)							\$0.00
	(3-4)							\$0.00
	5	Part Total			1			\$0.00
	6	Job 3 Total						\$0.00
	Item	Labor Ope	erations	Work Order	Tech ID	Labor Time	Labor Rate	Labor Subtotal
	1	Complaint-Verify						\$0.00
	2	Cause- Diagnostics	-					\$0.00
	3	Correction-Repair		İ	1		i ·	\$0.00
ا ــ ا		Labor Total						\$0.00
4	Item	Part Desc	cription	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
Job	(3-1)	•		•	1	- doublety	1 -100	\$0.00
ا ب	(3-2)			<del>                                     </del>	<del>                                     </del>			\$0.00
	(3-3)			<del> </del>	<del>  </del>			\$0.00
	(3-4)		<del>- · · · · · · · · · · · · · · · · · · ·</del>	<del> </del>	<del>  </del>			\$0.00
		Part Total	<del></del>	<del> </del>	<del>  </del>		<del> </del>	\$0.00
		Job 4 Total		<del>                                     </del>	<del>                                     </del>		<del> </del>	\$0.00
	Item	Labor Ope	Brations	Work Order	Tech ID	Labor Time	Labor Rate	
	1	Complaint-Verify		VIUOI		-user rille		\$0.00
	2	Cause- Diagnostics		<del> </del>	<del> </del>			\$0.00
	3	Correction-Repair		<u> </u>	<del>  </del>		<b> </b>	\$0.00
5		Labor Total	<del></del> -					\$0.00
	Item	Part Desc	cription	Part Number	Parts ID	Quantity	Part Price	Part Subtotal
Job	(3-1)						1	\$0.00
ا ت ا	(3-2)					·	1	\$0.00
	(3-3)							\$0.00
	(3-4)							\$0.00
		Part Total						\$0.00
	6	Job 5 Total						\$0.00

 Parts:
 \$881.27

 Labor:
 \$630.00

 Shop Supplies
 \$25.00

 Total:
 \$1,536.27

Please sign below to authorize this estimate	
Printed Name:	Date:
Signature:	