

Ship to:	N/A	Date	08/26/16	Time	14:48:32 (O)	Page	01
		Account No.	5283008	Phone No.		Invoice No.	W33194
		Ship Via		Purchase Order			
		FARM CERT		Salesperson			
Invoice to:	DANNY MILES						

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X564902	CORN HEAD		X H01293X680794	07/01/00	
	1293		E		

REPAIR# 1 C RMA01 RDO-900-014 08/16/16 08/16/16
CORNHEAD INSPECTION

Inspect cornhead and make quote for the customer
PROMOAG inspection 1- 318.50

PARTS
LABOR

10404099

REPAIR TOTAL==>

REPAIR# 2 C ES901 RDO-080-400 08/16/16 08/16/16
WASH EQUIPMENT

Washed dirt and debris out of the auger bed trough on corn head

LABOR

10404099

REPAIR TOTAL==>

REPAIR# 3 C RMA01 10-670-030 08/16/16 08/17/16
KNIFE STALK ROLL CONVERSION (ONE ROW)

Remove stalk rolls and install Calmer chopping stalk rolls.
(Customer supplied parts)

LABOR

10404099

REPAIR TOTAL==>

REPAIR# 4 C RMA01 10010BJ 08/16/16 08/17/16
STALK ROLL SHAFT SEAL, REPLACE

Remove and replace all stalk roll shaft seals

AN102266 SEAL 24 10.37

PARTS

LABOR

10404099

REPAIR TOTAL==>

Ship to:	N/A
Invoice to:	DANNY MILES

Date	Time	Page
08/26/16	14:48:32 (O)	02
Account No.	Phone No.	Invoice No.
5283008		W33194
Ship Via	Purchase Order	
FARM CERT		
	Salesperson	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X564902		X H01293X680794	07/01/00	
CORN HEAD		E		
1293				

REPAIR# 5 C RMA01 10-170-020 08/16/16 08/19/16
 GATHERER CHAIN DRIVE SPROCKET, R&R OR REPLACE
 Remove gatherer chain drive sprocket.
 Flip sprocket so it drives chains from the other side
 Reinstall to specifications.

LABOR
 10404099 REPAIR TOTAL==>

REPAIR# 6 C RMA01 NA 08/18/16 08/18/16
 snout bracket
 Replace broken upper snout hold pivot.
 AH143462 PIVOT 1 N 67.53

PARTS
 LABOR
 10404099 REPAIR TOTAL==>

REPAIR# 7 C RMA01 10-180-010 08/18/16 08/18/16
 AUGER DRIVE CHAIN, R&R OR REPLACE
 Remove row unit drive shaft shield.
 Disconnect and remove auger drive chain.
 Reinstall to specifications.
 Replaced both drive chains

AH147697 ROLLER CHA 2 53.24
 PARTS
 LABOR
 10404099 REPAIR TOTAL==>

REPAIR# 8 C RMA01 10-170-050 08/18/16 08/18/16
 GATHERER CHAIN, R&R OR REPLACE

CONTINUED ON PAGE 03

Ship to:	N/A	Date	08/26/16	Time	14:48:32 (O)	Page	03
		Account No.	5283008	Phone No.		Invoice No.	W33194
Invoice to:	DANNY MILES	Ship Via	Purchase Order				
		FARM CERT					
		Salesperson					

SERVICE INVOICE

STK#/FLEET#	CORN HEAD	HRS	PIN/EIN	WARRANTY DATE	HRS
X564902	1293		X H01293X680794	07/01/00	
			E		

Remove gatherer shield or gatherer sheet
as required.
Release gatherer chain tension.
Loosen idler support.
Remove gatherer chain.
Reinstall to specifications.

AN102009	LINK CHAIN	24	51.09
PM38658	ANTI-SEIZE	1	12.59
	ANTI-SEIZE Compound		
14H821	NUT	1	1.05
	PARTS		
	LABOR		
10404099			REPAIR TOTAL==>

REPAIR# 9 C RMA01 RDO-174-001 08/18/16 08/18/16

CENTER AUGER FLOOR R&R
Replace center and outer floors.
Replace bolts.

FRT	SHIP/HANDLING	1	57.00
H150663	SNAP RING	2	1.14
H179193	SHEET	1 N	184.82
H179209	SHEET	1 N	235.65
H179210	SHEET	1 N	235.65
03M7190	BOLT	45 O	.74
03M7191	BOLT	12	.74
03M7192	BOLT	15	.69
03M7193	BOLT	24	.97
14M7296	FLANGE NUT	85	1.18
	PARTS		
	LABOR		

CONTINUED ON PAGE 04

Ship to:	N/A	Date	08/26/16	Time	14:48:32 (O)	Page	04
		Account No.	5283008	Phone No.		Invoice No.	W33194
Invoice to:	DANNY MILES	Ship Via	Purchase Order				
		FARM CERT					
		Salesperson					

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X564902		X H01293X680794	07/01/00	
		E		
10404099		REPAIR TOTAL==>		

REPAIR# 10 C RMA01 10-040-020 08/18/16 08/18/16

DECK PLATE POSITION SENSOR, R&R

CONDITION:

Deck plate position sensor linkage is broken

ADDITIONAL DESCRIPTION:

Right side deck plate linkage replace.

AH159809	LINKAGE	1	48.03
	Tie Rod Assembly		

10404099

REPAIR TOTAL==>

REPAIR# 12 C RMA01 NA 08/18/16 08/25/16

GREASE ROW UNITS, TEST RUN MACHINE

Grease all row units and test run head

AN102562	LUBRICANT	6	3.67
H150663	SNAP RING	1	1.14
JD7759	GREASE FIT	6	.96
	Lubrication Fitting		
15H690	PIPE PLUG	4	5.24

10404099

REPAIR TOTAL==>

REPAIR# 13 C RMA01 RDO-070-DIAG 08/16/16 08/16/16

HYDRAULIC DIAGNOSTICS

Hydraulic leak under head for deck plate adjustment.

Found hole in hose after further inspection.

CONTINUED ON PAGE 05

Ship to:		Date	Time	Page
		08/26/16	14:48:32 (O)	05
		Account No.	Phone No.	Invoice No.
		5283008		W33194
Invoice to:	DANNY MILES	Ship Via	Purchase Order	
		FARM CERT		
				Salesperson

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X564902	CORN HEAD		X H01293X680794	07/01/00	
	1293		E		

Other hose had cracks.
Replace both hoses for deck plates.

X1JS43-6-4	FITTING	4	10.54
X487TC-4-RL	Bulk Hose 1/4IN	18	5.00
	PARTS		
	LABOR		

10404099 REPAIR TOTAL==>

***** WORK ORDER TOTALS *****

PARTS
LABOR

777428 1240072183 TOTAL FARMPLAN CHG