

Time: 08:03  
Date: 01/13/2016  
Page: 1/1

Invoice Number 071327

SOLD TO  
1290  
THE ELLSWORTH COOP  
PO BOX 397  
ELLSWORTH, KS 67439

Employee: 5 ,  
Sales Rep: 0 , Salesman  
Accounting Day: 10

Part Number	Line	Description	Quantity	Price	Net	Total
244-9209	RAY	1983 Ford Truck F700 6.1 L 370 CID V8	1.00			
244-9209	RAY	Starter - Remfd - Standard	1.00			
		Core Deposit				
		Gas Truck				

Delivery:  
Attention:  
Tax Exemption:  
PO#:  
Terms: SERVICE CHG

Matt Hutchens  
Customer Signature  
ALL GOODS RETURNED MUST BE ACCOMPANIED BY THIS INVOICE  
NO RETURNS AFTER 30 DAYS  
NO RETURNS ON ELECTRICAL  
ITEMS..

CUSTOMER COPY

Subtotal 84.99  
SALES TAX 8.7500% 7.44

Total 92.43  
Charge Sale 92.43

19561

QTY.	PART NO. AND DESCRIPTION	PRICE
2	G4002 LED lights	
2	67000 pig tails	
2	43572 brackets	
2	91740 grommets	
6	crimp connectors	
1	ft heat shrink	
	silver & black paint	
8	self tapping screws	
	Dielectric grease	
1	EOH217322 DB speed gear	
1	speedometer drive key	
8	AP24 spark plugs	
1	6536 ignition wire	
1	M515937 intake manifold gasket	
1	C26650 water outlet gasket	
4	hose clamps	
3	cans parts cleaner	
2	tubes silicone	
1	qt anti-freeze	
1	1440B carburetor kit	
1	60003 carburetor gasket	
1	16-2784 PCV Valve	
ACCESSORIES		418.41
TOTAL ACCESSORIES		

NAME <i>Elsworth Corp</i>		CUSTOMER'S ORDER NO.	DATE <i>3-6-15</i>
ADDRESS		ORDER WRITTEN BY	PROMISED A.M. P.M.
CITY, STATE, ZIP			
HOME PHONE	BUS. PHONE	EXT.	ODOMETER IN <i>71357</i>
YEAR, MAKE AND MODEL <i>F800</i>	LICENSE NUMBER	ODOMETER OUT	
SERIAL NUMBER	MOTOR NUMBER	TERMS	
DESCRIPTION OF WORK			
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF.			
Replace tail lights, mounting brackets, and grommets. Old ones were corroded and rotted out. Fix speedometer.			
Check rough running and loading up at idle. Changed power valve in carburetor. Changed spark plugs because two on left bank were discolored. Found intake leaking. Replace intake manifold gasket. Also replaced one ignition wire where end wasn't making good contact. Replaced PCV valve.			
Did DOT Inspection			
____ LITERS/GALS. OF GAS @		TOTAL LABOR	<i>825.00</i>
____ LITERS/QTS. OF OIL @		TOTAL PARTS	<i>418.41</i>
____ kg/LBS. OF GREASE @		ACCESSORIES	
		GAS, OIL AND GREASE	
		SUBLET REPAIRS	
		EPA / WASTE DISPOSAL	
		TAX	<i>1243.41</i>
		TOTAL	<i>88.90</i>
		THANK YOU	<i>1332.31</i>

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SAVE OLD PARTS? ☐ YES ☐ NO

SIGNATURE

*Thank you*



20802

QTY.	PART NO. AND DESCRIPTION	PRICE
1	BH 38307 F. brake hose	
1	BH 38308 F. brake hose	
<del>1</del>	<del>MC 106445 master cyl.</del>	
1	2512138 brake booster	
	frt on everything	
1	85814 light socket	
5	qts brake fluid	
4	cans brake lnr	
1	MC 106445 master cyl.	
1	UP321HR Front Shoe Kit	
1	WC 73537 wheel cyl.	
1	WC 73538 wheel cyl.	
1	WC 37147 wheel cyl.	
1	WC 37148 wheel cyl.	
2	370001A F. wheel seals	
1	194 bulb	

 DR  
 DR  
 RA  
 SWT

NAME <i>Elkworth Corp</i>		CUSTOMER'S ORDER NO.	DATE <i>3-9-17</i>
ADDRESS		ORDER WRITTEN BY	PROMISED
CITY, STATE, ZIP		A.M. P.M.	
HOME PHONE <i>1983</i>	BUS. PHONE	EXT.	ODOMETER IN <i>84,300</i>
YEAR, MAKE AND MODEL <i>1983 Ford F800</i>	MOTOR NUMBER <i>370</i>	LICENSE NUMBER <i>637122</i>	ODOMETER OUT
SERIAL NUMBER <i>FDNF82H5DVA47454</i>	TERMS		

 PI  
 N

PI

PI

PI

PI

PI

DR

DESCRIPTION OF WORK	AMOUNT
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF.	
Check brake. Master cyl. was leaking down firewall, brake booster is leaking fluid up vac. line. Front brake hoses are rotting. Replaced master cyl., booster, and both front hoses. Pressure bleed system. Something in front brakes is letting air in system. Replaced front wheel cyls. brake shoes and wheel seals. Bleed system. Fixed LF marker light.	
Did DOT inspection.	

LITERS/GALS. OF GAS @	TOTAL LABOR	<i>862.50</i>
LITERS/QTS. OF OIL @	TOTAL PARTS	<i>1054.42</i>
kg/LBS. OF GREASE @	ACCESSORIES	
<i>15X3 F. brakes</i> <i>Obscure F. drums #</i>	GAS, OIL AND GREASE	
<i>3.5" DOHZ-1125-C</i> <i>5 bolt 120641</i> <i>44448F</i> <i>2898/2827</i> <i>821-9150</i>	SUBLET REPAIRS	
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.	EPA / WASTE DISPOSAL	
SAVE OLD PARTS? <input type="checkbox"/> YES <input type="checkbox"/> NO	TAX	<i>1916.92</i> <i>143.77</i>
SIGNATURE	TOTAL THANK YOU	<i>204069</i>

(MAY BE CONTINUED ON OTHER SIDE)

TOTAL PARTS

ACCESSORIES

TOTAL ACCESSORIES



20472

QTY.	PART NO. AND DESCRIPTION	PRICE
1	10-4123 yoke	WT
2	72-1125 shaft	PD
2	10-D332 yoke slip	PD
2	10-D432 yoke	PD
1	10-D463 yoke	PD
2	10-4103 yoke	PD
4	5-170X u-joints	PD
4	449D lock screws	PD
1	442 XWITX-W3XD PTO	PD
1	5-P-1004 input gear	PD
	1/4" x 2" iron	
3	Cleaning pads	
8	gts 9DW	
2	cone parts clean	
	freight on everything	
		1191 74

NAME <i>Edworth Corp</i>		CUSTOMER'S ORDER NO.	DATE <i>8-16-16</i>
ADDRESS		ORDER WRITTEN BY	PROMISED A.M. P.M.
CITY, STATE, ZIP			
HOME PHONE	BUS. PHONE	EXT.	ODOMETER IN <i>83,143</i>
YEAR, MAKE AND MODEL <i>83 Ford 370</i>		LICENSE NUMBER	ODOMETER OUT
SERIAL NUMBER	MOTOR NUMBER	TERMS <i>FDNF82H5DVA47454</i>	

DESCRIPTION OF WORK	AMOUNT
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF.	
Remove broken PTO. Check transmission and PTO gears - OK. Pump bracket broke and let pump fall about 6 inches. This caused the drive line to bind up and broke PTO. Welded & reinforced bracket. Put new PTO on and replaced both PTO drive lines. Reinstall drive line!	

(MAY BE CONTINUED ON OTHER SIDE)

TOTAL PARTS	LITERS/GALS. OF GAS @	TOTAL LABOR	<i>1684 25</i>
ACCESSORIES	LITERS/QTS. OF OIL @	TOTAL PARTS	<i>1191 74</i>
<i>Drig. 41DXWAHX-W3XD</i>	kg/LBS. OF GREASE @	ACCESSORIES	
		GAS, OIL AND GREASE	
		SUBLET REPAIRS	
		EPA/WASTE DISPOSAL	
		TAX	<i>1875 99</i> <i>140 70</i>
TOTAL ACCESSORIES	I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.	TOTAL	<i>2016 69</i>
	SAVE OLD PARTS? <input type="checkbox"/> YES <input type="checkbox"/> NO	THANK YOU	
	SIGNATURE		