

DB 6581

1988 GMC

8

Date	Quan.	Part #	Description	Price	Ext.	Milag
9/11/08	1.5	LABOR	install trailer plug			
	1	755-1526	plug			
			2011/2012			
8/9/11	1	12014	oxygen sensor			
	4	R43TS6	spark plugs			
	1	FE0115	fuel pump			
	1	FS0177	strainer			
	1	AR221	relay			
	1	3481	fuel filter			
	8	LABOR	install listed parts			49641
			2012/2013			
8/21/12	1	3-1757	Idle air control valve			
	1	6036	air filter			
	1	RR2121	rotor			
	1	RR209	cap			
	1	TS4052	temp sender			50201
8/30/12	1	out labor	eagle, check for bad computer			
8/31/12	1	XTP647	ECM			
9/10/12	1	6801252	left tail lamp lens			
			reroute #4 plug wire			
	10	LABOR	diagnose and replace listed parts 8/21-9/10			
5/29/13	1	7575	battery			50500
			2013/2014			
8/20/13	1	213-4508D	alternator			50536
						50634
4/17/14	1	246-5074	starter			
			2014/2015			
8/25/14	2	LABOR	lube and oil			50982
	4	5w30	oil			
	1	1040	filter			

1 of 2

DB 6581

8

	1	H6054	headlamp		
	0.75	RainX	washer solvent		
	0.5	green	antifreeze		
12/12/14	1	49-190	wiper motor		51063
	1.5	LABOR	install listed parts		
5/29/15	1	72132	master cylinder		
			2015/2016		
8/19/15	2	LABOR	replace muffler		51572
8/28/15	2	LABOR	replace fuel pump and sender		
			2016/2017		
11/16/16	1	LABOR	Replace plug wires and clean plugs		
			2017/2018		
12/20/17	3	LABOR	find and tighten ecm 1 fuse, no voltage to injector		

2 of 2