

03/07/2018 10:44:31 am

Fleet Management

Fleet Asset Service History

Page: 1

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	12 - ENGINE REPAIR/TUNE UP	11/21/2017	173,073.00	Hours	
Service Detail: Vendor: 23112 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: REPLACED ENG INJECTOR SLEEVES, FLUSHED COOLING SYSTEM & REPLACED COOLANT (DUE TO FUEL MIXING WITH COOLANT)						
ENG HRS = 13,984						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	13 - OIL & FILT	11/21/2017	173,073.00	Hours	
Service Detail: Vendor: 23112 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: LUBE, OIL, & OIL FILTER CHANGE						
ENG HRS = 13,984						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	13 - OIL & FILT	06/21/2017	166,770.00	Hours	
Service Detail: Vendor: 23112 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: LUBE, OIL, & OIL FILTER CHANGE						
ENG HRS = 13,408						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	13 - OIL & FILT	04/06/2017	163,267.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: LUBE, OIL CHANGE, AND OIL FILTER CHANGE						
ENG HRS = 13160						

03/07/2018 10:44:31 am

Fleet Management Fleet Asset Service History

Page: 2

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	13 - OIL & FILT	01/06/2017	158,910.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: DRAINED & REPLACED OIL; REPLACED OIL & FUEL FILTER; LUBED CHASSIS; CHKD FLUIDS; ADDED QT OF TRANS FLUID						
ENG HRS = 12,780						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	14 - BRAKES	04/06/2017	163,267.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: REPLACED BOTH SETS OF REAR BRAKE SHOES						
ENG HRS = 13,160						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	14 - BRAKES	01/06/2017	158,910.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: REPLACED AIR DRIER CARTRIDGE ON BRAKE SYSTEM						
ENG HRS = 12,780						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	15 - BATTERY	01/15/2018	14,067.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: charge 2 new batteries and install						

03/07/2018 10:44:31 am

Page: 3

Fleet Management

Fleet Asset Service History

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	15 - BATTERY	01/15/2018	0.00	Hours	
<div> <div> Service Detail: Vendor: 2015 Cost: SR: </div> <div> Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished: </div> </div>						
<div> Comments: INV# 155527 QTY 2 - BATTERIES INTERSTATE 31-ECL </div>						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	16 - FUEL SYST	11/21/2017	173,073.00	Hours	
<div> <div> Service Detail: Vendor: 23112 Cost: SR: </div> <div> Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished: </div> </div>						
<div> Comments: REPLACED FUEL FILTER ENG HRS = 13,984 </div>						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	16 - FUEL SYST	06/21/2017	166,770.00	Hours	
<div> <div> Service Detail: Vendor: 23112 Cost: SR: </div> <div> Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished: </div> </div>						
<div> Comments: REPLACED FUEL FILTER ENG HRS = 13,408 </div>						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	16 - FUEL SYST	03/22/2017	0.00	Hours	
<div> <div> Service Detail: Vendor: 12020 Cost: SR: </div> <div> Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished: </div> </div>						
<div> Comments: PUMP OUT FUEL TANK ON TRK 33 (UNLEADED FUEL PUMPED INTO DIESEL TANK) </div>						

03/07/2018 10:44:31 am

Fleet Management

Fleet Asset Service History

Page: 4

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	16 - FUEL SYST	01/06/2017	158,910.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: DIAGNOSED AND REPAIRED FOR LOST FUEL PRIME.						
ENG HRS = 12,780						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	17 - ELECT SYST	08/08/2017	168,925.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: Install new alternator & test.						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	17 - ELECT SYST	08/07/2017	0.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: Charge batteries test alternator & order						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	17 - ELECT SYST	08/07/2017	0.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: Test and remove alternator.						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	17 - ELECT SYST	08/07/2017	0.00	Hours	
Service Detail: Vendor: 5101 Cost: 243.65 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: QTY 1 - ALTERNATOR 110-555PHO MID 4C / PURCHASED BY TERRY LYONS FOR REPLACEMENT.						

03/07/2018 10:44:31 am

Fleet Management Fleet Asset Service History

Page: 5

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	17 - ELECT SYST	05/05/2017	0.00	Hours	
Service Detail: Vendor: 3034 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: REPLACEMENT BULB FOR SPOTLIGHT						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	17 - ELECT SYST	04/06/2017	163,267.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: REPLACED 3 LIGHTS AND LED LIGHT BAR						
ENG HRS = 13,160						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	11/29/2017	13,988.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: finish radiator replacement, connect hoses, refill radiator, check operation. take for test drive.						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	11/29/2017	0.00	Hours	
Service Detail: Vendor: 3034 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: QTY 2 - NAPA HD ANTIFREEZE						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	11/28/2017	13,988.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: Drain and remove radiator, move brackets to new radiator and install.						

03/07/2018 10:44:31 am

Fleet Management Fleet Asset Service History

Page: 6

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	11/28/2017	0.00	Hours	
Service Detail: Vendor: 20086 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: QTY 1 - REPLACEMENT RADIATOR (SLIGHTLY DENTED BUT WITH FULL WARRANTY)						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	11/21/2017	0.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: Radiator leaking, take water to Westphalia and follow truck back to Burlington, order radiator.						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	11/21/2017	173,073.00	Hours	
Service Detail: Vendor: 23112 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: REPLACED RADIATOR AND HEATER HOSES, REPLACED SURGE TANK						
ENG HRS = 13,984						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	07/13/2017	167,725.00	Hours	
Service Detail: Vendor: 23112 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: SERVICE A/C - EVACUATE & RECHARGE SYSTEM; LOSING VOLTAGE TO BLOWER MOTOR; TRACED WIRE AND REPAIRED ONE TERMINAL AT THE POWER DISTRIBUTION MODULE; ADDED 0.4 LBS OF REFRIGERANT R134A						

03/07/2018 10:44:31 am

Fleet Management

Fleet Asset Service History

Page: 7

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	18 - COOLING SY	06/21/2017	166,770.00	Hours	
Service Detail: Vendor: 23112 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: REPLACED HVAC CONTROL HEAD W/ USED ONE: TRACED WIRE FOR A/C, REPAIRED WIRE AT TEMP ENG HRS = 13,408						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	20 - TRANSMISSN	04/06/2017	163,267.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: INSTALLED NEW SEAL ON TRANSMISSION DIPSTICK ENG HRS = 13,160						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	24 - MISC PARTS	01/29/2018	0.00	Hours	
Service Detail: Vendor: 5101 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: PARTS: QTY1-NPT-BUSHING B VM4E QTY1-VALVE-DRAIN CNTR3						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	24 - MISC PARTS	11/29/2017	0.00	Hours	
Service Detail: Vendor: 3034 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: TWO SCREWS & WASHERS, THREE HOSE CLAMPS, & TWO REDUCER BUSHINGS						

03/07/2018 10:44:31 am

Fleet Management Fleet Asset Service History

Page: 8

Fleet Asset	Description	Service Code	Closed Date	Actual Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	24 - MISC PARTS	04/10/2017	0.00	Hours	
Service Detail: Vendor: 1044 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: PASSENGER MIRROR PARTS						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	25 - ASSOC EQUI	02/02/2018	42.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: New 33 arrived, look over and operate unit. Auxiliary power will not shut off. troubleshoot electrical.						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	25 - ASSOC EQUI	01/16/2018	0.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: find air leaks, replace 3/8 elbow fitting on service brake valve. order 2 tank drain valves.						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	29 - MISC EXPNS	02/15/2018	114.00	Hours	46 - TERRY LYON
Service Detail: Vendor: Cost: 0.00 SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: Install seat covers, remove interior plastics						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	29 - MISC EXPNS	09/15/2017	0.00	Hours	
Service Detail: Vendor: 2250 Cost: SR:						
Standard Service Information: System Level: Repair Reason: Part Failure: Work Accomplished:						
Comments: QTY 2 - 22" ANCO WIPER BLADES						

03/07/2018 10:44:31 am

Fleet Management
Fleet Asset Service History

Page: 9

Fleet Asset	Description	Service Code	Closed Date	Actual Meter Reading	Meter Type	Service Technician
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	29 - MISC EXPNS	09/15/2017	0.00	Hours	
Service Detail:		Standard Service Information:				
Vendor: 2250		System Level:				
Cost:		Repair Reason:				
SR:		Part Failure:				
		Work Accomplished:				
Comments: QTY 2 - 18" ANCO WIPER BLADES						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	29 - MISC EXPNS	04/06/2017	163,267.00	Hours	
Service Detail:		Standard Service Information:				
Vendor: 5101		System Level:				
Cost:		Repair Reason:				
SR:		Part Failure:				
		Work Accomplished:				
Comments: ANNUAL D.O.T. INSPECTION						
ENG HRS = 13,160						
OLD 33	2006 FREIGHTLIN/TEREX M2106, 55'	31 - AIR FILTER	06/21/2017	166,770.00	Hours	
Service Detail:		Standard Service Information:				
Vendor: 23112		System Level:				
Cost:		Repair Reason:				
SR:		Part Failure:				
		Work Accomplished:				
Comments: REPLACED ENGINE AIR FILTER & CABIN AIR FILTER						
ENG HRS = 13,408						

03/07/2018 10:44:31 am

**Fleet Management
Fleet Asset Service History**

Page: 10

PARAMETERS ENTERED:**Fleet Asset:** OLD 33**Location:** All**Class:** All**Service Code:** 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 24, 25, 26, 27, 29, 31, 32, 33, 34, 35, 36, 37, 38**Closed Date:** 01/02/2017 To 03/07/2018**Service Technician:** All**Vendor:** All**Service Detail:** Yes**Standard Service Information:** Yes**Comments:** Yes