FT18611 DP100 ser. 3DP0030

Engine very tired, tranny has shifting issues-control valve not available, steering cylinder from FT97001-leaks, might not be hooked up, air compressor shot-hard to get air pressure to build up. Might not have lights, moved to another unit. 31191 hrs. as of 8/17

Previous Rayment picker FT17762 Asset tag 029577