and the same of the	
C = -/A/	VOICE
SERV	A TOTAL STATE

INVOICE NUMBER: Invoice Date:	11-29-18
Due	\$16,240.56
Make	AA
Model	420D
Serial #	0BLN08124
Equip No	
Machine ID	
Meter Reading	
PSO/WO	

Customer#	PO#		Doc Date	Salesman	Division Store	Terms
Gustoniel #			10-31-18			4
Overality	Item		Description		Unit Price	Extension
TENVIN	BOTH CYLIND	ERS AT 3000 PSI HE OTHER PASSEI I CUSTOMER SAI	ONE CYLINDER OF GAVE A PRICE OF SEND BACK .	IS TO		
		TOTA	AL LABOR	SEG. 14		
		SEC	GMENT 14 TOTAL			
PRE-PAY	MENT					
1.00	_	A/R	OTHER			
		TOTA	AL MISC CHGS	SEG. 55		
		SEC	GMENT 55 TOTAL			
		ENI GAR	AHOMA STATE TAX D CITY TAX FIELD COUNTY TA C O D			
Parts						
Labor Misc.						
Tax						
TOTAL						\$16,240.5

\$16,240.56

INVOICE NUMBER: 11-29-18 Invoice Date: \$16,240.56 Due AA Make 420D Model 0BLN08124 Serial # Equip No Machine ID Meter Reading

10-31-18		4
Description	Unit Price	Extension
		High Bring

TOTAL PARTS

SEG. 13

F/R LBR

PSO/WO

1.00

INBOUND FREIGHT

TOTAL MISC CHGS

SEG. 13

SEGMENT 13 TOTAL

REPLACE GASKET/RESEAL 2 SWING CYLINDER TWO

CUSTOMER COMPLAINT: REPLACE GASKET/ RESEAL 2 SWING CYLINDER CAUSE OF FAILURE:

WELD CRACKED

RESULTANT DAMAGE:

LEAKING OIL

REPAIR PROCESS COMMENTS:

PERFORM SEPD0776 - 00 SERVICE MAGAZING THE BARREL CAN CRACK AROUND WELD ON 191-8161 SWING CYLINDER TESTED BOTH CYLINDERS AT 3000 PSI ONE CYLINDER IS LEAKING OUT WELD THE OTHER PASSED GAVE A PRICE TO SUPERVISER CONTACT CUSTOMER SAID SEND BACK . CUSTOMER COMPLAINT:

REPLACE GASKET/ RESEAL 2 SWING CYLINDER

CAUSE OF FAILURE:

WELD CRACKED

RESULTANT DAMAGE:

LEAKING OIL

REPAIR PROCESS COMMENTS:

PERFORM SEPD0776 - 00 SERVICE MAGAZING THE BARREL CAN CRACK AROUND WELD ON 191-8161 SWING CYLINDER

PSO/WO

Customer#	PO#		Doc Date	Salesman	Division	Store	Terms
Name and Address of the Owner, where the Owner, which is the Own			10-31-18			1	4
Quantity	Item	De	scription		Unit Price		Extension

GREASE
INSTALLED HYDRAULIC CONNECTORS FROM OLD CYLINDERS
ON REMANUFACTURED CYLINDERS
INSTALLED REMANUFACTURED SWING CYLINDERS
INSTALLED HYDRAULIC HOSES
INSTALLED TOP PIVOT PLATE
INSTALLED ROD PINS IN BACKHOE ASSEMBLY
GREASED ASSEMBLY POINTS
CUSTOMER COMPLAINT:
SWING CYLINDERS LEAKING HYDRAULIC FLUID AT ROD
END
CAUSE OF FAILURE:
FAILED SEALS
RESULTANT DAMAGE:
LOW HYDRAULIC FLUID

REPAIR PROCESS COMMENTS: REMOVED ROD PINS IN BACKHOE ASSEMBLY REMOVED HYDRAULIC HOSES FROM CYLINDE HOSES FROM CYLINDERS AND CAPPED CONNECTOR ASSEMBLIES REMOVED TOP PIVOT PLATE REMOVED SWING CYLINDERS SENT SWING CYLINDERS TO OKC FOR TROUBLESHOOTING AND REPAIR DUE TO NON REPAIRABLE ISSUES WITH CYLINDERS, ORDERED REMANUFACTURED SWING CYLINDERS CLEANED PIVOT PLATE AND PIVOT POINTS ON FRAME OF GREASE INSTALLED HYDRAULIC CONNECTORS FROM OLD CYLINDERS ON REMANUFACTURED CYLINDERS INSTALLED REMANUFACTURED SWING CYLINDERS INSTALLED HYDRAULIC HOSES INSTALLED TOP PIVOT PLATE INSTALLED ROD PINS IN BACKHOE ASSEMBLY GREASED ASSEMBLY POINTS SEAL S 6 3K-0360 6V-8398 SEAL O RING S 6

381-8054

09131

2

INVOICE NUMBER:

11-29-18

Invoice Date:	11-25-10
Due	\$16,240.56
Make	AA
Model	420D
Serial #	0BLN08124
Equip No	
Machine ID	
Meter Reading	
PSO/WO	

ustomer#	PO#		Doc Date		Salesman	Division	Store	Terms
astollier i			10-31-18					4
Quantity	Item		escription			Unit Price		Extension
		SEGMENT	11 TOTAL					
REPLACE	WINDSHIELD							
1 1	64-1070	GLASS	N					
		TOTAL PA	RTS	SEG.	12			
1.00		WINDSHIE	LD					
		TOTAL MI	SC CHGS	SEG.	12			
		SEGMENT	12 TOTAL					

#### REMOVE & INSTALL SWING CYLINDER

CUSTOMER COMPLAINT: SWING CYLINDERS LEAKING HYDRAULIC FLUID AT ROD END CAUSE OF FAILURE: FAILED SEALS RESULTANT DAMAGE:

LOW HYDRAULIC FLUID
REPAIR PROCESS COMMENTS:
REMOVED ROD PINS IN BACKHOE ASSEMBLY
REMOVED HYDRAULIC HOSES FROM CYLINDERS AND CAPPED
CONNECTOR ASSEMBLIES
REMOVED TOP PIVOT PLATE
REMOVED SWING CYLINDERS
SENT SWING CYLINDERS TO OKC FOR TROUBLESHOOTING
AND REPAIR
DUE TO NON REPAIRABLE ISSUES WITH CYLINDERS,
ORDERED REMANUFACTURED SWING CYLINDERS
CLEANED PIVOT PLATE AND PIVOT POINTS ON FRAME OF

INVOICE NUMBER: 11-29-18 Invoice Date: \$16,240.56 Due AA Make 420D Model 0BLN08124 Serial # Equip No Machine ID Meter Reading **PSO/WO** 

Customer#	PO#	Doc Date	Salesman	Division Store	Store	Terms
		10-31-18				4
Quantity	Item	Description		Unit Price		Extension

F/R LBR

SEGMENT 10 TOTAL

REPAIR SWING LOCK

CUSTOMER COMPLAINT: LEVER MISSING TO ENGAGE BACKHOE SWING LOCK

CAUSE OF FAILURE: LEVER REMOVED BY PREVIOUS OWNER

RESULTANT DAMAGE:

NONE

REPAIR PROCESS COMMENTS:

INSTALLED LEVER WITH NEW HARDWARE

ATTACHED CABLE ASSEMBLY TO LEVER

TESTED LEVER AND LOCK ASSEMBLY LOCK NOW ENGAGING AND DISENGAGING

CUSTOMER COMPLAINT:

LEVER MISSING TO ENGAGE BACKHOE SWING LOCK

CAUSE OF FAILURE: LEVER REMOVED BY PREVIOUS OWNER

RESULTANT DAMAGE:

NONE

REPAIR PROCESS COMMENTS:

INSTALLED LEVER WITH NEW HARDWARE

ATTACHED CABLE ASSEMBLY TO LEVER

TESTED LEVER AND LOCK ASSEMBLY

LOCK NOW ENGAGING AND DISENGAGING

8T-6902 1 183-6081 CLIP

BOLT-M10

N N

183-6084 183-6085

BEARING BEARING N N

TOTAL PARTS

SEG. 11

F/R LBR

Customer # PO #	Doc Date	Salesman Division		Store	Terms	
	10-31-18				4	
Quantity	Item	Description		Unit Price		Extension

CAUSE OF FAILURE:
CORROSION OF HINGE FROM BATTERY FUMES
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
REMOVED BATTERY DOOR
CLEANED DIRT OUT OF BATTERY COMPARTMENT
REMOVED LATCH ASSEMBLY FROM OLD DOOR
INSTALLED LATCH ASSEMBLY ON NEW DOOR
INSTALLED BATTERY DOOR COVER

3 8T-4200 3 8T-4224 1 151-2963 BOLT S WASHER S COVER AS N

TOTAL PARTS

SEG. 09

F/R LBR

SEGMENT 09 TOTAL

REPAIR HANDLE SWITCH

CUSTOMER COMPLAINT:
REAR WINDOW LATCH NOT FUNCTIONING
CAUSE OF FAILURE:
BROKEN WINDOW RELEASE SWITCH
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
REMOVED WINDOW LATCHES
INSTALLED WINDOW LATCHES
ADJUSTED LATCH HASP

1 119-8349 CAP 1 164-1352 LATCH AS 1 164-1353 LATCH AS

TOTAL PARTS SEG. 10

N

N

N

INVOICE NUMBER: Invoice Date:	11-29-18
Due	\$16,240.56
Make	AA
Model	420D
Serial #	0BLN08124
Equip No	
Machine ID	
Meter Reading	
PSO/WO	Market Andrews

Customer#	PO#	O# Doc Date	Salesman	Division Store	Terms	
	10-31-18				4	
Quantity	Item	Description		Unit Price	:	Extension

REPLACED DOOR GAS SHOCK REMOVED LEFT SIDE OF HOOD REMOVED RIGHT SIDE OF HOOD

REMOVED FRONT AND REAR GAS SHOCKS INSTALLED FRONT AND REAR GAS SHOCKS INSTALLED RIGHT SIDE OF HOOD INSTALLED LEFT SIDE OF HOOD

1 8E-1118 2 114-8861 1 159-4269 ANTENNA AS S
PRING AS N
PRING AS-GA S

TOTAL PARTS

SEG. 08

F/R LBR

SEGMENT 08 TOTAL

REPLACE BATTERY COVER/LATCH

CUSTOMER COMPLAINT:
BATTERY COVER HINGE RUSTED SHUT AND BENT FROM
OPENING AND CLOSING
CAUSE OF FAILURE:
CORROSION OF HINGE FROM BATTERY FUMES
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
REMOVED BATTERY DOOR
CLEANED DIRT OUT OF BATTERY COMPARTMENT

REMOVED LATCH ASSEMBLY FROM OLD DOOR INSTALLED LATCH ASSEMBLY ON NEW DOOR INSTALLED BATTERY DOOR COVER CUSTOMER COMPLAINT:
BATTERY COVER HINGE RUSTED SHUT AND BENT FROM OPENING AND CLOSING

Customer#	PO#		Doc Date	Salesman	Division St	ore Terms
	AMOUNT DESCRIPTION OF THE PARTY		10-31-18			4
Quantity	Item	0	Description		Unit Price	Extension

INSTALLED NEW HORN SWITCH
TESTED VOLTAGE AT HORN AGAIN
VOLTAGE AT HORN BUT STILL NOT FUNCTIONING
REMOVED HORN
INSTALLED NEW HORN
HORN FUNCTIONING

F/R LBR

Meter Reading PSO/WO

SEGMENT 07 TOTAL

REPAIR SG GAS SHOCKS (ORD PCK)

CUSTOMER COMPLAINT:

HOOD NOT STAYING OPEN DUE TO WEAK GAS SHOCKS DOOR CLOSING DUE TO WEAK GAS SHOCK CAUSE OF FAILURE: FAILED GAS SHOCKS IN HOOD AND ON DOOR RESULTANT DAMAGE: NONE REPAIR PROCESS COMMENTS: REMOVED DOOR GAS SHOCK REPLACED DOOR GAS SHOCK REMOVED LEFT SIDE OF HOOD REMOVED RIGHT SIDE OF HOOD REMOVED FRONT AND REAR GAS SHOCKS INSTALLED FRONT AND REAR GAS SHOCKS INSTALLED RIGHT SIDE OF HOOD INSTALLED LEFT SIDE OF HOOF CUSTOMER COMPLAINT: HOOD NOT STAYING OPEN DUE TO WEAK GAS SHOCKS DOOR CLOSING DUE TO WEAK GAS SHOCK CAUSE OF FAILURE: FAILED GAS SHOCKS IN HOOD AND ON DOOR RESULTANT DAMAGE: NONE REPAIR PROCESS COMMENTS: REMOVED DOOR GAS SHOCK

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
		10-31-18				4
Quantity	Item	 Description		Unit Price		Extension

F/R LBR

SEGMENT 06 TOTAL

#### REPAIR HORN PLUGGER

CUSTOMER COMPLAINT:
HORN NOT FUNCTIONING
CAUSE OF FAILURE:
BAD HORN AND SWITCH
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
CHECKED FUSE FOR HORN
HORN FUSE WAS GOOD
TESTED VOLTAGE AT HORN WHEN SWITCHED PUSHED
NO VOLTAGE AT HORN
REMOVED HORN SWITCH
INSTALLED NEW HORN SWITCH
TESTED VOLTAGE AT HORN AGAIN
VOLTAGE AT HORN BUT STILL NOT FUNCTIONING
REMOVED HORN
INSTALLED NEW HORN

HORN FUNCTIONING
CUSTOMER COMPLAINT:
HORN NOT FUNCTIONING
CAUSE OF FAILURE:
BAD HORN AND SWITCH
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
CHECKED FUSE FOR HORN
HORN FUSE WAS GOOD
TESTED VOLTAGE AT HORN WHEN SWITCHED PUSHED
NO VOLTAGE AT HORN
REMOVED HORN SWITCH

INVOICE NUMBER:

11-29-18

ITIVOICE Date.	71.40
Due	\$16,240.56
Make	AA
Model	420D
Serial #	0BLN08124
Equip No	
Machine ID	
Meter Reading	
PSO/WO	

Customer#	PO#	Doc Date	Salesman	Division St	tore Terms
The State of the S		10-31-18			4
Quantity	Item	Description		Unit Price	Extension

INSTALLED HEADLINER
INSTALLED DOME LIGHT
INSTALLED RADIO
INSTALLED NEW WIPER BLADES FOR FRONT AND BACK
CUSTOMER COMPLAINT:
FRONT WINDSHIELD MISSING WIPER BLADE AND NOT
FUNCTIONING

REAR WINDSHIELD MISSING WIFER BLADE AND NOT FUNCTIONING CAUSE OF FAILURE: MISSING FUSES BROKEN REAR WIPER MOTOR RESULTANT DAMAGE: NONE REPAIR PROCESS COMMENTS: CHECKED FUSES FOR WIPER MOTORS FUSES MISSING INSTALLED NEW FUSES FRONT WIPER WORKING BUT REAR NOT WORKING REMOVED RADIO REMOVED DOME LIGHT REMOVED HEADLINER

REMOVED REAR WIPER MOTOR
INSTALLED NEW WIPER MOTOR
INSTALLED HEADLINER
INSTALLED DOME LIGHT
INSTALLED RADIO

INSTALLED NEW WIPER BLADES FOR FRONT AND BACK BOLT 8C-4982 N LLADE 101-0745 N HORN AS-12 V 164-9425 SWITCH AS. N 169-0587 N 197-8973 6 330-5026 MOTOR GP-WIP N

TOTAL PARTS

SEG. 06

INVOICE NUMBER: 11-29-18 Invoice Date: \$16,240.56 Due AA Make 420D Model 0BLN08124 Serial # Equip No Machine ID Meter Reading PSO/WO

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
A CONTRACTOR OF THE PARTY OF TH		10-31-18			_	4
Quantity	Item	Description		Unit Price		Extension

SEAT BELT EXPIRED CAUSE OF FAILURE: SEAT BELT EXPIRED RESULTANT DAMAGE: NONE REPAIR PROCESS COMMENTS: REMOVED SEATBELT INSTALLED SEATBELT 1 190-8919

HELT GP-SEAT N

TOTAL PARTS

SEG. 05

F/R LBR

SEGMENT 05 TOTAL

REPAIR WINDSHIELD WIPER MOTOR

CUSTOMER COMPLAINT: FRONT WINDSHIELD MISSING WIPER BLADE AND NOT FUNCTIONING REAR WINDSHIELD MISSING WIPER BLADE AND NOT FUNCTIONING CAUSE OF FAILURE: MISSING FUSES BROKEN REAR WIPER MOTOR RESULTANT DAMAGE: NONE REPAIR PROCESS COMMENTS: CHECKED FUSES FOR WIPER MOTORS FUSES MISSING INSTALLED NEW FUSES FRONT WIPER WORKING BUT REAR NOT WORKING REMOVED RADIO REMOVED DOME LIGHT REMOVED HEADLINER REMOVED REAR WIPER MOTOR INSTALLED NEW WIPER MOTOR

INVOICE NUMBER: 11-29-18 Invoice Date: \$16,240.56 Due AA Make 420D Model 0BLN08124 Serial # Equip No Machine ID Meter Reading PSO/WO

Customer#	PO#	Doc Date	Salesman	Division St	tore Terms
Deposite Control of the Control of t		10-31-18			4
Quantity	Item	Description		Unit Price	Extension

BROKEN SIGNAL LAMP LENS

CAUSE OF FAILURE: BROKEN LAMPS AND BULBS RESULTANT DAMAGE:

NONE

REPAIR PROCESS COMMENTS:

REMOVED BROKEN LAMPS INSTALLED NEW LAMPS

REMOVED BROKEN FRONT SIGNAL LENS

INSTALLED NEW SIGNAL LENS

BULB 2 7S-1800 105-8069 LAMP GP N N LAMP A 115-1716 S FLUG KIT 155-2270 N 174-8957 LENS N LAMP AS-FLOO 418-5542

TOTAL PARTS

SEG. 04

F/R LBR

SEGMENT 04 TOTAL

REPLACE SEAT BELT

CUSTOMER COMPLAINT: SEAT BELT EXPIRED

CAUSE OF FAILURE: SEAT BELT EXPIRED RESULTANT DAMAGE: NONE REPAIR PROCESS COMMENTS: REMOVED SEATBELT

INSTALLED SEATBELT CUSTOMER COMPLAINT:

INVOICE NUMBER: Invoice Date:	11-29-18			
Due	\$16,240.56			
Make	AA			
Model	420D			
Serial #	0BLN08124			
Equip No				
Machine ID				
Meter Reading				
PSO/WO				

stomer#	PO#		Doc Date	Salesman	Division Store	Terms	
Color Marie Color			10-31-18			4	
Quantity	Item	Des	cription		Unit Price	Extensio	
1 5P- 1 5P- 1 5P- 1 5P- 2 8T- 1 9U- 1 148	D LOWER DASH	PLATE	N N S N N N				
	3 - 8 4 9 3 3 - 8 6 4 4	HOSE AS HOSE AS	N N	SEG. 03			
		SEGMENT (	3 TOTAL	F/R LBR			

#### REPAIR LIGHTS

CUSTOMER COMPLAINT:
LIGHTS NON FUNCTIONING FRONT AND BACK
BROKEN SIGNAL LAMP LENS
CAUSE OF FAILURE:
BROKEN LAMPS AND BULBS
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
REMOVED BROKEN LAMPS
INSTALLED NEW LAMPS
REMOVED BROKEN FRONT SIGNAL LENS
INSTALLED NEW SIGNAL LENS
CUSTOMER COMPLAINT:
LIGHTS NON FUNCTIONING FRONT AND BACK

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
And a second second		10-31-18				4
Quantity	Item	Description		Unit Price	3	Extension

HYDRAULIC LEAKS FOUND UNDER HYDRAULIC TANK CAUSE OF FAILURE: CORRODED HYDRAULIC HOSES LOOSE HOSE CLAMPS ON HYDRAULIC TANK RESULTANT DAMAGE: NONE REPAIR PROCESS COMMENTS: REMOVED CORRODED HYDRAULIC BACKHOE BUCKET HOSES INSTALLED NEW HYDRAULIC BACKHOE BUCKET HOSES REMOVED CORRODED HYDRAULIC FRONT LOADER HOSES INSTALLED NEW HYDRAULIC FRONT LOADER HOSES REMOVED RUBBER FLOOR MAT REMOVED FLOOR PLATE REMOVED LOWER DASH COVER REMOVED LOWER DASH PLATE TIGHTENED HOSE CLAMPS ON HYDRAULIC TANK INSTALLED FLOOR PLATE INSTALLED LOWER DASH PLATE INSTALLED LOWER DASH COVER INSTALLED RUBBER FLOOR MAT CUSTOMER COMPLAINT: HYDRAULIC HOSES CORRODED HYDRAULIC LEAKS FOUND UNDER HYDRAULIC TANK

CORRODED HYDRAULIC HOSES
LOOSE HOSE CLAMPS ON HYDRAULIC TANK
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
REMOVED CORRODED HYDRAULIC BACKHOE BUCKET HOSES
INSTALLED NEW HYDRAULIC BACKHOE BUCKET HOSES
REMOVED CORRODED HYDRAULIC FRONT LOADER HOSES
INSTALLED NEW HYDRAULIC FRONT LOADER HOSES
INSTALLED NEW HYDRAULIC FRONT LOADER HOSES
INSTALLED NEW HYDRAULIC FRONT LOADER HOSES
REMOVED RUBBER FLOOR MAT
REMOVED FLOOR PLATE
REMOVED LOWER DASH COVER
REMOVED LOWER DASH PLATE
TIGHTENED HOSE CLAMPS ON HYDRAULIC TANK

CAUSE OF FAILURE:

INVOICE NUMBER: 11-29-18 Invoice Date: \$16,240.56 Due AA Make 420D Model 0BLN08124 Serial # Equip No Machine ID Meter Reading PSO/WO

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
		10-31-18				4
Quantity	Item	Description		Unit Price		Extension

NONE

RESULTANT DAMAGE:

NONE

REPAIR PROCESS COMMENTS: DRAINED ENGINE, HYDRAULIC AND TRANSMISSION OIL REMOVED ENGINE OIL, HYDRAULIC, TRANSMISSION AND

FUEL FILTERS REPLACED FILTERS FILLED OILS INSTALLED NEW TRANSMISSION DIPSTICK ALTERNATOR BELT SET LOOSE REPLACED ALTERNATOR BELTS

EFI	TACED ALTERNATOR	CDEDIO	**
1	4N-8597	VEE BELT SET	N
1	7W-2326	FILTER A	S
1	101-3743	SEAL	S
+	7W-2326 101-3743 104-8566 110-6326	CAGE A	N
7	104-8366	MAIN ELEMENT	S
1	110-6326		0
1	110-6331	ULEMENT	5
2	159-6102	ELEMENT	S
2 2 1	275-9883	CEAL	8888
7	465-6505	FILTER HYDR	S
т.		FILTER HYD	S
1	471-7003		
6	2487521X	OW TDTO 1GAL	S
13	3096932X	OILCAT HYDRO, 1	GLS
2	5153973X	15W40 DEO(ULS)	LGLS

TOTAL PARTS

SEG. 02

F/R LBR

SEGMENT 02 TOTAL

REPAIR HYDRAULIC LEAK(S)

CUSTOMER COMPLAINT: HYDRAULIC HOSES CORRODED

INVOICE NUMBER: Invoice Date:	11-29-18
Due	\$16,240.56
Make	AA
Model	420D
Serial #	0BLN08124
Equip No	
Machine ID	
Meter Reading	
BSOMIO	

ustomer#	PO#		Doc Date	Salesman	Division Store	Terms
atropation to the second	Aller and the Auto-Consequence of the Consequence o		10-31-18			4
Quantity	Item	Description	on		Unit Price	Extension
CUSTOM QUOTE	ER	EATE LIST OF ISSUES : SERVICE AND REPAIRS FUSE-MINI	FOR			
		TOTAL PARTS	SEG.	01		
		TOTAL LABOR	SEG.	01		
1.00		SUPPLIES				
		TOTAL MISC C	HGS SEG.	01		
		SEGMENT 01	TOTAL			

#### PERFORM 500 SVC HOUR MAINT

CUSTOMER COMPLAINT:
CUSTOMER WANTED 500 HOUR SERVICE PERFORMED
CAUSE OF FAILURE:
NONE
RESULTANT DAMAGE:
NONE
REPAIR PROCESS COMMENTS:
DRAINED ENGINE, HYDRAULIC AND TRANSMISSION OIL
REMOVED ENGINE OIL, HYDRAULIC, TRANSMISSION AND
FUEL FILTERS
REPLACED FILTERS
FILLED OILS
INSTALLED NEW TRANSMISSION DIPSTICK
ALTERNATOR BELT SET LOOSE
REPLACED ALTERNATOR BELTS
CUSTOMER COMPLAINT:
CUSTOMER WANTED 500 HOUR SERVICE PERFORMED
CAUSE OF FAILURE:

Customer#	PO#		Doc Date	Salesman	Division	Store	Terms
			10-31-18				4
Quantity	Item	D	Description		Unit Price		Extension

#### PROFORMA INVOICE

#### TROUBLESHOOT MACHINE

CUSTOMER COMPLAINT: CUSTOMER WANTED LIST OF ISSUES WITH MACHINE AND SERVICE PERFORMED CAUSE OF FAILURE: WINDSHIELD CRACKED SWING CYLINDERS LEAKING OIL HYDRAULIC LINES WORN HYDRAULIC LINES FROM TANK LEAKING NON FUNCTIONING LIGHTS, FRONT AND BACK BROKEN TURN SIGNAL LENS HORN AND HORN SWITCH NON FUNCTIONING GAS SHOCKS FOR HOOD AND LEFT DOOR NON FUNCTIONING BATTERY COVER RUSTED CLOSED LEVER FOR SWING LOCK NOT INSTALLED REPAIR PROCESS COMMENTS: EXAMINE MACHINE TO CREATE LIST OF ISSUES FOR CUSTOMER QUOTE CREATED FOR ALL SERVICE AND REPAIRS CUSTOMER COMPLAINT: CUSTOMER WANTED LIST OF ISSUES WITH MACHINE AND SERVICE PERFORMED CAUSE OF FAILURE: WINDSHIELD CRACKED SWING CYLINDERS LEAKING OIL

HYDRAULIC LINES WORN
HYDRAULIC LINES FROM TANK LEAKING
NON FUNCTIONING LIGHTS, FRONT AND BACK
BROKEN TURN SIGNAL LENS
HORN AND HORN SWITCH NON FUNCTIONING
GAS SHOCKS FOR HOOD AND LEFT DOOR NON FUNCTIONING
BATTERY COVER RUSTED CLOSED
LEVER FOR SWING LOCK NOT INSTALLED
REPAIR PROCESS COMMENTS: