

Invoice

Estimate Ref:

Date Printed: 08/11/2017

Printed Time: 10:41 am

Time Promised: 8/11/2017 6:48:35 AM

Hav/Ref:

2014 RAM 5500 6.7L

VIN: 3C7WRNFL5EG131512

License:

Mileage In: 130,633

Date Written:

07/27/2017

Unit #: 24

Mileage Out: 130,662

DOM:

Cell:

Job Name	Description	Technician	Qty	List	Extended
Job #1	Customer states there is an engine noise.				0.00
Labor P.E.C.	Work Requested - Customer states there is an engine noise.				
	Work Performed - Inspected and found that the engine had an internal failure causing low compression. Removed and replaced the engine with a long block.				
	During repairs we found that the upper radiator had a crack in the bottom left corner, the fan hub bearing was making noise, and the lower radiator hose had a small tear in it.				
	Assembled the vehicle, filled with fluids and test drove the vehicle.				
Labor P.E.C.	Work Requested - ENGINE - Replace - Long Block - Includes: R&I Engine And Replacement Of All Necessary Components.				
Labor P.E.C.	Work Requested - With After Market Grill Guard - ADD				
Part 15w-40	15w-40		13.00		
Part ANT 501	Coolant Red		3.00		
Part 008130-AZ	Brake Clean		1.00		
Part 68005334AB	Exhaust Manifold to turbo Charger Gasket 6.7L		1.00		
Part 5135789AB	Exhaust Manifold Gasket		6.00		
Part R8229037AB	Long Block		1.00		
Part S3976-AZ	Oil Filter Cummins DSL		1.00		
Part 68157291AA-LC	Fuel Filter 6.7L 2013-Present-53		1.00		
Part 52014723AD	Lower Radiator Hose		1.00		
Part 4428639	Bearing Fan Hub		1.00		
Part 38285	Belt Tensioner Assembly		1.00		
Part 68024672AB	Intake Horn Gasket for 6.7L		1.00		
Part 52014720AA	Radiator		1.00		
Part Automachine	Exhaust Manifold Resurface		1.00		
Part 134ra	134-RA		2.00		
Part 55056966AA	Hose		1.00		
Part 82300234AC	Gear Sealant		1.00		
Part 008130-AZ	Brake Clean		1.00		
Part ATF+4	ATF+4		1.00		

Job Total:

Recommendations

Job Name	Description	Recommended Date	Mileage
Job #4	During repairs we discovered the air charge line at the turbo has almost had the air filter housing rub thru the line.	7/12/2015 12:00:00AM	8,000

Invoice

Estimate Ref:

Date Printed: 08/11/2017

Printed Time: 10:41 am

Hav/Ref:

Time Promised: 8/11/2017 6:48:35 AM

2014 RAM 5500 6.7L

VIN: 3C7WRNFL5EG131512

License: 501428 #24

Mileage In: 130,633

Date Written: 07/27/2017

Unit #: 24

Mileage Out: 130,662

DOM:

Payment Date	Type	Method	Amount
--------------	------	--------	--------

Parts:

Labor:

Sublet:

Misc:

Hazmat: *

Supplies: *

Tax Total:

Invoice Total: **\$21,609.92**

INVOICE

Org. Est. #
ASE Master Certified

Invoice from History

Work Completed : 12/04/2019

Date: 12/04/2019

2014 RAM - 5500 - 6.7L

Lic # : 501428 #24

Odometer In : 224068

Unit # : 24-MATT

VIN # : 3C7WRNFL5 EG131512

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Ext
					Customer states the vehicle has a noise under the vehicle and the truck tracks sideways when going down the road. Inspected and found that the front pinion is loose in the front axle. The tracking problem is because the thrust angle of the rear axle has changed.	
Org. Estimate 0.00				Revisions 0.00	Current Estimate 0.00	

Labor:

Parts:

SubTotal:

Tax:

Total:

Bal Due:

[Payments -]