

Repair Order

Vehicle : 1995 MCI COACH
 VIN : 1M8PDMPA6SP047103
 Fleet # : CM15086
 : 10/29/2018 3:37:47 PM

Last Mileage : 0
 Fleet Driver :
 Odometer In : 0
 Odometer Out : 0

Parts

Qty	Code/Tech*	Description	Condition	Unit Price	Price
1		BAGGAGE DOOR 2.5" RUB RAIL			
1		2.5" RUB RAIL BETWEEN DOORS			
1		2.5" RUB RAIL REAR OF REAR			
2		2.5" RUB RAIL REAR SIDE SERVICE DOOR			
2		2.5" RUB RAIL REAR OF REAR SERVICE DOOR			
1		2.5" RUB RAIL REAR SIDE SERVICE			
1		CAP FRONT OF COND. DOOR RUB RAIL			
7		2.5" RUB RAIL END CAP			

Sublet/Misc.

Qty	Code/Tech*	Description	Unit Price	Price
1		DRIVER'S/PASSENGER SIDE GLASS		
1		COMPLETE PAINT/WHITE AND BLACK		

INSTALL NEW MCI FIBERGLASS FRONT END AND HEADLIGHT UPGRADE/NEW BODY STYLE.

Labor

Parts

Sublet/Misc.

Shop Supplies

Charges

Sales Tax

Tax Exempt

Repair Total

\$15,531.61