

INVOICE

20499

INVOICE

Print Date : 05/24/2011

2005 Ford - Pickup F250 Super Duty

6.0L, V8, VIN (P)

Lic # : 46-902

Odometer In : 186976

Unit # : 5R110W OE RF

Vin # : 1FTSX21P35EB32420 4X4

Hat # : CV

Ref # : WHITE

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
PARTS TO REBUILD TRANSMISSION w/ TORQUE CONVERTER.				REBUILD TRANSMISSION	
5R55EL	1.00			TEAR DOWN, CLEAN & INSPECT. PERFORM	
MERCON SP				ALL UPDATES AND REPLACE NECESSARY	
FLUID	21.00			PARTS.	
TRANSFER CASE FLUID - MOBIL 1				R&R LABOR	
SYN				REMOVE & REPLACE LABOR	
TC	3.00			Warranty on this work is 12 months or 12,000	
Shop Supplies				miles, whichever comes first. Specifications on	
				attached warranty form must be adhered to.	
				PLEASE NOTE: Any other parts that are installed	
				not pretaining to the transmission, listed on this	
				invoice, are not covered under this	
				warranty and there are no labor claims.	
				Transmission repair is intricate work. While we	
				strive to perform our work properly, occasionally	
				leaks do appear. Please check for leaks the first few	

Unit # : 5R110W OE RF

Vin # : 1FTSX21P35EB32420 4X4

Hat # : CV

Ref # : WHITE

Part Description / Number	Qty	Sale	Extended	Labor Description	Exten
PARTS TO REBUILD TRANSMISSION w/ TORQUE CONVERTER.				REBUILD TRANSMISSION	
5R55EL	1.00			TEAR DOWN, CLEAN & INSPECT. PERFORM ALL UPDATES AND REPLACE NECESSARY PARTS.	
MERCON SP				R&R LABOR	
FLUID	21.00			REMOVE & REPLACE LABOR	
TRANSFER CASE FLUID - MOBIL 1				Warranty on this work is 12 months or 12,000 miles, whichever comes first. Specifications on attached warranty form must be adhered to.	
SYN				PLEASE NOTE: Any other parts that are installed not pertaining to the transmission, listed on this invoice, are not covered under this warranty and there are no labor claims.	
TC	3.00			Transmission repair is intricate work. While we strive to perform our work properly, occasionally leaks do appear. Please check for leaks the first few weeks and notify us immediately if any are discovered. Your trust and business is greatly appreciated.	
Shop Supplies				ENVIRONMENTAL FEE	
Pd. ^{Ch} 62263 5-24-11					
[Technicians : Please Select, Technician]					

Org. Estimate \$0.00

Revisions \$0.00

Current Estimate \$ 0.00

Additional Cost

Revised Estimate

Labor:

Labor/Notes

Qty	Code/Tech*	Reference	Description
7	CN*	96	SHOP REPAIR LABOR
FOUND VEHICLE RUNNING ROUGH.....CODES PRESENT FOR #7 AND #8 CYLINDER CONTRIBUTION FA BOOST PRESSURE NO DETECTED.....REPLACED ALL 8 FUEL INJECTORS, STAND PIPES, AND DUM PLUGS.....CLEARED CODES.....FILLED WITH COOLANT AND NEW DEGAS BOTTLE CAP.....TEST DROVE.....ALL OK AT THIS TIME			
FOUND RF CALIPER/HOSE SIEZED UP.....REPLACED CALIPER AND HOSE.....FOUND COOLANT DEG HAS CRACK IN IT.....REPLACED BOTTLE AND FILLED WITH COOLANT			

Parts

Qty	Code/Tech*	Reference	Description	Condition	Un
2	-	6E7Z-9A332-A	FUEL TUBE		
2	-	3C3Z-6584-BA	GASKET		
2	-	W302908	FUEL TUBE		
8	-	4C3Z-9E527-BRM	INJECTOR		
2	-	53-S	ANTI-FREEZE (STATION BULK)		
1	NOE	81953401	Coolant Reservoir Cap		
1	CAL	SE5573A	Brake Caliper w/ Hardware - Right Front (Eclipse		
1	-	CORE	Core Charge		
1	-	CORECREDIT	Core Credit		
1	UP	609617	BRAKE HOSE		
1	NOE	6051843	Pressurized Coolant Reservoir		

Labor

Parts

Sublet/Misc.

Supplies/Enviro Fees

Charges

Sales Tax

- ✓ Antilock Brakes
- ✓ Instrument Cluster Module
- ✓ Airbag
- ⚠ OBDII

Engine - Memory Codes

P0401 | EGR Insufficient Flow Detected
P0674 | Cylinder 4 Glow Plug Circuit
P0675 | Cylinder 5 Glow Plug Circuit

Transmission

Antilock Brakes

Instrument Cluster Module