

Invoice Date
5/28/2019

Invoice # _____

INVOICE

**PLEASE PAY
THIS AMOUNT**

\$4,922.84

Make checks payable to:

☐ Please check box if address is incorrect or has changed and
indicate on back of invoice

Invoice

DESCRIPTION	UNIT PRICE	QTY	TOTAL
-------------	------------	-----	-------

Ecm diagnostics and repair <i>Volvo with ISX. Uprate to 500hp, speed limiter 80mph</i>			
---	--	--	--

SUBTOTAL

TOTAL

PAID

DUE \$1,750.00

Invoice Date

12/12/2019

Invoice #

INVOICE**PLEASE PAY
THIS AMOUNT**

\$1,378.01

Make checks payable to:

☐ Please check box if address is incorrect or has changed, and indicate change(s) on reverse side.

Have E-Mail? Please write it here: _____

PLEASE DETACH AND RETURN TOP PORTION WITH PAYMENT

		VIN#	Hours/Miles/Unit #	
		9N275478	850,878/ 01	
P.O. No.	Terms	Year/Make/Model	Driver's Name/Phone #	
		2009 Volvo		
Description		Qty	Rate	Amount
The drive shaft was rubbing on the frame of the truck. Checked it over and found the drivers front drive axle spring hanger was missing bushing and was worn out causing the frame to sit too low. Removed the spring hanger. While removing the spring hanger it was necessary to remove the bushing from the spring. It had rusted solid and the bolt would not release. Removed and replaced the spring bushing and spring hanger with other components and found the frame to sit high enough that it wouldn't hit the driveline. 5027		6		
Wheel Nut		2		
Spring Bracket		1		
Wear Plate		1		
Spacer		1		
Split Pin		1		
Spring Bushing		1		
Hardware		1		
Spring Bushing Stud Bolt		8		
Sales Tax		1		
Total				\$1,378.01
Balance Due				