

D G 2617

Invoice #
10588DATE
10-30-2017

NAME:LRM

HPHONE:
WPHONE:TAG:NO TEMP21
YR:2005 MAKE:STERLING
MODEL:MIXER
MILEAGE:
MOTOR:
VIN:AV43175PO NUMBER:
MANUF:

NOTES:

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
L	FULL SERVICE AND LUBE	1.00		0	289.99
4707	BRAKE KIT	1.00		0	89.99
47697	SEAL	1.00		0	69.59
L	REMOVE AND REPLACE WHEEL SEAL AND BRAKE KIT	2.00		0	190.00
6598	AIR FILTER	1.00		0	89.99
L	ADJUST BRAKES	3.00		0	36.00

I hereby authorize the repair work hereafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purposes of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs hereto.

Parts	249.57
Labor	515.99
Subtotal	765.56
COLORADO TAX	37.23
Non Taxable	0.00

Total 802.79

Charge 802.79

Signature X

Attn: All Tire Customers Lugnuts Must Be Retorqued After 50 Miles

DG2617

Invoice #
10942

DATE
12-26-2017

NAME:LRM

HPHONE:
WPHONE:

PO NUMBER:
MANUF:

TAG:NO TEMP21
YR:2005 MAKE:STERLING
MODEL:MIXER
MILEAGE:
MOTOR:
VIN:AV43175

NOTES:

PART#	DESCRIPTION	QTY	PRICE	DISC	TOTAL
1035	AIR FITTINGS	1.00		0	68.59
F2DZ11654	HEAD LIGHT SWITCH	1.00		0	215.59
F8TB13K359AB	MULTI FUCTIONING SWITCH	1.00		0	137.59
6511	AIR TANK	1.00		0	207.59
L	REMOVE AND REPLACE AIR TANK AND FITTINGS	2.00		0	190.00
L	TRACK DOWN SHORTED WIRES REPAIR WIRES REPLACE HEADLIGHT SWITCH AND TURN SIGNAL SWITCH, TRUCK NEEDS CLUSTER IN DASH REPLACED, GUAGES DO NOT WORK	3.00		0	285.00

PD CK.2020

\$6811.47

Parts
n Labor
y Subtotal
COLORADO TAX
Non Taxable
n -----
Total 1147.7
Charge 1147.7