

## Service Invoice

Customer PO #:

Benco Machinery, LLC 7600 N Bryant Ave. Oklahoma City, OK 73121 P.405.486.7789

Customer Number:	
10019	

Work Order #:	18001028
Date Opened:	8/11/2019
Date Closed:	9/1/2019
Tech:	ΔD

Cu	istomer Info:
E	Benco Machinery, LLC
7	7600 N. Bryant Ave
(	Oklahoma City, OK 73121
_	

Location of Repair:	
Pittsburg County, OK	

Make	Model	Serial Number	Hours In	Hours Out
CAT	D6M	4JN00885	6532	6533

## Service requested:

Calibrate brakes, install GPS and replace track roller

Work Order Summary per segment:	Travel Labor	Parts	Repair Labor	Mileage	Segment Total
<b>01</b> ] Calibrated the service brakes	\$259.00	\$0.00	\$97.00	\$486.00	\$842.00
02] Installed GPS unit	\$0.00	\$139.94	\$0.00	\$0.00	\$139.94
03] Replaced track roller	\$0.00	\$285.59	\$24.25	\$0.00	\$309.84
				Total	\$1,291.78

Work Performed 1]	/ork Performed 1]		Part #		Description		Quantity	Price
Calibrated service brakes								
	Hours/Mileage		Rate		Total		Parts Total	\$0.00
Travel Labor	3.5	\$	74.00		\$259.00		Travel Labor	\$259.00
Mileage	162	(	\$3.00		\$486.00		Mileage	\$486.00
Repair Labor	1	\$	97.00		\$97.00		Repair Labor	\$97.00

Work Performed 2]			Part #	Descr	iption	Quantity	Price
Installed GPS unit		2	21676888	GPS Device		1	\$139.94
	Hours/Mileage	R	late	Total		Parts Total	\$139.94
Travel Labor				\$0.00		Travel Labor	\$0.00
Mileage				\$0.00		Mileage	\$0.00
Repair Labor				\$0.00		Repair Labor	\$0.00

Work Performed 3]		Part #	Desci	ription	Quantity	Price
Replaced track roller.		CR6153	D/F Roller G	р	1	\$270.59
Replaced track folici.		6V-3303	Bolt		4	\$10.64
		5P-8247	Washer		4	\$4.36
	Hours/Mileage	Rate	Total		Parts Total	\$285.59
Travel Labor			\$0.00		Travel Labor	\$0.00
Mileage			\$0.00		Mileage	\$0.00
Repair Labor	0.25	\$97.00	\$24.25		Repair labor	\$24.25

## **Explanation of work performed:**

SEG. 01: I raised the machine into the air and blocked. I performed the service brake calibration with CAT ET. Then I put the machine back down on the ground and tested the brakes. Brakes are now working correctly.

SEG. 02: One of Bennett's techs installed GPS unit on the machine.

SEG. 03: While performing the brake calibration, I found that the center roller on the right track was loose from the roller frame and was damaged. I looked up the parts needed and ordered them. I sent the parts to the jobsite for the Bennett tech there to

Due Date	NA
Please Pay This Amount	\$1,291.78