

CASE IH 4410 SN: JFG0007284 HR (5167.0 W:00)
Sold By: 999 PO #: 1119081 Date 6/19/19 WORK ORDERS WK00730
Ship By: Tax #: Open

Work Order Summary

- 01 REPLACE KNEE JOINTS
- 02 REPLACE BOOM WIRING HARNESS
- 03 REPLACE RIGHT HAND STEERING CYLINDER
- 04 REPLACE J-ARM AND BUSHING
- 05 REPLACE RIGHT HAND SWING WELDMENT
- 06 REPLACE BACK RACK WEAR PADS
- 07 REPLACE BOOM TIP FOLD PADS
- 08 RESEAL ENGINE OIL COOLER
- 09 REPLACE ALTERNATOR
- 10 REPLACE REAR SHOCKS
- Other Charges

** TOTAL 4979.75

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

Group: 11

01 REPLACE KNEE JOINTS

REBUILT ALL FOUR KNEE JOINTS. HAD TO PRESS ALL THE OLD PINS OUT AND LOWER THE BOTTOM STRUT. CLEANED ALL THE GREASE OUT, INSTALLED NEW PINS AND BUSHINGS.

LABOR

** TOTAL LABOR

* SEGMENT SUBTOTAL

CASE IH 4410 SN: JFG0007284 HR 5167.0 W:00
 Sold By: 999 PO #: 1119081 Date 6/19/19 WORK ORDERS WK00730
 Ship By: Tax #: Open

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

02 REPLACE BOOM WIRING HARNESS

THE BOOM WIRING HARNESS CONNECTORS AND WIRES WERE CRACKING. INSTALLED NEW HARNESS AND CHECKED OPERATION.

LABOR

** TOTAL LABOR

* SEGMENT SUBTOTAL

03 REPLACE RIGHT HAND STEERING CYLINDER

THE RIGHT HAND STEERING CYLINDER WAS LEAKING AND THE ROD WAS PITTED SO IT COULD NOT BE RESEALED. REMOVED THE OLD CYLINDER AND INSTALLED A NEW ONE.

LABOR

** TOTAL LABOR

* SEGMENT SUBTOTAL

04 REPLACE J-ARM AND BUSHING

REPLACED THE RIGHT HAND J-ARM WITH NEW BOLTS.

LABOR

** TOTAL LABOR

* SEGMENT SUBTOTAL

CASE IH 4410 SN: JFG0007284 HR 5167.0 W:00
 Sold By: 999 PO #: 1119081 Date 6/19/19 WORK ORDERS WK00730
 Ship By: Tax #: Open

Tax	D	Qty	Description -----*	Price	Amount
05 REPLACE RIGHT HAND SWING WELDMENT					
THE RIGHT HAND SWING WELDMENT WAS BREAKING. UNHOOKED THE BOOM AND REMOVED THE SWING WELDMENT. INSTALLED A NEW WELDMENT.					
LABOR					
** TOTAL LABOR					
* SEGMENT SUBTOTAL					
06 REPLACE BACK RACK WEAR PADS					
REPLACE WEAR PADS ON THE BACK RACK.					
LABOR					
** TOTAL LABOR					
* SEGMENT SUBTOTAL					
07 REPLACE BOOM TIP FOLD PADS					
THE PADS AND SHIMS FOR THE TIP FOLD WERE BROKEN AND SMASHED. REMOVED OLD PARTS AND INSTALLED NEW ONES.					
LABOR					
** TOTAL LABOR					
* SEGMENT SUBTOTAL					

CASE # 4410 SN: JFG0007284 HR 5167.0 W:00
 Sold By: 999 PO #: 1119081 Date 6/19/19 WORK ORDERS WK00730
 Ship By: Tax #:
 Open

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

08 RESEAL ENGINE OIL COOLER

THE ENGINE OIL COOLER WAS LEAKING OIL. DRAINED COOLANT, DISASSEMBLED OIL COOLER AND REPLACED GASKETS.

LABOR

** TOTAL LABOR

* SEGMENT SUBTOTAL

09 REPLACE ALTERNATOR

THE ALTERNATOR WAS NOT CHARGING. CUSTOMER GOT A NEW ALTERNATOR AND I INSTALLED. RAN CHECKED OPERATION.

LABOR

** TOTAL LABOR

* SEGMENT SUBTOTAL

10 REPLACE REAR SHOCKS

REPLACED THE BACK SHOCKS. REMOVED THE OLD ONE AND INSTALLED NEW REAR SHOCKS.

LABOR

** TOTAL LABOR

***PLEASE PAY FROM THIS INVOICE - NO STATEMENT WILL BE SENT**

* SEGMENT SUBTOTAL