

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:	
	Invoice Date:	5/29/2020
	Location:	
	Work Order Number:	
	Payment Type:	
	Page:	1 of 1

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R		1RW8370REFD103356	GL103356	

/Gen-Hydraulic Retail

COMPLAINT:

01 Hydraulic Repairs
hydraulic oil filter code.

CORRECTION:


replaced sensor, code went away

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE591430	SENSOR	1.00				

Miscellaneous Charges:
Service Accessories

Customer PO No:
Tax Exempt No:
Advisor:

Labor:
Parts:
OL&M:
Misc:
Sales Tax:
Grand Total: \$174.17



REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:			
	Invoice Date:	3/6/2019		
	Location:			
	Work Order Number:			
	Payment Type:			
	Page:	1 of 2		
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	2104	1RW8370REFD103356	GL103356	

/Gen-Engine Warranty

COMPLAINT:

Machine was throwing
VGT codes 2795.03, .04 and .07
RE549136
engine
FM electrical
Failure date 2/21/19


1.2 diagnose
6 repair

CAUSE:

Turbocharger and turbo position sensor failed.

CORRECTION:

Diagnosing showed turbo and sensor had both failed.
Replaced turbo and turbo sensor.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7865	SCREW	1.00				
19M7868	SCREW	1.00				
24M7298	WASHER	1.00				
51M7095	O-RING	1.00				
R318954	GASKET	1.00				
R528247	O-RING KIT	1.00				
R534121	CAP SCREW	4.00				
R535094	Gasket	1.00				
R538777	GASKET	1.00				
R56466	O-RING	1.00				
R63548	O-RING	1.00				
R86588	O-RING	2.00				
RE285844	CLAMP	1.00				

CONTINUED ON NEXT PAGE->

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:	
	Invoice Date:	3/6/2019
	Location:	
	Work Order Number:	
	Payment Type:	
	Page:	2 of 2

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	2104	1RW8370REFD103356	GL103356	

/Gen-Engine Warranty

RE549136	Turbocharger	1.00
RE549136-CR	CORE for Turbocharger	-1.00
RE572398	Vane Position Sensor	1.00
T15712	O-RING	2.00
TY26101	Brake & Parts Cleaner	1.00

INVOICE CONTAINS \$6.51 DISCOUNT

Customer PO No:
Tax Exempt No:
Advisor:

Labor:	
Parts:	
OL&M:	
Misc:	
Sales Tax:	
Grand Total:	\$4,226.81



REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:			
	Invoice Date:	2/20/2019		
	Location:			
	Work Order Number:			
	Payment Type:			
	Page:	1 of 1		
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	2104	1RW8370REFD103356	GL103356	

/WARRANTY JOB CODE-1 Warranty

COMPLAINT:

fan drive and driven are leaking.

RE578435

FM 14 leaking.

Failure date 2/15/19

.85 diagnose

7.58 repair

CAUSE:

fan drive and driven were shot

CORRECTION:

took drives off and put new paddle style on.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572545	Fan Driven Assy 9.0L FT4 - Dry	1.00				
RE578435	Fan Driver Assy, 9.0L FT4- Dry	1.00				

Labor:
Parts:
OL&M:
Misc:
Sales Tax:
Grand Total: \$3,350.44

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:			
	Invoice Date:	2/20/2019		
	Location:			
	Work Order Number:			
	Payment Type:			
	Page:	1 of 4		
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	2104	1RW8370REFD103356	GL103356	

/WINTERSPECIAL Retail

COMPLAINT:

01 OPENING JOB CODE FOR WINTER SERVICE SPECIALS.

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY25684	CLASSIC GLASS CLEANER	1.00				
DRC4601	56ct ROLL TOWELS SINGLE ROLL	1.00				
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
3970	SERVICE LABOR DISCOUNT	1.00				
5267	ADVERTISE/PROMO-MONTEZUMA PARTS & SERV	2.00				
5280	MFG-WARRANTY DIFFERENCE-ALL DEPTS	1.00				

Comments: Extended warranty deductible

/ROWCROPINSPECTION Retail

COMPLAINT:

02 ULTIMATE PERFORMANCE INSPECTION ROW CROP TRACTORS

CORRECTION:

ENGINE
COOLING SYSTEM
ELECTRICAL
POWER TRAIN
STEERING & BRAKES
HYDRAULIC SYSTEM
OPERATOR'S STATION

/TRACTORCAB Retail

COMPLAINT:

CONTINUED ON NEXT PAGE->

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:	
	Invoice Date:	2/20/2019
	Location:	
	Work Order Number:	
	Payment Type:	
	Page:	2 of 4

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	2104	1RW8370REFD103356	GL103356	

/TRACTORCAB Retail
03 Operator Station Repairs

CORRECTION:
steering pivot was very loose, found a loose bolt and tightened it,

/TRACTORENGINE Retail
COMPLAINT:
04 Engine Repairs

CORRECTION:
put on a new fan belt, replaced aux tensioner, put in new bolt.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7865	SCREW	1.00				
R222393	V-BELT - FAN DRIVE	1.00				
RE582501	Bolt Tensioner	1.00				

/TRACTORHYDRAULIC Retail
COMPLAINT:
06 Hydraulic Repairs

CORRECTION:
tractor had a oil leak on LH side by hydraulic pump, took rear duals off , ordered 2 new lines and 2 fittings and put them on.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
61M5016	Elbow Fitting	1.00	8.03	8.03	80.03	1
RE583345	HYDRAULIC	1.00				
RE583681	CHECK VALV	1.00				

CONTINUED ON NEXT PAGE->

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:	
	Invoice Date:	2/20/2019
	Location:	
	Work Order Number:	
	Payment Type:	
	Page:	3 of 4

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	2104	1RW8370REFD103356	GL103356	

/TRACTORHYDRAULIC Retail
RE586877 OIL LINE 1.00

/TRACTORELECTRICAL Retail
COMPLAINT:
07 Electrical Repairs

CORRECTION:
touch screen was not working right, replaced it.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
PFA10760	MONITOR	1.00				

/TRACTORSTEER/BRAKES Retail
COMPLAINT:
08 Steering and Brake Repairs

CORRECTION:
took both side duals off and took tie rods loose, replaced boots, put all back together.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R216823	SPRING	4.00				
R216824	SPRING	4.00				
R216827	BOOT	4.00				

/gen-electrical Retail
COMPLAINT:
diagnose code

CONTINUED ON NEXT PAGE->

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:	
	Invoice Date:	2/20/2019
	Location:	
	Work Order Number:	
	Payment Type:	
	Page:	4 of 4

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	2104	1RW8370REFD103356	GL103356	

/Gen-Electrical Retail

CORRECTION:

diagnosed code and found the connector on the fuel sensor harness was broke, took awhile to find it and fix it.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
57M7546	ELEC. CONNec	3.00				

Miscellaneous Charges:
Service Accessories



Labor:	
Parts:	
OL&M:	
Misc:	
Sales Tax:	
Grand Total:	\$5,184.71

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

	Invoice Number:	
	Invoice Date:	8/9/2017
	Location:	
	Work Order Number:	
	Payment Type:	
	Page:	1 of 1

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	1085	1RW8370REFD103356	GL103356	

PIP16RW667I Warranty

COMPLAINT:

01 16RW667A-L - 6R-9R HITCH/SCV LEVER IMPROVEMENT - MANDATORY

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
MPR13011	PRODUCT IM	1.00				
—						
—						

PIP16RW711B Warranty

COMPLAINT:

02 16RW711A/B - 8R/ 8RT SYNCHRONIZER SPEED MISMATCH CODE IMPROV

CORRECTION:

Miscellaneous Charges:
Service Accessories

Labor:
Parts:
OL&M:
Misc:
Sales Tax:
Grand Total: \$714.29

REMIT TO:

Invoice To Account No:

SERVICE INVOICE

Invoice Number: Invoice Date: 11/23/2016 Location: Work Order Number: Payment Type: Page: 1 of 1	Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
	JOHN DEERE 8370R	837	1RW8370REFD103356	GL103356	

/TRACTORENGINE Warranty

COMPLAINT:

fuel leaking under cab.

CAUSE:

fuel tank breather grommet missing. R114023. FM 14 leaking. Failure date 11/22/16.

CORRECTION:

fuel leak under the cab, spent a long time diagnosing and looking for the leak, took a lot of shields off, took floor mat out, took floor plates out, couldn't find anything, found pressure and return fuel lines, blew into return and tried finding leak, saw fumes on top of tank, took lh rear duals off, found the tank breather had come out of the tank, took a lot more stuff off to get to cab mount bolts, raised cab, the grommet had popped out of the tank and fuel had been sloshing out, got a new grommet and put it in, put breather back on, put cab down and put everything back together, test ran and no leak.
3.5 hr diagnosing.
9.13 repair
.5 cleaning.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R114023	GROMMET	1.00				

Labor:
Parts:
OL&M:
Misc:
Sales Tax:
Grand Total: \$1,315.36