Submitted by	_	Description of Work
Email		Replace hydraulic Cylinder for Dump bed
Phone		Repair and fixes needed
Repair Order #		Topan and most results
Date/Time	4/7/21	
Customer/Unit #	1997 Freightliner Dump Truck	
Hours/Milage	257,050	
Serial Number	1FVXJLBB8WH923787	Authorized by

	Category	THE STATE OF THE S	Part Numbers and Description	
	TO STREET OF THE PARTY OF THE P	Quantity	HER THE STATE OF T	Amount
Trailer		1	4 stage Hydraulic Cylinder	
Truck	x	1	Fuel Filter	
Reefer		1	Oil Seal	
Vehicle		1	Hub Gaskets	
Misc.		1	Pinon Seal	
Service		1	Oil Seal Retainer	
Vehicle		1	Hex Head Plug	
Verneie	Repair Reason	2	Meritor Kit 16.5x7	
Preventive	X	1	R12 Valve w/ Bracket	
Breakdown		1	Break Air Valve	
Routine			Shop Supplies	
Accident			Total \$	
Fuel			Description of Work Performed	
	System Codes	System	Alberta Caracteria	Hrs. Labor
01-A/C	16-Suspension		Parts Only Invoice	
02-Cab	23-Fuel System			
13-Brakes	30-Electrical	1.7		
17-Tires	50-Accessories			
22-Axels	95-Coolant			
26-Trans	70- 5th Wheel			
40-Engine	80- Exhaust			
90-Lights	96-Misc.		Hours Labor	

	Shop Supplies/Parts \$		1 Fig. 1 19 - 151 William
\$	Total Labor Cost =	Total hours Hr.	
	Credit card Fee of 3.5% \$	have him it is in all in	
\$4085.86	Total charges for the Repair \$		

Submitted by		Description of Work
Email		
Phone		Replace hydraulic Cylinder for Dump bed
Repair Order #		Repair and fixes needed
Date/Time	4/7/21	
Customer/Unit #	1997 Freightliner Dump Truck	
Hours/Milage	257,050	
Serial Number	1FVXJLBB8WH923787	Authorized by 1

1 11 11 11	Category		Part Numbers and Description	
		Quantity		Amount
Trailer			Remove and replace Components and install new cylinder- 2 Mechanics needed	6.5 Hrs.
Truck	x		Truck would not stay running Replaced gasket for governor and fuel filter	2.5 Hrs.
Reefer			Replaced leaking wheel seal	3.0 Hrs.
Vehicle			Removed and repaired Differential Pinion Seal	3.0 Hrs.
Misc.			Fixed high and low gear issue	2.0 Hrs.
Service			Removed splitter from rear of transmission after finding water in air filter low piston was seized from rust	
Vehicle			Fixed leaking break valve and break chamber that is leaking	3.5 Hrs.
	Repair Reason		•	
Preventive	X			
Breakdown				
Routine			Shop Supplies	
Accident			Total \$	
Fuel			Description of Work Performed	
	System Codes	System		Hrs.
01-A/C	16-Suspension		Labor invoice	
02-Cab	23-Fuel System			
13-Brakes	30-Electrical			
17-Tires	50-Accessories			
22-Axels	95-Coolant			
26-Trans	70- 5th Wheel			
40-Engine	80- Exhaust			
90-Lights	96-Misc.		Hours Labor	

\$	Shop Supplies/Parts \$	
\$1312.50	. Total Labor Cost =	Total hours 17.5 Hr.
	Credit card Fee of 3.5% \$	

Submitted by	1	Description of Work
Email		Danels Front Left Avia
Phone		Repair Front Left Axle Repair Broken Leafspring Bolt
Repair Order #	2000	Replace broken Headlamp
Date/Time	3/23/21	
Customer/Unit #	1997 Freightliner Dump Truck	
Hours/Milage	225,996	
Serial Number	1FVXJLBB8WH923787	Authorized by

	Category		Part Numbers and Description	
177. 5 25%		Quantity		Amount
Trailer		1	Leaf Spring Bolt	
Truck	X	1	H6054XVBX Headlamp	
Reefer				
Vehicle				
Misc.				
Service				
Vehicle				
	Repair Reason			
Preventive				
Breakdown	X			
Routine			Misc. Shop Supplies	
Accident			Total \$	
Fuel			Description of Work Performed	
	System Codes	System		Hrs. Labor
01-A/C	16-Suspension	96	Took axle aprart from leaf spring, adjust leaf spring and centered them back where they needed to be to align new bolt	4.0
02-Cab	23-Fuel System		Moved axle back in place from where it shifted	
13-Brakes	30-Electrical		Aligned leaf springs back in place put U bolts back and repaired issues	
17-Tires	50-Accessories		Replaced Broken Headlamp	
22-Axels	95-Coolant			
26-Trans	70- 5th Wheel			
40-Engine	80- Exhaust			
90-Lights	96-Misc.		Hours Labor	4.0

	Shop Supplies/Parts \$	
	Total Labor Cost =	Total hours 4 Hr
	Credit card Fee of 3.5% \$	
\$739.50	Total charges for the Repair \$	

Submitted by		Description of Work
		Full Service
Email		
Phone		
Repair Order#		
Date/Time	3/11/21	
Customer/Unit #	1997 Freightliner Dump Truck	
Hours/Milage	225,679	
Serial Number	1FVXJLBB8WH923787	Authorized by

C	ategory	Ш		Part Numbers and Description	
		Q	uantity		Amount
Trailer		\parallel	1	85748 Oil Filter	
Truck	x	††	1	86472 Fuel Filter	-
Reefer		$^{\dagger \dagger}$	1	89071 Cooling	
Vehicle		#	1	88744 Air Filter	1 -
Misc.		#	7	15W-40 Oil	
Service		#	1	Hydraulic Fluid	1 -
Vehicle		#	1	Hydraulic Stop Leak	
	Repair Reason	11			
Preventive	х	$^{\dagger \dagger}$			
Breakdown		1			
Routine		1			
Accident		\parallel		Total \$:
Fuel				Description of Work Performed	
	System Codes	s	ystem		Hrs. Labor
01-A/C	16-Suspension	П	96	Change oil and oil filter	
02-Cab	23-Fuel System	#		Changed coolant filter and fuel filter	
13-Brakes	30-Electrical	#		Changed air filter	
17-Tires	50-Accessories	\parallel		Added 7 quarts of oil and hydraulic fluid back to the unit	
22-Axels	95-Coolant	I		Added stop leak to hydraulic system	
26-Trans	70- 5th Wheel	1			3.0
40-Engine	80- Exhaust	1			
90-Lights	96-Misc.	1	K. 187	Hours Labor	3.0

•	Shop Supplies/Parts \$	
	75.00 per hour Total Labor Cost =	Total hours 3 Hrs.
5	Credit card Fee of 3.5% \$	
\$608.61	Total charges for the Repair \$	

Submitted by		Description of Work
Submitted by		Replace U Bolts and Spring Bolts
Email		
Phone		
Repair Order#		
Date/Time	3/31/21	
Customer/Unit #	1997 Freightliner Dump Truck	
Hours/Milage	256,999	
Serial Number	1FVXJLBB8WH923787	Authorized by



C	ategory	Part Numbers and Description		Part Numbers and Description	
		t	Quantity		Amount
Trailer		t	2	Leaf spring U Bolts	
Truck	х	t	1	Leaf spring Bolts	_
Reefer		t			
Vehicle		t			
Misc.		t			
Service		t			
Vehicle		t			
	Repair Reason	t			
Preventive	х	t			
Breakdown		t			
Routine		t		Shop Supplies	3
Accident		Ť		Total \$	1
Fuel		Ť		Description of Work Performed	
	System Codes	Ī	System	2860 45 1 65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Hrs. Labo
01-A/C	16-Suspension	Ī	96	Replaced U Bolts in right front spring and replaced spring bolt	3.5
02-Cab	23-Fuel System	T			
13-Brakes	30-Electrical	T			
17-Tires	50-Accessories				
22-Axels	95-Coolant	T			
26-Trans	70- 5th Wheel	T			
40-Engine	80- Exhaust	Ī			
90-Lights	96-Misc.	T		Hours Labor	3.5

	Shop Supplies/Parts \$)
Total hours 3.5 Hr.	Total Labor Cost =	5
	Credit card Fee of 3.5% \$	
	Total charges for the Repair \$	\$565.75

Submitted by	\mathbf{T}	Description of Work
Email	_	Replace Water pump
Phone	Lancas	Replace Water pump
Repair Order #		
Date/Time	3/16/21	
Customer/Unit #	1997 Freightliner Dump Truck	
Hours/Milage	225,750	
Serial Number	1FVXJLBB8WH923787	Authorized by

	Category		Part Numbers and Description	
		Quantity		Amount
Trailer		1	42146 Water Pump	
Truck	X	8	50/50 Conventional	
Reefer			,	
Vehicle				
Misc.				
Service				
Vehicle		1		
	Repair Reason			
Preventive	X			
Breakdown				
Routine				
Accident			Total \$	
Fuel		Description of Work Performed		
	System Codes	System		Hrs. Labor
01-A/C	16-Suspension	96	Remove and Replace water pump	
02-Cab	23-Fuel System		Add 8 quarts 50/50 Conventional	
13-Brakes	30-Electrical			
17-Tires	50-Accessories			
22-Axels	95-Coolant	1		
26-Trans	70- 5th Wheel			
40-Engine	80- Exhaust			
90-Lights	96-Misc.	1	Hours Labor	2.0

	Shop Supplies/Parts \$	
	. Total Labor Cost =	Total hours 2 Hrs.
	Credit card Fee of 3.5% \$	
\$515.83	Total charges for the Repair \$	