

**Ship
To**

CUSTOMER ACCT NO.		PHONE NUMBER		SALESMAN		INVOICE NO. > -----				
CUSTOMER ORDER NO.				TAX ID NO.			DATE 06-07-21		SHIP VIA WILL CALL	
LOC	PART NUMBER	DESCRIPTION	ORD	SHIP	B/O	LIST	UNIT PRICE	EXTENSION		
	03-07189	CLAMP AXLE	1	1						
04106	03-07771-003	SHIM-LOW AIR SUSP	1	1						

CUSTOMER SIGNATURE _____

BILL TO

DELIVER TO

PARTS INVOICE:

DATE SHIPPED	SHIP VIA	DATE INVOICE	SALESPERSON	UNIT ID	VIN	TERMS	CUSTOMER REFERENCE
6/2/2021	LOCAL/PICKUP	6/2/2021	JASONR			CHECK	

QTY SHP	QTY B/O	ITEM	DESCRIPTION	BIN	UNIT PRICE	EXTD PRICE
2		101D/MAE 66145	SHOCK ABSORBER, GAS-MAGNUM *D	63D		
	2	101D/MAE 65411	SHOCK ABSORBER, GAS-MAGNUM *D	62TOP		
1		101X/J20-6005	DRAGLINK	NOLOC		
2		101D/TDA XK2121443E	RELINED BRAKE SHOES *D	RSHOP		
2		101D/TDA XK2121443E-CORE	RELINED BRAKE SHOES *D	BINCOR		
1		101D/BW 1008325	KIT-CAMSHAFT BRACKET *D	20top		
-2		101D/TDA XK2121443E-CORE	RELINED BRAKE SHOES *D	BINCOR		

SUB-TOTAL

TAX

SHIPPING

TOTAL

507.10

BILL TO

DELIVER TO

PARTS INVOICE:

DATE SHIPPED		SHIP VIA	DATE INVOICE	SALESPERSON	UNIT ID	VIN	TERMS	CUSTOMER REFERENCE
5/17/2021		LOCAL/PICKUP	5/17/2021	WENDYC			CHECK	UNIT 7
QTY SHP	QTY B/O	ITEM	DESCRIPTION	BIN	UNIT PRICE	EXTD PRICE		
4		101D/MAE 65400	SHOCK ABSORBER, GAS-MAGNUM *D	63B				
1		101D/BW 808069N	CAMSHAFT-(CW) *D	55A				
1	1	101D/BW 808068N	CAMSHAFT-(CCW) *D	55A				
1		101D/ABP N42A 33030CD	COMBO-BULK-NO CLEVIS *D	66C				
2		101D/PH 213 8 RL 250	HOSE - .406 ID, WIRE REINFORC	RSHOP				
2		101D/PH 20821 08 08NP	FITTING-HOSE, REUSABLE	RSHOP1				
3		101D/BW 127808N	KIT-CAMSHAFT BUSHING *D	86L				
1		PREPAY	101218000 PREPAY FOR BACK ORDERED					
PARTS BW 808068N								

99 parts

SUB-TOTAL	
TAX	
SHIPPING	
TOTAL	554.53

CUSTOMER ACCT NO.		PHONE NUMBER		SALESMAN		INVOICE NO. >			
CUSTOMER ORDER NO.				TAX ID NO.		DATE 07-12-21		SHIP VIA WILL CALL	
LOC	PART NUMBER	DESCRIPTION	ORD	SHIP	B/O	LIST	UNIT PRICE	EXTENSION	
93A01	HC0010-06	BUMPER-PB 378 & 379 CON	1	1					
09G02	3-2048-3	BEZEL-HEADLAMP, DUAL REC	2	2					
	visa								
CCCC AAA SSSS HH HH CC CC AA AA SS SS HH HH CC AA AA SS HHHHHH CC AAAAAA SSS HHHHHH CC CC AA AA SS SS HH HH CCCC AA AA SSSS HH HH PARTS FREIGHT SALES TAX *CASH TOTAL 660.26									

CUSTOMER SIGNATURE _____

308-632-2911

BILL TO

DELIVER TO

PARTS INVOICE:

DATE SHIPPED	SHIP VIA	DATE INVOICE	SALESPERSON	UNIT ID	VIN	TERMS	CUSTOMER REFERENCE
9/7/2021	LOCAL/PICKUP	9/8/2021				CHECK	

QTY SHP	QTY B/O	ITEM	DESCRIPTION	BIN	UNIT PRICE	EXTD PRICE
2		101D/SET 189800FA35	SEAT-HRTG SILVER HB 20IN 15 *D	SOUTH		

SUB-TOTAL

PREPAY

TAX

SHIPPING

TOTAL 1,099.98

Workscope

Extended Price

 Total Segment Parts
 Total Segment Labor
 Total Segment Miscellaneous

Segment Total 195.47

Troubleshoot - Fault Codes**Customer complaint:**

Has check engine light.

Resultant damage:

none

Repair process comments:

Trouble shot and found 174-3 fuel temp to high. Troubleshoot wiring and was good. Found temp sensor was bad. Cleaned areas and installed new temp sensor. Fault codes gone.

Parts

1	2644297	SENSOR TEMP	45.27
---	---------	-------------	-------

Labor

Total Labor

 Total Segment Parts
 Total Segment Labor
 Total Segment Miscellaneous

Segment Total 247.67

Reseal - Exhaust Manifold**Customer complaint:**

Reseal exhaust manifold

Resultant damage:

Studs drilled out, new studs installed, manifold resealed.

Repair process comments:

Removed air ducting and noticed air ducting had big hole so sent it to repair. Drained coolant, removed turbo, thermostat, hoses, and exhaust manifold. During process of removing rusted studs a total of 8 needed extracted. And number 6 lower hole needed helicoid. Extracted all 8 holes and helicoid number 6. Cleaned and tapped all holes. Installed all new studs with antiseize. Installed new manifold, turbo, and torqued to specs. Had to order correct manifold as picked up air ducting away from covers. Installed proper fittings and elbows for correct manifold set up. Programmed injectors, filled with coolant. Ran to operating temperature and topped off.

Parts

1	1393550	GASKET-REGUL
2	3S9643	SEAL
2	2477133	REGULATOR-TE
12	2N2766	LOCK NUT
11	1061792	STUD TAPER
1	1061793	STUD
1	1986068	SEAL-INTEGRA
1	1142687	SEAL-O-RING
1	6V5266	SEAL O RING
1	1S4295	GASKET

Proposal Date

10/14/2021

Page 5 of 5

Workscope

Extended Price

-4	8T4983	CLAMP
-1	1384611	GASKET
-11	1384611	GASKET
-1	6V9049	DRILL
1	0307949	ELBOW
1	6V9003	ELBOW

Labor

Flat Rate Labor

1,889.02

Total Segment Parts

Total Segment Labor

Total Segment Miscellaneous

Segment Total

4,741.23

Total Invoice Parts

Total Invoice Labor

Total Invoice Miscellaneous

Total Tax

Please detach and include this portion with your payment.

Account Number	Invoice Number	Proposal Date
	NOT AN INVOICE	10/14/2021

Please Pay This Amount:

\$12,412.59

Workscope

Extended Price

Removed air ducting and noticed air ducting had big hole so sent it to repair. Drained coolant, removed turbo, thermostat, hoses, and exhaust manifold. During process of removing rusted studs a total of 8 needed extracted. And number 6 lower hole needed helicoiled. Extracted all 8 holes and helicoiled number 6. Cleaned and tapped all holes. Installed all new studs with antiseize. Installed new manifold, turbo, and torqued to specs. Had to order correct manifold as picked up air ducting away from covers. Installed proper fittings and elbows for correct manifold set up. Programmed injectors, filled with coolant. Ran to operating temperature and topped off.

Parts

1	0R7923	TURBO GP
1	0R7923CC	TURBO GP-CoreChg
-1	0R7923WC	TURBO GP-CoreChg
-1	6V9048	DRILL
1	MTKFLF/FRE1020-0001	HOSE, CAC
2	FLEB9224-0406	CLAMP CAC
-1	0307949	ELBOW
1	MSCANTI-1	ANTIFREEZE
1	FLETLC500S	5 STAINLESS LAP JO

Miscellaneous

1	osp	Repair Tube
---	-----	-------------

Miscellaneous

1	FRT
1	FRT
1	FRT
1	FRT

Total Segment Parts
Total Segment Labor
Total Segment Miscellaneous

Segment Total	2,540.01
----------------------	-----------------

Repair - Hose(S) - Power Steering

Customer complaint:

Needs new power steering hose.

Resultant damage:

none

Repair process comments:

Drained power steering fluid, removed old leaking hose. Installed new hose with new clamps. Also supported with extra piece of rubber hose against frame to avoid leaks after rubbing. Filled with fluid.

Parts

43	4568421	Hose Bk 716-12
2	FLE9410H	CLAMP 9/16 to 1-1/16
43	4231985	IN HOSE-BLK
-43	4568421	Hose Bk 716-12
3	FLEPTATF-MP-QT	FLUID TRANS QT MUL
-1	FLEPTATF-MP-QT	FLUID TRANS QT MUL

Labor

Total Labor

131.00

Service Invoice Proposal

Proposal Date

10/14/2021

Page 1 of 5

Jobsite:

Account Number		Invoice Number	Customer PO	Division	
		NOT AN INVOICE		TK	
Document Number		Payment Terms	Service Call Date	Service Writer	
			08/30/2021		
Make	Model	Serial Number	Customer Equipment Number	Equipment Number	Last Meter
AA	3406	2WS32472		EQN027925	956281

Workscope	Extended Price
-----------	----------------

Remove & Install - Unit Injector

Customer complaint:

Needs valves adjusted.

Resultant damage:

none

Repair process comments:

Took off valve covers. After removing rocker arms, found broken #6 Rocker arm. Inspected all components. Cleaned areas and surfaces. Installed new injectors and rocker arm, torqued to specs. Set valves and injectors to specs.

Parts

1	10R8500	INJ KIT
1	10R8500CC	INJ KIT-CoreChg
6	8S9191	BOLT
2	MSCAZP-10	AZ BRAKE CLEAN
1	20R3322	ARM A UI ROC
1	20R3322CC	ARM A UI ROC-CoreChg
-1	10R8500WC	INJ KIT-CoreChg
-1	20R3322WC	ARM A UI ROC-CoreChg

Labor

Total Labor

Total Segment Parts
Total Segment Labor
Total Segment Miscellaneous

Segment Total 4,688.21

Remove & Install - Turbocharger

Customer complaint:

Needs new turbo and exhaust manifold.

Resultant damage:

none

Repair process comments: