Date:

4/17/2020

Bill To

	Service Order	Purchase Order	Service Writer	Authorizer		
ltem	Description		Quantity	Rate	Amount	
Comp	laint: Headlights are intermit	lent				
Cause	e: Faulty wiring					
Labor	Correction:					
	Chassis / Lighting & Electric	cal / Repair all necessary wiring to lights				
				Subtotal	\$623.00	
Comp	plaint: Engine smokes and no	power				
Cause	e: CAC is leaking (Inspection)					
Labor	Correction: Engine / Turbo / Remove ar	nd replace CAC				
Parts	WASHER - 87511 - A					
Parts	Hex Nut - 10242 - A					
Parts	Air Filter - AF886 - A					
Parts	WASHER - FA88448 - A					
				Subtotal	\$480.22	
Comp	plaint: A/C does not work	and the control of th	A-0-4-0-1-0-1-0-1-0-1-0-1-0-1-0-1-0-1-0-1			
Caus	e: Low on freon and blower a	irflow is low (Inspection)				
Labor	Correction:					
	Chassis / Air Conditioning 8 vacuum and recharge A/C s	& Heating / Remove evaporator and clea system	n. Install and			
Parts	Freon - R134A - A					
				Subtotal	\$380.3	
Comp	laint: Repair bent bumper	WHERE FOR THE STREET STREET, STREET STREET, STREET STREET, STR		and the second second second second second		
Cause	e: Bent bumper (Inspection)					
abor	Correction:	versus basis access for the state of the				
	Chassis / Chassis / Bend bu	umper back away from steer tire		MR Park Control		
				Subtotal	\$89.0	

Description	Quantity	Rate	Amount
hit: AT100 VIN: 1FDZU82A7NVA24656	Labor		
In Service Date: 12:00AM T0/19/2021 Chassis: 313,000 Miles	Parts		
	Subtotal		
	Total		\$1,750.57

Date:

7/9/2020

Bill To

Remit Payment To

Service Order Purchase Order Service Writer Authorizer Item Description Quantity Rate Amount Complaint: Service call: check for engine smoking DAMAGE Cause: low on coolant, blown hose on engine. engine overheated Type: Unscheduled repair Labor Correction: Engine / Cooling System / Drive to 235 and meridian north. Repair blown hose. Refill with coolant, escort to shop, Engine now has miss and needs to be further investigated before going back into service Parts Red butt connector - 92822 - A Parts 1156 bulb - 82673 - A Parts Blue w/brass sleeve butt connector - 94728 - A ATO 15 blue fuse - 84789 - A Parts Radiator Hose - D1030-2468 - A Parts 1GL Antifreeze - ORDEX50/50 - A Parts ATO 10 red fuse - 83027 - A Parts #10 x 1 hex head screw - P29041 - A Parts 1GL Antifreeze - ORDEX50/50 - A Subtotal \$516.00

Complaint: Check engine damage

Cause: Driver ran truck in overheat stage for extended time. Type: Unscheduled repair (Inspection)

Labor Correction:

Engine / Pistons / Repair damage Disassembled engine and found #2 piston has been hot enough to melt. Removed and honed and polished #2 cylinder wall. Replaced #2 piston and rod assembly. Replaced all rod and main bearings. Repaired cylinder head as necessary. Installed cylinder head and top end. Installed all accessories. Had turbo machined due to poor mating surface. Ran and tested engine. Engine is running properly at this time.

Parts Cap Screw - 10226 - A

Parts Piston - FFIHZ6108X - A

Parts Ring Set - FFIHZ6148AA - A

Parts Rod Bearing - F261215 - A

Parts Head Gasket Set - FFIHZ6079A - A

Parts Shipping - 31193 - A

De	escription	Quantity	Rate	Amount
rts Oi	il Pan Set - F83958073 - A			
arts FI	lexible CYL. Hone - 2ZZH2 - A			
arts E	ngine Cyl 2ZPJ9 - A			
arts S	hipping - Shipping - A			
arts B	Sanjo Connector - 4942278 - A			
arts H	Heater Hose - D1029-2932 - A			
arts P	PCV grommet - 42344 - A			
arts P	PCV grommet - 42049 - A			
arts F	PCV grommet - 42324 - A			
arts S	Seal grommet - 3103015CUM - A			
abor F	Resurface turbo - A			
Parts (Connector - 92822 - A			
Parts I	Lamp assy - D8HZ-15542-B - A			
Parts	Fasteners - 56 - A			
Parts	M12 Lock Washer - 80278 - A			
			Subtotal	\$6,214.74
Parts Parts Parts Parts Parts	Chassis / Air Conditioning & Heating / Hook up gauges and check A/C. Found system is low on freon. Found leak at hose ends. Replaced seals and pressure checked. Filled with freon and checked operation. Seal, grommet - 3684091 - A Seal grommet - 3684091 - A Pigtail - 94902TLT - A Maker lamp 2.5 yellow - G1033 - A Washer Pump - 11-512 - A Wiper motor - DENG2008-105-1 - A			
Parts	Freon - R134A - A			
Parts	Wire-OSP 1U2Z-14S411-BNB - A			
Parts	Switch, w/s wiper, Ford - F3HZ-17A553-A - A			
			Subtotal	\$926.82
1992 In Se	Shop Supplies AT100 VIN: 1FDZU82A7NVA24656 Ford LT8000 ervice Date: 12:00AM 10/19/2021 ssls: 313,000 Miles	Lat Pai		and the second s
Orlat	and Cicigor inites	Su	btotal	

Date:

11/30/2020

Bill To

tem Description Quantity Rate Complaint: Service Call: Fuel and Oil leak Cause: Customer request Labor Correction: Chassis / Chassis / Service Call to APAC: Fuel filter housing fell off- Replace mounting bolts Parts 1/4 tube union - 91819 - A Parts 1/4 tube brass sleeve - 84321 - A Parts 1/4 tube brass surt - 84326 - A Parts 5/16-24x1 1/2 UNF Cap Screw - FA68219 - A Subtotal Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wifring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wifring Parts Switch, dimmer, Standard - DS70 - A Subtotal	
Cause: Customer request Labor Correction: Chassis / Chassis / Service Call to APAC: Fuel filter housing fell off-Replace mounting bolts Parts 1/4 tube union - 91819 - A Parts 1/4 tube brass sleeve - 84321 - A Parts 1/4 tube brass nut - 84326 - A Parts 5/16-24x1 1/2 UNF Cap Screw - FA68219 - A Subtotal Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (napection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Cause: Customer request (napection) Labor Correction: Chassis / Chassis / Repair Wirring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (napection) Labor Correction: Chassis / Chassis / Repair Wirring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal	Amount
Correction: Chassis / Chassis / Service Call to APAC: Fuel filter housing fell off-Replace mounting bolts Parts 1/4 tube union - 91819 - A Parts 1/4 tube brass sleeve - 84321 - A Parts 1/4 tube brass nut - 84326 - A Parts 5/16-24x1 1/2 UNF Cap Screw - FA68219 - A Subtotal Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Subtotal Complaint: Service Call: No Speedometer Cause: Customer request (inspection) Labor Correction: Chassis / Chassis / Repair Wirring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (inspection) Labor Correction: Chassis / Chassis / Repair Wirring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal	
Chassis / Chassis / Service Call to APAC: Fuel filter housing fell off- Replace mounting bolts Parts 1/4 tube union - 91819 - A Parts 1/4 tube brass sleeve - 84321 - A Parts 1/4 tube brass nut - 84326 - A Parts 5/16-24x1 1/2 UNF Cap Screw - FA68219 - A Subtotal Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Subtotal Complaint: Service Call: No Speedometer Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Parts 1/4 tube brass sleeve - 84321 - A Parts 1/4 tube brass nut - 84326 - A Parts 5/16-24x1 1/2 UNF Cap Screw - FA68219 - A Subtotal Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction:	
Parts 1/4 tube brass nut - 84326 - A Parts 5/16-24x1 1/2 UNF Cap Screw - FA68219 - A Subtotal Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Subtotal Complaint: Service Call: No Speedometer Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Parts 5/16-24x1 1/2 UNF Cap Screw - FA68219 - A Subtotal Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Subtotal Complaint: Service Call: No Speedometer Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Subtotal Complaint: Service Call: No Speedometer Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Electrical / No left turn on hood - Bad connection	
Complaint: Service call: Throttle linkage needs repaired Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Subtotal Complaint: Service Call: No Speedometer Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Service call: Throttle linkage needs repaired Subtotal Complaint: Service Call: No Speedometer Cause: Customer request (Inspection) Labor Correction: Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	\$202.25
Labor Correction: Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	\$148.5
Chassis / Chassis / Repair Wiring Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Parts Switch, dimmer, Standard - DS70 - A Subtotal Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Complaint: No left turn on hood Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	\$112
Labor Correction: Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
Chassis / Lighting & Electrical / No left turn on hood - Bad connection	
	\$9
TO THE PROPERTY OF THE PROPERT	\$3

Date:

1/5/2021

Apex Trucking Inc. 302 W 61st Street N. Park City, KS 67204

Complaint: Unit is idling to high

Remit Payment To
Apex Truck & Tractor Repair, Inc.
302 W 61st Street N.
PARK CITY, KS 67204

	Service Order		Authorize	and the second second second second	
broso toro tolende	=				
tem	Description		Quantity	Rate	Amount
Compla	int: Steam clean unit				
Cause:	Customer request				
abor	Correction:				
	Chassis / Chassis / Steam of	dean unit		Subtotal	\$74.25
Comple	aint: Repair oil leaks				
Cause:	: Customer request				
Labor	Correction: Engine / Lubrication / Repa	ir oil leaks			
Parts	8" black cable tie - 94610 -	A			
Parts	15.5" black cable tie - 9461	1 - A			
Parts	#12 Hose Clamp - 86726 -	A			
				Subtotal	\$845.96
Compl	laint: Repair air leaks	auther described and another professional and an analysis of the state			
Cause	: Customer request				
Labor	Correction: Engine / Valves / Repair a	r leaks			
Parts	#4 Hose - PH/213/4/300 -	A			
Parts	Freight - Freight - A				
Parts	Fitting #4x#4 - FG6276 - A			200 CO. (200 CO.)	posts as a susceptibility
				Subtotal	\$375.
Comp	laint: Check Brakes				
Cause	: Customer request				
Labor	Correction:				
	Chassis / Frame / Check	Brakes		90000	
				Subtotal	\$9

	Description	Quantity	Rate	Amount
USO	: Customer request			
abor	Correction: Transmission / Internal Gears & Clutches / Unit is idling to high			
arts	Pressure sensor - 1749-2134 - A		• • • • • •	
			Subtotal	\$162.65
ompla	aint: Check PTO opperation			
ause:	Customer request			
abor	Correction:			
	Transmission / PTO / Check PTO operation		Subtotal	\$99.00
omple	aint: Federal Annual DOT Inspection			
ause:	Customer request			
abor.	Correction: Chassis / Chassis / Federal Annual DOT Inspection			
	Chasas / Chasas / Country and Country		Subtotal	\$99.00
ompla	aint: P/S Leaks			
ause:	Customer request (Inspection)			
abor	Correction:			
	Chassis / Instrument & Controls / P/S Leaks		Subtotal	\$49.50
Compl	aint: Repair A/C line and charge A/C			
	Customer request (Inspection)			
	Correction:			
	Chassis / Air Conditioning & Heating / Repair A/C line and charge A/C			
Parts	A/C Line - #10LFSVR - A			
			Subtotal	\$368.50
	Shop Supplies			
Jnit: A	T100 VIN: 1FDZU82A7NVA24656	Labor		
992 Fo	ord LT8000	Deute		
	ice Date: 12:00AM 10/19/2021 s: 313,000 Miles	Parts		
		Subtot	tal	
		Total		\$2,386.56
	narges not included in total. You will be charged for any core that is not in retu			

Date:

2/2/2021

Bill To

Remit Payment To

	Service Order	Purchase Order	Service Writer	Author	rizer
ltem	Description		Quantity	Rate	Amount
Compla	aint: Repair lug nuts on RR a	xie			
Cause:	Customer Request				
Labor	Correction: Chassis / Chassis / Repai	r lug nuts on RR axle			
Parts	3 1/16 LH G8 Inner Nut - I	BAT-13-3029L - A			
				Subtotal	\$392.48
Compl	aint: Service Unit	The second secon			
Cause	: Customer request (Inspection)				
Labor	Correction: Engine / Filters / Service	Unit			
Parts	4" exhaust clamp - FLTE	C40PLA - A			
Parts	Red butt connector - 928	22 - A			
Parts	1/4" stud red ring termina	I - P50606 - A			
Parts	Oil Filter - P559126 - A				
Parts	Water Filter - P554071 -	A			
Parts	Door panel clips - 45475	0 - A			
				Subtotal	\$248.
	Shop Supplies				

Shop Supplies

Unit: AT100 VIN: 1FDZU82A7NVA24656

1992 Ford LT8000

In Service Date: 12:00AM 10/19/2021

Chassis: 313,000 Miles

Labor

Parts

Subtotal

Total

\$716.68

Date:

2/19/2021

Bill To

Remit Payment To

Authorizer Service Order Purchase Order Service Writer Amount Rate Description Quantity Item Complaint: Make DOT Repairs Cause: Customer Request Correction: Labor Chassis / Chassis / Make DOT repairs Parts Mudflap - GT2436XD - A Parts Adapter - OTRLF350 - A Model 15 SS ID Bar Kit - 15741R - A Parts Fitting, Shut Off Cock 1/4, Parker - V402-4 - A Parts 5/16-18x3 G8 Cap Screw - FA68025 - A Parts 5/16 Flat Washer - FA88446 - A Parts 5/16-18x1 G8 Cap Screw - FA68017 - A Parts One Shot Brake Clean - P20100 - A Parts 3/8-16x1 1/4 G8 Cap Screw - FA68033 - A Parts 3/8 Flat Washer - FA88447 - A Parts Subtotal \$1,135.78 Complaint: Federal Annual DOT Inspection Cause: Customer request Labor Correction: Chassis / Chassis / Federal Annual DOT Inspection Subtotal \$99.00 Shop Supplies Unit: AT100 VIN: 1FDZU82A7NVA24656 Labor 1992 Ford LT8000 In Service Date: 12:00AM 10/19/2021 Parts Chassis: 313,000 Miles Subtotal

Total

\$1,384.67

Date:

3/9/2021

Bill To

Complaint: Replace Turbo exhaust gasket

Cause: Customer request (Inspection)

-	Service Order	Purchase Order	Service Writer	Authoriz	ter
tem	Description		Quantity	Rate	Amount
ompl	aint: Service Call				
Cause	: Exhaust leak				
abor	Correction: Engine / Turbo / Replace tu	rbo gasket, and top off coolant			
Parts	Turbo gasket - DLM-E7HZ6	N640A - A			
Parts	Switch, dimmer, Standard -	DS70 - A			
Parts	Fleetguard f/s separator - F	S19931 - A			
				Subtotal	\$375.70
Comp	plaint: Repair Air to Air Tube	Child Auditor republishment or software from the contract of t			
Caus	e: Customer request (Inspection)			
Labor	Correction: Engine / Air Intake / Induction	on / Repair Air to Air Tube			
Parts	#44 Hose Clamp - 86733 -	A			
Parts	Exhaust clamp - 309 - A			Subtotal	\$382.4
Comp	plaint: Service call: Repair air	leak			
	e: Broken air line : Other (Inspection)				
Labor	Correction: Chassis / Cab / Removed d	amaged section of air line and installed	new		
Parts	1/4 tube brass sleeve - 843	21 - A			
Parts	.250" tab yellow female qui	ck slide - 60521 - A		Annual parents	programme agreement agreement
				Subtotal	\$150.6

Quantity Rate Amount correction: Engine / Gaskets / Removed the four mounting nuts and took oil lines to the turbo loose and removed old gasket. Cleaned off old gasket material and installed new. Installed the retaining nuts and then reo-ringed the oil return line due to no o-ring and installed the oil supply line to the turbo. Started truck found no exhaust leaks and then washed truck and returned to service after checking fluids. Then cleaned tools and work bay task complete. \$396.00 Subtotal Shop Supplies Unit: AT100 VIN: 1FDZU82A7NVA24656 Labor 1992 Ford LT8000 **Parts** In Service Date: 12:00AM 10/19/2021 Chassis: 313,000 Miles Subtotal \$1,464.63 Total

Date:

4/13/2021

Bill To

coupels are large	Service Order	Purchase Order	Service Writer	Author	lzer
tem	Description		Quantity	Rate	Amount
Compl	aint: Air leak				
Cause	: Stainless steel line broke a	nd was leaking			
Labor	Correction: Engine / Air Intake / Induction	on / Replace steel line and put truck ba	ck in service		
Parts	5/16" stud ring terminal - Ps	51954 - A			
Parts	Stainless Steel Hose Asser	nbly - HA-T1167-10-110210-114.50 - A			
				Subtotal	\$430.70
	Chassis / Air Conditioning &	& Heating / Charge A/C		Subtotal	\$148.50
P-1/880/880-190	Shop Supplies				
1992 In Se	AT100 VIN: 1FDZU82A7NV Ford LT8000 rvice Date: 12:00AM 10/19/20 sis: 313,000 Miles		Lab Par Sub		
			Tota		\$ 627.81

Date:

6/2/2021

Bill To

Remit Payment To

Service Order Purchase Order Service Writer Authorizer Description Quantity Rate Amount Complaint: Repair air leak Cause: Valve bracket broken and was rubbing on frame Type: Unscheduled repair Labor Correction: Chassis / Chassis / Open hood and tie into main air line at compressor . Raise bed up and block bed up in the air . Pull old brake valve off truck . Punch broken bolts out of frame . Replace brake air valve and attach to frame with new bolts . Reattach air lines and secure air lines . Air up truck and inspect for air leaks Parts R12 Valve W/ Bracket - BW103009N - A Parts 3/4 Brass Bushing - 86662 - A Parts 6x16 Mirror - FLTMR4014 - A Subtotal \$543.88 Complaint: Install pressure switch Cause: Pressure switch bad Type: Unscheduled repair (Inspection) Labor Correction: Chassis / Chassis / Pull dash panel replace pressure switch . And put dash back together Parts 3/8-16x1 1/4 G8 Cap Screw - FA68033 - A Parts 3/8 Flat Washer - FA88447 - A Parts 3/8-16 G8 Hex Nut - FA68402 - A Parts Switch - D3TZ-9A050-B - A Parts 3/8-16x1 1/2 G8 Cap Screw - FA68034 - A Parts Blue butt connector - 92823 - A Parts Switch, dimmer, Standard - DS70 - A Parts 8" black cable tie - 94610 - A Parts 18 Wiper blade - Rainx - R18 - A Parts 5/8 G8 Lock Nut - 53985 - A Subtotal \$235.96

Complaint: Remove and reinstall torque rods

Cause: Customer request Type: Unscheduled repair (Inspection)

Quantity Rate aption Amount Chassis / Raise and block bed up in the air . Pull both old torque rods Chassis / Crisos out to be rebushed . Install new torque rods . Antiseize all bolts sent torque rods . Antiseize all bolts and tighten . Install new Bushings - A \$720.60 Subtotal Shop Supplies Unit: AT100 VIN: 1FDZU82A7NVA24656 Labor 1992 Ford LT8000 In Service Date: 12:00AM 10/19/2021 **Parts** Chassis: 313,000 Miles Subtotal \$1,656.64

Total

Date:

7/21/2021

BIII To

Remit Payment To

Authorizer Service Order Purchase Order Service Writer Amount Rate Item Description Quantity Complaint: Service call truck wont move OOS Cause: Trans failure Labor Correction: Transmission / Automatic Transmission / drove out to the trucks location attempted to gear truck into gear but was unsuccessful. I went to frightliner got a chain and used my service truck to get the truck out of the intersection and returned to the shop with the driver. Subtotal \$367.50 Shop Supplies Labor Unit: AT100 VIN: 1FDZU82A7NVA24656 1992 Ford LT8000 **Parts** In Service Date: 12:00AM 10/19/2021 Chassis: 313,000 Miles Subtotal \$418.77 Total *: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

Date:

7/26/2021

Bill To

Complaint: Send Transmission to Outside Shop for Repair

	Service Order	Purchase Order	Service Writer	Authorizer	
	20.0				
Item	Description		Quantity	Rate	Amount
Comp	laint: Remove Transmission				
Cause	: Transmission has no forwar	rd gears Type: Unscheduled repair			
Labor	Correction: Transmission / Automatic Tr out transmission to be repai	ransmission / Unbolt and remove transmired.	ission . As send		
Parts	Transmission Filter - 51551	- A			
Parts	Speedometer Interface - 52	89 - A			
				Subtotal	\$1,272.01
Comp	laint: Install Transmission				
Cause	: Rebuilt transmission Type:	Unscheduled repair (Inspection)			
Labor	Correction: Transmission / Automatic Tr Install torque converter bolts transmission with fluid.	ansmission / Install new transmission and and tighten . Install drive line and tighte	nd tighten bolts. en bolts. Full		
Parts	Air Shift - 328723X - A				
Parts	3/32 x 1 1/2 Cotter Pin - 101	2 - A			
Parts	1/4 tube x 1/4 pipe brass ma	le elbow - 84283 - A			
Parts	15.5" black cable tie - 94611	- A			
Parts	Plug, right angle STT - 9499	3 - A			
Parts	4" exhaust clamp - FLTEC40	PLA - A			
Parts	3/8 Lock washer - FA530A -	A			
Parts	1/2 Lock washer - FA532A -	A			
Parts	3/8-16x3 G8 Cap Screw - FA	68040 - A			
Parts	5/8-11x1 1/2 G8 Cap Screw	- FA68096 - A			
Parts	3/8-16 G8 Hex Nut - FA6840	2 - A			
Parts	3/8 Flat Washer - FA88447 -	A			
Parts	Lamp, red oval STT - G6002	-A			
				Subtotal	\$1,215.70

Quantity Rate Amount pescription use: No forward gears Type: Unscheduled repair (Inspection) Labor Transmission Rebuild - A Labor Cable Manufature - A Parts Modulator Cable - 036_225-36K - A \$3,534.41 Subtotal Complaint: Service Unit Cause: Pm service Type: Preventive maintenance (Inspection) Labor Correction: Engine / Filters / Raise hood. Drain oil from engine. Refill engine with oil. Replace oil filter and fuel filter and Air filter. Check fluid levels in both differentials and transmission. Check lights. Found rear differential leaking .replace water filter Parts Filter, air, Fleetguard - AF886 - A Parts Fleetguard f/s separator - FS19931 - A Parts Oil Filter - P559126 - A \$272.72 Subtotal Complaint: No head lights Cause: Customer request (Inspection) Labor Correction: Chassis / Lighting & Electrical / LIGHTING SYSTEM - HEADLAMP SWITCH, R&R Subtotal \$108.90 Shop Supplies Labor Unit: AT100 VIN: 1FDZU82A7NVA24656 1992 Ford LT8000 **Parts** In Service Date: 12:00AM 10/19/2021 Chassis: 313,000 Miles Subtotal \$6,904.84 Total

Date:

10/12/2021

Bill To

		94		Authorizer	
	Service Order	Purchase Order	Service Writer		
			Quantity	Rate	Amount
tem	Description				
ompl	laint: service call hub cap bro	ke			
ause	: plastic center was pulled ou	t Type: Damage caused by driver			
	Correction: Chassis / Chassis / I gathere truck location. I removed the oil, while i was out at the truck the truck to service.	ed my tools and went to kenworth than d broken hub cap and installed the new o k location I topped off the other hub as	rove out to the one and filled with well and returned		
Parts	Hub Cap - HA4009 - A				
Parts	75W-90 Mobile 1 - 104361E	X - A		Subtotal	\$258.60
Carried State of St.	Shop Supplies				
Init: A	AT100 VIN: 1FDZU82A7NVA	24656	Lat	oor	
992 F	ord LT8000		Par	ts	
hass	vice Date: 12:00AM 10/19/202 is: 313,000 Miles		Sul	ototal	
			Tot	al	\$291.80