

DN2411

Estimate

Date: 6/1/2020

Bill To

Remit Payment To

Service Order

Purchase Order

Service Writer

Authorizer

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

**Complaint:** Service Call to Hutch.

Diagnose and repair air leak &amp; exhaust leak DOT

**Cause:** flex pipe broke at muffler and burnt air line **Type:** Unscheduled repair**Labor Correction:**

Chassis / Chassis / temporary repair exhaust and repair air line, replace flex pipe at shop

Parts Washer - 87511 - A

Parts Hex Bolt - FA68401 - A

Parts Washer - FA88445 - A

Parts Washer - FA88446 - A

Parts 1/2 Strap &amp; Bolt Kit - 6.5-70-18X - A

Parts 1/4 Dot Union Instant Fitting - 91819 - A

Parts Exhaust Clamp - EC50PLA - A

Parts 4" Flex Pipe - 09-080441K120 - A

Parts Break Chamber - SC20 - A

Parts Cap Screw - FA68117 - A

Parts Cap Screw - 10224 - A

Parts Nut - FA68400 - A

<b>Subtotal</b>	\$831.10
-----------------	----------

**Complaint:** Service Call to Adjust brakes**Cause:** Adjustment (Inspection)**Labor Correction:**

Chassis / Chassis / Travel to location and adjust all brakes

Parts Nylon 12 T - PH/1220-4A-BLK1000 - A

<b>Subtotal</b>	\$299.18
-----------------	----------

**Complaint:** AC doesn't blow very hard DOT**Cause:** Customer request **Type:** Unscheduled repair (Inspection)**Labor Correction:**

Chassis / Air Conditioning &amp; Heating / Inspect ducting and install defrost fan

Description	Quantity	Rate	Amount
Parts Defroster Fan - HD10200 - A	1		
<b>Subtotal</b>			<b>\$258.28</b>

**Complaint:** Repair coolant leak

**Cause:** Hoses leaking (Inspection)

**Labor Correction:**

Engine / Cooling System / Replace damaged heater hoses and fill with coolant

Parts Lock Nut - 53983 - A

Parts Cap Screw - FA68068 - A

Parts Cap Screw - FA68070 - A

Parts Washer - FA88449 - A

**Subtotal** **\$329.29**

**Complaint:** Service call- no interior lights or cb DOT

**Cause:** tail light wiring pinched between bed and frame **Type:** Other (Inspection)

**Labor Correction:**

Chassis / Lighting & Electrical / repair wiring and replace fuse

Parts 16-14 UI Heat Sealbutt Connector - 92823 - A

Parts 30 Amp Autofuse - 84790 - A

Parts Connector - 92810 - A

Parts Circuit Breaker - CB1911-30 - A

Parts Fuse - 83029 - A

**Subtotal** **\$517.22**

**Complaint:** PTO inop

**Cause:** air leak (Inspection)

**Labor Correction:**

Chassis / Chassis / Found broken air line to PTO. Repaired line

Parts Conn-Str.P - 23-14392-000 - A

Parts Universal Fitting - 23-14393-000 - A

**Subtotal** **\$335.49**

**Complaint:** Service call: Check for vibration

**Cause:** Vibration (Inspection)

**Labor Correction:**

Chassis / Chassis / Traveled to location. Checked vibration. Found driveline was severely damaged. Removed drive line and too to have repaired. Upon repair returned to truck and installed driveline. Test drove to check for vibration.

Labor Weld HD Driveshaft - A

Labor Install HD U Joint - A

Labor Install Center Bearing - A

Parts Bearing Center - 10094142 - A

Parts Nut - 231502 - A

Parts U Joint Kit - 5675X - A

Parts Weld Tube - N628347 - A

Description	Quantity	Rate	Amount
Parts Shop Supplies - Shop Supplies - A			
		<b>Subtotal</b>	<b>\$1,468.18</b>

**Complaint:** Perform complete service

**Cause:** Service due (Inspection)

**Labor Correction:**

Engine / Filters / Perform complete service

Parts Lube Filter - LF9009 - A

Parts Fuel/Water Separator - FS1251 - A

Parts Fleetguard air filter - AF886 - A

Parts Fleetguard air filter - AF886 - A

**Subtotal** **\$298.89**

**Complaint:** Check charging system

**Cause:** low voltage (Inspection)

**Labor Correction:**

Engine / Starting & Charging / Checked charging system. Found alternator has failed. Removed and replaced alternator and batteries.

Parts HP-31D Battery - SL131SA - A

Parts Battery terminal - 41412 - A

Parts 24SI HP AL - DR/8600310 - A

**Subtotal** **\$805.93**

Shop Supplies

Unit: AT69 VIN: 1FDZU82E8RVA32418

1994 Ford LT8000

Chassis: 82,256 Miles

**Labor**

**Parts**

**Subtotal**

**Total**

**\$5,522.30**

Estimate

Date: 10/5/2020

Remit Payment To

Service Order

Purchase Order

Service Writer

Authorizer

5

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Low power ,

Cause: Customer Request

Labor Correction:

Chassis / Chassis / Service Call to Cassidy: Unit had low power.

Subtotal \$396.00

Complaint: No Power

Cause: Customer request (inspection)

Labor Correction:

Chassis / Chassis / Adjust fuel pump

Subtotal \$198.00

Complaint: Replace heater core

Cause: Customer Request (inspection)

Labor Correction:

Engine / Cooling System / Replace Heater Core

Parts Heater core, Ford - F1HZ-18476-B - A

Subtotal \$293.62

Shop Supplies

Unit: AT69 VIN: 1FDZU82E8RVA32418

1994 Ford LT8000

Chassis: 82,256 Miles

Labor

Parts

Subtotal

Total

\$998.10

Estimate

Date:

2/8/2021

Bill To

Remit Payment To

Service Order

Purchase Order

Service Writer

Authorizer

Item	Description	Quantity	Rate	Amount
<b>Complaint:</b> Federal Annual DOT Inspection				
<b>Cause:</b> Customer request				
Labor	<b>Correction:</b> Chassis / Chassis / Federal Annual DOT Inspection			
<b>Subtotal</b>				\$99.00

**Complaint:** Thaw Unit**Cause:** Customer request (Inspection)

Labor	<b>Correction:</b> Engine / Filters / Thaw Unit			
Parts	Fleetguard f/s separator - FS1251 - A			
Parts	Diesel 911, Power service - DIESEL 911 - A			
Parts	Fleetguard f/s separator - FS1251 - A			
Parts	ATO 25 clear fuse - 83029 - A			
Parts	BATTERY - SLI31SA - A			
Parts	3/8 Flat Washer - FA88447 - A			
Parts	3/32 x 1 1/2 Cotter Pin - 1012 - A			
Parts	Clutch brake, Meritor - MAFB175 - A			
Parts	ATO 25 clear fuse - 83029 - A			
Parts	AGC 25 Glass Fuse - 3019 - A			
Parts	Starting Fluid, Kwik Start - 81030 - A			
<b>Subtotal</b>				\$476.83

Shop Supplies

## Description

Quantity

Rate

Amount

VIN: 1FDZU82E8RVA32418

1994 Ford LT8000

Chassis: 82,256 Miles

Labor

Parts

Subtotal

Total

\$621.36

Estimate

Date: 3/22/2021

Bill To

Remit Payment To

Service Order

Purchase Order

Service Writer

Authorizer

Item	Description	Quantity	Rate	Amount
<b>Complaint:</b> P.M. Service				
<b>Cause:</b> Customer request				
<b>Labor Correction:</b> Engine / Filters / drained oil greased the truck removed and replaced the oil, fuel and air filters. Filled engine with oil and returned the truck to service.				
Parts	Fleetguard f/s separator - FS1251 - A			
Parts	Fleetguard lube filter - LF9009 - A			
Parts	Filter, air, Fleetguard - AF886 - A			
<b>Subtotal</b>				\$267.14

**Complaint:** Diag. And Repair A.C. system**Cause:** A.C. system not blowing cold **Type:** Unscheduled repair (Inspection)

**Labor Correction:**  
Chassis / Air Conditioning & Heating / Charged the system and confirmed the compressor is working. Checked the system for leaks. Found the hose between the compressor and the condenser is leaking at the crimp. Removed the hose and sent it out to be repaired. When it came back the hose was reinstalled and the system vacuumed and charged. Inspected for leaks again. Found the Evaporator coil is leaking.

Parts Evaporator - E-824UA - A

Parts Freon - R134A - A

**Subtotal** \$564.99**Complaint:** Diag. And repair HVAC Blower Motor**Cause:** Customer request (Inspection)

**Labor Correction:**  
Chassis / Air Conditioning & Heating / Repair blower motor

Parts #8 - #8 Ac Line - 828AC - A

Parts Blue butt connector - 92823 - A

Parts ATO 25 clear fuse - 83029 - A

Parts A/C orifice tube - MT0092 - A

Parts Foam Cleaner, evap & heater, Kool-it - 96030 - A

Description

Quantity

Rate

Amount

Subtotal

Shop Supplies

Unit: AT69 VIN: 1FDZU82E8RVA32418

1994 Ford LT8000

Chassis: 82,256 Miles

Labor

Parts

Subtotal

Total

\$1,388.48



Estimate

Date: 7/7/2021

Bill To

Remit Payment To

Service Order

Purchase Order

Service Writer

Authorizer

Item	Description	Quantity	Rate	Amount
<b>Complaint:</b> Alternator squealing and not putting out any voltage				
<b>Cause:</b> Customer request				
<b>Labor Correction:</b> Chassis / Lighting & Electrical / Remove and replace alternator				
Parts	Alternator - 8600310 - A			
Parts	1/2-13x1 G8 Cap Screw - FA68060 - A			
			<b>Subtotal</b>	<b>\$467.17</b>

**Complaint:** Service Unit**Cause:** PM service **Type:** Preventive maintenance (inspection)

**Labor Correction:**  
Engine / Filters / Raise hood. Drain oil from engine. Refill engine with oil. Replace oil filter and fuel filter and Air filter. Check lights. Check lights in both differentials and transmission.

Parts Filter, air, Fleetguard - AF886 - A

Parts Fleetguard f/s separator - FS1251 - A

Parts Fleetguard lube filter - LF9009 - A

**Subtotal** **\$268.51**

Shop Supplies

**Unit:** AT69 **VIN:** 1FDZU82E8RVA32418

1994 Ford LT8000

**Chassis:** 82,256 Miles**Labor****Parts****Subtotal****Total****\$795.06**