

		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
		5TFSZ5AN9HX112613		1	1	12/09/20 13:03	02/03/21	
		VEHICLE DESCRIPTION				TAG NO.	STATUS	
		2017 TOYOTA TACOMA ACA					COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS	
							Cash	
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT	

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount																																											
A	GEN		A60		Customer																																												
Concern	INSTALL HEADS--																																																
Cause	motor had excessive amount of dirt in motor. to clean it would have left motor rusty and over time engine would have failed. also parts in the timing cover and on the cams was broken. would have had to replace everything in the cams..																																																
<table><tr><th>Part Number</th><th>Description</th><th>Qty.</th><th>Unit Price</th><th>Ext. Price</th></tr><tr><td>300-65350</td><td>SMITHS/ENGINE ASSY</td><td>1</td><td></td><td></td></tr><tr><td>CQ24060</td><td>adv/hose</td><td>1</td><td></td><td></td></tr><tr><td>T,00272SLLC2</td><td>SUPER LONG LIFE COOL</td><td>2</td><td></td><td></td></tr><tr><td>T,04152YZZA1</td><td>REPLACEABLE ELEMENT</td><td>1</td><td></td><td></td></tr><tr><td>T,9043012031</td><td>GASKET</td><td>1</td><td></td><td></td></tr><tr><td>T,002790W20101</td><td>0W20 BULK OIL-W</td><td>7</td><td></td><td></td></tr><tr><td>T,8946704120</td><td>SENSOR, AIR FU</td><td>1</td><td></td><td></td></tr></table>							Part Number	Description	Qty.	Unit Price	Ext. Price	300-65350	SMITHS/ENGINE ASSY	1			CQ24060	adv/hose	1			T,00272SLLC2	SUPER LONG LIFE COOL	2			T,04152YZZA1	REPLACEABLE ELEMENT	1			T,9043012031	GASKET	1			T,002790W20101	0W20 BULK OIL-W	7			T,8946704120	SENSOR, AIR FU	1					
Part Number	Description	Qty.	Unit Price	Ext. Price																																													
300-65350	SMITHS/ENGINE ASSY	1																																															
CQ24060	adv/hose	1																																															
T,00272SLLC2	SUPER LONG LIFE COOL	2																																															
T,04152YZZA1	REPLACEABLE ELEMENT	1																																															
T,9043012031	GASKET	1																																															
T,002790W20101	0W20 BULK OIL-W	7																																															
T,8946704120	SENSOR, AIR FU	1																																															
						Line Total...	\$5,362.49																																										
B	GEN		A60		Customer																																												
Concern	PERFORM FRONT AND REAR BRAKE JOBS---REPLACED RR BRAKE LINKAGE AND BROKLINKAGE IS MISSING AND BACKING PLATE RUSTED OUT																																																
Cause	on the passenger side of the rear brakes every part was missing. there was no brake line. the emergency brake cable was cut. the backing plate was damaged. to remove the backing plate. the wheel baring needed replaced. the linkage on the drivers side was also damaged. parts in there was bent.																																																
Correction	on the passenger side we put everything that was needed to make brakes function properly. we had to replacethe wheel bearings to take the baking plate off and put the new plate on. ols wheel bearing was in very poor working condition and could not be reused. the axle shaft was a little damaged so we replaced it also. on the driver side we replaced the linkage and pads and shoes. both rear drums were un turnable. they was badly dented up from previous brake linkage not working properly. had to bleed out braking system.																																																

		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
		5TFSZ5AN9HX112613		1	1	12/09/20 13:03	02/03/21	
		VEHICLE DESCRIPTION				TAG NO.	STATUS	
		2017 TOYOTA TACOMA ACA					COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS	
							Cash	
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT	

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount
------	---------	-----------	------	-------	------	--------

B Continued

Part Number	Description	Qty.	Unit Price	Ext. Price
T,4755004030	CYLINDER ASSY,	1		
T,4764304030	LEVER, AUTOMAT	1		
T,0495408030	REACTION PLATE	1		
T,0494902060	PLUG KIT, RR D	1		
T,0494204010	SPRING KIT, RR	1		
T,0449504010	SHOE ASSY,	1		
T,0494104010	SPRING KIT, RR	1		
T,4732704080	TUBE, RR BRAKE	1		
T,4642004131	CABLE ASSY, PA	1		
T,4704304030	PLATE SUB-ASSY	1		
T,4764404030	LEVER, AUTOMAT	1		
T,90114A0009	BOLT, SERRATIO	4		
T,9052041019	RING, SNAP	1		
YH140819	ADV/BRAKR DRUMS	2		
T,0494304010	STRUT KIT, RR	1		
GNAD976	adv/frontbrakepads	1		
T,4231104082	SHAFT, RR AXLE	1		
T,4245004010	BEARING ASSY,	1		

Line Total... \$2,360.04

C + GEN A60 Customer
Concern REPLACE RADIATOR

Line Total... \$145.00

		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
		5TFSZ5AN9HX112613		1	1	12/09/20 13:03	02/03/21	-----
		VEHICLE DESCRIPTION					TAG NO.	STATUS
		2017 TOYOTA TACOMA ACA						COMPLETE
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS	
							Cash	
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT	

Customer Totals

Charge Description	Amount
Labor	
Parts	
Misc Charges	
SalesTax	
Total Amount Due	\$8,600.00

Check	\$8,600.00
CTRL#	---

X

CUSTOMER SIGNATURE