

Invoice for RO

Service Advisor:

Posted Date: 09/03/21 at 03:48 PM

Client:

Vehicle: 2013 Peterbilt 389 Base

	2013 Peterbilt 389 Base 12.9L 6Cyl DIESEL MX VIN: 1XPXDP9XDD199560 License: N/A Unit #: Color: N/A Odometer In: 583354 / Out: 583354	RO : Time-In: 08/23/21 at 07:01 PM Save Parts: No
--	---	---

Client concerns:

- REMOVE AND REPLACE TURBO

1 - REMOVE AND REPLACE TURBO		
Labor:	Pulled boost pipe drained coolant and removed wiring pulled turbo and had to removed stud from manifold installed new turbo and orings filled with coolant washed off test drive all is good	
Parts:	GASKET-EXHAUST TURBO	1
	STUD-METRIC CYL	4
	GASKET FLANGE TURBO	1
	BUSHING-ADAPTER	3
	NUT-HEX-M10X1.0	4
	O-RING	2
	O-RING	2
	RED ANTIFREEZE	2
✓ Approved on 08/23/21 at 07:01 PM		\$1,258.98

RO Fees	
Fee:	Shop Supplies
Subtotal	

Total Repair Order & Signature:

Total Labor:

Total Parts:

Total Fees:

Subtotal:

Grand Total: \$1,332.00

BALANCE DUE: \$0.00

X

✓ PAID

Completed Transactions		
09/03/21	\$1,332.00	Check Payment