

SOLD TO	

SALES-ON

TEAM

TK# 2000

PAGE 1

Powered by RoadSync

Invoice Total

LINE ITEMS

\$4819.20

COMMENTS

RECEIPT DETAILS

CLERK
PAYMENT METHOD
AMOUNT
CONVENIENCE FEE
GRAND TOTAL

\$4999.92

PAYER'S SIGNATURE

[Handwritten Signature]

PAID IN FULL

Please note that the charge may show up on your credit card statement as ROADSYNC, our payments partner.
No Refunds or Returns

This site uses RoadSync. For more information on RoadSync text RSINFO to (855) 936-4044.

[REDACTED]

PAID BY [REDACTED]

Fullbay Total

LINE ITEMS

\$1697.23

COMMENTS
RECEIPT DETAILS

CLERK
PAYMENT METHOD
AMOUNT
CONVENIENCE FEE
GRAND TOTAL

[REDACTED]
\$1760.88

PAYER'S SIGNATURE

[Signature]

PAID IN FULL

Please note that the charge may show up on your credit card statement as ROADSYNC, our payments partner.
No Refunds or Returns

This site uses RoadSync. For more information on RoadSync text RSINFO to (855) 936-4044.

H
R
T
P
62
M

PAID BY

Fullbay Total

LINE ITEMS

\$1097.23

COMMENTS

RECEIPT DETAILS

CLERK

PAYMENT METHOD
AMOUNT

CONVENIENCE FEE

GRAND TOTAL

\$1760.88

PAYER'S SIGNATURE

PAID IN FULL

Please note that the charge may show up on your credit card statement as ROADSYNC, our payments partner.
No Refunds or Returns

This site uses RoadSync. For more information on RoadSync text RSINFO to (855) 936-4044.

[REDACTED]

PAID BY

February 10/2020

LINE ITEM NO

\$1697.23

COMMENTS

RECEIPT DETAILS

CLERK
PAYMENT METHOD
AMOUNT
CONVENIENCE FEE
GRAND TOTAL

[REDACTED]

\$1760.88

PAYER'S SIGNATURE

[REDACTED]

PAID IN FULL

Please note that the charge may show up on your credit card statement as ROADSYNC, our payments partner.
No Refunds or Returns

This site uses RoadSync. For more information on RoadSync text RSINFO to (855) 936-4044.

[REDACTED]

Subtotal Amount	\$709.72
-----------------	----------

Total Amount	\$709.72
--------------	----------

[REDACTED]

* Visa Credit	\$709.72
---------------	----------

- Customer Copy -



Subtotal Amount	\$709.72

Total Amount	\$709.72
--------------	----------



* Visa Credit	\$709.72
---------------	----------

- Customer Copy -

Invoice

Page 1

						201 182899	

Tractor #	Year	Make Model	Odometer	VIN #	Engine Make/Model
2000	06	FTL COLUMBIA	1160000	X10593	DET
Trailer #		Make Model	License #	Hubodometer	

Work Requested

MIKE REQUESTS:

ETA

UNIT SVCD: TRACTOR

R/R STEERS W/ GY ---, BALANCE. PREMIUM PM W/ ROTELLA 15W40. 3-AXLE ALIGNMENT. TRACTOR DOT.

DESCRIPTION	UOM	REG. PRICE	PRICE	QTY	EXTENDED AMOUNT
ENDURANCE LHS 295/75R22.5 ST					
NEW DOT# LST					
TIRE FET					
ENDURANCE LHS 295/75R22.5 ST					
NEW DOT# RST					
TIRE FET					
15W40 PREMIUM TRACT DOT					
CHANGE TO ACTUAL OIL USED					
LF3620/P552100/B495 DET OIL					
LF3620/P552100/B495 DET OIL					
FF5369W/P550463/PF7621 FUEL					
DETAIL FILTER OR 0 QTY					
DETAIL FILTER OR 0 QTY					
TA TRUCK SERVICE DOT STICKER					
STANDARD SERVICE LABOR					
ROTELLA CHARGE C6					
15W40 ROTELLA BULK					
16-18972-000 LATERAL CONT ROD					
VALVE STEM ALUM TR545D					
D LP22.5 USED TIRE					
TREAD: 13/32					
D LP22.5 USED TIRE					
TREAD: 13/32					
ALIGNMENT SHIM SMALL					
THREE AXLE ALIGNMENT					
ED TO BE FREE OF DEFECTS IN MATERIALS					
OM THE ORIGINAL DATE OF SERVICE					
STANDARD SERVICE LABOR B					
STANDARD SERVICE LABOR					
PRE-TAPE 1 OZ 6 OZ STRIPS					
WIZARDS METAL POLISH CLOTH					
SHOP SUPPLY/ENVIRONMENTAL FEE					

Invoice

1



Tractor # 2000	Year 06	Make/Model FTL COLUMBIA	Odometer 521521	Vin # X10593	Engine Make/Model DET
Trailer #	Year 00	Make/Model	License #	Hubodometer	

ETA

Work Requested

MIKE REQUESTS:

TRACTOR: ULTIMATE PM WITH ROTELLA 15W 40 AND STEER BRAKES AND DRUMS

UNIT SVCD: TRACTOR

DESCRIPTION
CM 10082217 HUB W/ABS RING
STM 330 3106 GASKET
STM 449 4973 PRO TORQUE DRIVE
4707Q PLUS BRAKE SHOE KIT
4702Q PLUS BRAKE SHOE KIT
R/R DRIVE AXLE WHEEL SEAL (1)
50-100 MILES OF OPERATION AFTER WHEEL
TMC, NWRA, AND TRUCK OE MANUFACTURERS.
STANDARD SERVICE LABOR B
STANDARD SERVICE LABOR
INSTALL BRAKES W WHEEL SEAL
WHILE PERFORMING WHEEL SEAL SERVICE
STANDARD SERVICE LABOR B
STANDARD SERVICE LABOR
BRAKE SHOE REPLACE (1 AXLE)
FOR 1 AXLE
50-100 MILES OF OPERATION AFTER WHEEL
TMC, NWRA, AND TRUCK OE MANUFACTURERS.
STANDARD SERVICE LABOR B
STANDARD SERVICE LABOR
75W90 SYNTHETIC GEAR OIL QUART
JOHNSON BRAKE PARTS CLEANER 13
AXLE SURGEON
15W40 ULTIMATE
15W40 DELVAC BULK
LF3620/P552100/B495 DET OIL
LF3620/P552100/B495 DET OIL
FF5369W/P550463/PF7621 FUEL
DETAIL FILTER OR 0 QTY
DETAIL FILTER OR 0 QTY
STANDARD SERVICE LABOR
MUFFLER CLAMP
SHOP SUPPLY/ENVIRONMENTAL FEE

Date	Invoice #
12/11/2021	

		Year, Make, Model
		07
QTY	Description	
	REPAIRS MADE: PRESSURE TESTED THE ENGINE AND IT HAS A BLOWN HEAD GASKET. TORE THE ENGINE DOWN AND FOUND THAT IT ALSO HAD DROPPED LINERS AND THE ENGINE BLOCK WOULD HAVE TO BE COUNTER BORED AND NEW OVERHAUL KIT INSTALLED. PARTS WERE ORDERED FOR THE JOB DUE TO NATIONAL BACK ORDER WE HAD TO WAIT TO COMPLETE THE JOB.	
	PARTS HEAD \$3655.20 OVERHAUL KIT \$3753.77 ROD BEARINGS \$348.65 VALVE COVER GASKET \$52.75 OIL PAN GASKET \$68.75	
	HOURS OF LABOR	

Total	\$10,000.00
-------	-------------

Date	
3/9/2022	

Information
MILEAGE: 1178567

PO Number		Year, Make, Model	
		2007 FL COLUMBIA	
QTY	Description		
	FREIGHTLINER CAME OUT TO CUT THE COUNTER BORES DUE TO THE DROP LINERS. AFTER CUTTING THE COUNTER BORES WE INSTALLED NEW OVER HAUL KIT, NEW HEAD, NEW OIL FILTERS AND FUEL FILTERS. RAN AN OVER HEAD. TOOK TRUCK FOR TEST DRIVE.		
1	COUNTER BORE BLOCK (FREIGHTLINER)		
11	GALLON OF OIL		
2	OIL FILTERS		
1	FUEL FILTERS		
10	ANTIFREEZE		
4	BATTERY		
1	SHOP SUPPLY FEE		
41.5	IN SHOP LABOR HOURS		

Total	\$10,932.72
--------------	-------------

Invoice

Year	Make/Model
07	FTL COLUMBIA
Year	Make/Model
00	

Odometer	VIN #	Engine Make/Model
1194681	7LX10593	OTHER

Work Requested: MIKE REQUESTS: C/A AIR LEAK ON THE TRUCK

UNIT SVCD: TRACTOR

DESCRIPTION
AS9911 W26-358-9911 AIR BAG
HDR60850002
BRACKET
PINS
HBMHSJFR200
FLAGSTAFF
FREIGHT
R&R AIR BAG TRACTOR
STANDARD SERVICE LABOR B
STANDARD SERVICE LABOR
HX CP PL USS 5/8X2 8
FN HEX 8 PL 5/8-11
A/B 90 ML EL 1469X4
SHOP SUPPLY/ENVIRONMENTAL FEE
MECHANICAL HOURLY LABOR

TOTAL ► \$ 1,619.72

SERVICE INVOICE:

DATE INVOICE

5/16/2022

CUSTOMER PG

YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODGOMETER
2007	FTL	CL120	1FUJA6CK37LX10593	2000	0	6/30/2006	06R0892128	1198559

JOB #1 01D

DETROIT ENGINE COMPLAINT

COMPLAINT

DETROIT ENGINE COMPLAINT:

>>DIAGNOSTICS<<

CHECK ENGINE LIGHT IS ACTIVE. FAULTS ON DASH FOR INJECTOR RESPONSE TIME LONG.
(RECENTLY HAD TURBO REPLACED AT ANOTHER FACILITY).

CAUSE

CORRECTION

WENT OUT TO UNIT AND CONNECTED TO DIAG LINK. FOUND ACTIVE CODES FOR INJECTOR RESPONSE TIMES LONG FOR CYLS #2, #4, AND #6. STARTED ENGINE AND FOUND ENGINE HAS SEVERE MISFIRE. DROVE UNIT INTO SHOP. REMOVED INJECTOR HARNESS AND CHECKED FOR SHORT TO GROUND IN HARNESS. HARNESS IS GOOD. FOUND UNIT HAS POWER PROGRAMMER UNIT INSTALLED. REMOVED PROGRAMMER JUMPER HARNESS CONNECTOR AND RECONNECTED INJECTOR HARNESS DIRECTLY TO ENIGINE SENSOR HARNESS. STARTED ENGINE TO VERIFY OPERATION. ENGINE RUNS AS DESIGNED WITH PROGRAMMER REMOVED. REASSEMBLED UNIT. REPAIR COMPLETE.

DESCRIPTION

TRUCK REPAIR LABOR GUIDE

Year	Make		Model		Model No	
2007	FREIGHTLINER		COLUMBIA			
Plate #	VIN		Mileage In	Mileage Out	Sec Serial	
Time In	Date Promised	Date Of Purchase:	Notified Date:	Notified Time:	Appointment Date:	Completed Date:
NOTHING BUT TIME TRANSPORT						

Description

N/A

Problem: A/C IN LIVING QUARTERS AND ELECTRICAL OUTLETS NOT WORKING

Cause: BREAKER UNDER STEP WELL TRIPPED

Solution: DIAGNOSED TRACED ,TRIPPED AND RESET BREAKER . NOTE BREAKER DID NOT LOOK TRIPPED HAD TO PUT METER ON TO FIND ,TRIPPED AND RESET ,

TESTED INVERTOR OUTLETS RAN GENI AND TESTED A/C AND WATER HEATER -

Work performed by: HOLSTON

Total Labor

N/A

Problem: WANTS NEW INVERTOR INSTALLED, CUSTOMER HAS PART IN FRONT OF FRIDGE

Cause: ?

Solution: SEE JOB 1 , INVERTOR IS WORKING AS DESIGNED DOES CUSTOMER STILL WANT NEW INSTALLED APROX 227.50 TO INSTALL

Total Labor

N/A

Problem: HOT WATER NOT WORKING

Cause:

Solution: SEE JOB 1 - Work performed by: HOLSTON

Total Labor

Date : 5/5/2022

Page : 1

Vehicle : 2007 FREI

Unit # : 2000

VIN : X10593

Engine :

Mileage : 1198435

Description

Reason for Replacement

ABSOLUTELY NO WARRANTY ON ANY ELECTRICAL LABOR
THAT AN
HALF AN HOUR) WILL BE CHARGED AT FIRST, BUT
ING TO ACTUAL LABOR TIME SPENT PER MECHANIC.
INLET TEMP SENSOR

LEAN

FUEL L3578FN

OK Bad

Recommendation

OK Bad

Recommendation

OK Bad

Recommendation

Total : \$197.86

Invoice

Tractor #	2000	Year	07	Make/Model	PTL	Location	COLOMBIA	License #		Customer	1134681	City	TURKISH	Phone	0000
Tractor #		Year	00	Make/Model		License #				Subcontractor					
Work Requested				WORK REQUESTS:				C/A AIR LEAK ON THE TRUCK							
UNIT SVCD: TRACTOR															

DESCRIPTION
AS9911 W6-358-9911 AIR BAG
HERN0850002
BRACKET
PINS
HERN0850002
FLAGSTAFF
FREIGHT
R&R AIR BAG TRACTOR
STANDARD SERVICE LABOR 2
STANDARD SERVICE LABOR
EX CP PL USS 5/8X1 2
FW HEX 5 PL 5/8-11
A/B 90 ML EL 1469X4
SHOP SUPPLY/ENVIRONMENTAL FEE
MECHANICAL HOURLY LABOR

1. 613 72

Date : 3/30/2022

Vehicle : 2007 FREI

Unit # : 2000

VIN : X10593

Engine :

Trans :

Mileage : 1184150

Description	Part Number	Part Description	Reason for Replacement
DETROIT AND N 14 CUMMINS -PM OIL CHANGE FILTER & LUBRICATION ON			
TRACTORS: MERCEDES ENGINES INCLUDED CHANGE ENGINE OIL WITH UP TO 2 OIL			
FILTERS, 2 FUEL FILTERS, AND 44 QUARTS OF OIL			
* additional parts/oil extra			
OIL WILL NO LONGER BE PUT INTO ANY CONTAINERS, UNLESS PURCHASED			
		FILTER OIL LFP2160	
		FILTER FUEL L3578FN	
		OILBLK15W40 SHELL ROT	
REPPLEASE OIL PAN GASKET AND FILL TUBE			
		FILL TUBE GASKET	
		PAN BOLT WITH BUSHING	
		PAN GASKET	
		BRAKE CLEAN	
		OILBLK15W40 SHELL ROT	
GA REPLACE U JOINT			
		U-JOINT	
GA RESET PIPE			

Total : \$1,670.02

Invoiced: 3/18/2022

2007 FREIGHTLINER Columbia

VIN: 1FUJA6CK37LX10593
Mileage In: 1,179,725
Mileage Out: 1,179,725

Recommendations

Recommend Replacing / Finding Better Solution For Turbo Drain Line.

Description

- 1 Troubleshoot Engine Oil Leak
Found Oil Drain Line Has Been Modified & Has Pre Formed Radiator
Hose Installed To Connect The Oil Drain Line.
Removed Line & Located New Hose.
Installed Hose & New Clamps
Ran Unit & Verified No Leaks Present At This Time.
Ops Check Good
- 2 Pre Formed Hose
- 3 Hose Clamp
- 4 Parts Cleaner
- 5 CCD fee

Total: \$134.03

Date : 5/4/2022

Vehicle : 2007 FREI

Unit # : 2000

VIN : X10593

Engine :

Trans :

Mileage : 1198435

Description	Part Description	Reason for Replacement
Part Number		
CHECK EXHAUST LEAK		

DETROIT AND N 14 CUMMINS -PM OIL CHANGE FILTER & LUBRICATION ON
TRACTORS: MERCEDES ENGINES INCLUDED CHANGE ENGINE OIL WITH UP TO 2 OIL
FILTERS, 2 FUEL FILTERS, AND 44 QUARTS OF OIL

* additional parts/oil extra

OIL WILL NO LONGER BE PUT INTO ANY CONTAINERS, UNLESS PURCHASED

Paid By :

Total :

\$1,379.79

Invoice

Tractor # 2000	Year 07	Make/Model FTL COLUMBIA	License # N5235HY TN	Odometer 859753	VIN # 7LX10593	Engine Make/Model OTHER
Trailer #	Year 00	Make/Model	License #	Hubodometer		

Work Requested

WHEEL SEAL LEAKING AGAIN

UNIT SVCD: TRACTOR

DESCRIPTION	
JOHNSEN BRAKE PARTS CLEANER	13
STM 330 3106 GASKET	
SHOP SUPPLY/ENVIRONMENTAL FEE	
MECHANICAL HOURLY LABOR	

TOTAL ► \$

83.86