

INVOICE

30902

Invoice from History

Printed Date: 11/21/2023

Work Completed: 11/16/2023

2011 Utility - Van Dry - ThermoKing

Lic #: 845143

Odometer In : 0

VIN #: 1VYBS2533 CM401104

Part Description	Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Housing, Shaft Idler		1.00			REEFER UNIT - Diagnose	1.50	
781013					- Found snapped belt, inspected all pulleys, idler housing is binding and catching during rotation, other belts are dri-rotted. Recommend replacement of all three belts and idler housing assembly. Located and ordered parts per Martin O.'s approval.		
Belt		1.00					
780629							
Belt		1.00			REEFER UNIT - Repair	5.00	
781341					- Removed and replaced defective idler housing assembly and installed belts. Adjusted all belts. Started and ran unit for approximately 1/2 hour and reinspected belt tensions. Readjusted lower belt tension. All looks good. Reassembled and parked trailer.		
Belt		1.00					
780603							
Shop Supplies					EPA		

[Payments -]

Labor:

Parts:

HazMat:

Sub:

Tax:

Total: \$3,160.29

Bal Due:

Vehicle Received: 11/16/2023

Signature

Date