

STATE OF MISSOURI

Item	Description
Parts	Archer Premium Arpeco 15W40 API CK-4/SN / Gallon Bulk
Parts	WIX Primary Spin-On Fuel Filter

Complaint: Rebuild engine/ swap parts

Cause: Customer request

(Inspection)

Labor **Correction:**
Chassis / Chassis / Rebuild engine / swap parts

Parts Rebuilt Kubota D722 engine

Parts Freight Charge

Parts Gaskets Kit

Parts Water Pump Assembly

Parts Hoses

Parts Shipping and Handling

Parts Thermostat

Parts Thermostat Gasket

Parts Compressor Drive Belt

Parts Water Pump Belt

Parts Molded Coolant Hose

Parts Fuel Line Fitting

Parts Fuel Line Tee

Parts Coolant Reservoir Cap

Parts Intake Air Hose

Parts Fan Drive Belt

Parts Alternator Belt

PM: Replace batteries

Cause: Customer request

(Inspection)

Labor **Correction:**
1-Engine / Starting & Charging / Includes: Perform Load tests on battery(s). Visually inspect electrical connections. Perform Voltage drop test at starter connections. Test for proper powers and grounds. Monitor starter actuation and verify correct engagement. Advise owner of findings.

Parts MagnaPower 925 CCA Group 31 Commercial Battery (Deka Value Line)

Parts Dirty Core for MagnaPower 925 CCA Group 31 Commercial Battery (Deka Value Line)

STATE OF MISSOURI

Quantity Rate

Item	Description
Parts	Archer Premium Arpeco 15W40 API CK-4/SN / Gallon Bulk
Parts	WIX Primary Spin-On Fuel Filter

Complaint: Rebuild engine/ swap parts**Cause:** Customer request

(Inspection)

Labor **Correction:**
Chassis / Chassis / Rebuild engine / swap parts

Parts Rebuilt Kubota D722 engine

Parts Freight Charge

Parts Gaskets Kit

Parts Water Pump Assembly

Parts Hoses

Parts Shipping and Handling

Parts Thermostat

Parts Thermostat Gasket

Parts Compressor Drive Belt

Parts Water Pump Belt

Parts Molded Coolant Hose

Parts Fuel Line Fitting

Parts Fuel Line Tee

Parts Coolant Reservoir Cap

Parts Intake Air Hose

Parts Fan Drive Belt

Parts Alternator Belt

PM: Replace batteries**Cause:** Customer request

(Inspection)

Labor **Correction:**
1-Engine / Starting & Charging / Includes: Perform Load tests on battery(s). Visually inspect electrical connections. Perform Voltage drop test at starter connections. Test for proper powers and grounds. Monitor starter actuation and verify correct engagement. Advise owner of findings.

Parts MagnaPower 925 CCA Group 31 Commercial Battery (Deka Value Line)

Parts Dirty Core for MagnaPower 925 CCA Group 31 Commercial Battery (Deka Value Line)

21919

6/14/2023

Unit #

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Customer states: Perform a visual inspection and advise the owner of needs.

Cause: Customer request

00-000 00-000 00000.0

Labor **Correction:** 00000.0

Chassis / Chassis / Customer states: Perform a visual inspection and advise the owner of needs. Passenger side outer dual has screw in it, doesn't seem to leak. See attached picture.

00-000 00-000 00000.0

Subtotal

Complaint: Customer states: Suspects the reefer unit needs a head gasket. Confirm and make an estimate.

Cause: Customer request

00-000 00-000 00000.0

Labor **Correction:**

Reefer Unit / Reefer Engine / Customer states: Suspects the reefer unit needs a head gasket. Confirm and make an estimate. Remove engine and diagnose. Found head was cracked.

Subtotal

PM: Full Service (Chassis Lube, Engine Oil & Filters)

Cause: Customer request

(PM)

Labor **Correction:**

1-Engine / Lubrication / Includes: Drain engine oil and refill crankcase. Remove and replace engine oil filter(s). Inspect and replace as needed, Fuel Filter(s), Water Filter, and Air Filter(s). Lubricate chassis and perform free visual inspection of the vehicle.

Parts Baldwin Full-Flow Spin-On Lube Filter

Parts Baldwin High Efficiency Spin-On Fuel Filter

21919

6/14/2023

Unit #

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Customer states: Perform a visual inspection and advise the owner of needs.

Cause: Customer request

Labor **Correction:**

Chassis / Chassis / Customer states: Perform a visual inspection and advise the owner of needs. Passenger side outer dual has screw in it, doesn't seem to leak. See attached picture.

Item **Description**

Complaint: Customer states: Suspects the reefer unit needs a head gasket. Confirm and make a

Cause: Customer request

Labor **Correction:**

Reefer Unit / Reefer Engine / Customer states: Suspects the reefer unit needs a head gasket. Confirm and make an estimate. Remove engine and diagnose. Found head was cracked.

PM: Full Service (Chassis Lube, Engine Oil & Filters)

Cause: Customer request

(PM)

Labor **Correction:**

1-Engine / Lubrication / Includes: Drain engine oil and refill crankcase. Remove and replace engine oil filter(s). Inspect and replace as needed, Fuel Filter(s), Water Filter, and Air Filter(s). Lubricate chassis and perform free visual inspection of the vehicle.

Parts **Baldwin Full-Flow Spin-On Lube Filter**

Parts **Baldwin High Efficiency Spin-On Fuel Filter**

Inherent Core for MagnaPower 925 CCA Group 31 Commercial Battery (Deka Value Line)

PM: MVI Inspection

Cause: Customer request

(PM) (00.500.10 to 00000.00)

Labor **Correction:**

Chassis / Chassis / Missouri State Inspection

Complaint: windshield

Cause: Customer request

(Inspection)

Parts Replacement Windshield and Installation Kit

Labor Install Windshield

Complaint: Reefer fan system diagnostics and repair

Cause: Failed switch

(Inspection)

Labor **Correction:**

Chassis / Chassis / Inspection and testing of the evaporator fan control system found a failed pressure switch. Bypassed the switch and the fan system is operating at this time. The switch needs to be replaced. Also the control panel inside the cab does not appear to be working correctly. Remove and replaced the switch assembly and retested. The fan system works normally.

Parts Pressure Sensor

Parts Drop Ship Charge

(Inspection)

Correction:

1-Engine / F

turning off the fuel to the engine when commanded. Removed the fuel line for replacement and found a spring was out of place. Corrected the spring placement and reinstalled. The shut-off system operates correctly now.