

INVOICE

DATE	INVOICE #
1/29/2004	2212

P.O. #/CONTACT	TERMS
	Due on receipt

QUANTITY	DESCRIPTION	RATE	AMOUNT
1	Harsh RDL 40 Hoist W/ Electric Pump		
1	10 Ft. Flat Bed installed on 1997 International Sales Tax		
	9.9-13.5 T		
	Paint check # 2580		
DISCLAIMER OF WARRANTY: Central Truck Equipment, Inc. makes no warranty, expressed or implied, that extends beyond the description of the items above, unless otherwise noted in writing. By acceptance of the items listed above, the customer acknowledges that the he/she (customer) has either examined the items as fully as desired, or has been given the opportunity for such examination and has refused to make such examination. Central Truck Equipment, Inc. neither assumes nor authorizes any other person to assume for it any liability in connection with this sale. Central Truck Equipment, Inc. must do all authorized warranty work or the customer assumes full responsibility for it. TERMS: Invoices over 30 days late may be subject to a service charge of 2%/mon (24% APR) or a minimum of \$1.00. In the event that Central Truck Equipment, Inc. employs an attorney for collections of any amount, the customer agrees to pay all collection and attorney fees, plus all court costs. There will be a \$30.00 fee on all returned checks.			
			Total \$4,539.00

1997 International 4700 Base 7.3L 8Cyl
DIESEL T444E Turbocharged
VIN: 1HTSCABM0VH478016
License: 532831
Color: White
Odometer In: 120222 / Out: 120237

RO #5932
Time-In: 02/10/23 at 04:44 PM CST
Promised Time-Out: 02/28/23 at 05:00 PM
CST
Save Parts: No

Client concerns:

- Warm engine light on on the dash and engine will only idle
- Parking brake isn't holding

1 - Warm engine light on on the dash and engine will only idle

Labor:

Pulled trouble codes from vehicle and researched codes for reliability. Followed OEM pinpoint testing procedure. See video for details. Inspected and tested wiring and found the wiring and connectors were okay. The next step in the testing procedure would be to replace the accelerator pedal position sensor and then retest

✓ Approved on 02/10/23 at 04:48 PM CST

2 - Parking brake isn't holding

Labor:

Inspected parking brake and found that the shoes are worn thin. There is a slight adjustment left that can be made, but the shoes are thin enough they should be replaced. Recommend replacing the shoes and springs.

✓ Approved on 02/10/23 at 04:48 PM CST

3 - Parking Brake Repair

Labor:

Remove parking brake drum and inspected parking brake and found that the shoes are worn thin. There is a slight adjustment left that can be made, but the shoes are thin. Replaced parking brake shoes and necessary hardware. Made necessary adjustments to the parking brake and checked for correct operation

Part:

Parking Brake Shoe Kit

✓ Approved on 02/22/23 at 03:36 PM CST

4 - Accelerator Pedal Position Sensor Replacement - Aftermarket

Labor:

Remove and replace accelerator pedal assembly with new aftermarket part. Clear codes and run engine to check correct operation of engine

Part:

DM Accelerator Pedal Assembly

✓ Approved on 02/22/23 at 03:36 PM CST

Total Repair Order & Signature:

pd
4/14/23

Total Jobs:

Total Fees:

Subtotal:

Taxes:

Grand Total:

BALANCE DUE: \$1,769.10

X