

1999 Isuzu NPR Base 4.8L 4Cyl DIESEL 4HE1
Turbocharged
VIN: JALB4B147X7018926
License: 532834
Color: White
Odometer In: 116325 / Out: 116335

RO #5701
Time In: 12/20/22 at 08:58 AM CST
Save Parts: No

Client concerns:

- Replace transmission with remanufactured unit - look into brand options
- Kirk will be trailering truck from Salina on Monday or Tuesday 12/19 or 12/20

1 - Replace transmission with remanufactured unit - Customer Supplied

Labor: Remove and replace transmission assembly with customer supplied part. Fill transmission fluid with new transmission fluid and Lucas transmission treatment. Run engine to operating temperature to check for leaks. Recheck fluid level and test drive vehicle to check for correct operation of transmission. Recheck fluids and for leaks.

Parts: Eco Ultra Medallion Plus Full Synthetic Global Multi-Vehicle Automatic Transmission Fluid
LP Lucas Transmission Treatment
CQ Transmission Filter
BR Hose Clamp
Misc Hardware

✓ Approved on 02/01/23 at 08:22 AM CST

Total Repair Order & Signature:

X

Total Jobs:
Total Fees:
Subtotal:
Taxes:
Grand Total:
BALANCE DUE: \$1,798.26

pd 4/1/23

INVOICE

5443

Org. Est. # 002278

INVOICE

Date: 07/18/2017

1999 Isuzu - NPR - 4.8L L4

Lic # :532834 - KS

Odometer In : 98266

Odometer Out : 98276

VIN # :JALB4B147 X7018926

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
TURBO MOUNTING GASKET 8-973474-412-0	1.00			Vacuum front floor board and wash front windows while in for service.	
TURBO MOUNTING NUT 9-09842-007-0	4.00			51-POINT ACDelco Inspection Performed inspection per ACDelco check sheet.	
TURBO MOUNTING STUD 9-04731-028-0	2.00			CUSTOMER STATES HEARS A RATTLE NOISE DRIVING DOWN THE HIGHWAY. - Check and report.	
TURBO MOUNTING STUD 9-04731-025-0	2.00			PULL TURBO AND REMOVE BROKEN STUDS TO RESEAL MOUNTING	
GASKET 1-09630-085-0	4.00			Removed broken bolts and studs from turbo and exhaust manifold and reassembled with new gaskets and hardware. One bolt was very difficult to remove and required multiple attempts.	
O-RING 1-09623-462-0	1.00			REPLACE LEAKING VACUUM PUMP Replaced leaking vacuum pump that is drive from the back of the alternator. Replaced worn belts while apart.	
7/16-14 Grde 5 Hex Nut L95680	30.00			PATCH COOLANT RESERVOIR	
VACUUM PUMP ASSEMBLY 8-97167-894-0	1.00				
GASKET 1-09630-083-0	2.00				
GASKET 1-09630-085-0	2.00				
AUTO V-BELT / Accessory Drive Belt 17420	2.00				
AUTO V-BELT / Accessory Drive Belt 17620	1.00				
Shop Supplies					
Hazardous Materials					

Revision # 1, Previous Estimate Amount: 1.63, Additional Cost: 2100.58, Revised Estimate: 2102.21, Parts: \$1057.78 Labor: \$963.12 Sublet: \$0.00 Taxes & Fees: \$179.68
Authorized by - Wollesen, Kirk, Date - 6/30/2017, Time - 6:35 PM, Initialed By - Shop, Written By - Kreever, Eljah, Phone Number - : 785-658-5240xSusan

Revision # 2, Previous Estimate Amount: 2102.21, Additional Cost: 60.16, Revised Estimate: 2162.37, Parts: \$0.00 Labor: \$53.95 Sublet: \$0.00 Taxes & Fees: \$6.21
Authorized by - Wollesen, Kirk, Date - 6/30/2017, Time - 6:42 PM, Initialed By - Shop, Phone Number - : 785-658-5240xSusan

Revision # 3, Previous Estimate Amount: 2162.37, Additional Cost: 6.90, Revised Estimate: 2169.27, Parts: \$9.80 Labor: \$0.00 Sublet: \$0.00 Taxes & Fees: \$-2.70
Authorized by - Wollesen, Kirk, Date - 6/30/2017, Time - 6:42 PM, Initialed By - Shop, Phone Number - : 785-658-5240xSusan

Labor:

Parts:

HazMat:

SubTotal:

Tax:

Total:

Bal Due: \$2,405.15

[Payments -]

PO #: 1
REF #: 7

Item #	Size	Description	Slmn/Tech	Qty	PET	Parts	Labor	Extended
000-179	LT235/85R16	FIRESTONE TRANSFORCE	9999/11	6				
		AT2 [BL] [120] [R] [10]						
TD		TIRE DISPOSAL FEE	9999/11	6				

Comments:

THANK YOU FOR YOUR BUSINESS!

WE NOW HAVE A PAYMENT DROP BOX LOCATED TO THE LEFT OF THE OFFICE FRONT DOOR

Cash:		Name	Acct	Auth	Amount	Parts:	
Credit Card:						Labor:	
						Subtotal:	
Amount Tendered:						Excise Tire Tax:	
Total:	-					Sales Tax:	
Change:						Total:	\$1168.55

Customer Authorization: _____