

SERVICE INVOICE

● ● ● ● ● ● ● ● ● ●

SEGMENT# 1 C 5237 NA

Replace Seat

CORRECTION:

Tech 5237

- Removed 4 hold down bolts on the seat
- Removed the seat from the machine
- Placed new seat in position
- Reinstall 4 hold down bolts
- Complete

FREIGHTIN
22P-57-11202

FREIGHT IN
SEAT ASS'Y

1
1 N

PARTS

LABOR

11700001

SEGMENT TOTAL==>

***** WORK ORDER TOTALS *****

PARTS

LABOR

EPA CHARGE

SHOP SUPPLIES

SUB TOTAL==>

CO STATE TAX

DENVER City

RTD GREATER DENVER Special

SCIENTIFIC & CULTURAL FAC.(CD) Special

TOTAL CHARGE SALE

2808.04

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/BIN	WARRANTY DATE	HRS
C009626	PC88MR-8 HYDRAULIC	7414	6251		
B-04	PC88MR-8		WY 291421	2016	

SEGMENT# 1 C 5094 NA 04/01/24 04/01/24

Fix and install

CORRECTION:

Tech 5094

- Install new hydraulic cylinder rod guard
- Ears welded to cylinder that pads bolt to were bent
- Was able to use a hammer and drift to straighten ears
- One of the ears had a caved in bolt hole
- Bolt would not go through hole
- Used a die grinder to make hole round again
- Using supplied hardware and new pads, bolt pads to ears
- Attach new rod cover
- Test function to check for cover sliding on pads
- Cover seems to move freely at this time
- Park machine in yard
- Repair complete
- SMR 7414 hours

ADDITIONAL DESCRIPTION:

Will have to fix mounting brackets and install new guard.

May need more time if have to cut off and weld new ears for bracket.

FREIGHTIN	FREIGHT IN	2
01010-80816	BOLT	4
01010-81025	BOLT	2
01643-30823	WASHER	4
01643-31032	WASHER	2
20T-70-71630	PAD	2 N
20T-70-71640	COLLAR	2 N

CONTINUED ON PAGE 02

SERVICE INVOICE

● ● ● ● ● ● ● ●

1245.64