

MATERIAL ALL PARTS NEW UNLESS SPECIFIED. USED, R-REBUILT, RQ-RECONDITIONED

QTY. PART NO. NAME OF PART

1 257204001 2 Pos. switch
1 257541011 3 Pos. speed switch

TOTAL PARTS

MECHANICS RECOMMENDATIONS

WARRANTY
Y/N

CUSTOMER'S INFORMATION

RECEIVED (DATE & TIME) A.M. P.M.

12-21-23 2-1-24

CUSTOMER'S ORDER NO.

1691120691000134

YEAR MAKE MODEL

75 750

LICENSE NO.

1442

ODOMETER

1442

☐ LUBE ☐ OIL CHANGE ☐ FLUSH TRANS. ☐ FLUSH DIFF. ☐ WASH ☐ POLISH

CHARGE FOR HAZARDOUS OR OTHER WASTE REMOVAL *

Cleaned all connections, reset codes. Replaced kill switch on Backhoe off. Replaced 3 wiper Torsion speed control on Backhoe all. check wiring to all sensors. 3.

METHOD OF PAYMENT:

☐ CHECK ☐ CHARGE

☐ CASH

Doing business with customer has been completed and customer has been notified. No charges shall accrue or be due and payable for a period of 3 working days from date of notification.

TOTAL 578.00

replaced, except those for which there is a core charge, unless I do not desire the return of any of the parts that are

or damage caused by theft, fire, or acts of nature, I authorize materials. I authorize you and your employees to operate my and delivery at my risk. An express mechanic's lien is hereby in amount of the repairs thereto. If I cannot repair prior to their assembly fee of \$ will be applied.

Date	10/23/2023	Time	10:13:42 (O)	Page	1
Account No	TER01001			Est No	02
				001238	
Ship Via			Purchase Order	TBD	
Tax ID No					
			Salesperson	527	
ESTIMATE EXPIRY DATE: 11/22/2023					

SERVICE ESTIMATE - NOT AN INVOICE

This is the quote for the oil & fuel service for the RTX750.
 This quote will not cover any additional freight or repairs
 that may be needed. If the technician runs into any
 additional concerns he will stop repair and a new quote
 will be generated.
 Please let me know if you authorize the repairs that are
 listed.

Stock #: 1064016 RTX750

MS #: 1VR9112M691000134

Make: VE Model: RTX750

Is to have the following work done

PM04 - 1000 Hour PM

ADDITIONAL DESCRIPTION:

HRS

1. PM04 - 1000 Hour PM (PM04V)

PM04 - 1000 Hour PM

Quantity

Part#	Description	Qty
DELO	15W40 OIL	3
154908001	OIL FILTER - CU	1
180012271	FUEL FILTER	1

MISCELLANEOUS CHARGES:

Description
 FREIGHT

Estimate is good for thirty (30) days from date above.

Thank You For Your Business!

Date 10/23/2023	Time 10:13:42 (O)	Page 2
Account No TER01001	Phone No 8063502900	Est No 02 001238
Ship Via	Purchase Order TBD	
Tax ID No		
		Salesperson 527
ESTIMATE EXPIRY DATE: 11/22/2023		

SERVICE ESTIMATE - NOT AN INVOICE

Authorization: _____

TOTAL: 1613.32

Estimate is good for thirty (30) days from date above.

Thank You For Your Business!

WO #	W03444
Equip	2023 VERMEER LP XD Traile
Serial #	7NWH16A81PK050342
Equipment ID	01-01-1060633
Hours / Miles	411

Trailer (N/A for skid mounted)	
Tires and Rims	INSPECTED
Trailer Lights	INSPECTED
Breakaway Brake Cable (Inspect)	INSPECTED
Breakaway Brake Circuit (Test)	INSPECTED
Brakes - Test/Adjust	INSPECTED
Brake Controller - Test/Adjust	INSPECTED
Highway Lights	INSPECTED
Slip Hook	INSPECTED
Towing Chain	INSPECTED
Jack Stand	INSPECTED

Date	Time	Page
11/09/23	13:14:19 (0)	01
Account No		Inv No
TER01001		W0344114
Ship Via	Purchase Order	
Tax ID No		
		Salesperson
		389

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
1064016	RTX750	1060	1VR9112M691000134		
	RTX750				

SEGMENT# 1 S 1957 2006V 10/31/23 10/31/23 11/09/23

2006 - Throttle Cable/Actuator R&R CMP

CAUSE:

Machine will not start

CORRECTION:

Auto throttle spring was off reconnected and cleaned
fuel shut off and pushed back in and tested machine will
start and run tried it several times and would start
returned machine to service

ADDITIONAL DESCRIPTION:

UNIT WILL NOT START

1. 2006 - Throttle Cable/Actuator R&R CMP
(2006V)
- 2006 - Throttle Cable/Actuator R&R CMP
1. Vermeer Parts Manual Page Reference, 6-2

Quantity

11100000

S

Thank You For Your Business!

Date	Time	Page
11/09/23	13:14:19 (O)	02
Account No	Inv No	
TER01001	W0344114	
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	389	

SERVICE PRELIMINARY

STK#/FLEET#

1064016

RTX750

RTX750

HRS PIN/EIN

1060 1VR9112M691000134

WARRANTY DATE

HRS

TOTAL CHARGE SALE

311.70



X

Authorized By

Thank You For Your Business!

Branch			
REPRINT			
Date	Time	Page	
07/17/23	22:05:51 (B)	01	
Account No	Phone No	Inv No	
AW BR001			
Ship Via	Purchase Order		
Tax ID No			
			Salesperson 389

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
1049462	VERMEER RTX750	1413	1VR9112M691000134	
	RTX750		MXCSGN	

SEGMENT# 1 C 3841 4L00V 06/28/23 06/29/23 07/07/23

4L00 - Hydraulic Labor

CAUSE:

both rear steer hyd lines where found to have been blown
and need to be replaced with new and top off fluid

CORRECTION:

replace both rear steer hyd lines with new

ADDITIONAL DESCRIPTION:

REAR STEER HOSE LEAKING

1. 4L00 - Hydraulic Labor (4L00V)
- 4L00 - Hydraulic Labor

Quantity

FI	FREIGHT-IN AND
101519005AG	ISO 100 BULK
261471001Z	HOSE
296295828	HOSE-HYD-.25X4

10200014

LABOR
CONTINUED ON PAGE 02

345.25

Branch			
Date 07/17/23	Time 22:05:51 (B)	Page 02	
Account No AW BR001	Phone No	Inv No	
Ship Via		Purchase Order	
Tax ID No			
		Salesperson 389	

SERVICE INVOICE

STK#/FLEET#
1049462

VERMEER RTX750
RTX750

HRS PIN/EIN
1413 1VR9112M691000134
MXCSGN

WARRANTY DATE HRS

ENVIRO CHARGE
SHOP SUPPLIES
SUB TOTAL==>
: DISTRICT NO 1
TX STATE TAX
CUSTOMER TOTAL

775.37

Branch			
Date	Time	Page	
06/28/22	22:09:03 (B)	02	
Account No	Phone No	Inv No	
Ship Via		Purchase Order	
Tax ID No			
		Salesperson 389	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
1049462	VERMEER RTX750	1181 1VR9112M691000134		
	RTX750	MXCSGN		

SEGMENT# 2 C 7003 0000V 02/02/22 02/03/22 03/29/22

0000 - Diagnostic

CORRECTION:

The return line for the injectors was leaking fuel all down the front of the engine. Replaced the rubber return lines and tested. This also was contributing to the over heating issue.

ADDITIONAL DESCRIPTION:

Fuel Leak

- 1. 0000 - Diagnostic (0000V)
- 0000 - Diagnostic

Quantity

10200014

SEGMENT# 3 C 2013 4033V 02/02/22 02/03/22 03/29/22
4033 - PUMPS-HYDROSTATIC R&R INCLUDE FLUSHING CMP*****

CAUSE:

Low hydraulic pressure on trencher attachment

CORRECTION:

Customer brought machine in with low hydraulic pressure. Flow tested the trencher attachment and it had low flow and no pressure. Checked the EDC on the pump and found no issues. Removed the EDC from the pump and found that the swash plate had failed. Removed the gear pump from the pump stack and found that it had failed and sent metal

CONTINUED ON PAGE 03

Branch			
Date	Time		Page
06/28/22	22:09:03	(B)	04
Account No	Phone No	Inv No	
Ship Via	Purchase Order		
Tax ID No			
			Salesperson 389

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
1049462	VERMEER RTX750	1181	1VR9112M691000134		
	RTX750		MXCSGN		
296387479			FILTER ELEMENT		
	FILTER ELEMENT - HYD				
6988096			ANTIFREEZE/COOL		
787-4			HYD HOSE		
10200014					

 DOCUMENT TYPE: 22

Branch			
Date	Time	Page	
10/21/22	22:07:42 (B)	03	
Account No	Phone No	Inv No	
Ship Via		Purchase Order	
Tax ID No			
		Salesperson 389	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
1049462	VERMEER RTX750	1283	1VR9112M691000134	
	RTX750		MXCSGN	

greased the machine. All good at this time.

ADDITIONAL DESCRIPTION:

DIAGNOSE AND REPAIR DIFF ISSUES

SEGMENT# 4 C 2013 00000 07/08/22 07/12/22 08/26/22
 WRITE OFF
 WRITING OFF LABOR DUE TO CUSTOMER MACHINE COMING BACK
 MULTIPLE TIMES.

***** WORK ORDER TOTALS *****

PARTS
 LABOR
 SUB TOTAL==>
 TX SPECIAL TAX
 TX STATE TAX
 CUSTOMER TOTAL

