

Work Order Period

02/23/2024 03:27 PM

09/10/2024 03:27 PM

Tel:		Fax:	
Rental Period Invoiced:		0 days	

Quote #	Res. #	Ctr. #	Order #	Job #/PO#
0	0	0	188621	

Item Code	Description	Qty	T
NON INVENTORY	CSS9293 CRANK SHAFT SENSOR	1	
NON INVENTORY	A31012 FUEL PICKUP (IN TANK)	1	
NON INVENTORY	33960 FUEL FILTER	1	
NON INVENTORY	BOSFOUR-LOO-129 FUEL RAIL	1	
NON INVENTORY	BOSFOUR-LOO-143 FUEL RAIL	1	
NON INVENTORY	RO 455 120 042 FUEL INJECTORS	8	
NON INVENTORY	904-124 PRIMER HOUSING SEAL KIT	1	
NON INVENTORY	HIGH PRESSURE PUMP	1	
LABOR-VEHICLE	LABOR-VEHICLE	32	

2007 Chevy
7F139161

Work Order Notes

Damage Waiver

0.00

Subtotal

Customer: 3000
Print Time: 9:51:15AM
Terms: Credit Card

Item	Description	Ship Qty	Back Order	UOM	Unit Price	Amount
1	IIS0986437332SE-IIS 2006-2010 LBZ LMM Duramax Industrial Injection Reman Stock CP3 Injection pump CORE CHARGE OF \$300 APPLIES Warehouse: Texas Warehouse WARNING: This product contains chemicals known to the State of California to cause cancer and/or birth defects or other reproductive harm.	1	1	0	Each	
Ship Via: UPS Ground						
2	COREIIS300 \$300.00 Core Charge Warehouse: Texas Warehouse	1	1	0	Each	
Ship Via: UPS Ground						

Net Order:

740.00

ORDER DATE 08/19/24	REQ DATE 08/20/24	SHIP DATE 08/20/24	CUSTOMER P/O NUMBER EQ61-15399		PAYMENT TERMS NET 30 DAYS	
			ORDERED BY		SHIP VIA PICKUP / WILL CALL	
PRODUCT / DESCRIPTION			QUANTITY OPEN	U/M	QUANTITY SHIPPED	QUANTITY BACKORDERED

REB0986-435-521

INJECTOR REMAN 6.6L DURAMAX

2006-2007 LBZ VIN 2 D

COR0986-435-521

1 EA

1

0

ORDER DATE 08/19/24	REQ DATE 08/20/24	SHIP DATE 08/20/24	CUSTOMER P/O NUMBER EQ61-15399	PAYMENT TERMS NET 30 DAYS			
			ORDERED BY	SHIP VIA PICKUP / WILL CALL			
PRODUCT / DESCRIPTION			QUANTITY OPEN	U/M	QUANTITY SHIPPED	QUANTITY BACKORDERED	PRICE / EXTENSION

REB0986-435-521

7 EA

7

0

INJECTOR REMAN 6.6L DURAMAX

2006-2007 LBZ VIN 2 D

T-1TN00179-1

COR0986-435-521

Warranty 24 Months

Unlimited Mileage

This injector is a coded injector requiring the injector code be entered into the engine ECM, not doing so will result in poor engine performance. The code for this injector is 8 digits long.