

***** Customer Review *****

Date / Time: 10/25/2022 11:30:33AM

Repair Order: 126503

Customer: 22636

Invoice Total: \$11,840.14

Charge

Page 4 of 4

Customer P/O: need

mseedorf

Completion Date:

Task 5 Totals: \$630.00

Totals

Total Parts:

Total Core Chg:

Total Core Ret:

Total EHC:

Total Labor:

Total Miscellaneous:

Invoice Subtotal:

Total Tax:

Invoiced Total: \$11,840.14

Payment Method

Charge

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. Clerical errors subject to correction. 1.5% per month service charge on all past due accounts.

***** Customer Review *****

Date / Time: 7/27/2020 1:41:02PM
Repair Order: 102342
Customer: 22636

Invoice Total: \$ 51,106.11

Charge

Page 1 of 7

Customer P/O: needs akrause

Completion Date:

Unit Number: 536

Model Year: 2013

Make/Model: Peterbilt

Type: Truck

VIN: 1XPXD49X6DD163050

Meter: 837109 Miles

ECM Reading: 1

Engine Model : ISX

Engine S/N : 79554568

Ext. Warranty : ENGINE ENCORE 2YR 200K 11-14-16

Task: 1 45-020001 Engine R & I From Frame

Department: Service

Complaint: Replace engine per estimate attached.

Correction: Removed and replaced engine

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc	Shop Supplies - Service	Misc		1.00
CLASSRE-C	DR6588D/ENG L1 CORE	Inherent		1.00
ENG SER# 60840646				
DR7004RXCUM	ENGINE ISX 15	Part	EACH	1.00
ENG SER# 60840646				
CLASSRE-C	DR6588D/ENG L1 CORE	Part	EACH	(1.00)
3081695	SEAL,O RING	Part	EACH	1.00
3678606CUM	SEAL,O RING	Part	EACH	4.00
3902663CUM	SCREW,HEX FLANGE HEAD	Part	EACH	2.00
	CAP			
3678912CUM	SEAL,O RING	Part	EACH	1.00
3049221CUM	SAL,RNG 0829	Part	EACH	1.00
3678603CUM	SEAL,O RING	Part	EACH	3.00
CPB63062RS2HT	BEARING- PILOT (2.833X1.179)	Part	EACH	1.00
4059172CUM	SEAL,O RING	Part	EACH	1.00
3684338CUM	GASKET,CONNECTION	Part	EACH	1.00
3163075	PAINT-APEX RED	Part	EACH	1.00
3678756CUM	SEAL,O RING	Part	EACH	1.00
4966441CUM	EXHAUST GASKET	Part	EACH	1.00
4963857CUM	GASKET,INJECTOR	Part	EACH	1.00
5292265CUM	ISOLATOR- THERMAL	Part	EACH	1.00
3687932CUM	FILLER CAP	Part	EACH	1.00
2869220CUM	RETAINER,COVER	Part	EACH	1.00
127760DAN	BRAKE CLUTCH 2.000-10	Part	EACH	1.00
	SPLINE			
HWJ05756	WASHER, SAE FLAT WASHER- 7/1	Part	EACH	5.00
HWJ00972	BOLT, 7/16-14 X 1-1/2 GR8	Part	EACH	1.00
166582	TIE STR S/S TAB BLACK	Part	EACH	12.00

*** Customer Review ***

Date / Time: 7/27/2020 1:41:02PM
 Repair Order: 102342
 Customer: 22636
 Branch:
 Invoice Total:

Charge

Page 2 of 7

Customer P/O: needs akrause Completion Date:

D84-1000-6061620	BELT-POLY 6 RIBS X 1620 END/	Part	EACH	1.00
D84-1000-6122310	BELT-POLY 12 RIBS X 2310 END	Part	EACH	1.00
8-44147	TIE-CABLE NYL HD BLK 15 120	Part	EACH	24.00
HWC01079	BOLT-HEX M20-2.50X120 CL1	Part	EACH	2.00
HWC04916	NUT-HEX SL NYL M20-2.50X2	Part	EACH	2.00
K37-1004	FILTER-FUEL/WATER PACCAR	Part	EACH	1.00
HWU20285	BOLT-HEX M8-1.25X25 CL10.9 Z	Part	EACH	2.00
HWU05730	WASHER, SAE FLATWASHER-5/16	Part	EACH	4.00
5526-100X200	HEATER HOSE 1 DIAMETER	Part	EACH	4.00
AC11100	O-RING #10 (PKG.25)	Part	EACH	1.00
AC10650	O-RING #6 (PKG.25)	Part	EACH	1.00
250-70-18X	STRAP KIT	Part	EACH	1.00
3033247CUM	SEAL,O RING	Part	EACH	1.00
3102802CUM	O-RING	Part	EACH	1.00
B9224-0406TRP	CLAMP DA009	Part	EACH	2.00
17B-500-12SS	5x12 SS FLEX	Part	EACH	1.00
20A500	CLAMP-5 {14-11434} DA011	Part	EACH	2.00
1360-4	SLEEVE, 1/4	Part	EACH	1.00
19241	INSERT, 1/4	Part	EACH	1.00
HWU05795	WASHER, SAE FLATWASHER-5/8	Part	EACH	2.00
HWU01687	BOLT, 5/8-11 X 1-1/2 GR 8 H	Part	EACH	1.00
CC36074FLG	EG PREMIX 50/50	Part	EACH	61.00
105816EXX	15W40 DELVAC 1300 BULK QTS	Part	EACH	50.00
900R-32	RUBBER TUBE CLAMP, CVD 2	Part	EACH	1.00
01406	3 ROLOC 50 GRIT	Part	EACH	1.00
24704N-604WHD	FITTING-SAE45 STL FSTRSWV	Part	EACH	2.00
H06904-250RWHD	HOSE-HYD/AIR 3/16 250'	Part	EACH	2.00
V50-6027-01500	HOSE	Part	EACH	1.00

Task Subtotals

Parts:
 Core Chg:
 Core Ret:
 EHC:
 Labor:
 Miscellaneous:
 Task 1 Subtotals: \$43,390.42

Task: 2 43-00000
 Complaint: Inspect dpf

Exhaust System

Department: Service

*** Customer Review ***

Date / Time: 7/27/2020 1:41:02PM
 Repair Order: 102342
 Customer: 22636

Charge

Page 3 of 7

Customer P/O: needs akrause Completion Date:

Correction: Check the DPF, R&I the step and DPF and elbow to the Decomp pipe. Took the DPf aprt and noticed the bottom clamp was all soot, found the DPF is cracked- leaking.

Supp. Part	Description / Ref Number	Misc	U/M	Quantity	Price	Extended Price
ShopSupSvc	Shop Supplies - Service	Misc		1.00		
Task Subtotals				Parts:		
				Core Chg:		
				Core Ret:		
				EHC:		
				Labor:		
				Miscellaneous:		
				Task 2 Subtotals:		

Task: 3 71100040 Misc Repairs Department: Service

Supp. Part	Description / Ref Number	Misc	U/M	Quantity	Extended
ShopSupSvc	Shop Supplies - Service	Misc		1.00	
Task Subtotals				Parts:	
				Core Chg:	
				Core Ret:	
				EHC:	
				Labor:	
				Miscellaneous:	
				Task 3 Subtotals:	\$0.00

Task: 4 45-000000 Engine System Department: Service

Complaint: Replace motor mounts.
 Correction: Replaced the rear and front motor mounts. Rear were bolted to the cab support.

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc	Shop Supplies - Service	Misc		1.00
05-16401	MOUNT-ENGINE RUBBER	Part	EACH	2.00
12448TBG	SUPPORT-ENGINE REAR	Part	EACH	2.00
W34-1095-070	BOLT-FLANGE M16X2X70 10.9	Part	EACH	4.00

***** Customer Review *****

Date / Time: 7/27/2020 1:41:02PM
Repair Order: 102342
Customer: 22636

*****Charge*****

Page 4 of 7

Customer P/O: needs akrause

Completion Date:

Task Subtotals

Parts:
Core Chg:
Core Ret:
EHC:
Labor:
Miscellaneous: _____
Task 4 Subtotals:

Task: 5 41-000000 Intake System**Department: Service**

Complaint: Replace air filters.
Correction: Changed out air cleaners and primary fuel filter.

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc	Shop Supplies - Service	Misc		1.00
X011622	FILTER-AIR PACCAR 15 PRF FI	Part	EACH	2.00

Task Subtotals

Parts:
Core Chg:
Core Ret:
EHC:
Labor:
Miscellaneous: _____
Task 5 Subtotals:

Task: 6 32-010014 Starting System - Batteries - Replace**Department: Service**

Correction: Replaced the 3 batteries and cleaned up and sealed the cables.

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc	Shop Supplies - Service	Misc		1.00
CLASSAI-C	GR 31 BATTERY CORE	Inherent		3.00
X				
PX31925CEXCH	BATTERY-CHAMPION, 925 CCA,	Part	EACH	3.00
	1			
X				
CLASSAI-C	GR 31 BATTERY CORE	Part	EACH	(3.00)
80370PTX	PROTECTOR-BATTERY	Part	EACH	1.00

*** Customer Review ***

Date / Time: 7/27/2020 1:41:02PM
 Repair Order: 102342
 Customer: 22636

It

I

Charge

Page 5 of 7

Customer P.O. needs

akrause

Completion Date:

Task Subtotals

Parts:
 Core Chg:
 Core Ret:
 EHC:
 Labor:
 Miscellaneous:
 Task 6 Subtotals: _____

Task: 7 22-000000

Rear Axle

Department: Service

Complaint: reinstallation drive axles - pulled when towed in
 Correction: installed axle shaft that was removed for towing.

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc 330-3111	Shop Supplies - Service GASKET	Part	EACH	1.00

Task Subtotals

Parts:
 Core Chg:
 Core Ret:
 EHC:
 Labor:
 Miscellaneous:
 Task 7 Subtotals: _____

Task: 8 49-490002

Reprogram Ecm

Department: Service

Complaint: Reprogram truck to 1850 torque from 2050 torque.
 Correction: Calibrated all the ECM's to 1850 ft lbs torque from 2050 ft lbs. Also made sure no faults and correct in the features the faults that were in ECM. Printed new engine.

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc	Shop Supplies - Service	Misc		1.00
SubletSvc	Sublet Service	Misc		1.00

***** Customer Review *****

Date / Time: 7/27/2020 1:41:02PM
Repair Order: 102342
Customer: 22635

*****Charge*****

Page 6 of 7

Customer P/O: needs akrause Completion Date:

Task Subtotals

Parts:
Core Chg:
Core Ret:
EHC:
Labor:
Miscellaneous:
Task 8 Subtotals: _____

Task: 9 45-000000 Engine System
Complaint: replace dpf
Cause: cracked
Correction: replaced dpf

Department: Service

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc	Shop Supplies - Service	Misc		1.00
2871453CUM	GASKET-DPF ASSY	Part	EACH	2.00
2871581RXCUM	FILTER PARTICULATE	Part	EACH	1.00
CLASSXY-C	2871581D MODULE L1 CORE	Inherent		1.00
2866337CUM	GASKET-CIRCULAR 5	Part	EACH	1.00
2866636CUM	GASKET-EXHAUST 4	Part	EACH	2.00
2880215CUM	GASKET-AFM DEVICE	Part	EACH	2.00
4988280CUM	GASKET-PUMP HYDRAULIC	Part	EACH	1.00

Task Subtotals

Parts:
Core Chg:
Core Ret:
EHC:
Labor:
Miscellaneous:
Task 9 Subtotals: _____

Task: 10 13-00000 Brakes - Disc Type Air Brakes - Diagnose
Complaint: adjust brakes

Department: Service

Supp. Part	Description / Ref Number	Misc	U/M	Quantity
ShopSupSvc	Shop Supplies - Service	Misc		1.00

*** Customer Review ***

Date / Time: 7/27/2020 1:41:02PM
Repair Order: 102342
Customer: 22636

Charge
Page 7 of 7

Customer P/O: needs

akrause

Completion Date:

Task Subtotals

Parts:

Core Chg:

Core Ret:

EHC:

Labor:

Miscellaneous:

Task 10 Subtotals: _____

Motor mounts - ~~\$1,000~~ \$871.28

Battery - \$356.43

Reprogram + Deleted \$294.00

DPF - \$2,200.00

For sure \$700.00
Request Renewal Credit

Totals

Total Parts:

Total Core Chg:

Total Core Ret:

Total EHC:

Total Labor:

Total Miscellaneous:

Invoice Subtotal: _____

Total Tax:

Invoiced Total:

\$51,106.11

Payment Method

Charge

Our Williston Location has Moved!
Our new address in Williston is 14058 James Drive; just north of the highway 2 and highway 85 bypass intersection. Any questions please call (701)774-3007.

Signature _____ Date _____

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. Clerical errors subject to correction. 1.5% per month service charge on all past due accounts.

Training 6 months
DPF - 1 year

Page 1 of 2

**** See Last Page for Invoice Total ****

Invoice: 291500095
Date / Hour: 5/30/2019 9:18:47AM
Repair Order: 136519
Customer: 22636

Charge

Page 2 of 2

Customer P/O: 053653019JE bboutain 008

Orig R/O: 0 Completion Date: 5/20/2019

Task: 2 45-000000 ENGINE SYSTEM

Complaint: PERFORM SERVICE LETTER 2052

Correction: WAS DONE LAST YEAR, CHECK HISTORY, FILLED FOR REIMBURSEMENT

Supp.	Part	Description / Ref Number
	ShopSup	MISC SHOP SUPPLIES TS

Task 2

Total Parts:	
Total Core Charge:	
Total Core Ret:	
Total Labor:	
Total Miscellaneous:	
Invoice Subtotal:	
Total Tax:	
Total Invoice:	\$3,368.77

Signature _____ Date _____

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. Clerical errors subject to correction. 1.5% per month service charge on all past due accounts.

*** Customer Review ***

Date / Time: 7/29/2021 9:57:49AM
 Repair Order: 100764
 Customer: 14748

SG PACCAR

Page 1 of 3

Customer P/O: CALL kslod

Completion Date:

Unit Number: 163050
 Type: Service
 In-Service Date: 03/27/2012

Model Year: 2013
 VIN: 1XPXD49X6DD163050

Make/Model: PETERBILT 389
 Meter: 974442 Miles

Task: 1 1052 Jx Courtesy Vehicle Assessment -
 Complaint: Task to perform a courtesy 15 minute Vehicle Assessment to check
 Correction: COMPLETED INSPECTION

Department: Service

Supp	Part	Description / Ref Number	Misc	U/M
	006	N21JUN2789		
				Task Subtotal:

CUSTOMER RE

Task: 2 043000000 EXHAUST GROUP
 Complaint: DEF LIGHT IS ON, STARTING TO DERATE.
 Correction: 6/23/2021 5:05:05 PM 10825 GOT TRUCK IN SHOP. CONNECTED INSITE. RETRIEVED FC. HAS FC FOR DPF

Department: Service

DIFERENTIAL PRESSURE AND TOO TREQUENT REGEN DPF JUST CLEANED AND ONLY 6 MONTHS OLD. PRINTED REGEN HISTORY. HAS BACK TO BACK REGENS. DISCONNECTED EXHAUST RAN SNAP TEST. CUSTOMER SLEEPING IN TRUCK. WILL PULL TRUCK IN TOMORROW TO REMOVE DPF FOR INSPECTION.
 6/25/2021 4:12:28 PM 11146 REMOVED DPF AND SENT IT FOR A FLOW TEST, GOT A NEW DPF, INSTALLED NEW DPF. FORCED TRUCK INTO REGEN, EVERYTHING IS GOOD AT THIS MOMENT.

Supp	Part	Description / Ref Number	Part	U/M	Quantity
PACCR	2872468CUM	SENSOR-TEMPERATURE	Part	EA	2.00
PACCR	90-0013	CLAMP-V BAND 5"	Part	EA	1.00
PACCR	2866337CUM	GASKET-CIRCULAR 5"	Part	EA	2.00
PACCR	5579293RXCUM	KIT,PARTICULATE FILTER	Part	EA	1.00
PACCR	5579293RXCUM-C	CORE-PARTICULATE FILTER	Inherent		1.00
	001	DPF FLOW TEST	Misc		1.00

*** Customer Review ***

Date / Time: 7/29/2021 9:57:49AM
Repair Order: 100764
Customer: 14748

SG PACCAR

Page 2 of 3

Customer P/O: CALL

kstod

Completion Date:

Task Subtotals

Hours: 6.00

Parts:

Core Chg:

Core Ret:

EHC:

Labor:

Miscellaneous:

Task 2 Subtotals:

\$3,711.34

CUSTOMER REVIEW

*** Customer Review ***

Date / Time: 7/29/2021 9:57:49AM
Repair Order: 100764
Customer: 14748

SG PACCAR

Page 3 of 3

Customer P/O: CALL

kstod

Completion Date:

Totals

Total Parts:

Total Core Chg:

Total Core Ret:

Total EHC:

Total Labor:

Total Miscellaneous:

Invoice Subtotal:

Total Tax:

Invoiced Total:

\$3,890.13

Payment Method

SG PACCAR

Authorization Number:

ANY COMPLAINT REGARDING WORKMANSHIP CONCERNING REPAIRS PERFORMED BY THE DEALERSHIP MUST BE BROUGHT TO THE ATTENTION OF THIS DEALERSHIP WITHIN 30 DAYS OF RECEIPT OF THE VEHICLE BY THE CUSTOMER FOLLOWING A REPAIR OR IT WILL BE DEEMED WAIVED FOR ALL PURPOSES. THIS LANGUAGE SHALL NOT CONSTITUTE A WARRANTY FOR ANY PURPOSE. PARTS RETURNED FOR CREDIT MUST BE ACCOMPANIED BY THIS INVOICE AND MAY BE SUBJECT TO A MINIMUM RETURN CHARGE OF 10% OF THE PURCHASE PRICE. SPECIAL ORDER PARTS MAY ALSO BE SUBJECT TO A NON-REFUNDABLE DEPOSIT. SPECIAL ORDER ELECTRICAL PARTS ARE NOT RETURNABLE. CORES MUST BE RETURNED WITHIN 30 DAYS. ALL ACCOUNTS ARE DUE AND PAYABLE WITHIN TERMS. A FINANCE CHARGE OF 1.5% (18% PER ANNUM) WILL BE CHARGED ON ALL PAST DUE ACCOUNTS. A \$25 FEE WILL BE CHARGED FOR ALL RETURNED CHECKS.

Signature: _____

Under section 405(b) of the Internal Revenue Code, you may be liable for a 12% tax on the total charge invoiced here if you purchased this vehicle new within the 6 months.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability in parts shipments by the supplier or the transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs therein. Seller not responsible for alternate transportation due to the above.

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The seller dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit or income or any other incidental damages.

*** Customer Review ***

Date / Time: 10/25/2022 11:30:33AM
Repair Order: 126503
Customer: 22636

Charge

Page 1 of 4

Customer P/O: need	mseedorf	Completion Date:
Unit Number: 536	Model Year: 2013	Make/Model: Peterbilt
Type: Truck	VIN: 1XPXD49X6DD163050	Meter: 1133241 Miles
		ECM Reading: 9866
Engine Model : ISX	Engine S/N : 79554568 new 60840646	
Ext. Warranty : ENGINE ENCORE 2YR 200K 11-14-16	Engine Warranty : New eng 08/18/20 837109 miles	

Task: 2 34-040000 Lighting System - Clearance/Marker - Diagnose Department: Service

Complaint: Check and advise on auxiliary lights inop and keeps blowing the fuse

Correction: Checked fuses and there were no fuses blown. Notice that the aux switch is stuck off. Removed the switch panel and the connector was not connected. Could not get the lights to turn on. Rechecked the fuses and none of them are blown.

Recieved wiring diagrams from Peterbilt, started diag from the auxiliary switch, switch was seized, I also want to note that many wires had broken jackets in the dash
- noted yel2942-0 from switch splices into random unmarked 4 wire loom (the correct wire in the harness lays cut next to it)

Checked out dash was open found wires they were talking about followed the cable the wire went into it goes back to plug in by the trailer cord talked to customer showed me what switch and lights that were not working tested the switch had power coming in nothing going out, swapped connectors with the switch next to it, all customer installed light now work

Switch is bad for auxiliary lights its also proprietary from Peterbilt
talked with customer and he just wants the switch part number and he will source one

Customer asked me to look at load light switch as they were inop
Used fog light switch on load light plug and lights came on
Pugged back into load light switch and they worked
Cleaned terminals on switch and connector, put side of truck back together
Had to use nut and bolts for auxiliary lights as the mounting holes were stripped out as they only used self tapping screws.

Fog Light Plug

Supp	Part	Description / Ref Number		U/M	Quantity
	HWC09028	SCREW-MACHINE M5X 08 PH	Part	Each	4.00
	S34-6003-0525TP00B	FASTENER-PSD2-2 M5X.8X25MM	Part	Each	2.00
		B			
	PA72218	SCREW	Part	Each	3.00
	PA72220	SCREW	Part	Each	1.00
	HWC12726	NUT-HEX M6X1 GR10	Part	Each	4.00
	HWJ11390	WASHER	Part	Each	8.00
	HWJ10142	BOLT-HEX M6-1.00X25 CL10.9 Z	Part	Each	4.00

Task 2 Subtotals

Parts:

Labor:

Task 2 Totals:

\$1,628.45

*** Customer Review ***

Order / Date: 10/25/2022 11:39:31 AM
 Repair Order: 1285515
 Evaluation: 7/25/26

*** Change ***

Page 2 of 4

Customer FVO: 10000

10000000

Examination Date

Task: 3 45-000001 Engine Diagnostics

Department: Service

Complaint: Check and advise on check engine light coming on, showing boost pressure and blowing black smoke

Correction: Checked out hooked up computer checked codes have intake pressure codes inspected sensor is plugged up truck smokes black removed pipe off back of DPF is breached and needs to be replaced on the snap shot the dos inlet temp was over 800 degrees should not get over 600 pulled pipe off back of turbo ran a snap test failed smokes real bad showed chris agreed talked to customer said Pete just put 1 and 6 injectors in if customer states smoked worse after that checked on parts

got ok to replaced injectors replaced 3 4 and 5 injectors and tubes assembled engine ran another snap test passed got a small puff of grey and cleared up installed exhaust piping removed drivers side step removed DPF and catalyst DPF was bad catalyst was face plugged cleaned catalyst replaced DPF assembled truck will need a regen after other repairs are done
 Reset DPF to NEW
 made and attached a warranty download
 Cleared faults and backed out for a regen

Replaced
 3
 4
 5
 injectors
 tubes
 7/25/26
 tested

Supp	Part	Description / Ref Number	Part	Unit	Quantity
	55794177XCUM	KIT, INJECTOR	Part	Each	4.00
	CLASSPS-C	2872161D/ INJ L1 CORE	Inherent		4.00
	4520PEN	BRAKE CLEAN	Part	Each	4.00
	CouponKW	Kenworth Coupon Redemption (*)	Misc		(1.00)
	102122-6E7GE				
	CLASSPS-C	2872161D/ INJ L1 CORE	Part	Each	(4.00)
	5579293CUM	KIT, Particulate Filter	Part	Each	1.00
	2697334CUM	SENSOR, PRS TEMPERATURE	Part	Each	1.00

July
 27
 year

Task 3 Subtotals

Parts:
 Core Charge:
 Core Ret:
 Labor:
 Miscellaneous:
 Task 3 Totals: \$7,874.51

Task: 4 13-100000 Brakes - Air Brakes - Diagnose

Department: Service

Complaint: Check and repair for bad air leak

Date / Time: 10/25/2022 11:39:53 AM
Report Order: 1265773
Customer: 22536

Page 3 of 4

Completion Date

- Checked unit for any air leaks, aired up system and started to spray air lines with soapy water
- noted air compressor discharge has rubbed a hole in an air tank supply line
- well need new air tank supply line and compressor discharge (both are rubbed through)
- noted another rubbed line (green line) under cab by firewall
- noted fuel shut off line rubbed on motor mount and leaking at engine air fitting
- noted air compressor is not rubbed all the way through, other lines were bubbling air on making it look like the discharge was leaking
- noted air fitting on transmission valve leak
- replaced fittings above and lines
- tested and these no longer leak
- noted air leak from fan solenoid fitting on firewall (quoted this part and put in work order, parts not on hand)
- started tying air lines and securing them.

Task 4 Subtotals	Parts:	
	Labor:	
Task 4 Totals:		\$1,184.33

Department: Service

Supp	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
Task 5 Subtotals						