

Labor	Correction: Engine / Bottom End / Replaced Engine with Ford Remanufactured Engine. Per Ford's requirement for warranty we replaced the intake plenum. Installed new air filter. Found serpentine belt tensioner bad upon disassembly so we replaced it on assembly of the replacement engine. - Completed: 5/5/2023	42.00000	
Parts	ENGINE - 8C3Z6006BARM	1.00000	
Parts	Intake plenum - 615-461	1.00000	
Parts	FILTER, AIR - FIL9883	1.00000	
Parts	Dirty Core for ENGINE - 8C3Z6006BARM-CORE	-1.00000	
Parts	Inherent Core for ENGINE - 8C3Z6006BARM-CORE	1.00000	
Parts	DRIER - 6E7Z19959AA	1.00000	
Parts	serpentine belt tensioner pulley - 89263	1.00000	
Parts	CROSS OVER PIPE GSK - 35789	1.00000	
Parts	CROSS OVER PIPE GSK - 35791	1.00000	
Parts	Idler pulley - 38001	1.00000	
Parts	EXHAUST FLANGE BOLTS - ES75105	1.00000	
Parts	BUTTON HEAD TIE PK 5 - GR-83-6052	2.00000	
Parts	ZIPTIE 14.6" 50 LB - GR-83-6025	8.00000	
Parts	ZIPTIE 15" 120LB - GR-83-6029	8.00000	
Parts	CLAMP #28 - IDL6528E51	1.00000	
Parts	AC O-RING - CTT24661	2.00000	
Parts	AC O-RING - CTT24666	2.00000	

Item	Description	Quantity	Rate	Amount
Parts	A/C SEAL KIT - CTT T24068	2.00000		
Parts	GASOLINE - GASOLINE	10.00000		
Parts	Freon R134 - r134	2.40000		
Parts	GLOBAL ANTIFREEZE - OILGLOBALA/F	2.17000		

Subtotal

Complaint: BTA Tractor PM

Cause: Perform PM service on truck

Item	Description	Quantity	Rate	Amount
Complaint: RUNS BAD - FUEL SMELL				
Cause: Intake valve for cylinder #4 has made contact with the cylinder. Engine has dropped a valve				
Labor	Correction: Engine / Bottom End / Replaced Engine with Ford Remanufactured Engine. Per Ford's requirement for warranty we replaced the intake plenum. Installed new air filter. Found serpentine belt tensioner bad upon disassembly so we replaced it on assembly of the replacement engine. - Completed: 5/5/2023	42.00000		
Parts	ENGINE - 8C3Z6006BARM	1.00000		
Parts	Intake plenum - 615-461	1.00000		
Parts	FILTER, AIR - FIL9883	1.00000		
Parts	Dirty Core for ENGINE - 8C3Z6006BARM-CORE	-1.00000		
Parts	Inherent Core for ENGINE - 8C3Z6006BARM-CORE	1.00000		
Parts	DRIER - 6E7Z19959AA	1.00000		
Parts	serpentine belt tensioner pulley - 89263	1.00000		
Parts	CROSS OVER PIPE GSK - 35789	1.00000		
Parts	CROSS OVER PIPE GSK - 35791	1.00000		
Parts	Idler pulley - 38001	1.00000		
Parts	EXHAUST FLANGE BOLTS - ES75105	1.00000		
Parts	BUTTON HEAD TIE PK 5 - GR-83-6052	2.00000		
Parts	ZIPTIE 14.6" 50 LB - GR-83-6025	8.00000		
Parts	ZIPTIE 15" 120LB - GR-83-6029	8.00000		
Parts	CLAMP #28 - IDL6528E51	1.00000		
Parts	AC O-RING - CTT24661	2.00000		
Parts	AC O-RING - CTT24666	2.00000		

Engine / Bottom End / Replaced Engine with Ford Remanufactured Engine.
Per Ford's requirement for warranty we replaced the intake plenum. Installed
new air filter. Found serpentine belt tensioner bad upon disassembly so we
replaced it on assembly of the replacement engine. - Completed: 5/5/2023

Parts	ENGINE - 8C3Z6006BARM	1.00000		
Parts	Intake plenum - 615-461	1.00000		
Parts	FILTER, AIR - FIL9883	1.00000		
Parts	Dirty Core for ENGINE - 8C3Z6006BARM-CORE	-1.00000		
Parts	Inherent Core for ENGINE - 8C3Z6006BARM-CORE	1.00000		
Parts	DRIER - 6E7Z19959AA	1.00000		
Parts	serpentine belt tensioner pulley - 89263	1.00000		
Parts	CROSS OVER PIPE GSK - 35789	1.00000		
Parts	CROSS OVER PIPE GSK - 35791	1.00000		
Parts	Idler pulley - 38001	1.00000		
Parts	EXHAUST FLANGE BOLTS - ES75105	1.00000		
Parts	BUTTON HEAD TIE PK 5 - GR-83-6052	2.00000		
Parts	ZIPTIE 14.6" 50 LB - GR-83-6025	8.00000		
Parts	ZIPTIE 15" 120LB - GR-83-6029	8.00000		
Parts	CLAMP #28 - IDL6528E51	1.00000		
Parts	AC O-RING - CTT24661	2.00000		
Parts	AC O-RING - CTT24666	2.00000		

Page: 2 of 4

Item	Description	Quantity	Rate	Amount
Parts	A/C SEAL KIT - CTT T24068	2.00000		
Parts	GASOLINE - GASOLINE	10.00000		
Parts	Freon R134 - r134	2.40000		
Parts	GLOBAL ANTIFREEZE - OILGLOBALA/F	2.17000		

Subtotal

Complaint: BTA Tractor PM

Cause: Perform PM service on truck

1 25000

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
---------------	-------	----------	------------	-------------	----------------	--------

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: RUNS BAD - FUEL SMELL

Cause: Intake valve for cylinder #4 has made contact with the cylinder. Engine has dropped a valve

Labor	Correction: Engine / Bottom End / Replaced Engine with Ford Remanufactured Engine. Per Ford's requirement for warranty we replaced the intake plenum. Installed new air filter. Found serpentine belt tensioner bad upon disassembly so we replaced it on assembly of the replacement engine. - Completed: 5/5/2023	42.00000		
Parts	ENGINE - 8C3Z6006BARM	1.00000		
Parts	Intake plenum - 615-461	1.00000		
Parts	FILTER, AIR - FIL9883	1.00000		
Parts	Dirty Core for ENGINE - 8C3Z6006BARM-CORE	-1.00000		
Parts	Inherent Core for ENGINE - 8C3Z6006BARM-CORE	1.00000		
Parts	DRIER - 6E7Z19959AA	1.00000		
Parts	serpentine belt tensioner pulley - 89263	1.00000		
Parts	CROSS OVER PIPE GSK - 35789	1.00000		
Parts	CROSS OVER PIPE GSK - 35791	1.00000		
Parts	Idler pulley - 38001	1.00000		
Parts	EXHAUST FLANGE BOLTS - ES75105	1.00000		
Parts	BUTTON HEAD TIE PK 5 - GR-83-6052	2.00000		
Parts	ZIPTIE 14.6" 50 LB - GR-83-6025	8.00000		
Parts	ZIPTIE 15" 120LB - GR-83-6029	8.00000		
Parts	CLAMP #28 - IDL6528E51	1.00000		
Parts	AC O-RING - CTT24661	2.00000		
Parts	AC O-RING - CTT24666	2.00000		