	Service Order Purchase Order	Authorizer
	3234	1
Item	Description	Quantit
PM: FULL	DETAIL, AND BELLY WASH	
Cause: C	ustomer request (PM)	
Labor	Correction:	0.00000
	Chassis / Cab / completed 12/11	
PM: PRO	CESSING INSPECTION	CUSTOME! DECLINED
Cause: C	ustomer request (PM)	
Labor	Recommended Correction:	
	Chassis / Chassis / Initial Vehicle Condition Inspection	
PM: QUAI	LITY CONTROL INSPECTION/TEST DRIVE	
Cause: C	ustomer request (PM)	
Labor	Recommended Correction: Chassis / Cab / QUALITY CONTROL INSPECTION/TEST DRIVE	0.0000
Complain	t: Get truck started	
Cause: C	ustomer request	
Labor	Correction:	0.0000
	Chassis / Cab / COMPLETED	
Parts	GROUP 31 BATTERY - 7236 - A	:
Parts	Inherent Core for GROUP 31 BATTERY - 3234 - A	1
Parts	Dirty Core for GROUP 31 BATTERY - 3234 - A	-3
Complain	t: Sales Vehicle Inspection (WITHOUT OIL CHANGE)	
Cause: C	ustomer request	
Labor	Correction:	1.5000
	Chassis / Chassis / DROVE TRUCK LOOKED OVER AND TOPED OFF FLUIDS	
	SERVICE PRO BRAKE CLEANER 55 GAL DRUM - 1000040216 - A	

Davida	Inventory CEOCOO E ALII TEK OVALTDANI ATE IV (in physics 77 at 60 04 ann.) CEOCOO E	
Parts	Inventory: 650680-5: HI-TEK SYNTRAN ATF LV (in stock: 77 at \$6.04 per) - 650680-5 - A	1
Parts	Inventory: 680670-55: ELC 50/50 (in stock: 8 at \$8.41 per gal) - 680670-55 - A	1
Parts	WINDSHEILD WASHER FLUID - GAL - A	1
Complaint	DIESEL 6.7L POWERSTROKE Basic Oil Service (Lube, Oil & Filters)	
Cause: Cu	stomer request	
Labor	Correction: Engine / Lubrication / CHANGED THE OIL DURING ENGINE SWAP	1.00000
Parts	HI-TEK ELITE SAE 15W40 - 564100-55 - A	13
Parts	STP Oil Filter 6.7L Powerstroke - S10890 - A	1
Complaint	: TAG AND STICKER	
Cause: Cu	stomer request	
Labor	Correction: Chassis / Cab / INSTALLED THE TAGS AND STICKERS	0.15000
Complaint	engine swap	
Cause: Cu	stomer request (Inspection)	
Labor	Correction: Chassis / Cab / PULLED THE TRUCK IN AND STAGED THE TRUCK THEN PULLED THE HOOD AND RADIATOR THEN UNHOOKED EVERY THING FROM THE ENGINE THEN PULLED THE ENGINE AND PULLED THE TRUCK OUT AND CLEANED THE BAY THEN PULLED THE TRUCK IN AND SET THE NEW ENGINE IN AND HOOKED EVERYTHING UP THEN TOPED OFF ALL FLUIDS AND PRIMED THE FUEL AND DID TEST DRIVE	0.00000
Parts	Service Engine Assy - JC4Z6006B - A	1
Parts	Inherent Core for Service Engine Assy - 3234 - A	1
Parts	Dirty Core for Service Engine Assy - 3234 - A	-1
Parts	KIT - GASKET - FC3Z6079D - A	1
Complaint	tear down engine and swap parts	
Cause: Cu	stomer request (Inspection)	
Labor	Correction: Chassis / Cab / SWAPED THE PARTS FROM THE OLD ENGINE TO THE NEW ENGINE AND WASHED THE ENGINE BAY OUT	0.00000
Parts	Fuel Filter Return Line Connector Fitting - HC3Z-9A564-A - A	1
Parts	Gasket - BC3Z9D476B - A	1
Parts	Oil Separator DRW 17-19 6.7L POWERSTROKE - NED EOS202 - A	1
Parts	Oil filter housing gasket - BC3Z6840A - A	1
Complaint	: A/C INOP P0532	
Cause: Cu	stomer request (Procedure)	
	Correction:	1.00000
Labor	Chassis / Cab Hardware / REPLACED THE PRESSURE SWITCH AND TESTED THE A/C AND IT WORKED WITH NO CODES	

Cause: C	ustomer request (Procedure)						
Labor	Correction: Chassis / Cab / DS. INSTALLED THE GLASS	0.00000					
Parts	REPLACEMENT MIRROR GLASS LH UPPER W/ HEAT - 4773H	1					
Parts	MIRROR MOTOR 17 UP FORD - FU5Z17D696B - A	2					
Parts	REPLACEMENT MIRROR GLASS RH UPPER W/ HEAT - 4774H	1					
Complain	t: NEEDS 2 SMALL RED CLEARANCE LIGHTS						
Cause: C	ustomer request (Procedure)						
Labor	Correction: Chassis / Cab / REPLACED THE LIGHTS						
Complain	t: NEEDS ENGINE AIR FILTER						
Cause: C	ustomer request (Procedure)						
Labor	Correction: Chassis / Cab / REPLACED AIR FILTER	0.00000					
Parts	STP / Air Filter - SA10888	1					
Complain	t: NEEDS BOTH TIEROD ENDS						
Cause: C	ustomer request (Procedure)						
Labor	Correction: Chassis / Cab / PULLED THE OLD TIE ROD AND INSTALLED THE NEW AND SET TOE						
Parts	TIE ROD, COMPLETED - FC4Z3280HA - A	1					
Complain	t: NEEDS BOTH REAR SHOCKS						
Cause: C	ustomer request (Procedure)						
Labor	Correction: Brakes / Valves / REPLACED THE REAR SHOCKS	1.00000					
Parts	Shock Absorber Assy - FC4Z18125D - A	2					
Complain	t: AIR GUAGE NEEDS FIXED						
Cause: C	ustomer request (Inspection)						
Labor	Correction: Chassis / Cab / PULLED THE DASH APART AND REPAIRED THE BRACKET FOR THE GUAGE AND LET DRY THEN INSTALLED THE BRACKET AND GUAGE AND DASH						
Complain	t: INSTALL ALUMINUM WHEELS						
Cause: C	ustomer request (Inspection)						
Labor	Correction: Chassis / Cab / PULLEDN THE TRUCK IN AND SWAPPED THE WHEELS AND TIRES AND CLEANED UP TRASH						
	22.5X8.25 ALUMINUM WHEELS - FAKE ALCOA	1					
Parts							
Parts Parts	CHROME HUB CAPS AND LUG NUT COVER SET - HUB BLING	1					

Cause: Customer request (Inspection)

Labor Correction: 0.00000 Chassis / Cab / DROVE TRUCK THEN HAD TO FIND A NOISE FOUND THE NOISE AND FIXED EVERYTHIN GOOD NOW Complaint: REPLACE GOOSENECK BALL Cause: Customer request (Inspection) Recommended Correction: 0.00000 Labor Chassis / Cab / REPLACE GOOSENECK BALL Parts Raw Steel Trailer Hitch Ball, 30,000 lbs, 2-5/16-Inch Diameter, 2 x 3-1/2-Inch Shank - 40088 - A 1 Complaint: polish tanks, fix flooring, paint rusted part behind front bumper Cause: Customer request (Inspection) Labor Correction: 0.00000 Chassis / Cab / COMPLETED Complaint: needs rearview mirror, fix doors on bed and anything else you see that needs fixed Cause: Customer request (Inspection) Labor Correction: 0.00000 Chassis / Cab / completed Parts TUBING/HINGES - 2X3X.188T - A 1 Complaint: OIL LEAK, STEERING DARTS, POPPING IN FRONT END Cause: Customer request (Inspection) Labor Correction: 0.00000 Chassis / Cab / engine block plug leaking behind cylinder head removed old plug and installed plug from bad engine outside due to plug threads being bad also set toe positive 1/4 and checked spring pings and bushings cannot find cause for noise took on test drive and never noticed popping noise drives like a 750 and checked oil leak and no more leak at the moment rick to drive again and then close line if no issues

Unit: 13198 (2017 F750 Service) VIN: 1FDXW7DX6HDB10905

2017 Ford F-750 Chassis: 116.959 Miles

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature:	
Printed Name:	Date:

Order Event Log

Cart Name:

PO#: 05000554

Dealer:

Status: Completed Vehicle: 2017 Ford F-750

1FDXW7DX6HDB10905

Attachments





Parts Lists

Part Requested	Part Fulfilled	Description	Promotion	Response	Involce	Estimated Delivery	List Price	Net Price	Delivery option	Qty Req	Qty Ful	Item Price
JC4Z6006B	JC4ZE00EB	Service Engine Assy		Involced	4540809	11/05/2024 AM	\$5,421.18	\$4,800.00	Standard	1	1	
FC3Z6079D	FC3Z6079D	KIT - GASKET		Involced	4540809	11/05/2024 AM	\$975.00	\$643.50	Standard	1	1	

Order Total:

Total Core Price:

Total: \$3,943.60



Copyright © 2024 OEConnection. All Rights Reserved.