

Customer Information	Invoice	Additional Information
	Date: 1/05/2023 Reference: Salesperson:	PO Number: Work Order#: Entered By:

Qty	Description	Unit Price	Ext. Price
6.00	265/75R22.5 138L, M154 BW G (14 Ply), Toyo		
6.00	Tire Mount/Dismount - Commercial		
6.00	Balance Commercial		
4.00	DISPOSAL - PASS/LT		

Frederick & State

Subtotal:

CO Sales Tax:

Colorado Waste Tire Fee:

Frederick City:

Disposal Fee Commercial:

Terms: N/A

Total: \$3,550.43

1/05/2023 Payment# P-100358 Amount: \$3,550.43
3,550.43

Invoice Balance: \$0.00

Terms:	Due Date	Due Amt	Amt Remain
	1/05/2023	\$3,550.43	\$0.00

Parts	Labor	Subtotal	Taxes/Fees	FET	Total
					\$3,550.43

For safety, recheck wheel torque after 100 miles.

I hereby authorize the stated repair work to be done along with the necessary material, and hereby grant permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. is not responsible for loss or damage to vehicles, or articles left in vehicles, in case of fire, theft or any other cause beyond it's control. A 1.5% (18% APR) service charge will be assessed on any amount which becomes delinquent beyond 30 days.

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE.

ADVISOR	ADVISOR	ADVISOR	ADVISOR
ADVISOR	ADVISOR	ADVISOR	ADVISOR
ADVISOR	ADVISOR	ADVISOR	ADVISOR
ADVISOR	ADVISOR	ADVISOR	ADVISOR
ADVISOR	ADVISOR	ADVISOR	ADVISOR
ADVISOR	ADVISOR	ADVISOR	ADVISOR
ADVISOR	ADVISOR	ADVISOR	ADVISOR
ADVISOR	ADVISOR	ADVISOR	ADVISOR

SERVICE INVOICE

R200017824 92

INVOICE DATE

4/15/2023

Customer Phone:

DATE ARRIVED	SALES TYPE	TERMS	ID	ADVISOR	CUSTOMER PO	DATE INVOICE	
1/19/2023 4:40PM			3CM01957	KEVIN		4/15/2023	
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	IN SERVICE	DOOM IN	DOOM OUT
2003	FCC	XC CHASSIS	4UZAABHV93CM01957	RV	11/18/2003	35,193	35,193

Sold Operations

JOB #1 EA-CUM EXPRESS CUMMINS ENGINE COMPL. SERVICE - IBS

COMPLAINT EXPRESS CUMMINS ENGINE COMPLAINT ** LOST 6 GALLONS OF OIL. CAN SEE OIL ALL OVER THE ENGINE.

CAUSE

SERVICE INVOICE:

REFERENCE: |

Sold Operations (Cont.)

REMOVE ENGINE BELT. REMOVE AIR FILTER ASSEMBLY REMOVE AIR INTAKE TO ENGINE
REMOVE ELECTRICAL FROM CHASSIS SIDE. REMOVE POWERS AND GROUNDS OFF
ENGINE. REMOVE POWERS AND GROUNDS OFF ALTERNATOR. REMOVE ALTERNATOR.
REMOVE AC COMPRESSOR DID NOT REMOVE ANY OR BREAK LOOSE AC LINES. REMOVE
TRANSMISSION LINES REMOVE BRACKETS AND HOSES OFF ENGINE ALL THIS BECAUSE
ENGINE HAS TO COME OUT BOTTOM OF UNIT.

REMOVED TORQUE CONVERTER BOLTS. REMOVE DRIVE SHAFT REMOVE TRANS LINES
OFF TRANSMISSION.

REMOVING BRACKETS WIRING HOSES AND AIR LINES SO CAN DROP ENGINE OUT BOTTOM
OF UNIT ONLY WAY TO REPLACE ENGINE.

IN PROCESS OF REMOVING ENGINE.

TO GET ENGINE OUT HAD TO REMOVE EVERYTHING ENGINE IS OUT.

IN PROCESS OF GETTING NEW ENGINE TO INSTALL.

MOVING OVER MOUNTS FROM OLD ENGINE. AND INSTALL NEW BLOCK HEATER IN
BLOCK.

IN PROCESS OF INSTALLING NEW ENGINE

REMOVE AND INSTALL CORRECT BELLHOUSING AND INSTALL REAR MOTOR MOUNTS

INSTALLED BRACKETS FOR AC AND ALTERNATOR THEN INSTALL AC AND ALTERNATOR

INSTALL ENGINE FAN DRIVE INSTALL PULLEY FOR SERPENTINE BELT. TORQUE ALL
MOTOR MOUNTS TO SPEC. INSTALL AND TORQUE FLEX-PLATE. INSTALL NEW REAR MAIN
SEAL.

INSTALLING ACCESSORIES.

INSTALL TRANS AND TORQUED TO SPEC.

UNIT FAILED TEST DRIVE WILL DO DIAGNOSTICS WHY UNIT OVERHEATING.

UNIT ON TEST DRIVE.

UNIT PASSED TWO EXTENDED ROAD TEST WITH NO ISSUES.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	SOFTW	Technology Charge		
	LABOR			
1	200C/3289864	BELT,V RIBBED		
1	200C/3289864	BELT,V RIBBED		
1	200C/3289864	BELT,V RIBBED		
3	200C/3900630	SCREW,HEX FLANGE HEAD CAP		
1	200C/3900679	SCREW,HEX FLANGE HEAD CAP		
1	200C/3901249	SCREW,HEX FLANGE HEAD CAP		
1	200C/3925883	SCREW,HEX FLANGE HEAD CAP		
12	200C/3935892	SHAFT,ROCKER LEVER		
1	200C/3937219	LEVER,ROCKER		
1	200C/3954655	COUPLING,PLAIN HOSE		
1	200C/3955045	TUBE,FUEL SUPPLY		
1	200C/3955094	BRACE,AIR COMPRESSOR		
1	200C/3955465	TUBE,CPR WATER INLET		

SERVICE INVOICE: .

REFERENCE:

Sold Operations (Cont.)

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	200C/3955466	TUBE,CPR WATER OUTLET		
1	200C/3958304	HOUSING,GEAR		
1	200C/3959312	BRACE,AIR COMPRESSOR		
1	200C/3963983	WASHER,SEALING		
8	200C/3963990	WASHER,SEALING		
1	200C/3976833	TENSIONER,BELT		
1	200C/4890833	SEAL,OIL		
1	200C/4933532	PLUG,PIPE		
1	200C/4988280	GASKET,HYDRAULIC PUMP		
1	200C/5286964	COMPRESSOR,1 CYL AIR		
1	200C/DR6290RX	ENG ISB 5.9 02 B 260@2600		
-1	200C/DR6290RX-CORE	ENG ISB 5.9 02 B 260@2600		
1	200F/04-18912-000	PIPE, EXH OUT		
1	200F/04-19104-009	PIPE-FLEX EXH, 4X9 INCH, SST		
1	200F/05-17927-000	HOSE RAD LOWER		
1	200F/05-17927-000	HOSE RAD LOWER		
1	200F/05-20559-000	HOSE-RAD,UPPER,ISB,EPD		
2	200F/23-14396-001	ELBOW-90,PTC, 12 MPT TO .25 NT		
3	200V/ABP N35 40PLSG	CLAMP-EXHAUST-BAND,4 INCH POL,		
2	200V/BRZ 62012H C	CLAMP-HOSE,11/16-1 1/4IN, 1/2		
1	200V/BRZ 62016H C	CLAMP 13/16 1 - 1/2		
2	200V/BRZ 62040H C	CLAMP 206 - 300		
2	200V/BRZ 62040H C	CLAMP 206 - 300		
2	200V/BRZ 62044H C	CLAMP		
2	200V/BRZ 9240H	CLAMP 2 1/16 - 3		
3	200V/BRZ 9240H	CLAMP 2 1/16 - 3		
2	200V/BRZ B9224 0341 FRB	CLAMP-HD SPRING T BOLT,HOSE,3.		
2	200V/BRZ B9224 0369FRU	CLAMP-HD SPRING T BOLT,HOSE,3.		
3	200V/BRZ CT 450 L SS	CLAMP W/ LINER		
2	200V/BRZ CT 550 L SS	CLAMP		
1	200V/BRZ HTM 550	CLAMP 4 3/4 - 5 5/8		
2	200V/BRZ HTM600	HI TORQUE CLAMP		
1	200V/BRZ VT10321 B	CLAMP-V BAND,TURBO,HOSE,3.21IN		
1	200V/BW 5010669N	GOVERNOR - D2A,NONADJUSTABLE		
1	200V/BW 5010669N	GOVERNOR - D2A,NONADJUSTABLE		
1	200V/FAR 114880 3	ECO 9 3/4 SIDEINLET		
1	200V/FAR 114880 3	ECO 9 3/4 SIDEINLET		
1	200V/FG FS19596	FILTER PAC FS		
8	200V/GT 4230SB3/8	HOSE-HTR, 38 INCH ID,BULK		
1	200V/GT 4230SB5/8	HEATER HOSE, 5/8 INCH ID		

SERVICE INVOICE:

REFERENCE:

Sold Operations (Cont.)

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
5	200V/GT 4230T3.8X25	HOSE 3/8		
1	200V/HDX DQ6032	KIT-DRYER,COALESCING FILTER&GA		
14	200V/OWT AMAB53	*ABP OAT ELC NEW STYLE50/50		
1	200V/PH VS249F10 8	COUPLING		
14	200V/PIC 4520	NON-CLOR BRAKE CLEANER		
2	200V/PIC 4520	NON-CLOR BRAKE CLEANER		
1	200V/PSM 3500022	ENGINE BLOCK HEATER		
1	200X/AHS 12MPB-12FP90	BRASS FITTING		
1	200X/AHS BN46	BRASS FITTING		
4	200X/CP1052775	SUPER,ATF,QT (565167)		
12	200X/CP1052775	SUPER,ATF,QT (565167)		
5	200X/CP1078334	FLEET SUPREME CK-4 15W40		
35	200X/NPA 7709234	14 TIE WRAP BLK		
1	200X/WUR 1890124240	PX BLUE THREADLOCKER 242 36ML		
1	200X/WUR 1890182195	PX U.GREY RTV SILICONE 13OZ.		
1	200Z/TTP S25072	AIR COMPRESSOR DISCHARGE HOSE		
1	200C/DR6290RX-CORE	ENG ISB 5.9 02 B 260@2600		
-1	PAY	DEPOSIT ON REPAIR ORDER		
1	frt	FREIGHT		
1	frt	FREIGHT/discharge line		
	C	SERIAL NUMBER 60715549		

JOB #2 ENGCUM CUMMINS ENGINE COMPLAINT

SERVICE - IBS

COMPLAINT CONTINUED STORY FROM JOB #1

CAUSE

CORRECTION

GOT ENGINE INSTALLED WITH REPLACEMENT OF COOLANT HOSES. ALSO SECURED ALL ELECTRICAL AND ANY LINES THAT HAD TO MOVE TO INSTALL ENGINE HAD TWO ADD TRANSMISSION FLUID 3 GALLONS. ADDED ENGINE OIL 22 QUARTS ADDED COOLANT 12 GALLONS. ADDED POWER STEERING FLUID 4 QUARTS. ALSO EXHAUST NECK AND FLEX WITH CLAMPS BECAUSE IT WAS RUSTED OUT. REPLACE SEVERAL BOLTS NUTS AND WASHERS BECAUSE OF SEVERE RUST. REINSTALL REAR ENGINE DOOR STEAM CLEAN UNIT IN ENGINE AREA.

QTY	ITEM	DESCI	EXTD PRICE
	LABOR		

Sold Operations Totals

SERVICE INVOICE:

REFERENCE:

EFFECTIVE: 11/16/14 - CLOSED ON SUNDAYS
NOW AVAIL: 24/7 AFTER HRS CALL OUT - PARTS OR SERV

GRAND TOTALS BELOW

TERMS AND CONDITIONS OF SALE AND DISCLAIMER OF WARRANTIES

- Disclaimer for Labor.** Seller disclaims all warranties, either express or implied, for labor performed in the repair of Owner's vehicle; however, notwithstanding the foregoing, Seller shall warranty its labor for a period of ninety (90) days next following the date of such repair.
- Disclaimer for Parts.** Any warranties on the product sold hereby are those made by the manufacturer. Seller disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of the parts.
- Parts Return Policy.** Special order electrical parts require a deposit and are not returnable. All returnable parts are subject to the manufacturer's warranty and a fifteen percent (15%) restocking charge. All claims for returned parts must be accompanied by the purchase invoice. No refund after 30 days. Seller is not responsible for labor on parts not installed by in Seller's shop. We hereby certify that all parts were produced in compliance with all applicable requirements of sections 6, 7, and 12 of the Fair Labor Standards Act of 1938, as amended, and of regulations and orders of the administrator of wage and hour division issued under section 14 thereof.
- Terms.** Strictly cash unless arrangements made. Open account terms: Net 10th prox. All invoices remaining unpaid 30 days from the date of statement they appear on are subject to late charge of 1-1/2% per month.
- Mechanic's Lien Notice.** Failure to pay invoice places any vehicles worked on subject to repossession under §9.609, Texas Business and Commerce Code.

	ESTIMATED	BILLED
LABOR		
PARTS		
MISC		
SUBLET		
SUBTOTAL		

SHOP SUPPLIES

MISC SUPPLIES

TAX

TOTAL

\$25,881.98

AUTHORIZED BY: _____ DATE: _____

PRINT: _____ EMAIL: _____

CASH SALE

Invoice Created : 08/04/2023
Invoice Closed : 08/08/2023
Service Writer :
INVOICE NO. : 00003720
ESTIMATE REF NO. : 00005329
Technician :

Customer : Dan Wellman
Address : _____

Cell : (970) 396-1490 | Work : () -
Email : cwwellman@msn.com

Vehicle : 2003 FREIGHTLINER XC
Engine : 5.9 L L6 DIESEL | VIN : 4UZAABV93CM01957
License Plate : Color : _____
Mileage In : 668 | Mileage Out : 668

◆ Description of Parts	Price	QTY	DISC	Extended
Alternator N P/N 90014450				
1 Year Warranty Battery N P/N 8144				
18 Month Warranty Battery N P/N 7236				

All Parts are New Unless Shown as Used.

◆ Description Of Labor or Service	Labor	HR	DISC	Extended
Alternator- Replace				
Battery- Replace				

► Note:

08/07/2023:

Alternators normally charge starting at about 14, alternator for this motor home was at 12.2 when it arrived. Mechanic replaced alternator and it is now charging at 14.4. Batteries were then replaced as it began to leak battery acid. After replacing batteries: on Friday 08/04/2023 battery was at 12.8 and this morning Monday 08/07/2023 it was at 12.7, meaning battery is not draining.

----- Thank You For Your Business ! -----

PARTS AMOUNT:
LABOR AMOUNT:
SUBLET AMOUNT:

SUBTOTAL:
FEES:
EPA:
SHOP SUPPLIES:
TAXES:

TOTAL:

PAYMENTS:

\$1934.92

BALANCE DUE: \$ 0.00

Paid By: I

On: 08/08/2023 12:39 PM

X _____ Date: 08/08/2023