07/14/2025

Date	Invoice #
5/16/2025	02976

Bill To

P.O. No. Terms Project Hours

Due on recpt Kenworth T600 1XKA...

Item	Description	Qty	Rate	Amount
7200	Remove and install front and rear stabilizer bushings, replace bushings on the rear upper	24.5		
CAS73568	stabilizer, replace 2 air bags. Air Bag	2		

Thank you for your business.

Subtotal
Sales Tax (9.25%)

Total

Payments/Credits -\$3,456.15

Balance \$0.00



001-001-0000117442285

REMIT TO:

INVOICE 117442285 SOURCE POS

STORE NO.	SHIP LOC.		INVUICE TYPE ARGE SALE	QUO	06/07/24	1111001110	
SOLD TO					SHIP TO		in
CHECK NO.	SHIPPER N	AME	ORIG. INVOICE NO.	FREIGHT	BILL OF LADING	TERMS	
					WILL CALL	NET 30	
PURCHASE OR	DER NO.	REQUI	SITION/JOB NUMBER		ORDERED BY	ACCOUNT	SALESMAN
					вов	534951	5328
QUANTITY ORD.	SHIPPED	MFG.	PART NUMBER	DESCRIPTION	DN	UNIT PRICE	AMOUNT
2	2		S9370		AIR SPRING 2-580/8448 (EA)		
		S	ALES TAX	SALES TAX			

BALANCE

\$440.26

Parts & Service	Freight	Taxes
6410 10	9.00	

RECEIVED BY

RECEIVED DATE



Date	Invoice #	
5/16/2025	02976	

P.O. No.	Terms	Project	Hours
CONTRACTOR OF THE PARTY OF THE	CONTRACTOR DESCRIPTION OF THE PERSON OF THE	THE CONTRACT OF STREET	Control of the last of the las

Due on recpt Kenworth T600 1XKA...

Item	Description	Qty	Rate	Amount
7200	Remove and install front and rear stabilizer bushings, replace bushings on the rear upper	24.5		
CAS73568	stabilizer, replace 2 air bags. Air Bag	2		

Thank you for your business.

Subtotal	
Sales Tax (9.25%)	
Total	\$3,456.15
Payments/Credits	-\$3,456.15
Balance	\$0.00

Date	Invoice #	
8/5/2024	02742	

	P.O. No.	Terms	Project	Hours
		Due on recpt	Kenworth T600 1XKA	
Item	Description	Qty	Rate	Amount
20	Replaced Receiver/Drier and expansion valve. Flushed A/C system. Charged system. Tested wiring to fan switch, pressure switch, Resistor and fuses. Found and repaired broken wire to Compressor. Hooked laptop to truck to check faults and test TPS. Ordered Speed sensor.		5	
Thank you for yo	ur business.		Subtotal	
			Sales Tax (9.25%)	
			Total	
			Payments/Credits	
		19,2	Balance	\$710.13

Date Invoice # 10/16/2023 02466

P.O. No.	Terms	Project	Hours	
	D	V	95061	

Item	Description	Qty	Rate	Amount
1464	Remove and install clutch, Drill broken bolt out of the flywheel housing. Replace the rear crank seal, Surface the flywheel. Replace 2 front ujoints. Replace cab shocks and control valve.	29.5		
misc	Surface the flywheel	1		
MC MAX1083	Clutch	1		
NCB306SS	Pilot Bearing	1		
MC AHB200	Multi Piece Clutch Brake	1		
PA1136001	Seal	1		
SU15-677X	Universal Joint	2		
AUT171.H004	Control Valve	1		
MO 66178	Cab Shock	2		

Thank you for your business.

Subtotal

Sales Tax (9.25%)

Total

Payments/Credits

Balance

\$5,260.50

001-001-000114216178

REMIT TO:

INVOICE

114216178 SOURCE POS

TORENIA	CILID LOG		Bulgion				7	
TORE NO.	SHIP LOC.	-	INVOICE TYPE	QUOTE		INVOICE DATE	INVOICE NU	JMBER
505		CHA	ARGE SALE			01/29/24	1142161	78
DLD TO I					нір то			
HECK NO.	SHIPPER NAME		ORIG. INVOICE NO.	FREIGHT	BILL OF LADING		TERMS	
					WII	L CALL	NET 30	
PURCHASE OR	DER NO.	REQUISITION/JOB NUMBER			ORDERED BY		ACCOUNT	SALESMA
							534951	85
QUANTIT	Y	MFG.	PART NUMBER	DESCRIPTION			UNIT PRICE	AMOUNT
ORD.	SHIPPED 1	2666 V	/PC10225ZLAS25	DUMP PUMP 2'	7 GPM (CCW AIR SHIFT		· · · ·
		5	SALES TAX	SALES TAX				
						BALANCE DUE		\$713.8
								\$713.8
1	Parts & Serv \$664		Freigh	\$.00		DUE	\$48.88	\$713.8

RECEIVED BY

RECEIVED DATE

Page 1 of 1

Customer Copy